Hanson Construction Materials Pty Ltd

martens consulting engineers

Land Resources Assessment:
Hanson's Brandy Hill Quarry Expansion

P1303888JR05V03 May 2016



Copyright Statement

Martens & Associates Pty Ltd (Publisher) is the owner of the copyright subsisting in this publication. Other than as permitted by the Copyright Act and as outlined in the Terms of Engagement, no part of this report may be reprinted or reproduced or used in any form, copied or transmitted, by any electronic, mechanical, or by other means, now known or hereafter invented (including microcopying, photocopying, recording, recording tape or through electronic information storage and retrieval systems or otherwise), without the prior written permission of Martens & Associates Pty Ltd. Legal action will be taken against any breach of its copyright. This report is available only as book form unless specifically distributed by Martens & Associates in electronic form. No part of it is authorised to be copied, sold, distributed or offered in any other form.

The document may only be used for the purposes for which it was commissioned. Unauthorised use of this document in any form whatsoever is prohibited. Martens & Associates Pty Ltd assumes no responsibility where the document is used for purposes other than those for which it was commissioned.

Limitations Statement

The sole purpose of this report and the associated services performed by Martens & Associates Pty Ltd is to provide a Land Resources Assessment at the subject site in accordance with the scope of services set out in the contract / quotation between Martens & Associates Pty Ltd and Hanson Construction Materials Pty Ltd (hereafter known as the Client). That scope of works and services were defined by the requests of the Client, by the time and budgetary constraints imposed by the Client, and by the availability of access to the site.

Martens & Associates Pty Ltd derived the data in this report primarily from a number of sources which included correspondence regarding the proposal, examination of records in the public domain, interviews with individuals with information about the site or the project, and field explorations conducted on the dates indicated. The passage of time, manifestation of latent conditions or impacts of future events may require further examination / exploration of the site and subsequent data analyses, together with a re-evaluation of the findings, observations and conclusions expressed in this report.

In preparing this report, Martens & Associates Pty Ltd may have relied upon and presumed accurate certain information (or absence thereof) relative to the site. Except as otherwise stated in the report, Martens & Associates Pty Ltd has not attempted to verify the accuracy of completeness of any such information (including for example survey data supplied by others).

The findings, observations and conclusions expressed by Martens & Associates Pty Ltd in this report are not, and should not be considered an opinion concerning the completeness and accuracy of information supplied by others. No warranty or guarantee, whether express or implied, is made with respect to the data reported or to the findings, observations and conclusions expressed in this report. Further, such data, findings and conclusions are based solely upon site conditions, information and drawings supplied by the Client etc. in existence at the time of the investigation.

This report has been prepared on behalf of and for the exclusive use of the Client, and is subject to and issued in connection with the provisions of the agreement between Martens & Associates Pty Ltd and the Client. Martens & Associates Pty Ltd accepts no liability or responsibility whatsoever for or in respect of any use of or reliance upon this report by any third party.



© May 2016 Copyright Martens & Associates Pty Ltd All Rights Reserved

Head Office

Suite 201, 20 George Street, Hornsby, NSW 2077, Australia ACN 070 240 890 ABN 85 070 240 890

Phone: +61-2-9476-9999

Fax: +61-2-9476-8767 Email: mail@martens.com.au Web: www.martens.com.au

| | Document and Distribution Status | | | | | | | | | | | | | |
|--------------|----------------------------------|--------------------------------|-----------------|-------------------|-------------------------------------|-----------|---|--|--|--|--|--|--|--|
| Autho | r(s) | Reviewer(s) | | Project Manager | | Signature | | | | | | | | |
| Ann | a Wong | Daniel Dhiaco Andrew Norris | | Andrew Norris | 3 | Morri | | | | | | | | |
| | | | | Document Location | | | | | | | | | | |
| Revision No. | Description | Status | Release Date | File Copy | Hanson Construction Materials | ı | ı | | | | | | | |
| 1 | Client Issue | Draft 18.12.2015 1E, 1P 1P | | | | | | | | | | | | |
| 2 | Revised | Final | 19.01.2016 | 1E, 1P | 1P | | | | | | | | | |
| 3 | Consultation Review | Final | 27.05.2016 | 1E, 1P | 1P | | | | | | | | | |

Distribution Types: F = Fax, H = hard copy, P = PDF document, E = Other electronic format. Digits indicate number of document copies.

All enquiries regarding this project are to be directed to the Project Manager.



Contents

| 1 | OVERVIEW | 5 |
|-----|--|----|
| 1.1 | Introduction | 5 |
| 1.2 | Scope | 5 |
| 1.3 | Agency Consultation | 5 |
| 2 | SITE DESCRIPTION | 6 |
| 2.1 | Subject Site | 6 |
| 2.2 | Proposed Development | 6 |
| 3 | ASSESSMENT OF SURROUNDING LAND USES | 7 |
| 3.1 | Surrounding Land Uses | 7 |
| 3.2 | Potential Impacts on Surrounding Land Uses | 7 |
| 4 | ASSESSMENT OF SITE SOILS | 9 |
| 4.1 | Field Investigations | 9 |
| 4.2 | Site Soils | 9 |
| 4.3 | Impact Assessment of Proposed Development | 11 |
| 5 | ASSESSMENT OF AGRICULTURAL LAND CAPABILITY | 13 |
| 5.1 | Potential for Agricultural Land Use | 13 |
| 5.2 | Agricultural Impact Assessment of Proposed Development | 14 |
| 6 | ASSESSMENT OF SITE LANDFORMS AND TOPOGRAPHY | 16 |
| 6.1 | Geology and Rock Formations | 16 |
| 6.2 | Site Slopes | 17 |
| 6.3 | Topography and Quarry Landform | 17 |
| 6.4 | Land Slippage | 18 |
| | Impact Assessment of Proposed Development | 18 |
| 7 | CONCLUSIONS AND RECOMMENDATIONS | 20 |
| | REFERENCES | |
| | ATTACHMENT A – SITE PLAN | |
| | ATTACHMENT B – MA BOREHOLE LOGS | |
| | ATTACHMENT C – LAND ZONING MAP (HANSON, 2016) | |
| | ATTACHMENT D – HANSON BOREHOLE LOGS | |
| 13 | ATTACHMENT E - AGENCY CONSULTATION | 76 |



1 Overview

1.1 Introduction

This land resources assessment forms part of an Environmental Impact Study (EIS) submitted to the NSW Department of Planning and Environment (DoPE) to address Secretary's Environmental Assessment Requirements (SEARs) for the proposed expansion of Hanson's Brandy Hill Quarry, 979 Clarence Town Road, Seaham, NSW (SSD-5899).

This report should be read in conjunction with Martens and Associates (MA) Surface Water Assessment of the site (P1303888JR03V09, 2016b).

1.2 Scope

This assessment has been completed in order to satisfy amended SEARs issued by NSW DoPE (November 11, 2014) and recent correspondence with DoPE, relating to preparation of a land resources assessment. It shall:

- Assess surrounding land uses and summarise potential impacts due to the proposed development.
- Assess site soils.
- o Assess agricultural land capability.
- Assess site landforms and topography, including review of rock formations, steep slopes and land slippage.
- Review potential impacts on site soils, agricultural land capability, landforms and topography due to the proposed development.

1.3 Agency Consultation

Consultation with NSW Department of Agriculture was undertaken in preparation of this document. Details of correspondence are provided in Attachment E.



2 Site Description

2.1 Subject Site

The site is located at 979 Clarence Town Road, Seaham, NSW and comprises 22 individual lots owned by the Client within Port Stephens Shire Council. It has been used for extractive industry and processing of rhyodacite hard rock aggregate since 1983. The site occupies approximately 561 ha of which 18.6 ha is occupied by the quarry; 11.1 ha by the crushing plant; 5.3 ha by the aggregate stockpile area; and the remainder being bushland and cleared lands. The Client advises that the existing quarry consent is to a maximum excavation depth of 30 mAHD. The site layout and aerial is provided in Attachment A, SK001.

Further details regarding site and surrounding conditions are provided in the project Preliminary Environmental Assessment (Hanson, 2012a).

2.2 Proposed Development

Proposed final form development layout is shown overlaying recent site survey in Attachment A, SK002. The proposed expansion works include:

- 1. Expansion of the currently approved extraction boundary of the quarry to extend the life of operations by approximately 30 years.
- 2. Extraction to a maximum depth of -78 mAHD.
- 3. Increased annual extraction limit to 1.5 Mt per annum.
- 4. Relocation of existing plant infrastructure and incorporation of a new concrete batching plant with a capacity of 15,000 m³ per annum.
- 5. Receiving and recycling 20,000 t of concrete waste per annum.
- 6. New pre-coat plant and mobile pug-mill.



3 Assessment of Surrounding Land Uses

3.1 Surrounding Land Uses

A land use zoning map (produced by Hanson, 2016) based on Port Stephens LEP (2013) is provided in Attachment C. Site and surrounding land uses include:

- o RU1 Primary Production.
- o RU2 Rural Landscape.
- o E2 Environmental Conservation.
- o E3 Environmental Management.
- o SP2 Infrastructure (Cemetery).
- o R5 Large Lot Residential.

3.2 Potential Impacts on Surrounding Land Uses

Potential impacts which may arise due to the proposed development have been considered in a number of expert reports. Potential impacts and the reports in which they have been addressed include:

- Land resources impacts addressed in this report.
- o Biodiversity impacts refer Appendix 7 of the EIS.
- o Traffic and transport impacts refer Appendix 8 of the EIS.
- Noise impacts refer Appendix 9 of the EIS.
- Blasting impacts refer Appendix 10 of the EIS.
- Air quality impacts refer Appendix 11 of the EIS.
- Heritage impacts refer Appendix 12 of the EIS.
- Water impacts refer Appendix 13 of the EIS.
- Waste impacts refer Appendix 14 of the EIS.
- Visual impacts refer Appendix 15 of the EIS.
- Hazard impacts refer Appendix 16 of the EIS.
- o Socio-economic impacts refer Appendix 17 of the EIS.



Potential impacts to sensitive receivers within each surrounding land use have been considered in these reports, as well as the acceptability of impacts and recommended mitigation measures. The main body of the EIS summarises the pertinent findings of each impact assessment report.

Duplication of these findings has not been undertaken as part of this assessment. Rather, this report addresses the following potential land resource impacts, which have not been specifically addressed in the other reports:

- o Soil impacts refer Section 4 of this report.
- Agricultural land capability impacts refer Section 5 of this report.
- Landforms and topography impacts refer Section 6 of this report.



4 Assessment of Site Soils

4.1 Field Investigations

A site inspection was undertaken on 29th January 2015 for a Wastewater Assessment (P1303888JR04V01, 2015b), and included:

- Walkover inspection of the site to assess existing site conditions, local topography, geology, soil characteristics, hydrology and vegetation.
- Excavation of three boreholes (BH 101, BH 102, BH 103) using a 4wd truck mounted hydraulic auger to a maximum depth of 2 m below ground level (mBGL) to allow for the characterisation of underlying soils.
- Collection of representative soils samples from boreholes for future reference.

Borehole locations are shown on the site plan in Attachment A, SK001 and detailed borehole logs are provided in Attachment B.

4.2 Site Soils

4.2.1 Soil Landscape Mapping

The Soil Landscapes of the Newcastle 1:100,000 Sheet (Soil Conservation Service of NSW, 1995) indicates that site soils are Seaham (SE) and Hungry Hill (HH) on Carboniferous volcanics and sediments. Soils are primarily shallow to moderately deep (30 – 120 cm) rapidly drained loams and well / imperfectly drained soloths, with some moderately deep (> 140 cm) imperfectly / well drained chocolate soils on colluvial benches, moderately deep (> 90 cm) poorly drained structured loams on small alluvial flats, and shallow to moderately deep (20 – 100 cm) well drained lithosols. Limitations noted include steep slopes, mass movement hazard, shallow & stony soils, seasonal waterlogging (for lower slopes/benches), high erosion hazard, localised rock outcrops, and strongly acidic soils of low fertility.

Soils at high elevation (generally > 40 mAHD) are described as being 0.3 – 1.2 m deep and soils at low elevation (generally < 40 mAHD) as being 1 – 3 m deep. Soils at low elevation are also classified as being swampy and/or drainage plains, and limitations noted include being seasonally waterlogged and/or having a permanently high water table. However, the lower lying areas to be impacted by the proposed quarry expansion are better characterised as side slopes and would more closely correspond to the description for > 40 mAHD soil profile. We



consider it likely that the water table would be $0-5\,$ mBGL for the majority of low-lying swamp and rural land within the mapped Newcastle area.

4.2.2 Site Investigation

Site soil profile is summarised in Table 1 with detailed Martens and Associates (MA) borehole logs in Attachment B. A summary of site soil characteristics is provided in Table 2.

Table 1: Summary of typical soil layers for the site.

| Layer | Depth (m) ¹ | Agricultural Classification |
|------------|------------------------|-----------------------------|
| Loamy sand | 0.0 – 0.2 | LS |
| Sandy clay | 0.2 – 0.7 | SC |

Notes:

Table 2: Summary of site soil characteristics.

| Feature | Details | Description | Impact on Erosion |
|----------------------------|-----------|---|-------------------|
| Soil permeability category | 2a and 4a | Soils are moderately permeable. | Low |
| Coarse fragments (%) | 0 - 20% | Soils have low coarse fragment content. | Low |
| pH (1:5) ¹ | 4.5 | Soils are acidic. | Moderate |
| ECe (dS/m) ¹ | <4 | Soils not saline. | Low |
| P-sorption (mg/kg) 1 | 552 | Soils have a high phosphorus sorption capacity. | NA ² |

<u>Notes:</u>

Site specific soil testing was conducted as part of the EIS for the currently approved quarry by Hunter Valley Mining Corporation (1983). These findings were largely consistent with MA investigation findings:

- The majority of the site consists of sandy loams (< 50 cm) overlying weathering bedrock, with some gravels and kaolinite clays, as well as areas of rock outcrop.
- The soil layer thickens towards the base of the existing quarry due to colluvial deposits from upslope, and alluvial deposits are present in local drainage lines.
- o Soils are acidic with pH values ranging from 4.5 5.5.



Depth varies – indicative only.

¹ Chemical properties estimated based on local experience and Soil Landscapes of the Newcastle 1:100,000 Sheet (1995).

²Not applicable.

4.2.3 Acid Sulfate Soils

The site is mapped on the Department of Land and Water Conservation (DLWC) Acid Sulfate Soil Risk Map 1:25,000 Sheet 64 (1997) as 'no known occurrence of acid sulfate soil materials'.

The Port Stephens Council Local Environmental Plan (LEP) 2013 Acid Sulfate Soils Map Sheet ASS_004 classifies the site as Class 5, which does not typically consist of acid sulfate soils.

4.3 Impact Assessment of Proposed Development

4.3.1 Potential Impacts

Potential impacts which may arise due to the proposed development include:

- Surface soil erosion due vegetation disturbance and stormwater runoff from the proposed quarry.
- Increased sedimentation in receiving drainage lines due to site erosion.

4.3.2 Impact Assessment

Assessment of the site soils indicates that the sandy loam soils are not dispersive but have significant erosion potential. The site is not impacted by acid sulfate soils, hence adverse impacts on the ecosystem due to acidified soil and surface waters are not expected.

The proposed development will change the land use of existing vegetated areas to quarry. This will increase annual sediment loads running off of quarry faces. Site sediment erosion and control plans have been developed in order to address the risk of increased sediment loads. For more detail, refer to the MA Surface Water Assessment (P1303888JR03V09, 2016b).

Site sedimentation basins have been conservatively designed using best management practice in accordance with industry standards. These basins will ensure compliance with site Environmental Protection Licence (EPL) conditions by capturing and treating stormwater flows and, in conjunction with other sediment and control measures, ensuring there is no unacceptable increase in sediment loads from the site. Sediment and erosion control measures shall be applied during construction works stages to ensure mitigation of potential water quality impacts.

Site discharges will continue to be regulated under the site EPL #1879 conditions, and hence will ensure no unacceptable impacts on total



suspended solids (TSS) concentrations, oil and grease concentrations, and surface water pH.

4.3.3 Mitigation Measures

Mitigation measures have been incorporated within the quarry's design and include sediment basins and water capture, recycling and reuse systems.

These measures are considered adequate to appropriately mitigate risks.



5 **Assessment of Agricultural Land Capability**

5.1 Potential for Agricultural Land Use

Agricultural use is the most significant land use for the site and surrounding area based on the land zoning map (Attachment C) and has hence been assessed in greater detail as part of this assessment. We note that potential impacts to all other surrounding land uses have been assessed in other expert reports as summarised in Section 3.2.

Potential for agricultural land use is assessed based on constraints to agricultural production. NSW Agriculture Agfact AC. 25 (2002) provides guidelines on classifying the potential for agricultural land use. Classifications range from Class 1, representing land with few constraints and potential for a wide range of crops to be grown profitably, to Class 5, representing land with severe constraints which is unsuited to agriculture.

As discussed in Section 4.2, there are a number of constraints on the site which affect the agricultural potential, including:

- Shallow soils and areas of rocky outcrops.
- o Rapidly drained (sandy side slopes) and poorly drained (swampy valley floors) soils.
- Steep slopes.
- Acidic soils of low fertility.

Based on these constraints and the NSW Agriculture classifications, the site has a low agricultural capability and is likely Class 4 or 5, which are defined as follows:

- Class 4: Land suitable for grazing but not for cultivation. Agriculture is based on native pastures or improved pastures established using minimum tillage techniques. Production may be seasonally high but the overall production level is low as a result of major environmental constraints.
- Class 5: Land unsuitable for agriculture, or at best suited only to light grazing. Agricultural production is very low or zero as a result of severe constraints, including economic factors which prevent land improvement.

(NSW Agriculture Agfact AC. 25, 2002)



NSW Department of Agriculture has been consulted to confirm this classification, with details of correspondence provided in Attachment E. They concur that the land is most likely Class 5 and that further detailed assessment of agricultural potential is not required.

5.2 Agricultural Impact Assessment of Proposed Development

5.2.1 Potential Agricultural Impacts

Potential impacts which may arise due to the proposed development include:

- o Reduction to site agricultural use potential.
- o Bore drawdown at nearby poultry farms.

5.2.2 Impact Assessment

Existing site agricultural land use potential is considered to be minimal as agreed by NSW Department of Agriculture, and hence any further reductions to the agricultural land use potential of the site due to proposed quarry expansion are considered negligible.

NSW Department of Agriculture requested in their correspondence (Attachment E) that nearby poultry farm bores are assessed for potential drawdown. Drawdown at all licenced bores in the study area has been assessed in detail within the project Hydrogeological Assessment (P1303888JR02V04, 2015a). Within the Hydrogeological Assessment refer to Sections 6.2.4 and 6.3.5 for model results discussion, Sections 8.2 and 11 for impact management discussion, and Attachment C Figure 47 for predicted offsite bore drawdown plot. The assessment concluded that one nearby licenced bore (GW078135) is modelled to be subjected to >2 m of drawdown due to the proposed development.

In accordance with the NSW Aquifer Interference Policy (2012), it was recommended that further works are undertaken to determine measures required, to the Minister's satisfaction, to ensure long-term bore viability will not be affected or to assess necessary 'make good' provisions. It is also recommended that groundwater level monitoring be undertaken at this bore prior to proposed quarrying progression below existing approved quarry floor level to provide a benchmark for impact assessment. The Applicant's statement of commitments is to include measures to monitor and, should negative impacts be identified, address any loss of bore yield.



5.2.3 Mitigation Measures

Impacts to site agricultural potential are negligible and hence works are not considered necessary to mitigate this risk.

Further works are recommended to ensure offsite bore viability and necessary 'make good' provisions, and the Applicant has committed to addressing any loss of bore yield.

These measures are considered adequate to appropriately mitigate risks.



6 Assessment of Site Landforms and Topography

6.1 Geology and Rock Formations

6.1.1 Geological Mapping

The Newcastle 1:100,000 Geological Sheet 9232 (Geological Survey of NSW, Department of Mines, 1975) identifies the site as being underlain by the Carboniferous Paterson Formation which consists of acid lava flows, crystal tuff, interbedded conglomerate and ignimbrite.

Carboniferous rocks outcrop principally on the northern side of the Hunter River and are separated from the younger Coal Measure geology to the south by a fault system, known as the Hunter Thrust. The area is highly faulted and these faults cut off geological units abruptly.

6.1.2 Site Geological Investigations

Hanson has previously conducted geological investigations at the Brandy Hill Quarry, with a total of 10 site boreholes located around the quarry expansion area drilled up to approximately 110 mBGL. 3 boreholes were drilled as part of previous investigations in 2012 (BH401A, BH401, BH400), and 7 as part of the expansion EIS in 2014 (BH1401, BH1402, BH1403, BH1404, BH1405, BH1406, BH1407). Borehole locations are shown in Attachment A, SK001 with graphic drill logs provided in Attachment D.

The boreholes comprised of sandy loams and clays overlying weathered ignimbrite, sandstone or conglomerate, and confirmed the presence of Seaham Glacial Beds comprising sandstone, mudstone overlying Patterson Volcanics conalomerate comprising predominantly fine grained mudstone and sandstone (Hanson, 2014). At boreholes within the quarry void, ignimbrite is present at the surface due to soil overburden removal. Where rock overburden is present the sandstone, conglomerate and mudstone layers range from 10 to 58 mBGL. Isolated thin lenses of conglomerate, sandstone and granite are present within the ignimbrite rock mass. At the base of the ignimbrite, bore holes intercepted either sandstone or mudstone belonging to the Mount Johnson Formation.

Field measurements indicate the base of the ignimbrite dipping at 10 degrees to the south east. The ignimbrite is described as a hard rock, and the specific gravity has been tested at 2.67 for the ignimbrite and 2.6 for the sandstone (Hanson, 2014).



6.2 Site Slopes

The existing quarry (Attachment A, SK001) is situated on the eastern slopes of Brandy Hill (approximate elevation 35 to 100 mAHD) adjacent to the Deadman's Creek incised valley (approximate elevation 25 to 55 mAHD). Pre quarrying contours are given in the EIS for the currently approved quarry (Hunter Valley Mining Corporation, 1983) and show slopes of 10 – 30%. Slopes to the south of the site are generally consistent with pre quarrying slopes. Slopes north of the site on the opposite side of Deadman's Creek gradually increase to steeper slopes of > 50%.

Batter slopes of quarry benches range from approximately 60° to beyond 90° (over steepened), with the average batter slope being approximately 80°. The average pit slope of the quarry is approximately 25°.

6.3 Topography and Quarry Landform

The existing extraction pit collects stormwater from the disturbed portion of the site. The top bench of the existing pit represents the top of this catchment. Bunds direct stormwater runoff upslope of the pit north east to Deadmans Creek, west to an unnamed drainage path running to Barties Creek, and south east to the site western dam and through the site processing area.

The existing quarry pit is approximately 900 m long, 380 m wide and 70 m deep. The quarry has 6 benches and 2 rehabilitated former benches on the uppermost slopes which are no longer used for quarrying. Benches are typically east to south east facing and are stepped down on the mid to lower north-west slopes of Brandy Hill. Benches increase in length from upper to lower with the second last bench wrapping around the quarry to form an amphitheatre shape, with an opening to the east. The final drop cut to the currently approved extraction limit of 30 mAHD was made on 28th March 2014 and is currently being excavated.

The pit has elevations ranging from approximately 95 mAHD at the uppermost bench to 31 mAHD within the currently active base bench.

The crushing plant and stockpiling area is approximately 420 m long and 410 m wide. The plant is located on a mostly flat surface south of the quarry and haul road at approximately 33 to 37 mAHD. Aggregate stockpiles are located on three benches with elevations ranging from 32 to 45 mAHD. The plant area is separated from the quarry floor by a haul road up to 13 m above the quarry floor.



Natural ground levels at the site range from approximately 111 mAHD north-west of the quarry to approximately 32 mAHD south of the processing area.

6.4 Land Slippage

A Geotechnical Assessment previously conducted by MA (2016a) identified land slippage hazards onsite which were related to stability of pit slopes, benches and haul roads within the quarry, due to discontinuities within the rock mass. Risks of slope failure due to groundwater and seepage inflows are considered to be low (P1203463JR02V02, 2016a).

Potential hazards identified were generally confined to individual benches and included rock toppling, rock fall, rock slide and wedge failure. Complete bench failure was not observed and is not expected to be a likely failure mechanism. Further details of geotechnical investigations are provided in the site Geotechnical Assessment (P1203463JR02V02, 2016a).

Importantly, we note that land slippage hazards are localised within the quarry footprint. Any potential land slippage failure would be internalised, and there is no increased risk of land slippage in outside of the quarry footprint.

6.5 Impact Assessment of Proposed Development

6.5.1 Potential Impacts

Potential impacts which may arise due to the proposed development include:

 Slope failure within the quarry footprint extents, resulting in risk to life and commercial consequences of damage to the quarry and associated infrastructure.

6.5.2 Impact Assessment

The site has no history of major land slippage within the quarry footprint extents. Assessment of site slopes indicates that both pit slope failure risk and bench slope failure risk are generally low. The risks identified in the MA Geotechnical Assessment (P1203463JR02V02, 2016a) have been addressed and are managed through quarry operations and appropriate mitigation measures as recommended. These mitigation measures will continue during quarry expansion.

It is anticipated that internal slope stability risks are minimal and can be effectively managed through the implementation of the proposed geotechnical stability control measures.



Internal quarry slope failure and land slippage are risks inherent to the quarry operation. These risks are addressed through quarry operations and management, including regular inspection and maintenance. Quarry management recommendations provided in the past Geotechnical Assessment (P1203463JR02V02, 2016a) shall continue to be incorporated in quarry development.

6.5.3 Mitigation Measures

Land slippage controls have been incorporated within the quarry's design based on the recommendations of the MA Geotechnical Assessment (P1203463JR02V02, 2016a), and include:

- Trimming of batter slopes: Removal of hazardous blocks of rock and reduction of batter slope angles.
- Bunds: Installation at the base of the batter to control falling rocks, which are to be removed if bunds fill up.
- Positions of future bunds and material stockpiles: Located away from the edge of benches to prevent rock fall and unnecessary loading which may lead to instability.
- Cut-off drains: Suitable drains are excavated into the rock or formed by mound construction, and are used to intercept surface water run-off and reduce flows down the batter face. Sheet flow across slope surfaces is to be avoided during quarry expansion.
- Drains: Properly designed and constructed stormwater and subsoil drainage to prevent scour, ponding and limit inflow to a slope.

These measures are further detailed in the MA Geotechnical Assessment (P1203463JR02V02, 2016a). When implemented in conjunction with regular inspection and on-going maintenance, these measures are considered adequate to control internal quarry land slippage risk.

These measures are considered adequate to appropriately mitigate risks.



7 Conclusions and Recommendations

This Land Resources Assessment has yielded the following findings regarding potential impacts due to the proposed development:

- Potential impacts to surrounding land uses have been assessed in a number of expert reports which also consider acceptability of impacts and recommended mitigation measures.
- Assessment of site soils indicates that the site is not impacted by acid sulfate soils.
- o Increased site sediment and erosion will be effectively managed by the proposed sediment erosion control measures, such as sedimentation basins and water capture, recycling and reuse systems. The quarry will continue operating in accordance with EPL conditions, thereby ensuring no significant adverse off site sediment impacts.
- o The site has a low potential (most likely Class 5 land) for agricultural land use as confirmed by NSW Department of Agriculture. Offsite impacts to nearby licenced groundwater users have been assessed, and should unacceptable impacts occur the Applicant's statement of commitments includes measures to monitor and address any loss of bore yield.
- o The site has no history of major land slippage, and the assessment of site slope failure indicates that internal slope stability risks are minimal with the implementation of the proposed geotechnical stability controls.
- Any potential land slippage failure would be internalised, and there is no risk of slope slippage in the external environment.
- While risks of localised internal land slippage have been identified, they are considered acceptable as they will be managed by appropriate controls and ongoing monitoring.

The impacts of the proposed quarry extension at Hanson's Brandy Hill Quarry are considered acceptable with the proposed mitigation measures implemented. The quarry shall not impact on the soils, agricultural land capability, and landforms and topography in such a way as to have significant detrimental effects on surrounding ecological systems or land use for the duration of the proposed project and after rehabilitation.



8 References

Department of Land and Water Conservation (1997), Newcastle 1:25,000 Acid Sulfate Soil Risk Sheet 64.

Department of Primary Industries Office of Water (2012), NSW Aquifer Interference Policy.

Geological Survey of NSW, Department of Mines (1975), Newcastle 1:100,000 Geological Sheet 9232.

Hanson (2012a), Brandy Hill Quarry Expansion Project Preliminary Environmental Assessment.

Hanson (2012b), Brandy Hill Site Geology and Drilling Report.

Hanson (2014), Brandy Hill Site Geology and Drilling Report.

Hunter Valley Mining Corporation (1983), Environmental Impact Assessment, Hard Rock Quarry and Processing Plant at Brandy Hill Near Seaham.

Martens and Associates (2015a), Hydrogeological Assessment: Hanson's Brandy Hill Quarry Expansion, Ref: P1303888JR02V04.

Martens and Associates (2015b), Wastewater Assessment: Hanson's Brandy Hill Quarry Expansion, Ref: P1303888JR04V01.

Martens and Associates (2016a), Geotechnical Assessment: Brandy Hill Quarry, Seaham, NSW, Ref: P1203463JR02V02.

Martens and Associates (2016b), Surface Water Assessment: Hanson's Brandy Hill Quarry Expansion, Ref: P1303888JR03V09.

NSW Agriculture (2002), Agricultural Land Classification, Agract AC.25.


Port Stephens Council (2013) LEP 2013, Acid Sulfate Soils Map Sheet ASS 004, 1:80,000.


Soil Conservation Service of NSW (1995), Newcastle Soil Landscape Series Sheet 9232, 1:100,000.



9 Attachment A – Site Plan







10 Attachment B – MA Borehole Logs




| CL | IEN ⁻ | Γ | Н | anson C | onst | onstruction Materials Pty Ltd COMMENCED 29/01/15 COMPLETED 2 | | | | | | | 29/01/15 REF BH10 | | | | | |)1 | | | |
|---|------------------|-------|----------|-------------------------|----------|--|--------------------------|---------------------------------------|---|--|---|---|-------------------------------------|---|----------------------|----------------------|--|--------------------------|-----------|--|----------------------------|--|
| PR | OJE | СТ | W | astewat | er As | se | ssment | | | LOGGED | AB/AT | CHEC | CHECKED ANN | | | | | Sheet 1 | _ | 1 | | |
| | | | anson B | | _ | | | ISW | GEOLOGY | Dalwood Group | | VEGETATION Bushland | | | | PROJECT NO. P1303888 | | | | | | |
| _ | IPME | | IME | ISIONS | | | Mounted Au).9m depth | ger | | EASTING NORTHING | - | | RL SURFACE 41.60m AHD ASPECT South | | | | SLOPE 5-7° | | | | | |
| - | | | | ION DA | | 11 × C | л.этт аерит | | MAT | ERIAL DAT | ·A | ASFE | - | South | | SAMPLING & TESTING | | | | | | |
| МЕТНОВ | SUPPORT | WATER | MOISTURE | DEPTH (M) | DRILLING | | GRAPHIC LOG | CLASSIFICATION | | L DESCRIPTIO city or particle char y and minor comp consistency/relativ | acteristics, onents, ve density, | CONSISTENCY | | DENSITY INDEX | TYPE | DEPTH(M) | RESULTS AND ADDITIONAL OBSERVATIONS | | | | | |
| V | Nil | N | М | | | | | SP | Loamy SAND - Dark | hrown weak | dy structured | | | | | | | | - TOPS | OIL | _ | |
| v | Nil | N | м | 0.1 | | | | CL | , | · | • | | | | | | - RESIDUAL | | | | | |
| | | | | _ _ _ _ 0.5 | | | | 5. | Sandy CLAY - Lor becoming light brov str | w plasticity, c wn with depth ructured. | lark brown, , moderately | | | | | | | | - V Bit r | efusal at 0.5i | – – n. 0.5 | |
| тс | Nil | N | D | | | | | | SILTSTONE - Bro | wn, distinctly | weathered. | | | | Α | 0.7 | 3888/10 | 1/ 0.7 | | | - - 0.75_ - | |
| | | | | 0.9 | | | | | TC Bit refusal | at 0.9m on s | Itstone. | | | | | | | | | | | |
| | | | | 1.0 | | | | | | | | | | | | | | | | | 1 <u>.0</u> _ _ _ | |
| | | | | 1.25 | | | | | | | | | | | | | | | | | - 1.25_ - | |
| | | | | - - | | | | | | | | | | | | | | | | | <u>-</u> - | |
| | | | | 1.5 | | | | | | | | | | | | | | | | | 1 <u>.5</u> - - | |
| | | | | 1.75 - - | | | | | | | | | | | | | | | | | 1.75_ - | |
| | | | | 2.0 | | | | | | | | | | | | | | | | | _ 2.0 _ _ _ | |
| N Natural exposure SH Shoring N None observed D Dry RESIS* X Existing excavation SC Shotcrete X Not measured M Moist L Lov BH Backhoe bucket RB Rock Bolts \(\frac{\text{V}}{V}\) Water level Wet M Moth HA Hand auger Nii No support \(\frac{\text{V}}{V}\) Water level Wp Plastic limit H Hig | | | | | | | | e obse neasu er leve er outf | rved D Dry RESISTA red M Moist L Low I W Wet M Mode Wp Plastic limit H High low WI Liquid limit R Refus | NCE VS Ve S S S S S S S S S S S S S S S S S | oft L Loos rm MD Med ff D Dens rry Stiff VD Very | / Loose se ium Dense se Dense | U Undis | r sample sample sturbed sa rbed sam ure conte | ample iple ent | pp S VS D(| | ic cone meter sity | | CLASSIFIC/ SYMBOLS / SOIL DESC Y USCS N Agricu | AND RIPTION | |
| | | | | | | Е | XCAVATIO | ON LO | OG TO BE READ IN CONJUN | CTION WITH A | CCOMPANYING I | REPORT N | OTES A | ND ABI | BREV | /IATIC | ONS | | | | | |
| ı | | | | | | | | | | ************ | COCIATES DTVI | TD | | l | | | | - | | | | |

| CL | IEN | Τ | Н | Hanson Construction Materials Pty Ltd commenced 29/01/15 | | | | | | | COMPLETED 29/01/15 REF | | | | | | | 3H10 | 2 | | |
|---|---------|-------|--------------------------|--|-----------------------|--------------|----------------|--|---|--|--------------------------------|---|----------------------|---------------------|---|-----------------------------|-----------|--|---|--|--|
| PR | OJE | СТ | CT Wastewater Assessment | | | | | | LOGGED AB/AT | | | | | | | Sheet 1 | _ | | _ | | |
| | | | anson E | Brandy | Hill Quar | ry, I | NSW | GEOLOGY | Dalwood Group | VEGETATI | Bushland | | PROJECT NO. P1303888 | | | | | | | | |
| EQUIPMENT EXCAVATION DIMENSION | | | | 1010:12 | | k Mounted Au | iger | | EASTING | - | 1 | RL SURFACE 38.775m AHD | | | | | | | | | |
| EXC | | | | ION DA | | 1.5m depth | | MAT | NORTHING ERIAL DAT | · | ASPECT | 5 | South | 9.4 | | SLOPE | 5-7° | ' | | | |
| МЕТНОВ | SUPPORT | WATER | MOISTURE | | DRILLING R RESISTANCE | GRAPHIC LOG | CLASSIFICATION | MATERIAI SOIL NAME, plastic colour, secondar moisture condition, ROCK NAME, grail | L DESCRIPTIO ity or particle char y and minor comp consistency/relativ | N acteristics, onents, re density, | CONSISTENCY | DENSITY INDEX | TYPE | DEPTH (M) | MPLING & TESTING RESULTS AND ADDITIONAL OBSERVATIONS | | | | ıs | | |
| v | Nil | N | М | - | | | SP | Loamy SAND - Dark | Loamy SAND - Dark brown, weakly structured. | | | | | | | | - TOPSOIL | | | | |
| V | Nil | N | М | 0.1 - 0.25 - - 0.5 - - 0.7 | | | CL | Sandy CLAY - Lor becoming light brov str | | | | | A | 0.3 | 3888/10 | 02/0.3 | - RESIDU | JAL usal at 0.7m. | - 0.25_ - - 0.5_ | | |
| тс | Nil | N | D | 0.75 | | | | SILTSTONE - Bro | wn, distinctly | weathered. | | | | | | | - ROCK | | 0.75_ - - - 1.0 - - - - - - | | |
| | | | | 1.5 | | | | TC Bit refusal | at 1.5m on si | Itstone. | | | | | | | | | 1.55 | | |
| N Natural exposure SH Shoring N None observed D Discrete X Existing excavation SC Shotcrete X Not measured M M Backhoe bucket RB Rock Bolts W Water level W W PI No support | | | | | | | | rred M Moist L Low el W Wet M Mode Wp Plastic limit H High flow WI Liquid limit R Refus | NCE VS Ve S Sc erate F Fir St Sti sal VSt Ve H Ha | m MD Medium [ff D Dense ry Stiff VD Very Dens | Dense A A Dense U U D D Se M M | luger san Julk san Judistur Disturbe Toisture | | pr S V: D: | o Pocket p Standard S Vane sho CP Dynam penetro D Field der /S Water sa | nic cone ometer nsity | test S | LASSIFICAT YMBOLS AN OIL DESCRI Y USCS N Agricultu | ND IPTION | | |
| | | | | | | EXCAVATI | ON L | OG TO BE READ IN CONJUN | CTION WITH A | CCOMPANYING REP | ORT NOTE | S AN | D ABBRE | VIATIO | SNC | | | | | | |
| | | | | | | | | | IADTENIO 8 AO | COCIATES DIVITO | | Т | | | | | | | | | |

| CL | IEN | Γ | Н | anson C | onstru | iction Ma | teri | als Pty Ltd | COMMENCED 29/01/15 COMPLETED 29/01/15 | | | | | | | REF | E | 3H103 | 3 |
|---------------------------------|---|--|--------------------------------------|--|---|-------------------------------|----------------------------------|--|---|--|------------------------------|--|--------------------|---------------------|--|--------------------------|---------------|---|---------------------|
| PR | OJE | СТ | W | astewat | er Ass | essment | | | LOGGED | AB/AT | CHECKED | Δ | ANN | | | Sheet ' | 1 of ' | 1 | |
| _ | SITE Hanson Brandy Hill Quarry, NS EQUIPMENT 4WD Truck Mounted Auger | | | | | | | NSW | | | | | | | PROJECT NO. P1303888 | | | | |
| _ | | | OIME | NSIONS | | ck Mounted Au < 2.0m depth | iger | | EASTING NORTHING | - | RL SURFA | - | 2.19m AHD South | | | SLOPE | 5-7 | • | |
| | | | | ION DA | | | | MAT | MATERIAL DATA | | | | | SA | AMPLING & TESTING | | | | |
| МЕТНОВ | SUPPORT | WATER | MOISTURE | DEPTH(M) | DRILLING H RESISTANCE | GRAPHIC LOG | CLASSIFICATION | SOIL NAME, plastic colour, secondar moisture condition, ROCK NAME, grai | consistency/relativ | acteristics, onents, re density, | CONSISTENCY | DENSITY INDEX | ТҮРЕ | DEPTH (M) | A | | SULTS / | AND ERVATIONS | 5 |
| V | Nil | N | М | - - 0.2 | 88888888888888888888888888888888888888 | | SP | Loamy SAND - Dark | s brown, weak | ly structured. | | | А | 0.2 | 3888/10 |)3/ 0.2 | - TOPSC | | 0.25 |
| ٧ | Nil | z | М | 0.5 | | | CL | Sandy CLAY - Lo becoming light brov str | w plasticity, d wn with depth ructured. | ark brown, , moderately | | | A | 0.5 | 3888/10 |)3/ 0.5 | - V Bit re | fusal at 0.7m. | - - - 0.5 |
| тс | Nil | 2 | D | 0.75 | | | | SILTSTONE - Bro | wn, distinctly | weathered. | | | | | | | - ROCK | | 0.75_ |
| | | | | - - - - 2.25 | | | | TC Bit refusal | at 2.0m on si | Itstone. | | | | | | | | | - - - 2.25 |
| N B H S C V T | Na E: H Ba A Ha Sp C Co: V-E | itural e kisting ckhoe nd au ade ncrete Bit gsten | expos exca buck ger Core | ETHOD SU sure Sh avation SC set RE Nil | JPPORT H Shoring C Shotcret 3 Rock Bo I No supp | te X Not⊪ olts ∇7 Wat | e obsomeasi er levo er out | ured M Moist L Low el W Wet M Mode Wp Plastic limit H High flow WI Liquid limit R Refus | NCE VS Ve S Sc erate F Fir St Sti | ry Soft VL Very Loo ft L Loose m MD Medium I ff D Dense ry Stiff VD Very Dens rd | ose A A Dense U U D D Se M M | Auger sa Bulk san Indistur Disturbe Toisture | | pp S VS DO | Pocket per Standard Vane she CP Dynam penetro Field den S Water sa | ic cone meter sity | test S | CLASSIFICATI SYMBOLS ANI SOIL DESCRIF Y USCS N Agricultur | ON D PTION |
| | | | | | | EXCAVATION | J NC | OG TO BE READ IN CONJUN | CTION WITH A | CCOMPANYING REP | ORT NOTE | S AN | D ABBRE | VIATIO | ONS | | | | |
| | | |) | | | | | N | MARTENS & AS | SOCIATES PTY LTD | | - [| F | no | iino | orin | a I | 00 - | |

11 Attachment C – Land Zoning Map (Hanson, 2016)





12 Attachment D – Hanson Borehole Logs




HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG

HOLE: BH-400-DH PROJECTBRANDY HILL EXTENSION DRILLED: PAGE 1 OF 5

LOCATION:56 376668,6385668

LOGGED: P BROWNE 13/9/11



Hanson

HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG

HOLE: BHQ-400-DH


PROJECTBRANDY HILL EXTENSION

PAGE 2 OF 5

LOCATION:56 376668, 6385668

DRILLED:

LOGGED: P BROWNE 13/9/11



Hanson HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG HOLE: BH-400-PC LOCATION:56 376668, 6385668 PROJECT: BRANDY HILL EXTENSION DRILLED: PAGE 3 OF 5 LOGGED: P BROWNE 13/9/11 DPH LOG **DESCRIPTION** DPH LOG **DESCRIPTION** DARK GREY, FINE GRAINED IGNIMBRITE, VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 50cm APART, MINOR CALCITE PRESENT. DARK GREY, FINE GRAINED IGNIMBRITE, VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 40cm APART.. DARK GREY, FINE GRAINED IGNIMBRITE, VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 25cm APART, MINOR 5.3 DARK GREY, FINE GRAINED IGNIMBRITE, VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 40cm APART.. DARK GREY, FINE GRAINED IGNIMBRITE, VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED,. GREY, AND PINK FINE GRAINED IGNIMBRITE, SLIGHTLY WEATHERED, MEDIUM HARD, EVEN TEXTURED, FRACTURES 45° TO CORE AXIS.. GREY, GREEN FINE GRAINED IGNIMBRITE, SLIGHTLY WEATHERED, HARD, EVEN TEXTURED, FRACTURES 25cm APART, MINOR CALCITE PRESENT., BROWN CLAYS ON DARK GREY, FINE GRAINED IGNIMBRITE, VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 30cm APART.. CALCITE FRACTURES. VEINS 45° TO CORE AXIS GREY, MINOR RED WEATHERING, FINE GRAINED IGNIMBRITE, VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 30cm APART MINOR CALCITE PRESENT .. GREY FINE GRAINED IGNIMBRITE VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED.. GREY, FINE GRAINED IGNIMBRITE, VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 40cm APART SOME 45° TO CORE AXIS. GREY, FINE GRAINED IGNIMBRITE,VERY SLIGHTLY WEATHERED, VERY HARD, EVEN 58 TEXTURED, FRACTURES 25cm APART 45 to 90° TO CORE AXIS, MINOR CALCITE PRESENT.. DARK GREY, FINE GRAINED IGNIMBRITE, VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 40cm APART. 59 LIGHT BROWN WEATHERED IGNIMBRITE FRACTURED.. GREY GREEN, FINE GRAINED IGNIMBRITE, VERY GREY FINE GRAINED IGNIMBRITE VERY SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 60cm APART.. SLIGHTLY WEATHERED, VERY HARD, EVEN TEXTURED, FRACTURES 25cm APART 45 to 90° TO CORE AXIS, MINOR CALCITE PRESENT.. COMMENTS: 1 METRE INTERVAL MISSSING IN 51 TO 54 METRE INTERVAL. THIS IS PROBALY A LABELLING ERRROR WITH THE HOLE FINISHING AT 98 METRES. I HAVE KEPT TEH INTERVALS AS PER THE MARKING

HANSON CONSTRUCTION MATERIALS **GRAPHIC** DRILL LOG BH-400-PC HOLE: LOCATION:56 376668, 6385668 PROJECT: BRANDY HILL EXTENSION DRILLED: PAGE 4 OF 5 P BROWNE 13/9/11 LOGGED: PH LOG DPH DESCRIPTION LOG DESCRIPTION GREYI GNIMBRITE, HARD, SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 15cm APART, ALSO A VERTICAL FRACTURE IN THIS INTERVAL. GREYI GNIMBRITE, EQUANT HARD FRESH TO SKEIT GNIMBRITE, EQUANT HARD FRESH TO SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 20cm APART AT 10 TO 45° TO CORE AXIS, CALCITE VEINS 10° TO CORE AXIS. BROWN CLAY ON FRACTURES. .72 GREYI GNIMBRITE, HARD, SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 15cm APART, BROWN CLAY ON FRACTURES _73 GREY GREEN IGNIMBRITE, HARD FRESH TO SKIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 20cm APART AT 10' TO CORE AXIS, CALCITE VEINS 10' TO CORE AXIS. BROWN CLAY ON FRACTURES. GREYI GNIMBRITE, HARD, VERY SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 15 TO 30cm APART, RED CLAY ON FRACTURES GREYI GNIMBRITE, EQUANT HARD FRESH TO SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 20cm APART AT 10 TO 45° TO CORE AXIS, CALCITE VEINS 10° TO CORE AXIS. BROWN CLAY ON EPACTURES GREYI GNIMBRITE, EQUANT HARD FRESH TO SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 20cm APART AT 10 TO 45° TO CORE AXIS, CALCITE VEINS 10° TO CORE AXIS. BROWN CLAY ON GREYI GNIMBRITE, HARD, VERY SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 15 TO 30cm APART, RED CLAY ON FRACTURES FRACTURES. PINK,BROWN AND GREYI WELDED GNIMBRITE, HARD WEATHERED, FELDSPAR WHITE ALTERED TO 5mm. GREY GREEN IGNIMBRITE, HARD FRESH TO SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 20cm APART AT 45 TO CORE AXIS, BROWN CLAY ON GREY IGNIMBRITE, HARD, MEDIUM WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 15 TO 30cm APART, RED CLAY FRACTURES. ON FRACTURES GREYI GNIMBRITE, HARD, VERY SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 15 TO 30cm APART, RED CLAY ON FRACTURES GREYI GNIMBRITE, HARD, FRESH TO SLIGHTLY WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 20cm APART, CALCITE VEIN PARALLEL TO CORE AXIS ALTERED. BROWN CLAY ON FRACTURES. GREY IGNIMBRITE, HARD, MEDIUM WEATHERED, FELDSPAR WHITE ALTERED TO 5mm, FRACTURES 15 TO 30cm APART, RED CLAY \$000d \$00 70 0000 ON FRACTURES

Hanson HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG BH-400-PC HOLE: LOCATION 56 376668, 6385668 PROJECT:BRANDY HILL EXTN DRILLED: PAGE 5 OF 5 LOGGED: P BROWNE 13/9/11 DPH LOG DPH DESCRIPTION LOG **DESCRIPTION** 0 GREY GREEN. FINE GRAINED IGNIMBRITE EQUANT QUARTZ ANGULAR 3mm, FELDSPAR WHITE HIGHLY WEATHERED 2mm FRACTURES 0 80cm APART 45° TO CORE AXIS. GREY GREEN MINOR PINK AND GREEN FINE GRAINED HARD IGNIMBRITE, FRACTURES 40cm APART. CALCITE FILLED VEINS 45 TP 80° 91 TO CORE AXIS 0 GREY GREEN, FINE GRAINED IGNIMBRITE EQUANT FELDSPAR WHITE HIGHLY WEATHERED 5mm FRACTURES 20cm APART 80' TO CORE AXIS. CALCITE VEINS 10' TO CORE AXIS, 92 LARGER VEIN AT 82.0m PINK FINE GRAINED HARD IGNIMBRITE. _83 BROWN AND GREY GREEN, FINE GRAINED BROWN AND GRET GREEN, FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE EQUANT FRACTURES 20cm APART 80° TO CORE AXIS. CALCITE VEINS 10° TO CORE AXIS, NOW BROWN CLAYS RED TO PINK AND MINOR GREEN FINE GRAINED MEDIUM HARD TUFFACEOUS 84 MUDSTONE 00 0 GREY GREEN FINE GRAINED MEDIUM HARD GREY GREEN, WITH MINOR RED ALTERATION IN PLACES, FINE GRAINED IGNIMBRITE. SLIGHTLY WEATHERED FRACTURES 30cm APART 80° TO CORE AXIS. CALCITE VEINS 10 TO 45° TO CORE AXIS, LARGER VEIN AT 85.0m, VERTICAL VEIN AT 86m 0 TUFFACEOUS MUDSTONE 85 0 75 0 RED FINE GRAINED MEDIUM HARD TUFFACEOUS MUDSTONE 0 PINK, MINOR GREEN, VERY FINE GRAINED MUDSTONE, CALCITE FRACTURE 45° TO CORE 0 86 RED FINE GRAIED MEDIUM HARD MUDSTONE CROSS BEDDED GREEN FINE GRAINED FRACTURED MUDSTONE PINK VERY FINE GRAINED MUDSTONE, _87 97 CALCITE FRACTURE 45° TO CORE AXIS GREY GREEN, FINE GRAINED IGNIMBRITE. SLIGHTLY WEATHERED FRACTURES 10cm APART 10' TO CORE AXIS CALCITE FILLED AND WITH BROWN RED ALTERATION GREEN AND VIOTEL MYLOTISED MUDSTONE. PINK VERY FINE GRAINED MUDSTONE, FRACTURE 20cm APART RED, VIOLET AND GREEN MYLOTISED .88 98 MUDSTONE 0 00 GREY GREEN, WITH MINOR RED ALTERATION IN PLACES, MEDIUM GRAINED SLIGHTED WEATHERED IGNIMBRITE. FELDSPAR WHITE SLIGHTLY WEATHERED. FRACTURES 30cm APART 80° TO CORE AXIS. CALCITE VEINS 10 TO 45° TO CORE AXIS, LIGHT GREY GREEN VERY FINE GRAINED MEDIUM HARD MUDSTONE CALCITE VEINS 90° TO CORE AXIS FRACTURES 60cm APART 0 _89 99 0 00 90

COMMENTS:

Hanson HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG

HOLE: BH-401-DH PROJECTBRANDY HILL EXTENSION DRILLED: PAGE 1 OF 3

LOCATION:56 377298, 6385847

LOGGED P BROWNE 13/9/11

| | r | AGE I OF 3 | LOG | GED: | Р | BROWNE 13/9/11 |
|---|-----|---|----------------|------|--|--|
| DPH | LOG | DESCRIPTION | DPH | LOG | | DESCRIPTION |
| | | RED BROWN AND GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | | | 00000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| 1 | | RED BROWN MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | 11 | | 000000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| | | RED BROWN MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | | | 00000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| 3 4 | | RED BROWN MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | 13 | | 0000000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| | | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | 15 | | 0000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| | | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | 16 | | 00000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| - - - - - - - - - - 7 | | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | | | 00000000000000000000000000000000000000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| - - - - - 8 | | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | | | 00000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| | | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | 19 | | 90000000000000000000000000000000000000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| 10 | | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE | 20 | | 0000 | RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE |
| COMMENTS | | | | | | |

HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG BHQ-401-DH HOLE: LOCATION:473475,7696862 GDA PROJECTBRANDY HILL PIT DRILLED: PAGE 2 OF 3 LOGGED: P BROWNE 13/9/11 DPH LOG DPH **DESCRIPTION** LOG **DESCRIPTION** DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. 38 DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD 39 DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. COMMENTS:

Hanson HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG HOLE: BH-401-PC LOCATION:56 377298, 6385847 PROJECT: BRANDY HILL PIT DRILLED: LOGGED: P BROWNE 13/9/11 PAGE 3 OF 3 DPH LOG **DESCRIPTION** DPH LOG **DESCRIPTION** DARK GREY FINE GRAINED ALTERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. .52 DARK GREY FINE GRAINED MEDIUM HARD 53 DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD .55 DARK GREY FINE GRAINED MEDIUM HARD RED GRANITE GREY NAD GREEN GRANITE 58 DARK GREY FINE GRAINED ALTERED IGNIMBRITE. 59 DARK GREY FINE GRAINED ALTERED IGNIMBRITE. COMMENTS:

HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG HOLE: BH-400A-DH LOCATION:56 377937,6385796 PROJECTBRANDY HILL PIT DRILLED: PAGE 1 OF 3 LOGGED: P BROWNE 13/9/11 DPH LOG **DESCRIPTION** LOG **DESCRIPTION** RED BROWN MEDIUM HARD SLIGHTLY RED BROWN AND GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. RED BROWN AND MINOR GREY MEDIUM HARD RED BROWN MEDIUM HARD SLIGHTLY SLIGHTLY WEATHERED IGNIMBRITE. WEATHERED IGNIMBRITE. RED BROWN AND MINOR GREY MEDIUM HARD RED BROWN MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE.. SLIGHTLY WEATHERED IGNIMBRITE. 13 RED BROWN AND MINOR GREY MEDIUM HARD RED BROWN MEDIUM HARD SLIGHTLY SLIGHTLY WEATHERED IGNIMBRITE.. WEATHERED IGNIMBRITE.. RED BROWN AND MINOR GREY MEDIUM HARD RED BROWN MEDIUM HARD SLIGHTLY SLIGHTLY WEATHERED IGNIMBRITE. RED BROWN AND MINOR GREY MEDIUM HARD RED BROWN MEDIUM HARD SLIGHTLY SLIGHTLY WEATHERED IGNIMBRITE. WEATHERED IGNIMBRITE .. RED BROWN AND MINOR GREY MEDIUM HARD RED BROWN MEDIUM HARD SLIGHTLY SLIGHTLY WEATHERED IGNIMBRITE.. WEATHERED IGNIMBRITE. RED BROWN AND MINOR GREY MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. RED BROWN MEDIUM HARD SLIGHTLY RED BROWN MEDIUM HARD SLIGHTLY RED BROWN AND MINOR GREY MEDIUM HARD WEATHERED IGNIMBRITE.. SLIGHTLY WEATHERED IGNIMBRITE. RED BROWN AND MINOR GREY MEDIUM HARD RED BROWN AND GREY MEDIUM HARD SLIGHTLY SLIGHTLY WEATHERED IGNIMBRITE. WEATHERED IGNIMBRITE .. COMMENTS:


HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG BHQ-401A-DH HOLE: LOCATION:56 377937, 6385796 PROJECTBRANDY HILL PIT DRILLED: PAGE 2 OF 3 LOGGED: P BROWNE 13/9/11 DPH LOG **DESCRIPTION** DPH LOG **DESCRIPTION** RED BROWN FINE GRAINED MEDIUM HARD WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD FRESH IGNIMBRITE. RED BROWN FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD WEATHERED IGNIMBRITE. IGNIMBRITE. RED BROWN FINE GRAINED MEDIUM HARD WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. RED BROWN FINE GRAINED MEDIUM HARD WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD RED BROWN FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD WEATHERED IGNIMBRITE. IGNIMBRITE. 35 DARK GREY FINE GRAINED MEDIUM HARD RED BROWN FINE GRAINED MEDIUM HARD WEATHERED IGNIMBRITE. IGNIMBRITE. 36 DARK GREY FINE GRAINED MEDIUM HARD RED BROWN FINE GRAINED MEDIUM HARD IGNIMBRITE. WEATHERED IGNIMBRITE. RED BROWN FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD WEATHERED IGNIMBRITE. 38 DARK GREY AND RED BROWN FINE GRAINED RED BROWN FINE GRAINED MEDIUM HARD MEDIUM HARD WEATHERED IGNIMBRITE. WEATHERED IGNIMBRITE. 39 DARK GREY AND RED BROWN FINE GRAINED RED BROWN FINE GRAINED MEDIUM HARD MEDIUM HARD WEATHERED IGNIMBRITE. WEATHERED IGNIMBRITE. COMMENTS:

Hanson HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG BH-401A-PC HOLE: LOCATION:56 377937, 6385796 PROJECT: BRANDY HILL PIT DRILLED: LOGGED: P BROWNE 13/9/11 PAGE 3 OF DPH LOG **DESCRIPTION** DPH LOG **DESCRIPTION** DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. RED BROWN FINE GRAINED MEDIUM HARD WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. 58 DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE 59 DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. DARK GREY FINE GRAINED MEDIUM HARD SLIGHTLY WEATHERED IGNIMBRITE. COMMENTS:

GRAPHIC DRILL LOG

HOLE: BH-1401-DH PROJECTBRANDY HILL, ZONE 56 PAGE 1 OF 4

LOCATION:377467,6385110 GDA DRILLED: MACQUARIE DRILLING




GRAPHIC DRILL LOG

HOLE: BH-1401-DH PROJECTBRANDY HILL, ZONE 56 PAGE 2 OF 4

LOCATION:377467,6385110 GDA

DRILLED: MACQUARIE DRILLING


LOGGED: P BROWNE 22/5/14



GRAPHIC DRILL LOG

HOLE: BH-1401-DH
PROJECTBRANDY HILL, ZONE 56
PAGE 3 OF 4

LOCATION:377467,6385110 GDA DRILLED: MACQUARIE DRILLING






HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG

HOLE: BH-1401-DH PROJECTBRANDY HILL, ZONE 56 PAGE 4 OF 4

LOCATION:377467,6385110 GDA DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14




GRAPHIC DRILL LOG

HOLE: BH-1402-DH PROJECTBRANDY HILL, ZONE 56 LOCATION:377445, 6385345GDA

DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14




GRAPHIC DRILL LOG

HOLE: BH-1402-DH PROJECTBRANDY HILL, ZONE 56 PAGE 2 OF 4

LOCATION:377445, 6385345GDA

DRILLED: MACQUARIE DRILLING




GRAPHIC DRILL LOG

HOLE: BH-1402-DH PROJECTBRANDY HILL, ZONE 56 PAGE 3 OF 4

LOCATION:377445, 6385345GDA DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14






HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG

HOLE: BH-1402-DH PROJECTBRANDY HILL, ZONE 56 PAGE 4 OF 4

LOCATION:377445, 6385345GDA DRILLED: MACQUARIE DRILLING




GRAPHIC DRILL LOG

HOLE: BH-1403-DH PROJECTBRANDY HILL, ZONE 56 PAGE 1 OF 7

LOCATION:377250, 6385303GDA


DRILLED: MACQUARIE DRILLING



GRAPHIC DRILL LOG

HOLE: BH-1403-DH PROJECTBRANDY HILL, ZONE 56 PAGE 2 OF 7


LOCATION:377250, 6385303GDA DRILLED: MACQUARIE DRILLING



GRAPHIC DRILL LOG

HOLE: BH-1403-DH PROJECTBRANDY HILL, ZONE 56 PAGE 3 OF 7

LOCATION:377250, 6385303GDA DRILLED: MACQUARIE DRILLING






HANSON CONSTRUCTION MATERIALS


GRAPHIC DRILL LOG

HOLE: BH-1403-DH PROJECTBRANDY HILL, ZONE 56 PAGE 4 OF 7

LOCATION:377250, 6385303GDA DRILLED: MACQUARIE DRILLING




GRAPHIC DRILL LOG



LOCATION:377250, 6385303GDA

DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14



Hanson HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG HOLE: BH-1403-DH LOCATION:377250, 6385303GDA PROJECTBRANDY HILL, ZONE 56 DRILLED: MACQUARIE DRILLING PAGE 6 OF 7 LOGGED: P BROWNE 22/5/14 DPH LOG **DESCRIPTION** LOG **DESCRIPTION** DARK GREY FINE GRAINED IGNIMBRITE FELDSPAR 3mm, FRACTURES 40cm DARK RED BROWN FINE GRAINED IGNIMBRITE FELDSPAR 2mm, FRACTURES 40cm DARK GREY FINE GRAINED IGNIMBRITE FELDSPAR 3mm, FRACTURES 40cm DARK GREY FINE GRAINED IGNIMBRITE FELDSPAR 3mm, FRACTURES 40 TO 80cm DARK GREY FINE GRAINED IGNIMBRITE FELDSPAR 3mm, FRACTURES 40cm DARK GREY FINE GRAINED IGNIMBRITE FELDSPAR 4mm, FRACTURES 30cm SOME 45° TO CORE AXIS RED FINE GRAINED IGNIMBRITE GROUNDMASS LIGHT MHD HD VHD COMMENTS:

HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG


HOLE: BH-1403-DH PROJECTBRANDY HILL, ZONE 56

7

LOCATION:377250, 6385303GDA

DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14




GRAPHIC DRILL LOG

HOLE: BH-1404-DH PROJECTBRANDY HILL, ZONE 56

PAGE 1 OF 5

LOCATION:376295, 6386194GDA


DRILLED: MACQUARIE DRILLING



GRAPHIC DRILL LOG

HOLE: BH-1404-DH PROJECTBRANDY HILL, ZONE 56 PAGE 2 OF 5


LOCATION:376295, 6386194GDA DRILLED: MACQUARIE DRILLING



GRAPHIC DRILL LOG

HOLE: BH-1404-DH
PROJECTBRANDY HILL, ZONE 56
PAGE 3 OF 5

LOCATION:376295, 6386194GDA DRILLED: MACQUARIE DRILLING






HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG

HOLE: BH-1404-DH PROJECTBRANDY HILL, ZONE 56 PAGE 4 OF 5

LOCATION:376295, 6386194GDA DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14



Hanson HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG HOLE: BH-1404-DH LOCATION:376295, 6386194GDA PROJECTBRANDY HILL, ZONE 56 DRILLED: MACQUARIE DRILLING PAGE 5 OF 5 LOGGED: P BROWNE 22/5/14 DPH LOG **DESCRIPTION** DPH LOG **DESCRIPTION** GREY FINE GRAINED SANDSTONE WITH BLACK LAMINAE 80° TO CORE AXIS

COMMENTS:

90 VW W MW SW F

MHD HD VHD

100 VWWMW SW F


GRAPHIC DRILL LOG

HOLE: BH-1405-DH PROJECTBRANDY HILL, ZONE 56

LOCATION:376384, 6385562GDA DRILLED: MACQUARIE DRILLING

PAGE 1 OF 6

LOGGED: P BROWNE 22/5/14




GRAPHIC DRILL LOG

HOLE: BH-1405-DH
PROJECTBRANDY HILL, ZONE 56
PAGE 2 OF 6

LOCATION:376384, 6385562GDA DRILLED: MACQUARIE DRILLING


LOGGED: P BROWNE 22/5/14



GRAPHIC DRILL LOG

HOLE: BH-1405-DH PROJECTBRANDY HILL, ZONE 56 PAGE 3 OF 6

LOCATION:376384, 6385562GDA DRILLED: MACQUARIE DRILLING






HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG

HOLE: BH-1405-DH PROJECTBRANDY HILL, ZONE 56 PAGE 4 OF 6

LOCATION:376384, 6385562GDA DRILLED: MACQUARIE DRILLING LOGGED: P BROWNE 22/5/14




GRAPHIC DRILL LOG

HOLE: BH-1405-DH PROJECTBRANDY HILL, ZONE 56 PAGE 5 OF 6

LOCATION:376384, 6385562GDA


DRILLED: MACQUARIE DRILLING



GRAPHIC DRILL LOG

HOLE: BH-1405-DH PROJECTBRANDY HILL, ZONE 56 PAGE 6 OF 6


LOCATION:376384, 6385562GDA DRILLED: MACQUARIE DRILLING



GRAPHIC DRILL LOG

HOLE: BH-1406-DH PROJECTBRANDY HILL, ZONE 56 LOCATION:376633, 6385412GDA


DRILLED: MACQUARIE DRILLING



GRAPHIC DRILL LOG

HOLE: BH-1406-DH PROJECTBRANDY HILL, ZONE 56 PAGE 2 OF 6


LOCATION:376633, 6385412GDA DRILLED: MACQUARIE DRILLING



GRAPHIC DRILL LOG

HOLE: BH-1406-DH PROJECTBRANDY HILL, ZONE 56 PAGE 3 OF 6

LOCATION:376633, 6385412GDA DRILLED: MACQUARIE DRILLING






HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG


HOLE: BH-1406-DH PROJECTBRANDY HILL, ZONE 56 PAGE 4 OF 6

LOCATION:376633, 6385412GDA DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14




GRAPHIC DRILL LOG



LOCATION:376633, 6385412GDA

DRILLED: MACQUARIE DRILLING


LOGGED: P BROWNE 22/5/14



GRAPHIC DRILL LOG

HOLE: BH-1406-DH PROJECTBRANDY HILL, ZONE 56 PAGE 6 OF 6

LOCATION:376633, 6385412GDA DRILLED: MACQUARIE DRILLING




GRAPHIC DRILL LOG

HOLE: BH-1407-DH PROJECTBRANDY HILL, ZONE 56 LOCATION:377590, 6385578GDA

DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14




GRAPHIC DRILL LOG

HOLE: BH-1407-DH PROJECTBRANDY HILL, ZONE 56 PAGE 2 OF 5

LOCATION:377590, 6385578GDA

DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14



Hanson HANSON CONSTRUCTION MATERIALS GRAPHIC DRILL LOG HOLE: BH-1407-DH LOCATION:377590, 6385578GDA PROJECTBRANDY HILL, ZONE 56 DRILLED: MACQUARIE DRILLING PAGE 3 OF 5 LOGGED: P BROWNE 22/5/14 DPH LOG **DESCRIPTION** DPH LOG **DESCRIPTION** GREY FINE GRAINED IGNIMBRITE FELDSPAR & QUARTZ PHENOCRYSTSL, FRACTURES 50cm APART .52 LIGHT BROWN COARSE GRAINED SANDSTONE RARE SHALE CLASTS RED BROWN CONGLOMERATE FRAGMENTS TO 40mm SANDSTONE & QUARTZ, FRACTURES 20cm APART VIOLET VERY FINE GRAINED MUDSTONE LAMINAE 70° 53 TO CORE AXIS FRACTURED RED BROWN CONGLOMERATE FRAGMENTS TO 40mm SANDSTONE & QUARTZ, FRACTURES 20cm APART RED GREY FINE GRAINED IGNIMBRITE FELDSPAR & QUARTZ PHENOCRYSTSL, FRACTURES 50cm APART BROWN FINE GRAINED SANDSTONE MINOR COARSE GRAINED BANDS PERPENDICULAR TO CORE AXIS VIOLET FINE GRAINED SANDSTONE MINOR COARSE GRAINED BANDS PERPENDICULAR TO CORE AXIS LIGHT BROWN FINE GRAINED SANDSTONE MINOR COARSE GRAINED BANDS PERPENDICULAR TO CORE PINK SHALE LAMINAE PERPENDICULAR TO CORE AXIS RED BROWN FINE GRAINED SANDSTONE FELDSPAR FRAGMENTS MINOR LAMINAE RED BROWN FINE GRAINED SANDSTONE FELDSPAR FRAGMENTS MINOR LAMINAE RED BROWN FINE GRAINED IGNIMBRITE FELDSPAR & QUARTZ PHENOCRYSTSL, FRACTURES 45° TO CORE AXIS RED CALCITE LINED MHD HD VHD COMMENTS: LEGEND: VW VERY WEATHERED, W WEATHERED, MW MODERATELY WEATHERED, SW SLIGHTLY WEATHERED, F FRESH S SOFT, MHD MEDIUM HARD, HD HARD, VHD VERY HARD




HANSON CONSTRUCTION MATERIALS

GRAPHIC DRILL LOG

HOLE: BH-1407-DH PROJECTBRANDY HILL, ZONE 56 PAGE 4 OF 5

LOCATION:377590, 6385578GDA DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14




GRAPHIC DRILL LOG

HOLE: BH-1407-DH
PROJECTBRANDY HILL, ZONE 56
PAGE 5 OF 5

LOCATION:377590, 6385578GDA

DRILLED: MACQUARIE DRILLING

LOGGED: P BROWNE 22/5/14



13 Attachment E – Agency Consultation



Daniel Dhiacou

| From: Sent: To: | Andrew Docking <andrew.docking@dpi.nsw.gov.au> Wednesday, 10 December 2014 12:07 PM Daniel Dhiacou</andrew.docking@dpi.nsw.gov.au> |
|---|--|
| Cc: Subject: | Andrew Norris; Driver, Andrew (Parramatta) AU (Andrew.Driver@hanson.com.au) Re: P1303888 Brandy Hill Quarry Expansion - Preliminary Agricultural Land Capacity |
| Attachments: | Assessment OUT14 40206 Brandy Hill Quarry Expansion - Preliminary Agricultural Land Capacity Assessment.pdf |
| Daniel | |
| A letter for your records. | |
| Regards | |
| Post: NSW Department of Prin T: 02 8843 1122 M: 0437 896 | Ianagement Officer Agriculture NSW nary Industries Locked Bag 21 ORANGE NSW 2800 305 ov.au W: www.industry.nsw.gov.au |
| http://www.dpi.nsw.gov.au/agi | and guidelines are available at: riculture/resources/lup riculture/resources/lup/analysis-census-data |
| Building thriving, sustainable | e Agriculture for tomorrow's communities |
| On 4 December 2014 at 12:19, | Daniel Dhiacou < <u>DDhiacou@martens.com.au</u> > wrote: |
| Hi Andrew, | |
| Thank you for your response. | |
| | ough the response on letter head agreeing that the land is Class 5 and that formal tial is not required. This will enable us to add it as an addendum to a report. |
| Regards, | |
| Daniel Dhiacou | |
| Civil & Environmental Engineer | |



Martens & Associates Pty Ltd

Suite 201, 20 George St

Hornsby, NSW 2077

P + 61 2 9476 9999

F + 61 2 9476 8767

M 0418 678 004

www.martens.com.au

This message is intended for the addressee named and may contain confidential / privileged information. If you are not the intended recipient, please delete it and notify the sender. Views expressed in this message are those of the individual sender, and are not necessarily the views of Martens & Associates Pty Ltd. You should scan any attached files for viruses.

PLEASE NOTE MARTENS HAS MOVED TO GEORGE ST, HORNSBY

From: Andrew Docking [mailto:andrew.docking@dpi.nsw.gov.au]

Sent: Wednesday, 3 December 2014 4:13 PM

To: Daniel Dhiacou

Cc: Andrew Norris; Driver, Andrew (Parramatta) AU (Andrew.Driver@hanson.com.au)

Subject: Re: P1303888 Brandy Hill Quarry Expansion - Preliminary Agricultural Land Capacity Assessment

Daniel

Agree - no need for specific agriculture impact statement and detailed assessment regarding agriculture potential -- however when you look at the location there is poultry nearby and so EA should include a discussion on any potential farm bore drawdown.

Regards

Andrew Docking | Resource Management Officer | Agriculture NSW Post: NSW Department of Primary Industries | Locked Bag 21 | ORANGE | NSW 2800 T: 02 8843 1122| M: 0437 896 305 E: andrew.docking@dpi.nsw.gov.au | W: www.industry.nsw.gov.au Land use planning information and guidelines are available at: http://www.dpi.nsw.gov.au/agriculture/resources/lup http://www.dpi.nsw.gov.au/agriculture/resources/lup/analysis-census-data Building thriving, sustainable Agriculture for tomorrow's communities On 3 December 2014 at 08:31, Daniel Dhiacou < DDhiacou@martens.com.au> wrote: Hi Andrew, As per your discussion with Andrew Norris, please find attached the preliminary agricultural land capacity assessment for the Brandy Hill Quarry expansion. Could you please review and provide any comments at your earliest convenience. Regards, **Daniel Dhiacou**

Civil & Environmental Engineer

BEng (Hons1), DipEngPrac



| P <u>+ 61 2 9476 9999</u> |
|--|
| F <u>+ 61 2 9476 8767</u> |
| M 0418 678 004 |
| www.martens.com.au |
| This message is intended for the addressee named and may contain confidential / privileged information. If you are not the intended recipient, please delete it and notify the sender. Views expressed in this message are those of the individual sender, and are not necessarily the views of Martens & Associates Pty Ltd. You should scan any attached files fo viruses. |
| PLEASE NOTE MARTENS HAS MOVED TO GEORGE ST, HORNSBY |
| |
| |
| |
| |
| This message is intended for the addressee named and may contain confidential information. If you are not the intended recipient, please delete it and notify the sender. Views expressed in this message are those of the individual sender, and are not necessarily the views of their organisation. |
| |
| This message is intended for the addressee named and may contain confidential information. If you are not the intended recipient, please delete it and notify the sender. Views expressed in this message are those of the individual sender, and are not necessarily the views of their organisation. |
| |
| |
| |

Martens & Associates Pty Ltd

Suite 201, 20 George St

Hornsby, NSW 2077



TRIM: OUT14/40206

Daniel Dhiacou Civil & Environmental Engineer Martens & Associates Pty Ltd Suite 201, 20 George St Hornsby, NSW 2077

ddhiacou@martens.com.au

Dear Mr Dhiacou

P1303888 Brandy Hill Quarry Expansion - Preliminary Agricultural Land Capacity Assessment

Thank you for your correspondence of the 3 December 2014, NSW Primary Industries – Agriculture NSW has reviewed the soil assessment report for the proposed expansion and provides the following advice.

Agricultures NSW would concur that the land within the project area is of poor agricultural suitability, most likely agricultural land class 5, unsuitable for cultivation and minimal grazing

http://www.dpi.nsw.gov.au/ data/assets/pdf_file/0004/189697/ag-land-classification.pdf and therefore there is no need for further detailed assessment regarding agriculture potential.

However there are poultry farms nearby and so the Environmental Assessment should include a discussion on any potential impacts to these operations.

For your information there is an issue for agriculture guideline. http://www.dpi.nsw.gov.au/__data/assets/pdf_file/0005/367763/Agriculture-issues-for-extractive-industry-development.pdf

Thank you for providing the opportunity to comment on the agricultural suitability of the project site.

Yours sincerely

Andrew Docking
Resource Management Officer
Department of Primary Industries
Agriculture NSW
10 December 2014



Posted Faxed X andrew.docking@dpi.nsw.gov.au
Courier By Hand Contact: Daniel Dhiacou / Andrew Norris
Pl303888JC06V01
Pages: 3 + Attachment
cc. -

December 3, 2014

NSW Department of Agriculture Attn: Andrew Docking

Dear Andrew,

RE: BRANDY HILL QUARRY: PRELIMINARY AGRICULTURAL LAND CAPACITY ASSESMENT FOR QUARRY EXPANSION EIS

Martens and Associates have undertaken a review of available land and soil data at Hanson's Brandy Hill Quarry to allow assessment of the agricultural land capacity in the proposed expansion area. Refer to Attachment A for a site aerial and proposed final quarry form.

The quarry is situated on the eastern slopes of Brandy Hill (approximate elevation 35 to 100 mAHD) adjacent to the Deadman's Creek incised valley (approximate elevation 25 to 55 mAHD). Slopes are typically 10 - 35% with the area either operating quarry or native vegetation (forest).

The Newcastle 1:100 000 soil landscape sheet (DLWC, 1995) indicates that site soils are Seaham (SE) and Hungry Hill (HH) on Carboniferous volcanics and sediments. Soils are primarily shallow to moderately deep (30 – 120 cm) rapidly drained loams and well / imperfectly drained soloths, with some moderately deep (> 140 cm) imperfectly / well drained chocolate soils on colluvial benches, moderately deep (> 90 cm) poorly drained structured loams on small alluvial flats, and shallow to moderately deep (20 – 100 cm) well drained lithosols. Limitations noted include steep slopes, mass movement hazard, shallow & stony soils, seasonal waterlogging (for lower slopes/benches), high erosion hazard, localised rock outcrops, and strongly acidic soils of low fertility.

Site specific soil testing was conducted as part of the EIS for the currently approved quarry by Hunter Valley Mining Corporation (1983). The majority of the site consists of shallow (< 50 cm) sandy loams overlying weathering bedrock, with some gravels and kaolinite clays, as well as areas of rock outcrop. The soil layer thickens towards the base of the existing quarry due to colluvial deposits from upslope, and alluvial deposits are present in surrounding drainage lines. Soils are acidic with pH values ranging from 4.5 – 5.5.

Based on the available information we believe the proposed quarry expansion land has a low agricultural capability and is likely Class 4 or 5 based on NSW Agriculture Agfact AC. 25 (2002). We would appreciate your comments and advice as to whether further detailed assessment is required.

If you require any further information, please do not hesitate to contact the writer.

World Class Sustainable Engineering Solutions

Environmental
EIS & REF
Streams & rivers
Coastal
Groundwater
Catchments
Bushfire
Monitoring

Geotechnics
Foundations
Geotechnical survey
Contamination
Hydrogeology
Mining
Terrain analysis
Waste management

Water
Supply & storage
Flooding
Stormwater & drainage
Wetlands
Water quality
Irrigation
Water sensitive design

Wastewater
Treatment
Re-use
Biosolids
Design
Management
Monitoring
Construction

Civil
Earthworks
Excavations
Pipelines
Roads
Pavements
Parking
Structures

Head Office

Suite 201, 20 George Street Hornsby NSW 2077, Australia **Ph** 02 9476 9999 **Fax** 02 9476 8767

> mail@martens.com.au www.martens.com.au MARTENS & ASSOCIATES P/L ABN 85 070 240 890 ACN 070 240 890 For and on behalf of MARTENS & ASSOCIATES PTY LTD

DANIEL DHIACOU

BEng (Hons1), DipEngPrac
Civil & Environmental Engineer

ANDREW NORRIS

BSc (Hons), MEngSc, MAWA

Director/Project Manager

Alber



ATTACHMENT A - SITE AERIAL AND PROPOSED LAYOUT



