



Inspection report / Inspection: 1

Date: 31/03/2020	Asset owner's job ref.:	Project Name: 203302	Operator : CRAIG PICKUP	Section number: 1	Pipe Asset Id:
Method of inspection:	Cleaned: No	Criticality:			

Suburb: KIRRAWEE	Purpose: Structural Condition Inspection	U/S MH: A
Street: BIDURGAL	Asset Owner:	D/S MH: B
Site:	dvd no.:	Section length : 99.66 m
Location type: Light road	Cleaned No	Survey Dir : downstream
Shape Of Pipe : Circular	Width :	
Use of pipe: Drain	Dia/Height: 1200 mm	
Type of pipe: Stormwater	Depth: 0	
Weather: Dry	Pipe Material: Reinforced concrete	

Remarks :

1:795 Position Observation



99.66 m

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1

Inspection Pictures / Inspection: 1

Location/Street BIDURGAL	Town or suburb:	Date : 31/03/2020	Section number: 1	Sewer Ref.:
------------------------------------	-----------------	-----------------------------	-----------------------------	-------------



Photo: 1_1_7_A.JPG, Media No.: 20A BIDU_0, 00:08:08 99.66m,
Inspection (survey) abandoned, obstruction , DROP / DROP