





Key:




Soil remediation area ~ 9m²
Soil removal to 0.3 m
Approximately 5 m³

Former
Farm Shed

Key:

— Investigation area
X Validation Samples

Fig tree



1:282





Source: Six Maps


Figure 2: Farm pit validation


19038 R05


Site: 771 Cudgen Road
Location: Cudgen, NSW
Details: Validation Report
Client: Lendlease
Drawn: Glen Chisnall
Source: Google Earth














Key:

- X Validation sample
- Investigation Boundary
- Soil removal to 0.3 m
- Soil removal to 0.5 m
- Soil removal to 0.7 m

**Figure 8: Residential house validation
19038 R05**

Site: 771 Cudgen Road
Location: Cudgen, NSW
Details: Validation Report

Client: Lendlease
Drawn: Glen Chisnall
Source: Google Earth

Source: Google Maps





Figure 9: Farm pit and shed Groundwater sample locations Ref: 19038 R05	
Site: 771 Cudgen Road	
Location: Cudgen, NSW	
Details: Validation report	
Client: Lendlease	
Drawn: Glen Chisnall	
Source: Google Earth	



Figure 10: Farm dump and dam groundwater sample locations	
Ref: 19038 R05	
Site: 771 Cudgen Road	
Location: Cudgen, NSW	
Details: Validation report	
Client: Lendlease	
Drawn: Glen Chisnall	
Source: Google Earth	

