

Appendix A

Site Photographs



Photograph 3: Facing the North, showing the western and south western site boundary in the background, the nature corridor is present in the right of the photograph.



Photograph 4: Facing the East, showing scrubby native bushland, the culvert and the shallow gully are present in the eastern portion of the site.



Photograph 5: Facing the west, taken from the middle of the shallow gully facing towards the road. Steel cable has been previously used for fencing materials, assumed a result of flooding of lighter fencing materials in the past.



Photograph 6: Facing the North, showing fill materials used on the northern portion of the site, to the left of the picture scrubby native vegetation is present, while to the north minor revegetation the area has occurred.



Photographs 7: Facing the North West along the northern site boundary shows fill materials assumed from the main road construction, currently stored on the north western portion of the site.



Photograph 8: Facing the north east from the front of the site, showing filled areas and some minor regrowth of juvenile eucalypts.



Photograph 9: Facing the east, some burnt timber and steel products are present around the filled areas in the north of the site.



Photograph 10: construction materials and associated wastes present in the north western portion of the site.



Photograph 10: Road Construction materials placed on the north western portion of the site.



Photograph 11: Energy Transmission present running northwest-southeast approximately 200m to the southeast of the site.