



Photo 1 (Dec 06) – Overall view of the site, looking west



Photo 2 (Dec 06) – The existing (southern) gasholder



Photo 3 (Dec 06) – Communications cables located within ground level concrete trough, behind gasholder annuli (2m from fence which adjoins Burren St properties)



Photo 4 (Dec 06) – Sydney Water sewer line located under embankment (1m from fence which adjoins Burren St properties). Disused gasworks pipework also buried in embankment



Photo 5 (Dec 06) – Concrete structure appears to be buried between the two gasholder annuli



Photo 6 (Dec 06) – Annulus of demolished gasholder remains in situ, to the north of the existing gasholder



Photo 7 (Dec 06) – Cable pit (0.5m deep) which services communications cables, is located within 0.5m of the northern gasholder annulus (immediately behind 43 Burren St)



Photo 8 (Dec 06) – Low brick wall and concrete / tiled structure in the north west site area



Photo 9 (Dec 06) – Concrete structure in the north west site area



Photo 10 (Dec 06) – Pipework fitting located next to concrete troughing behind 43 Burren St



Photo 11 (Dec 06) – Cable pits servicing communications cables next to 43 Burren St (in north west site area)



Photo 12 (Dec 06) – Buried concrete / brick structure in north west site area