



Photo 13 (Dec 06) – Concrete retaining wall (with steel rails)



Photo 14 (Dec 06) – Additional level of brickwork on top of retaining wall area



Photo 15 (Dec 06) – Note difference in levels in north west area. Site is level with Burren Street, however area on top of retaining wall (and Stabling Yard surface level) is ~1.5m higher



Photo 16 (Dec 06) – Cable pit servicing communications cables in north west site area



Photo 17 (Dec 06) – Old electrical shed on embankment, south of the existing gasholder



Photo 18 (Dec 06) – Old electrical shed on embankment, south of the existing gasholder



Photo 19 (Dec 06) – Sydney Water sewer pit located in south west corner of site



Photo 20 (Dec 06) – Open drain located between western fenceline, and rear of Burren St properties. Drain is in poor condition and overgrown, and lies approx 1m below embankment level



Photo 21 (Dec 06) – Trees located to the south of the existing gasholder



Photo 22 (Dec 06) – Trees located along top of embankment, in south western site area



Photo 23 (Dec 06) – Tree located in south western corner of site



Photo 24 (Dec 06) – Trees located across embankment, to the south of the existing gasholder