



Photo 25 (Dec 06) - Trees and weeds located across embankment, to the south of the existing gasholder



Photo 26 (Dec 06) – Large tree located next to old electrical shed, south of existing gasholder



Photo 27 (Dec 06) - Trees located to the south of the existing gasholder



Photo 28 (Dec 06) – Trees located east of the existing gasholder



Photo 29 (Dec 06) – The annulus of the northern gasholder, and trees located behind 37 – 43 Burren St



Photo 30 (Dec 06) – Trees located behind 31-35 Burren St (double storey buildings)



Photo 31 (Dec 06) – Trees located in north west site area



Photo 32 (Dec 06) – Embankment and trees located along northern site boundary (adjacent to stabling yard)



Photo 33 (Dec 06) – Some waste materials on site



Photo 34 (Dec 06) – Embankment and waste materials in northern site area (adjacent to stabling yard)



Photo 35 (Dec 06) – Embankment along boundary of north eastern site area



Photo 36 (Dec 06) – The eastern site area