



**Photo 49** (Aug 06) – Two tar pits with concrete lids, in north west site area



**Photo 50** (Aug 06) – The location of testpit MG06, adjacent to the tar wells



**Photo 51** (Aug 06) – Brick structure adjacent to western tar well



**Photo 52** (Aug 06) – Water within the tar well (floating on top of tarry waste)



**Photo 53** (Aug 06) – Tar seeping through the brick wall of the tar pit (into testpit MG06)



**Photo 54** (Aug 06) – Tarry waste within the tar wells



**Photo 55** (Aug 06) – Tarry waste within the tar wells



**Photo 56** (Aug 06) – Brickwork beneath former retort house



**Photo 57** (Aug 06) – Tar within pipework removed from testpits beneath former retort house



**Photo 58** (Aug 06) – Pipework removed from testpits beneath former retort house



**Photo 59** (Aug 06) – Tar within testpit MG08, beneath the former retort house



**Photo 60** (Aug 06) – Tarry soils within testpit MG08, beneath the former retort house