



Photo 61 (Aug 06) – Tar within soil pores in natural clay, from testpit MG08 beneath former retort house



Photo 62 (Aug 06) – Fill profile in testpit MG10, beneath eastern edge of former retort house



Photo 63 (Aug 06) – Tarry materials and a buried brick structure within testpit MG10, beneath eastern edge of former retort house



Photo 64 (Aug 06) – Fill profile in testpit MG11, near location of former purifiers




Photo 65 (Aug 06) – Fill layers in testpit MG01, south of existing gasholder



Photo 66 (Aug 06) – Fill profile in testpit TP01, in south western corner of site



Photo 67 (Aug 06) – Fill profile in testpit TP03, along southern site boundary



Photo 68 (Aug 06) – Fill profile in testpit TP05, along southern site boundary



Photo 69 (Aug 06) – Fill profile in testpit TP06, in eastern site area



Photo 70 (Aug 06) – Fill profile in testpit TP07, in south eastern site area, including an old buried rail line



Photo 71 (Aug 06) – Fill profile in testpit TP08, in eastern site area



Photo 72 (Aug 06) – Fill profile in testpit TP10, on northern site boundary, including two stepped retaining wall