No. M10	Map Ref: M10	
140. 14110	map ici.	
Location: South-west of	of Perway Workshops No. 2, near Crane 3.	ecinct C

Condition:

Associated Items:

Description: Coal Stage - This dump supplies the three steam cranes. It is located adjacent to the track and has a concrete floor raised about 800mm above the track to facilitate loading. Two sides and the back of the dump are surrounded by a 1.5m high wall of recycled sheets of 7mm mild steel.

SIGNIFICANCE ASSESSMENT	2/5	INFORMANTS:	
Historic Association	2/5		
Technological Importance	2/5	€ .	3
Structural Integrity	2/5	REFERENCES:	
Relative Rarity	3/5		
Operational Ability	3/5		
Interpretive Ability	3/5		-
RECOMMENDATION: Record		PHOTOGRAPHS:	* · · · · · · · · · · · · · · · · · · ·
		B & W : 90-038-8-19	




Recorded by: D. Godden & J. Sheppard

No. C4 M12	Map Ref: M12		
Location: West of Main	workshops per way No.2	Precinct C	والتأت عناج
Condition:			

Description: P1010 - GRAFTON ENGINEERS BEDFORD - No's on 542, 362. CRANE No. 2151. 361 on Base.

A grafton steam crane with its beam intact. The beam is raised and lowered by twin tension rods with pulleys at the base end, around which the raising chains pass. The crane is not operational but is similar to crane 1 in most respects. If anything, more of the original fabric is evident on this machine.

SIGNIFICANCE ASSESSMENT Historic Association Technological Importance	4/5 4/5 4/5		
Structural Integrity Relative Rarity Operational Ability	3/5 4/5 1/5	REFERENCES:	
Interpretive Ability	4/5	. äk	Junequed vs. Ability
RECOMMENDATION: Conserve	Plantotout.	PHOTOGRAPHS: B & W: 90-038-2-11	RECOMMENDATION: Sho



Recorded by: D. Godden & J. Sheppard

CHULLORA HERITAGE ASSESSMENT, 1990

Historic Association

Structural Integrity

Operational Ability

Interpretive Ability

Relative Rarity

Technological Importance

MACHINERY/PLANT

No. M13	Map Ref:	
Location: Adjacent to C	Crane 3 Preci	nct C
Condition:		
Associated Items:	1	
condition and is normally st	ored near the crane coal bins	
condition and is normally st	ored near the crane coal bins.	
condition and is normally st	ored near the crane coal bins.	dumping loose material. It is in operationa
condition and is normally st	ored near the crane coal bins.	

REFERENCES:

RECOMMENDATION: Should remain with the steam crane and be conserved.

PHOTOGRAPHS:

90-038-2-18

3/5

3/5

4/5

3/5

4/5

4/5



Recorded by: D. Godden & J. Sheppard

NAME OF ITEM: R No. M14	Map Ref:	
Location: East of Cr	ane 3	Precinct C had weekened bridged enough
Condition:		50001500
Associated Items:		amint Englises.
Description: Redundan holds the slings, chains a	nt machinery is stored on the ed and hooks used by the two oper	ge of the plate rack area along with a welded steel sling bracket whi ational steam cranes.
SIGNIFICANCE ASSES	SSMENT 2/5	INFORMANTS: TYPE A STORAGE AND
Historic Association	2/5	Listoria Associationi. 225
Technological Importan		enterioral langularies
Structural Integrity	2/5	REFERENCES:
Relative Rarity	-/5	district Smith
Operational Ability	-/5	permittensi Ability
Interpretive Ability	/5	cucpontive Ability A/5
	:Slings, chains and hooks should e steam crane and should rema	
scrapped.		

CHULLORA HERITAGE ASSESSMENT, 1990

MACHINERY/PLANT

No. M2C1	Map Ref:	
Location: Behind bandsaw shed.		Precinct C
Condition:	7	
Associated Items:		
used for lifting store material from th	e open racks in Are	a C and transporting it to trucks for removal to the workshop.
SIGNIFICANCE ASSESSMENT	3/5	INFORMANTS:
SIGNIFICANCE ASSESSMENT Historic Association	3/5 2/5	INFORMANTS:
	500.0000	INFORMANTS:
Historic Association	2/5	INFORMANTS: REFERENCES:
Historic Association Technological Importance	2/5 1/5	
Historic Association Technological Importance Structural Integrity	2/5 1/5 4/5	




Retain in operation.

PHOTOGRAPHS:

B & W:

90-038-1-12



Recorded by: D. Godden & J. Sheppard

ANOLUUMO

HERIPAGE ASSESS MENT, 1998

MACHINERY/REANT

PRECI	INCT D	
Procing D		
		Conditions Tale
		satural EnthipsoleA
outed maide a legal fine at one stage. It is an air requirer analysis of a representation of the stage of the		
		SMINITICANCE ASSESSMENT Hisparic Suscitation Technological importance Structural Integrity Relative Party Operational Ability (Operational Ability (Interpretive Maility


CHULLORA HERITAGE ASSESSMENT, 1990

MACHINERY/PLANT

No. M19	Map Ref:		
Location:	North of central workshop crane tracks.	Precinct D	
Condition:	Fair	7%	

Description: This pressure vessel appears to have been located inside a building at one stage. It is an air receiver numbered A989. It rests on a concrete machine bed on its eastern end. It appears that it would once have been used in the sand blasting of materials used in construction units by the Per Way Workshops.

SIGNIFICANCE ASSESSMENT	2/5	INFORMANTS:	
Historic Association	2/5		
Technological Importance	2/5		
Structural Integrity	2/5		
Relative Rarity	2/5	REFERENCES:	
Operational Ability	2/5		
Interpretive Ability	2/5	31 =	
RECOMMENDATION: Record		PHOTOGRAPHS:	, , , , , , , , , , , , , , , , , , ,
X.		B & W:	Slides:



Recorded By: D. Godden & J. Sheppard