



**CHULLORA**  
**HERITAGE ASSESSMENT, 1990**

**BUILDING/STRUCTURE**

<b>NAME OF ITEM:</b> Conference Room	
<b>No.</b> B30	<b>Map Ref:</b>
<b>Location:</b> On the roadside of Carpenters Shop.	Precinct H
<b>Condition:</b>	
<b>Associated Items:</b>	
<b>Description:</b> Small weatherboard, clad, skillion roofed shed, used for meetings. This is a very basic building with three sliding windows on the eastern elevation and a roller door on the southern elevation.	
<b>SIGNIFICANCE ASSESSMENT</b> Aesthetic Value 2/5 Historic Association 1/5 Technological Importance 2/5 Structural Integrity 1/5 Interpretive Ability 3/5 Social Significance 1/5	<b>INFORMANTS:</b>  <b>REFERENCES:</b>
<b>RECOMMENDATION:</b> Record	<b>PHOTOGRAPHS:</b> B & W: 90-038-3 Slides:
	
Recorded By: D. Godden & J. Sheppard	
Date: May, 1990	

**CHULLORA**  
**HERITAGE ASSESSMENT, 1990**

**BUILDING/STRUCTURE**

<b>NAME OF ITEM:</b> Break Down Room														
<b>No.</b> B32	<b>Map Ref:</b>													
<b>Location:</b> Beside Crane 8	<b>Precinct H</b>													
<b>Condition:</b> Dilapidated.														
<b>Associated Items:</b>														
<p><b>Description:</b> The breakdown room is located beside the timber yard. It consists of an RSJ frame and corrugated cladding with a curved roof. Logs travelled on skids into the breakdown room where they were cut and shaped. The building appears to have been out of service for some time. All equipment has been removed and the cladding is deteriorating.</p>														
<p><b>SIGNIFICANCE ASSESSMENT</b></p> <table> <tr><td>Aesthetic Value</td><td>2/5</td></tr> <tr><td>Historic Association</td><td>1/5</td></tr> <tr><td>Technological Importance</td><td>3/5</td></tr> <tr><td>Structural Integrity</td><td>3/5</td></tr> <tr><td>Interpretive Ability</td><td>2/5</td></tr> <tr><td>Social Significance</td><td>2/5</td></tr> </table>	Aesthetic Value	2/5	Historic Association	1/5	Technological Importance	3/5	Structural Integrity	3/5	Interpretive Ability	2/5	Social Significance	2/5	<p><b>INFORMANTS:</b></p>	<p><b>REFERENCES:</b></p>
Aesthetic Value	2/5													
Historic Association	1/5													
Technological Importance	3/5													
Structural Integrity	3/5													
Interpretive Ability	2/5													
Social Significance	2/5													
<p><b>RECOMMENDATION:</b> Record</p>	<p><b>PHOTOGRAPHS:</b> B &amp; W: 90-038-3</p>	<p><b>Slides:</b></p>												
														

Recorded By: D. Godden & J. Sheppard


Date: May, 1990

**PRECINCT I**  
**No Inventory Items**

## PRECINCT J

# CHULLORA HERITAGE ASSESSMENT, 1990

## LANDSCAPE

<b>NAME OF ITEM:</b> Boabaob Tree		
<b>No.</b> L1	<b>Map Ref:</b>	<b>Precinct J</b>
<b>Location:</b> Northern edge of entrance to Loco Maintenance Centre. South of the Rehabilitation Buildings.		
<b>Condition:</b>		
<b>Associated Items:</b>		
<b>Description:</b> The BOABAB tree is the remainder of a pair. Is is a relatively small specimen but is significant in surviving in a relatively inhospitable climate. Is is one of a very few specimens outside a Botanical garden setting.		
<b>SIGNIFICANCE ASSESSMENT</b> Aesthetic Value /5 Historic Association /5 Technological Importance /5 Structural Integrity /5 Interpretive Ability /5 Social Significance /5		<b>INFORMANTS:</b>      <b>REFERENCES:</b>
<b>RECOMMENDATION:</b> Conserve		<b>PHOTOGRAPHS:</b> B & W:                      Slides:
		
Recorded By: D. Godden & J. Sheppard		Date: June, 1990



# CHULLORA HERITAGE ASSESSMENT, 1990

## BUILDING/STRUCTURE

NAME OF ITEM: 2 x Air Raid Shelters													
No. B73	Map Ref:												
Location: Southern edge of the locomotive centre	Precinct J												
Condition: Not original													
Associated Items:													
<p><b>Description:</b> The air raid shelters are brick walled, reinforced concrete roofed purpose built structures. The initial design included walls approximately 300mm thick and roof 200mm thick and did not include any windows. The shelters have been used for storage purposes since World War II and have been altered accordingly. New penetrations have been made in the walls and double wooden doors now allow easy access of goods. These shelters were inaccessible but identical shelters on other parts of the site have also had internal walls removed. The original layout of the air raid shelters is shown below. The toilets located beside the entrance have also been removed in most cases. The shelters are approximately 13 metres long x 4.5 metres wide.</p>													
<p><b>SIGNIFICANCE ASSESSMENT</b></p> <table> <tr> <td>Aesthetic Value</td> <td>3/5</td> </tr> <tr> <td>Historic Association</td> <td>2/5</td> </tr> <tr> <td>Technological Importance</td> <td>3/5</td> </tr> <tr> <td>Structural Integrity</td> <td>2/5</td> </tr> <tr> <td>Interpretive Ability</td> <td>3/5</td> </tr> <tr> <td>Social Significance</td> <td>3/5</td> </tr> </table>	Aesthetic Value	3/5	Historic Association	2/5	Technological Importance	3/5	Structural Integrity	2/5	Interpretive Ability	3/5	Social Significance	3/5	<p><b>INFORMANTS:</b> Phillip Lingard</p> <p><b>REFERENCES:</b></p>
Aesthetic Value	3/5												
Historic Association	2/5												
Technological Importance	3/5												
Structural Integrity	2/5												
Interpretive Ability	3/5												
Social Significance	3/5												
<p><b>RECOMMENDATION:</b> Consider for conservation</p>	<p><b>PHOTOGRAPHS:</b></p> <p>B &amp; W: Slides:</p>												
<p>SECTION ON A-A</p> <p>PLAN</p> <p>BRICKWORK AIR RAID SHELTER</p>													
Recorded By: D. Godden & J. Sheppard	Date: June, 1990												

# CHULLORA

## HERITAGE ASSESSMENT, 1990

## BUILDING/STRUCTURE

NAME OF ITEM: Watchmans Gatehouse

No. B78

Map Ref:

Location: Southern boundary of Precinct J

Precinct J

Condition: Good

Associated Items:

Description: The gatehouse is a small relatively modern building typical of the type at Chullora. It is a timber framed, corrugated iron roofed building which is entered from a ramp on either side. It has sliding windows so the guard can interview prospective visitors. Unlike some of the other gatehouses this one is still manned and functional.

SIGNIFICANCE ASSESSMENT	
Aesthetic Value	1/5
Historic Association	1/5
Technological Importance	1/5
Structural Integrity	4/5
Interpretive Ability	1/5
Social Significance	1/5

INFORMANTS:


REFERENCES:

RECOMMENDATION: Record

PHOTOGRAPHS:

B & W:

Slides:



Recorded By: D. Godden & J. Sheppard

Date: May, 1990