

# Visual Impact Assessment

## Remediation of Former Macdonaldtown Gasworks



Incoll Management Pty Ltd on behalf of  
Rail Corporation NSW

**Former Macdonaldtown Gasworks  
Burren St  
ERSKINEVILLE, NSW**

August 2010  
JBS 40913 - 15327

# **Visual Impact Assessment**

Remediation of Former Macdonaldtown  
Gasworks

Incoll Management Pty Ltd

On behalf of  
Rail Corporation NSW

Former Macdonaldtown Gasworks  
Burren St  
Erskineville, NSW

August 2010  
JBS40913-15327  
JBS Environmental Pty Ltd

# Table of Contents

List of Abbreviations .....	iv
Executive Summary.....	v
1 Introduction.....	6
1.1 Introduction and Background .....	6
1.2 Objectives .....	6
1.3 Reports Referenced .....	6
2 Site Condition & Surrounding Environment .....	8
2.1 Site Identification .....	8
2.2 Current Site Condition.....	8
2.3 Site Features Previously Identified .....	9
2.4 Surrounding Landuse .....	10
2.5 Topography .....	10
3 Summary of Proposed Works .....	11
3.1 Proposed Future Use .....	11
3.2 Proposed Remediation Works .....	11
4 Assessment of Visual Impact .....	13
4.1 Visual Absorption Capacity.....	13
4.2 Scenic Quality .....	13
4.3 Visual Impact Rating.....	13
4.4 Existing Visual Character of the Area .....	14
4.5 Identification of Near-Field Receptors .....	14
4.6 Visual Impact Post Remediation.....	15
4.7 Visual Impact During Remediation .....	15
5 Mitigation Measures .....	17
6 Conclusions and Recommendations .....	18
7 References .....	19
8 Limitations .....	20

## Figures

Figure 1 – Site Location

Figure 2 – Site Plan

Figure 3 – Remediation Areas

Figure 4 – Current Site View taken from central southern boundary

Figure 5 – Current Site View taken from central northern boundary

Figure 6 – Potential Layout of Remediation Works

Figure 7 – Simulated View of Remediation from central southern boundary

Figure 8 – Simulated View of Remediation from central northern boundary

Figure 9 – Potential Visual Impact of Remediation Works north of the site

Figure 10 – Potential Visual Impact of Remediation Works east of the site

Figure 11 – Potential Visual Impact of Remediation Works south of the site

Figure 12 – Potential Visual Impact of Remediation works west of the site