 <b>JBS</b> <small>ENVIRONMENTAL</small>	<b>Figure 4: Pre-Remediation Site Condition (taken from central southern boundary)</b>
<b>Client:</b> Incoll Management	<b>Job Number:</b> 40913
<b>Project:</b> Visual Impact Assessment	
<b>Site:</b> Former Macdonaldtown Gasworks	
<b>File Name:</b> 40913 R05 Figure 4	





**Figure 5: Pre-Remediation  
Condition of the site (taken  
from central northern boundary)**


Client: Incoll Management Job Number: 40913

Project: Visual Impact Assessment


Site: Former Macdonaldtown Gasworks

File Name: 40913 R05 Figure 5

Likely extent of area requiring enclosure during excavation. Excavation works likely to be staged, with partial sections enclosed, remediated and validation, until the entire area is completed



Possible location of second enclosure used for on site stockpiling, cement stabilisation and/or truck loading works. Likely to be installed as a 'permanent' fixture for the duration of the remediation works



Approximate Scale  
0m 50m



Figure 6: Potential Layout of Remediation Works

Client: Incolt Management	Job Number: 40913
Project: Visual Impact Assessment	
Site: Former Macdonaldtown Gasworks	
File Name: 40913 R05 Figure 6	