

AUSDILAPS
Specialist Building Inspections

ABN: 56 891 923 704

Telephone: 1800 Dilaps (345 277) Email: info@ausdilaps.com.au

PRE CONSTRUCTION CONDITION SURVEY

COMMISSIONED BY:

Lendlease Building Pty Limited
Level 14, Tower Three
International Towers Sydney Exchange
Place
300 Barangaroo Avenue
BARANGAROO NSW 2000

PROJECT:

Fort Street Public School, Millers Point NSW

SITE SURVEYED:

Upper Fort Street Public School
MILLERS POINT NSW 2000

INSPECTION DATE:

19 January 2021

JOB REFERENCE:

ADN21015A

INSPECTOR:

Farzad Rezvani
Property Condition Surveyor
M.Eng, MIEAust

WEATHER:

Mostly cloudy, 23°C

REPORT PREPARED BY:

Jen McCann



Table of Contents

Brief	3
Purpose of this Report.....	3
Areas Inspected.....	3
Limitations	3
Exclusions	3
Copyright	3
Terms and Conditions.....	4
Property Description	5
General Inspection Restrictions.....	5
Safety Issues	5
Property Sites Inspected	5
Explanation of Revisions	5
Defect Assessment: Major Defects.....	6
Defect Assessment: Minor Defects.....	7

BRIEF

AusDilaps was commissioned by
Lendlease Building Pty Limited
to carry out a pre-construction condition inspection and report in accordance with AS.4349.0 for the
Fort Street Public School, Millers Point NSW project.

PURPOSE OF THIS REPORT

This is a visual pre-construction inspection in accordance with AS 4349.0 and is intended to record the pre-construction condition of the property inspected and the surrounding areas. This is not a structural report and will not provide comment on the structural integrity or design of the inspected property; however it does include a photographic record of the main defects visible at the time of the inspection. The report is intended to be used to determine if change has occurred post-construction and if so, to what extent. This report and included photographs will be retained for use in/or during post-construction condition surveys.

LIMITATIONS

In accordance with AS 4349.0:

1. A visual only inspection may be of limited use to the client. In addition to a visual inspection, to thoroughly inspect the readily accessible areas of the property, further testing may be required whenever necessary.
2. This report does not include the inspection and assessment of items or matters outside the scope of the requested inspection and report.
3. This report does not include the inspection and assessment of items or matters that do not fall within the consultant's direct expertise.
4. The inspection only covers the readily accessible areas of the property and does not include areas, which were inaccessible or obstructed at the time of inspection. Obstructions are defined as any condition or physical limitation which inhibits or prevents inspection.
5. Australian Standard Inspection of Buildings, Part 1: Property Inspections – Residential buildings recognises that a standard property inspection report is not a warranty or an insurance policy against problems developing with the building in the future.

EXCLUSIONS

The client acknowledges that this report does not cover or deal with:

- (i) solving or providing costs for any rectification or repair work;
- (ii) the structural design or adequacy of any element of construction;
- (iii) detection of wood destroying insects such as termites and wood borers;
- (iv) the operation of fireplaces and chimneys;
- (v) any building services or appliances on the property;
- (vi) any swimming pools and associated pool equipment or spa baths and spa equipment or the like;
- (vii) whether the ground on which the building rests has been filled, is liable to subside, swell or shrink, is subject to landslip or tidal inundation, or if it is flood prone.

COPYRIGHT

All related council authorities are granted a perpetual non-exclusive license to make use of the copyright in all images supplied of council assets within this report, including the right to make copies available to third parties as though they were council images.

TERMS AND CONDITIONS

Important information regarding the scope and limitations of inspection and this report: Any person who relies upon the contents of this report does so acknowledging that the following clauses form an integral part of the report.

- 1. This report is not an all encompassing structural survey.** It is a reasonable attempt to identify any obvious or significant defects apparent at the time of the inspection. Whether a defect is considered significant or not, to a large extent, depends on the age and type of building A or property inspected. This report is not a Certificate of Compliance with the requirements of any act, regulation, ordinance or by-law or, as a warranty or an insurance policy against problems developing with the building or property in the future.
- 2. Only areas to which reasonable access is available were inspected.** AS 4349.0 defines reasonable access as "areas where safe, unobstructed access is provided and the minimum clearances specified below are available, or where these clearances are not available, areas within the inspector's unobstructed line of sight and within arm's length...". Reasonable access does not include removing screws and bolts to access covers or the use of destructive/invasive inspection methods, cutting or making access traps, moving heavy furniture, floor coverings or stored goods.
- 3. This report does not and cannot make comment upon:**
 - The assessment or detection of defects which may be subject to the prevailing weather conditions.
 - Whether or not services have been used for some time prior to the inspection and whether this will affect the detection of leaks or other defects.
 - The presence or absence of timber pests, gas-fittings, common property areas, environmental concerns, the proximity of the property to flight paths, railways, or busy traffic.
 - Noise levels, health and safety issues, heritage concerns, security concerns or systems; fire protection, site drainage.
 - Detection and identification of illegal building work, illegal plumbing work, durability of exposed finishes, neighbourhood problems, electrical installation, cables or reception systems, any matters that are solely regulated by statute.
 - Accordingly, this report does not guarantee that defects and/or damages do not exist in any inaccessible or partly inaccessible areas or sections of the property.
- 4. Asbestos, Lead and Mould Disclaimer:**

No inspection for asbestos, lead or mould was carried out at the property and no professional report on the presence or absence of them is provided. If asbestos is noted as present within the property or if the building was built prior to 1990 and you are concerned they may be present within the property then you should seek advice from a qualified specialist to identify the amount and importance of their presence and the cost of sealing or removal.
- 5. Estimating Disclaimer:**

This report does not provide any estimates on repair or remedial works. We recommend you consult a licenced builder to give an estimate on any work required.
- 6. Disclaimer of Liability:**

No liability shall be accepted on an account of failure of the report to notify any problems in the area(s) or section(s) of the subject property physically inaccessible during inspection, or to which access is denied. No responsibility can be accepted for defects which are latent or otherwise not reasonably detected on a visual inspection.
- 7. Disclaimer of Liability to Third Parties:**

This report is made solely for the use and benefit of the client named on the front of this report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the report wholly or in part. Any third party acting or relying on this report, in whole or in part does so at their own risk.

PROPERTY DESCRIPTION

Property Type:

- School

Building Type:

- Multi-storey, brick structure

GENERAL INSPECTION RESTRICTIONS

1. None noted at the time of the inspection.

SAFETY ISSUES

1. Please refer to 'Major Defects' for any Safety Issues related to building defects.

Important Note: Per AS 4349.0 Clause 4.2.f.2, the report shall identify any observed item that may constitute a present or imminent serious safety hazard.

PROPERTY SITES INSPECTED

- ☑ Internal Elements
- ☑ External Building Elements
- ☑ Garage/Carport
- ☑ Yard/Landscaping Elements
- ☑ Fences /Gates/Boundary Walls
- ☑ Paths/Paved Areas Inside the Property Boundary
- ☑ Swimming Pool and Surrounds
- ☑ Driveway/Crossover
- ☑ Kerbs/Gutters/Footpaths Outside the Property Boundary
- ☑ Roadways

Important Note: The areas listed above are a broad indication of the areas inspected. Damage and/or defects may be present and not detected in areas where the inspection was limited, obstructed, or access was not gained. Within these areas, some further restrictions may have been present restricting or preventing our inspection. If any recommendation has been made within this report to gain access to areas, gain further access to areas, or any area has been noted as being at "high risk" due to limited access, then further access must be gained. We strongly recommend that such access be gained to enable a more complete report to be submitted.

Drainage - Surface Water: Not inspected

Important Note: The site should be monitored during heavy rain to determine whether the existing drains can cope. If they cannot cope, then additional drains may be required.

Services: Not inspected

Important Note: In regard to plumbing or electrical, it should be noted that we are not plumbers or electricians and no comments are made to electrical or plumbing. We recommend that a qualified contractor be engaged to make comment on any matter dealing with plumbing or electrical issues.

EXPLANATION OF REVISIONS

Not applicable

DEFECT ASSESSMENT

Any crack/damage identified during the visual inspection of property, is measured using a crack gauge and is described for each location as per the following table.

CRACKING/DAMAGE CLASSIFICATION

Hairline cracks.	<0.1 mm	0 Hairline
Fine cracks that do not need repair.	<1 mm	1 Fine
Cracks noticeable but easily filled.	<5 mm	2 Slight
Crack can be repaired and possibly a small amount of wall/paving will need to be replaced.	<5 mm to 15 mm, or several cracks > 3mm	3 Moderate
Extensive repair work involving breaking out and replacing sections of walls/paving. Walls lean or bulge noticeably. Some loss of bearing in beams. Realignment work may be required for paving.	<15 mm to 25 mm, depends on number of cracks	4 Severe

** Referred to AS 2870: Residential slabs and footings – Construction, Table C2*

Defects in this reports are classified in two categories of Major and Minor.

MAJOR DEFECTS:

According to AS 4349.0 clause 1.3.9, a major defect is defined as “A defect of sufficient magnitude where rectification has to be carried out in order to avoid unsafe conditions, loss of utility or further deterioration of the property”. Per AS 4349.1 clause 4.2.4.1, where a major defect is mentioned in the report, it should be clearly described; including a general statement as to any observed minor defects and an explanation given as to why it is a major defect, along with its specific locations. AusDilaps, in consideration of ‘Acceptance Criteria’ as defined by AS 4349.0 Clause 2.4, and its years of experience and professional knowledge of staff, identifies and describes the major defects at the time of inspections based on one of the following reasons:

Reason	Reason for Identifying Major Defect
1	Large area is affected by the defect
2	Defect has substantially affected the serviceability of element
3	Defect presents risks of harm to people or damage to propertie(s)

DESCRIPTION

PAGE #

East wall of building A, north side. Showing slight stepped cracking in the mortar joints.	304
Damage in the timber decking at the southeast corner of building A.	321
General view of the timber deck on the east side of the property. Showing damage.	344
General view of the timber deck on the east side of the property. Showing damage.	346
General view of the timber deck on the east side of the property. Showing damage.	346
Damage in the step at the southeast corner of building B. Also showing cracking in the paving.	466
Movement in the heritage wall at the southwest corner of building B.	480
Movement in the heritage wall at the southwest corner of building B.	481

MINOR DEFECTS:

According to AS 4349.1 clause 4.2.4.2, minor defects are common to most properties and may include minor blemishes, corrosion, cracking, weathering, general deterioration, unevenness, and physical damage to materials and finishes. It is expected that defects of this type would be rectified as part of a normal ongoing maintenance.

DESCRIPTION	PAGE #
South wall in the entrance lobby. Showing nailing marks and damage.	22
Peeling paint in the west wall in the rainbow room.	28
Peeling paint in the east wall in the rainbow room, south side.	28
Patching in the east wall in the rainbow room toilet.	31
East wall in the auditorium. Showing peeling paint.	33
North wall in the auditorium. Showing peeling paint and water damage.	37
North wall in the auditorium. Showing peeling paint.	38
North wall in the auditorium. Showing paint.	39
North wall in the auditorium. Showing peeling paint.	41
North wall in the auditorium. Showing peeling paint.	42
General view in the stage area in the auditorium. Showing detached conduit.	42
General view in the stage area in the auditorium. Showing scratching in the skirting.	43
Chipping above the door in the east wall in the auditorium kitchenette. Also showing cracking.	48
Separation cracking between the door frame and the east wall in the auditorium kitchenette.	48
Separation cracking between the door frame and the east wall in the auditorium kitchenette.	49
Chipping and cracking in the north wall in the auditorium kitchenette.	50
South wall in the auditorium kitchenette. Showing a hole.	51
Water damage in the west wall in the auditorium kitchenette.	53
Cracking and chipping in the window frame in the north wall in the drama room.	54
West wall in the drama room. Showing staining.	55
Separation between the ceiling cornice and the ceiling in the drama room.	55
Fine cracking in the ceiling in the drama room.	56
Separation between the ceiling cornice and the north wall in the drama room.	56
Separation between the ceiling cornice and the north wall in the drama room. Also showing separation between the ceiling cornice and the ceiling.	56
Separation between the ceiling cornice and the east wall in the drama room.	57
South wall in the auditorium. Showing cracking.	58
Separation between the window frame and the south wall in the auditorium.	58
Separation between the window frame and the south wall in the auditorium.	59
Cracking in the window sill in the south wall in the auditorium.	63
Cracking in the window sill in the south wall in the auditorium.	63
General view in the electrical distribution board cupboard. Showing missing tile.	72
South wall in room 3. Showing peeling paint and damage.	76
Flooring in room 3. Showing staining.	78
Fine cracking in the west wall in the art room.	85
Fine cracking in the west wall in the art room.	86
Flooring in the art room. Showing staining.	87
Flooring in the art room. Showing staining.	88
South wall in the aqua 1 classroom. Showing peeling paint and damage.	100
Flooring in the aqua 1 classroom. Showing staining.	101
Water damage in the east wall in the aqua 1 classroom. Also showing cracking.	103
Cracking above the window in the south wall in the aqua 1 classroom. Also showing water damage.	103

Cracking above the window in the south wall in the aqua 1 classroom.	103
Fine cracking in the window sill in the south wall in the aqua 1 classroom.	104
Fine cracking in the east wall in the cobalt k classroom.	106
Flooring in the cobalt k classroom. Showing stain and patching.	109
East wall in the entrance to ruby k classroom. Showing nailing marks and hole.	111
North wall in the entrance to ruby k classroom. Showing nailing marks.	112
Flooring in the entrance to ruby k classroom. Showing staining.	114
Fine cracking in the window sill in the southwest corner in the entrance to ruby k classroom.	116
Crazing in the south wall in the entrance to ruby k classroom, west side.	116
Patched cracking in the northwest corner in the ceiling in the entrance to ruby k classroom.	116
Fine cracking in the middle window sill in the north wall in the entrance to ruby k classroom.	117
Damage in the door in the west wall in the west entrance.	119
Chipping in the door in the west wall in the west entrance.	119
Chipping in the steps in the toilet.	126
North wall in the storeroom. Showing patching.	127
West wall in the storeroom. Showing patching.	128
Fine cracking above the door in the south wall in the storeroom.	129
Patching in the ceiling in the storeroom, east side.	131
Fine cracking in the east wall in the storeroom, north side.	131
Separation in the northeast corner in the storeroom.	132
Scratching in the door in the storeroom.	132
Scratching in the door in the storeroom.	133
General view of the entrance to the cleaners room.	133
West wall in the cleaners room. Showing peeling paint.	133
West wall in the cleaners room. Showing peeling paint.	134
North wall in the cleaners room. Showing cracking.	134
South wall in the cleaners room. Showing fine cracking.	137
South wall in the cleaners room. Showing peeling paint.	137
Chipping in the east wall in the landing area in the stairway.	140
North wall in the stairway. Showing peeling paint.	141
Fine cracking in the east wall in the stairway.	142
Cracking in the ceiling in the ground floor corridor, outside the kitchen.	148
Ceiling in the ground floor corridor, outside the kitchen. Showing staining.	149
East wall in the kitchen. Showing peeling paint.	151
Peeling paint in the west wall in the kitchen.	153
Nail holes in the west wall in the kitchen.	153
South wall in the kitchen. Showing peeling paint.	154
Timber floor in the kitchen. Showing scratching in the skirting.	156
Peeling paint and cracking in the west wall in the south toilet.	157
Peeling paint and cracking in the west wall in the south toilet.	158
Peeling paint and crazing in the west wall in the south toilet.	158
Peeling paint in the east wall in the south toilet.	160
Fine cracking in the east wall in the level 1 corridor, outside the citrine classroom.	163
Fine cracking in the east wall in the citrine classroom.	167
Peeling paint in the east wall in the citrine classroom.	167
South wall in the citrine classroom. Showing nail markings.	169
South wall in the citrine classroom. Showing nail markings.	170
General view in the cleaners room. Showing patching and missing skirting.	175
South wall in the maths resources room. Showing peeling paint.	178

Cracking in the window sill in the west wall in the maths resources room.	180
Missing access hole in the ceiling in the maths resources room.	181
Ceiling in room 2. Showing peeling paint.	185
Ceiling in room 2. Showing peeling paint.	186
Water damage in the level 1 corridor, looking from the emerald classroom.	193
East wall in the level 1 corridor, north side. Showing cracking.	196
East wall in the emerald classroom. Showing nail markings.	198
Staining in the ceiling cornice in the northeast corner in the emerald classroom.	203
Water damage in the emerald classroom, west side.	205
Fine cracking in the west wall in the emerald classroom. Also showing water damage.	205
Fine cracking in the west wall in the lime classroom.	209
Crazing in the ceiling in the lime classroom.	210
Flooring in the lime classroom. Showing staining.	211
Fine cracking in the west wall in the lime classroom, adjacent to the door.	211
Peeling paint and crazing in the west wall in the stairway.	213
Fine cracking in the south wall in room 15.	219
East wall in room 15. Showing peeling paint.	220
East wall in room 15.	221
Fine cracking in the north wall in room 15.	222
Chipping in the north wall in room 15, adjacent to the door.	223
East wall in room 15. Showing peeling paint and crazing.	224
Floor slab in room 15. Showing scoring.	224
Fine cracking in the south wall in room 14.	226
Fine cracking in the south wall in room 14.	227
Separation in the window frame in the south wall in room 14.	227
Fine cracking in the north wall in room 14.	231
Fine cracking in the north wall in room 14.	232
Crazing in the north wall in room 14.	232
Ceiling in room 14. Showing staining.	233
Ceiling in room 14. Showing staining.	234
Peeling paint and crazing in the north wall in room 14.	235
Peeling paint in the east wall in the toilet in room 13.	237
Fine cracking in the north wall in room 13.	242
Slight stepped cracking in the mortar joint in the north wall of building A, outside room 15.	251
Erosion in the mortar joints in the north wall of building A, outside room 15.	251
Erosion in the mortar joints in the north wall of building A, outside room 15.	252
Chipping in the brick in the north wall of building A, outside room 15.	252
Mold on the soffit on the north side of building A, outside room 15.	253
North wall of building A, outside room 14. Showing chipping and nail markings.	254
Wide cracking in the wall on the north side of room 14.	255
Erosion in the mortar joints in the wall on the north side of room 14.	255
Erosion in the mortar joints in the wall on the north side of room 14.	256
Cracking in the paving on the north side of room 14.	256
Cracking in the paving on the north side of room 14.	257
General view of the wall on the north side of building A, outside the toilets. Showing wide cracking and movement.	258
North wall of building A, outside room 13. Showing chipping.	259
Erosion in the mortar joints in the north wall of building A, outside room 12.	260
West wall of building A, looking from room 12. Showing missing brick.	262
Movement and erosion in the west wall of building A.	262

General view of the paving on the north side of building A. Showing scoring and cracking.	264
General view of the paving on the north side of building A. Showing cracking.	264
General view of the paving on the north side of building A. Showing cracking.	265
Chipping in the north wall of building A, outside the auditorium kitchenette.	267
Chipping in the north wall of building A, outside the drama room.	268
North wall of building A. Showing peeling paint and dent in the down pipe.	269
Cracking in the paving on the north side of the auditorium.	272
Rusting above the window in the north wall of building A.	274
Rusting above the window in the north wall of building A.	275
Nail marking in the north wall of building A.	278
General view of the soffit at the entrance on the west side of building A. Showing peeling paint.	278
Chipping above the window in the south wall of building A, looking from the west entrance.	280
Nail markings in the west wall of building A, looking from the playground.	282
Rusting and cracking above the window in the north wall of building A.	287
Rusting above the window in the north wall of building A.	288
North wall of building A. Showing erosion in the mortar joints.	289
Cracking in the brick in the north wall of building A, outside room 23.	290
Peeling paint in the north wall of building A, outside the entrance.	290
Chipping in the steps at the north entrance.	292
Chipping in the north wall of building A, outside the entrance.	292
Cracking in the paving on the north side of building A.	294
North wall of building A, east side. Showing erosion in the mortar joints.	296
North wall of building A, east side. Showing corrosion.	297
North wall of building A, east side. Showing corrosion.	298
Chipping in the brick at the northeast corner of building A.	298
Slight, vertical cracking in the east wall of building A, north side	298
Slight, vertical cracking in the east wall of building A, north side.	299
East wall of building A, north side. Showing chipping above the window.	304
Cracking above the second window from the north in the brick in the east wall of building A.	306
Cracking above the third window from the north in the brick in the east wall of building A.	306
Cracking above the fourth window from the north in the brick in the east wall of building A.	306
General view of the garden bed on the east side of building A. Showing chipping.	309
Cracking and chipping above the third window from the north in the east wall of building A.	310
Cracking and chipping above the fifth window from the north in the east wall of building A.	310
East wall of building A, looking from the sixth window from the north. Showing damage above the window.	311
East wall of building A, looking from the eighth window from the north. Showing chipping above the window.	313
East wall of building A, looking from the ninth window from the north. Showing chipping above the window.	314
Chipping in the brick in the east wall of building A.	319
General view of the steps on the east side of building A, outside the main entrance. Showing chipping.	323

General view of the steps on the east side of building A, outside the main entrance.	
Showing chipping.	324
Chipping in the paving at the main entrance.	328
Slight cracking in the paving at the entrance.	328
Tile paving at the main entrance. Showing cracking.	329
Damage in the steps at the main entrance.	331
Cracking in the south wall at the entrance.	332
Cracking in the paving at the southeast corner of building A.	333
Paving at the southeast corner of building A. Showing cracking and movement.	334
Rusting in the south wall of the ventilation shed.	349
Missing top in the fence on the east side of the property.	350
General view of the gate on the east side of the property. Showing rusting.	351
Chipping in the base of the fence on the south side of building A, east side.	358
Chipping in the fence on the south side of building A, east side.	359
Cracking in the fence on the south side of building A, east side.	359
Cracking in the base of the fence on the south side of building A.	361
Cracking in the base of the fence on the south side of building A.	365
Subsidence in the paving on the south side of building A.	366
Fence on the south side of building A. Showing cracking in the base.	370
Damage above the window in the south wall of building A.	373
South wall of building A. Showing cracking above the window.	373
Cracking in the paving on the south side of building A.	376
Cracking in the paving on the south side of building A.	378
Chipping and cracking in the south side of building A.	384
Cracking in the paving on the south side of building A.	387
Slight cracking in the south wall of building A.	388
Bowing in the lintel in the south wall of building A, outside room 12.	389
Cracking in the doorstep on the south side of building A, outside room 12.	390
Cracking in the paving around the drain on the south side of building A, outside room 12.	390
Fence on the south side of building A, looking from room 12. Showing cracking.	391
Cracking in the base of the fence on the south side of building A, outside room 12.	392
Chipping in the base of the fence on the south side of building A, outside room 12.	392
Cracking in the paving on the south side of building A, outside room 13.	392
Cracking in the paving on the south side of building A, outside room 12.	396
Bowing and rusting in the lintel on the south side of building A, outside room 12.	397
Wide separation in the paving on the south side of building A, outside room 12.	397
Wide separation in the paving on the south side of building A, outside room 12.	398
Wide cracking and movement in the paving at the southwest corner of building A.	399
Wide cracking and movement in the paving at the southwest corner of building A.	400
Scoring in the paving on the west side of building A.	400
Cracking in the paving on the west side of building A.	401
Paving on the west side of building A. Showing wide cracking.	401
Cracking in the carpark at the southwest corner of building A.	402
Patching and cracking in the carpark at the southwest corner of building A.	402
Patching in the carpark at the southwest corner of building A.	403
Carpark at the southwest corner of building A. Showing patching.	403
Carpark at the southwest corner of building A. Showing patching and scoring.	404
Carpark at the southwest corner of building A. Showing patching.	404
Patching in the carpark at the southwest corner of building A.	405
Separation in the base of the fence on the south side of building A.	408
General view of the driveway on the south side of building A. Showing cracking.	408

General view of the driveway on the south side of building A. Showing cracking and patching.	409
Cracking in the base of the fence on the south side of building A.	410
Cracking in the driveway on the south side of building A.	412
General view of the driveway on the south side of building A. Showing cracking.	412
General view of the storm drain in the driveway on the south side of building A. Showing cracking.	412
General view of the pit lid in the driveway on the south side of building A. Showing cracking in the paving.	413
Cracking in the base of the fence on the south side of building A.	416
Stepped cracking in the south wall of building A.	418
General view of the driveway on the south side of building A. Showing chipping in the kerb.	422
Cracking in the driveway on the south side of building A.	424
Slight stepped cracking in the north wall of building F.	426
Erosion in the mortar joints in the north wall of building F.	426
Cracking in the paving on the west side of building B.	427
Cracking in the paving on the west side of building B.	428
Damage in the soffit at the northwest corner of building B.	429
Damage in the soffit on the north side of building B.	430
North wall of building B, west side. Showing cracking.	431
North wall of building B, west side. Showing erosion in the mortar joints.	432
North wall of building B. Showing damage in the soffit.	432
North wall of building B. Showing corrosion in the balcony.	433
North wall of building B. Showing erosion in the mortar joints.	433
North wall of building B. Showing erosion in the mortar joints.	434
Cracking on the underside of the balcony, on the north side of building B.	434
Cracking on the underside of the balcony, on the north side of building B.	435
General view of the pit lid in the paving at the northwest corner of building B. Showing cracking.	436
General view of the pit lid in the grass area at the northwest corner of building B. Showing cracking.	436
Cracking in the kerb at the northwest corner of building B.	436
Cracking and chipping in the kerb at the northwest corner of building B.	437
Chipping in the kerb at the northwest corner of building B.	437
General view of the grass area on the north side of building B.	437
Chipping in the kerb on the north side of building B.	438
North wall of building B. Showing damage in the soffit.	440
North wall of building B. Showing cracking in the underside of the balcony.	440
North wall of building B, outside the main entrance. Showing peeling paint.	440
North wall of building B, outside the main entrance. Showing peeling paint.	441
Wide cracking in the steps on the north side of building B, outside the entrance.	442
Crazing and cracking in the steps on the north side of building B, outside the entrance.	442
Crazing in the north wall of building B, outside the entrance.	443
Chipping in the awning on the south side of building B, outside the entrance.	444
North wall of building B. Showing erosion in the mortar joints.	447
North wall of building B. Showing erosion in the mortar joints.	448
General view of the garden bed on the north side of building B. Showing cracking.	449
General view of the garden bed on the north side of building B. Showing wide cracking.	449
General view of the garden bed on the north side of building B. Showing cracking.	450

Wide cracking in the garden bed on the north side of building B, outside the entrance.	450
Wide cracking in the garden bed on the north side of building B, outside the entrance.	451
General view of the garden bed on the north side of building B. Showing damage in the garden bed and the north wall.	452
Damage in the garden bed on the north side of building B. Also showing damage in the north wall of building B.	452
Missing brick in the north wall of building B. Also showing erosion in the mortar joints.	453
Leaning in the garden bed fence on the north side of building B.	453
Damage in the garden bed fence at the northeast corner of building B.	453
Damage in the garden bed fence at the northeast corner of building B.	454
Cracking in the paving at the northeast corner of building B.	454
Cracking in the paving at the northeast corner of building B.	455
Cracking in the paving at the northeast corner of building B. Also showing movement.	455
General view of the soffit on the north side of building B. Showing weathering and damage.	457
East wall of building B. Showing crazing.	461
East wall of building B, south side. Showing rusting and peeling paint.	463
Stepped cracking and movement in the east wall of building B, south side.	463
Slight stepped cracking in the mortar joints in the east wall of building B, south side. Also showing missing bricks.	464
Slight cracking in the mortar joints in the east wall of the building, south side. Also showing movement.	465
Cracking in the paving at the southeast corner of building B.	465
General view of the heritage wall, looking from the southeast corner of building B. Showing erosion in the mortar joints.	466
General view of the heritage wall, looking from the southeast corner of building B. Showing erosion in the mortar joints.	467
Cracking in the heritage wall, looking from the southeast corner of building B. Also showing erosion in the mortar joints.	467
Erosion in the mortar joints the heritage wall, looking from the southeast corner of building B. Also showing movement.	468
Cracking in the top of the heritage wall, looking from the southeast corner of building B.	468
Cracking and erosion in the top of the heritage wall, looking from the southeast corner of building B.	468
Cracking and erosion in the top of the heritage wall, looking from the southeast corner of building B.	469
Separation between the heritage wall and the south wall of building B.	469
General view of the top of the heritage wall at the southeast corner of building B. Showing cracking and movement.	469
Damage in the soffit on the west side of building B.	471
Damage in the soffit on the west side of building B.	472
West wall of building B, south side. Showing cracking above the window.	473
West wall of building B, south side. Showing damage above the window.	474
Slight cracking above the window in the west wall of the building, south side.	474
Cracking in the west wall of building B, south side.	475
General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.	477
General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.	478
General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.	479

Cracking in the paving at the southwest corner of building B.	479
Slight stepped cracking in the east wall of building F.	479
Slight stepped cracking in the east wall of building F. Also showing movement.	480
Slight stepped cracking in the east wall of building F.	480
Cracking in the paving on the west side of building B.	481
Wide cracking above the window in the south wall of building B.	488
Cracking and movement in the south wall of building B.	488
Cracking in the south wall of building B.	488
Cracking in the south wall of building B.	490
Cracking in the heritage wall on the south side of building B.	493
General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.	496
Mold and signs of water in the soffit on the south side of building B.	496
Detached down pipe in the south wall of building B.	498
Movement in the bricks in the south wall of building B.	499
Stepped cracking and erosion in the mortar joints in the south wall of building B.	500
General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.	503
General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.	507
General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.	508
Damage in the seats on the south side of building C.	510
General view of the heritage wall on the south side of building C. Showing erosion in the mortar joints.	511
Nail holes the heritage wall on the south side of building C.	512
Damage in the heritage wall on the south side of building C.	513
Slight cracking in the heritage wall on the south side of building C.	515
General view of the chimney on the south side of building C. Showing chipping.	522
Cracking in the west wall of building C, north side.	528
Rusting damage in the down pipe on the west side of building C.	528
Movement in the retaining wall at the northwest corner of building C.	529
Movement in the retaining wall at the northwest corner of building C. Also showing wide cracking.	529
Movement in the retaining wall on the west side of building C. Also showing slight cracking in the mortar joints.	529
Chipping in the retaining wall on the west side of building C.	531
General view of the retaining wall on the west side of building C. Showing damage.	532
Cracking in the doorstep on the west side of building C.	534
General view of the heritage wall on the south side of building C. Showing erosion in the mortar joints.	534
South wall of building C. Showing separation in the cladding.	535
Gap below the step in the south wall of building C.	535
Cracking in the north wall of building C, west side.	540
Slight cracking in the paving on the north side of building C.	542
Fine cracking in the north wall of building C.	545
Cracking in the paving at the northeast corner of building C.	545
Fine cracking in the paving on the east side of building C.	546
Fine cracking in the east wall of building C.	552
Separation between the fascia and east wall of building C.	553
Damage in the window sill on the east side of building C.	555
Peeling paint and staining in the ceiling in office 1.	567

Patching in the ceiling in office 1.	567
Separation in the cladding in the south wall in the bathroom.	571
Ceiling in the bathroom. Showing separation between cladding.	574
Ceiling in the bathroom. Showing separation between cladding.	574
Ceiling in the bathroom. Showing separation between cladding.	575
Ceiling in the kitchen. Showing separation between cladding.	584
Separation between the counter and the west wall in the kitchen.	588
General view of the ceiling on the north porch on building C. Showing cracking.	590
Separation above the column on the north porch on building C.	591
General view of the heritage wall on the south side of building C. Showing erosion in the mortar joints.	591
General view of the heritage wall on the south side of building C. Showing erosion in the mortar joints.	593
Cracking in the heritage wall at the southeast corner of the property.	594
Damage in the base of the fence on the south side of the driveway.	598
General view of the heritage post on the south side of the driveway. Showing cracking in the mortar joints.	600
General view of the heritage post on the south side of the driveway. Showing cracking in the mortar joints.	601
General view of the heritage post on the south side of the driveway. Showing erosion in the mortar joints.	602
General view of the paving on the south side of the driveway. Showing cracking.	603
Chipping in the base of the fence on the north side of the driveway.	605
Cracking in the base of the fence on the north side of the driveway.	606
Cracking in the driveway.	606
General view of the fence on the north side of the driveway. Showing chipping in the base.	609
General view of the fence on the north side of the driveway. Showing cracking in the base.	611
Cracking in the base of the fence on the east side of the property.	612
Cracking in the base of the fence on the east side of the property.	613
General view of the gate on the east side of the property. Showing leaning.	614
General view of the footpath on the east side of the property. Showing chipping.	614
Cracking in the base of the fence on the east side of the property.	615
Cracking in the base of the fence on the east side of the property.	616
Cracking in the base of the fence on the east side of the property.	616
General view of the fence on the east side of the property. Showing missing top.	617
East wall of the ventilation shed. Showing bubbling paint.	618
East wall of the ventilation shed. Showing bubbling paint.	619
Cracking in the footpath on the east side of the ventilation shed.	620
Cracking in the footpath on the east side of the ventilation shed.	621
General view of the paving on the north side of the ventilation shed. Showing patching.	623
General view of the grass area on the east side of Upper Fort Street. Showing chipping in the kerb.	624
General view of the power pole on the east side of Upper Fort Street, adjacent to the cycle way. Showing leaning.	626
General view of the cycle way. Showing cracking.	628
Cracking in the cycle way.	632
Cracking in the kerb on the east side of the cycle way.	632
Damage in the street sign in the cycle way.	633
Cracking in the cycle way.	634

Cracking in the cycle way.	635
Separation in the base of the fence on the south side of building G.	640
General view of the fence on the south side of building G. Showing cracking in the base.	643
General view of the paving on the south side of building G. Showing cracking and patching.	643
Cracking in the post on the east side of the pedestrian bridge on the south side of building G.	644
Cracking in the post on the east side of the pedestrian bridge on the south side of building G.	645
Crazing in the post on the west side of the pedestrian bridge on the south side of building G.	645
Crazing in the post on the west side of the pedestrian bridge on the south side of building G.	646
Cracking in the pedestrian bridge on the south side of building G.	646
Cracking in the pedestrian bridge on the south side of building G.	647
General view of the steps on the south side of the pedestrian bridge on the south side of building G. Showing chipping.	648
Crazing in the wing wall of the steps on the south side of the pedestrian bridge on the south side of building G.	649
Cracking in the post on the west side of the pedestrian bridge.	654
Cracking in the post on the west side of the pedestrian bridge.	655
Cracking in the paving on the west side of building J.	659
Cracking in the base of the fence on the west side of the property, looking from building F.	664
Cracking in the base of the fence on the west side of the property, looking from building F.	665
General view of the garden bed in the carpark on the north side of building A. Showing movement.	675
Hole in the artificial grass in the playground, east side.	684
Hole in the artificial grass in the playground, east side.	685
Hole in the artificial grass in the playground.	686
Hole in the artificial grass in the playground, west side.	686
Hole in the artificial grass in the playground, south side.	687

Yours faithfully



Michael Burford

AUSTRALIAN DILAPIDATIONS

Office: 1800 Dilaps (345 277)

Email: info@ausdilaps.com.au



Digitally signed by
Anthony Manning
Date: 2021.04.07
15:49:18 +10'00'

Signed by the Applicant:



Figure: 0001

UPPER FORT STREET PUBLIC SCHOOL, MILLERS POINT



Figure: 0002

BUILDING A

General view of building A.




Figure: 0003

INTERNAL- GROUND FLOOR

East wall in the entrance lobby.



Figure: 0004

East wall in the entrance lobby.



Figure: 0005

South wall in the entrance lobby.



Figure: 0006

South wall in the entrance lobby.



Figure: 0007

South wall in the entrance lobby.



Figure: 0008

Timber floor in the entrance lobby.



Figure: 0009

Timber floor in the entrance lobby.



Figure: 0010

North wall in the entrance lobby.



Figure: 0011

North wall in the entrance lobby.



Figure: 0012

North wall in the entrance lobby.



Figure: 0013

North wall in the entrance lobby.



Figure: 0014

South wall in the entrance lobby. Showing nailing marks and damage.



Figure: 0015

South wall in the entrance lobby. Showing nailing marks and damage.



Figure: 0016

West wall in the entrance lobby.




Figure: 0017

West wall in the entrance lobby.



Figure: 0018

North wall in the entrance lobby.



Figure: 0019

North wall in the entrance lobby.



Figure: 0020

General view of the entrance to the rainbow room.



Figure: 0021

East wall in the rainbow room.




Figure: 0022

East wall in the rainbow room.



Figure: 0023

North wall in the rainbow room.



Figure: 0024

North wall in the rainbow room.

Figure: 0025

West wall in the rainbow room.



Figure: 0026

West wall in the rainbow room.



Figure: 0027

South wall in the rainbow room.






Figure: 0028

South wall in the rainbow room.



Figure: 0029

Flooring in the rainbow room.



Figure: 0030

Flooring in the rainbow room.



Figure: 0031

Peeling paint in the west wall in the rainbow room.



Figure: 0032

Peeling paint in the west wall in the rainbow room.



Figure: 0033

Peeling paint in the east wall in the rainbow room, south side.



Figure: 0034

Ceiling in the rainbow room.



Figure: 0035

Ceiling in the rainbow room.



Figure: 0036

General view in the rainbow room toilet.



Figure: 0037

General view in the rainbow room toilet.



Figure: 0038

General view in the rainbow room toilet.




Figure: 0039

General view in the rainbow room toilet.



Figure: 0040

Tile floor in the rainbow room toilet.



Figure: 0041

Tile floor in the rainbow room toilet.



Figure: 0042

Patching in the east wall in the rainbow room toilet.



Figure: 0043

Ceiling in the rainbow room toilet.



Figure: 0044

Ceiling in the rainbow room toilet.



Figure: 0045

General view in the auditorium.



Figure: 0046

East wall in the auditorium.



Figure: 0047

East wall in the auditorium. Showing peeling paint.




Figure: 0048

East wall in the auditorium.



Figure: 0049

East wall in the auditorium.



Figure: 0050

East wall in the auditorium.



Figure: 0051

East wall in the auditorium.



Figure: 0052

East wall in the auditorium.



Figure: 0053

Ceiling in the auditorium, east side.



Figure: 0054

Ceiling in the auditorium, east side.



Figure: 0055

Timber floor in the auditorium, east side.



Figure: 0056

Timber floor in the auditorium, east side.



Figure: 0057

Timber floor in the auditorium, east side.

Figure: 0058

North wall in the auditorium.



Figure: 0059

North wall in the auditorium.



Figure: 0060

North wall in the auditorium. Showing peeling paint and water damage.





Figure: 0061

North wall in the auditorium. Showing peeling paint.



Figure: 0062

North wall in the auditorium.



Figure: 0063

North wall in the auditorium. Showing peeling paint.



Figure: 0064

North wall in the auditorium. Showing paint.



Figure: 0065

North wall in the auditorium.



Figure: 0066

North wall in the auditorium. Showing nail marks.

Figure: 0067

Ceiling in the
auditorium.



Figure: 0068

Ceiling in the
auditorium.



Figure: 0069

Timber floor in the
auditorium.





Figure: 0070

Timber floor in the auditorium.



Figure: 0071

North wall in the auditorium. Showing peeling paint.



Figure: 0072

North wall in the auditorium.

Figure: 0073

North wall in the auditorium. Showing peeling paint.



Figure: 0074

North wall in the auditorium.



Figure: 0075

General view in the stage area in the auditorium. Showing detached conduit.





Figure: 0076

General view in the stage area in the auditorium.



Figure: 0077

General view in the stage area in the auditorium. Showing scratching in the skirting.



Figure: 0078

North wall in the stage area in the auditorium.



Figure: 0079

North wall in the stage area in the auditorium.




Figure: 0080

Timber floor in the stage area in the auditorium.



Figure: 0081

Timber floor in the stage area in the auditorium.



Figure: 0082

Ceiling in the stage area in the auditorium.



Figure: 0083

Ceiling in the stage area in the auditorium.



Figure: 0084

West wall in the stage area in the auditorium.



Figure: 0085

West wall in the stage area in the auditorium.




Figure: 0086

West wall in the stage area in the auditorium.



Figure: 0087

West wall in the stage area in the auditorium.




Figure: 0088

South wall in the stage area in the auditorium.




Figure: 0089

South wall in the stage area in the auditorium.




Figure: 0090

East wall in the auditorium kitchenette.



Figure: 0091

East wall in the auditorium kitchenette.



Figure: 0092

Chipping above the door in the east wall in the auditorium kitchenette. Also showing cracking.




Figure: 0093

Separation cracking between the door frame and the east wall in the auditorium kitchenette.



Figure: 0094

Separation cracking between the door frame and the east wall in the auditorium kitchenette.



Figure: 0095

North wall in the auditorium kitchenette.



Figure: 0096

North wall in the auditorium kitchenette.



Figure: 0097

North wall in the auditorium kitchenette.



Figure: 0098

Chipping and cracking in the north wall in the auditorium kitchenette.



Figure: 0099

West wall in the auditorium kitchenette.



Figure: 0100

West wall in the auditorium kitchenette.



Figure: 0101

South wall in the auditorium kitchenette.



Figure: 0102

South wall in the auditorium kitchenette. Showing a hole.



Figure: 0103

South wall in the auditorium kitchenette.



Figure: 0104

Timber floor in the auditorium kitchenette.



Figure: 0105

Ceiling in the auditorium kitchenette.



Figure: 0106

Water damage in the west wall in the auditorium kitchenette.



Figure: 0107

North wall in the drama room.




Figure: 0108

North wall in the drama room.



Figure: 0109

Cracking and chipping in the window frame in the north wall in the drama room.



Figure: 0110

East wall in the drama room.



Figure: 0111

South wall in the drama room.



Figure: 0112

South wall in the drama room.



Figure: 0113

West wall in the drama room. Showing staining.



Figure: 0114

Separation between the ceiling cornice and the ceiling in the drama room.



Figure: 0115

Fine cracking in the ceiling in the drama room.



Figure: 0116

Separation between the ceiling cornice and the north wall in the drama room.



Figure: 0117

Separation between the ceiling cornice and the north wall in the drama room. Also showing separation between the ceiling cornice and the ceiling.



Figure: 0118

Separation between the ceiling cornice and the east wall in the drama room.



Figure: 0119

General view of the stage area in the auditorium, looking from the drama room.



Figure: 0120

General view of the stage area in the auditorium, looking from the drama room.



Figure: 0121

South wall in the auditorium. Showing cracking.




Figure: 0122

South wall in the auditorium.



Figure: 0123

Separation between the window frame and the south wall in the auditorium.



Figure: 0124

Separation between the window frame and the south wall in the auditorium.



Figure: 0125

South wall in the auditorium.



Figure: 0126

South wall in the auditorium.



Figure: 0127

South wall in the auditorium.



Figure: 0128

South wall in the auditorium.



Figure: 0129

Timber floor in the auditorium, south side.



Figure: 0130

Timber floor in the auditorium, south side.



Figure: 0131

Ceiling in the auditorium.



Figure: 0132

Ceiling in the auditorium.



Figure: 0133

South wall in the auditorium.



Figure: 0134

South wall in the auditorium.



Figure: 0135

South wall in the auditorium.



Figure: 0136

South wall in the auditorium.



Figure: 0137

Cracking in the window sill in the south wall in the auditorium.



Figure: 0138

Cracking in the window sill in the south wall in the auditorium.



Figure: 0139

Cracking in the window sill in the south wall in the auditorium.



Figure: 0140

South wall in the auditorium.



Figure: 0141

South wall in the auditorium.



Figure: 0142

General view of the auditorium office.



Figure: 0143

General view in the auditorium office.



Figure: 0144

General view in the auditorium office.



Figure: 0145

General view in the auditorium office.



Figure: 0146

General view in the auditorium office.



Figure: 0147

General view in the auditorium office.



Figure: 0148

General view of the craft room in the auditorium.



Figure: 0149

General view in the craft room in the auditorium.



Figure: 0150

General view in the craft room in the auditorium.



Figure: 0151

General view in the craft room in the auditorium.



Figure: 0152

General view in the craft room in the auditorium.



Figure: 0153

General view in the craft room in the auditorium.



Figure: 0154

General view in the craft room in the auditorium.



Figure: 0155

General view in the craft room in the auditorium.



Figure: 0156

General view in the ground floor corridor, outside the auditorium.



Figure: 0157

General view in the ground floor corridor, outside the auditorium.



Figure: 0158

West wall in the ground floor corridor, outside the auditorium.



Figure: 0159

West wall in the ground floor corridor, outside the auditorium.



Figure: 0160

East wall in the ground floor corridor, outside the auditorium.



Figure: 0161

East wall in the ground floor corridor, outside the auditorium.



Figure: 0162

General view of the electrical distribution board cupboard.

Figure: 0163

General view in the electrical distribution board cupboard.



Figure: 0164

General view in the electrical distribution board cupboard.
Showing missing tile.



Figure: 0165

General view in the electrical distribution board cupboard.
Showing missing tile.





Figure: 0166

General view in the electrical distribution board cupboard.



Figure: 0167

General view in the electrical distribution board cupboard.



Figure: 0168

General view in the electrical distribution board cupboard.



Figure: 0169

General view of the entrance to room 3.




Figure: 0170

East wall in room 3.



Figure: 0171

East wall in room 3.



Figure: 0172

East wall in room 3.



Figure: 0173

East wall in room 3.



Figure: 0174

North wall in room 3.



Figure: 0175

West wall in room 3.



Figure: 0176

South wall in room 3. Showing peeling paint and damage.



Figure: 0177

Ceiling in room 3.

Figure: 0178

Ceiling in room 3.



Figure: 0179

Ceiling in room 3.



Figure: 0180

Flooring in room 3.





Figure: 0181

Flooring in room 3.



Figure: 0182

Flooring in room 3.
Showing staining.



Figure: 0183

East wall in the
ground floor corridor,
outside room 3.



Figure: 0184

East wall in the ground floor corridor, outside room 3.



Figure: 0185

West wall in the ground floor corridor, outside room 3.



Figure: 0186

West wall in the ground floor corridor, outside room 3.



Figure: 0187

Timber floor in the ground floor corridor, outside room 3.



Figure: 0188

Flooring in the ground floor corridor, outside room 3.



Figure: 0189

Ceiling in the ground floor corridor, outside room 3.



Figure: 0190

Ceiling in the ground floor corridor, outside room 3.



Figure: 0191

West wall in the ground floor corridor, outside the art room.



Figure: 0192

West wall in the ground floor corridor, outside the art room.



Figure: 0193

East wall in the ground floor corridor, outside the art room.



Figure: 0194

East wall in the ground floor corridor, outside the art room.



Figure: 0195

East wall in the ground floor corridor, outside the art room.



Figure: 0196

East wall in the ground floor corridor, outside the art room.



Figure: 0197

General view of the entrance to the art room.




Figure: 0198

East wall in the art room.



Figure: 0199

East wall in the art room.



Figure: 0200

North wall in the art room.




Figure: 0201

North wall in the art room.



Figure: 0202

West wall in the art room.




Figure: 0203

West wall in the art room.



Figure: 0204

Fine cracking in the west wall in the art room.



Figure: 0205

Fine cracking in the west wall in the art room.



Figure: 0206

South wall in the art room.



Figure: 0207

South wall in the art room.



Figure: 0208

Ceiling in the art room.



Figure: 0209

Ceiling in the art room.



Figure: 0210

Flooring in the art room. Showing staining.



Figure: 0211

Flooring in the art room. Showing staining.



Figure: 0212

East wall in the ground floor corridor, outside aqua 1 classroom.



Figure: 0213

East wall in the ground floor corridor, outside aqua 1 classroom.



Figure: 0214

West wall in the ground floor corridor, outside aqua 1 classroom.



Figure: 0215

West wall in the ground floor corridor, outside aqua 1 classroom.




Figure: 0216

West wall in the ground floor corridor, outside aqua 1 classroom.



Figure: 0217

West wall in the ground floor corridor, outside aqua 1 classroom.



Figure: 0218

General view in the ground floor corridor, outside aqua 1 classroom.



Figure: 0219

General view in the ground floor corridor, outside aqua 1 classroom.



Figure: 0220

West wall in the ground floor corridor, outside ruby k classroom.



Figure: 0221

West wall in the ground floor corridor, outside ruby k classroom.



Figure: 0222

West wall in the ground floor corridor, outside ruby k classroom.



Figure: 0223

West wall in the ground floor corridor, outside ruby k classroom.



Figure: 0224

East wall in the ground floor corridor, outside ruby k classroom.



Figure: 0225

East wall in the ground floor corridor, outside ruby k classroom.



Figure: 0226

East wall in the ground floor corridor, outside ruby k classroom.



Figure: 0227

East wall in the ground floor corridor, outside ruby k classroom.



Figure: 0228

East wall in the ground floor corridor, outside cobalt k classroom.



Figure: 0229

East wall in the ground floor corridor, outside cobalt k classroom.



Figure: 0230

North wall in the ground floor corridor, outside cobalt k classroom.




Figure: 0231

North wall in the ground floor corridor, outside cobalt k classroom.



Figure: 0232

West wall in the ground floor corridor, outside cobalt k classroom.



Figure: 0233

West wall in the ground floor corridor, outside cobalt k classroom.



Figure: 0234

West wall in the ground floor corridor, outside cobalt k classroom.



Figure: 0235

General view in the ground floor corridor, outside cobalt k classroom.



Figure: 0236

Ceiling in the ground floor corridor, outside cobalt k classroom.



Figure: 0237

Timber floor in the ground floor corridor, outside cobalt k classroom.



Figure: 0238

General view of the entrance to the aqua 1 classroom.




Figure: 0239

East wall in the aqua 1 classroom.



Figure: 0240

East wall in the aqua 1 classroom.




Figure: 0241

East wall in the aqua 1 classroom.




Figure: 0242

East wall in the aqua 1 classroom.



Figure: 0243

North wall in the aqua 1 classroom.



Figure: 0244

North wall in the aqua 1 classroom.



Figure: 0245

West wall in the aqua 1 classroom.



Figure: 0246

West wall in the aqua 1 classroom.



Figure: 0247

West wall in the aqua 1 classroom.



Figure: 0248

South wall in the aqua 1 classroom.



Figure: 0249

South wall in the aqua 1 classroom. Showing peeling paint and damage.



Figure: 0250

South wall in the aqua 1 classroom.



Figure: 0251

South wall in the aqua 1 classroom.



Figure: 0252

Flooring in the aqua 1 classroom. Showing staining.

Figure: 0253

Ceiling in the aqua 1 classroom.



Figure: 0254

Ceiling in the aqua 1 classroom.



Figure: 0255

Ceiling in the aqua 1 classroom.





Figure: 0256

Water damage in the east wall in the aqua 1 classroom. Also showing cracking.



Figure: 0257

Cracking above the window in the south wall in the aqua 1 classroom. Also showing water damage.



Figure: 0258

Cracking above the window in the south wall in the aqua 1 classroom.



Figure: 0259

Fine cracking in the window sill in the south wall in the aqua 1 classroom.



Figure: 0260

Fine cracking in the window sill in the south wall in the aqua 1 classroom.



Figure: 0261

Fine cracking in the window sill in the south wall in the aqua 1 classroom.



Figure: 0262

General view of the entrance to the cobalt k classroom.



Figure: 0263

East wall in the cobalt k classroom.



Figure: 0264

East wall in the cobalt k classroom.



Figure: 0265

East wall in the cobalt k classroom.



Figure: 0266

East wall in the cobalt k classroom.



Figure: 0267

Fine cracking in the east wall in the cobalt k classroom.



Figure: 0268

North wall in the cobalt k classroom.



Figure: 0269

North wall in the cobalt k classroom.



Figure: 0270

North wall in the cobalt k classroom.



Figure: 0271

North wall in the cobalt k classroom.




Figure: 0272

West wall in the cobalt k classroom.



Figure: 0273

West wall in the cobalt k classroom.



Figure: 0274

South wall in the cobalt k classroom.



Figure: 0275

South wall in the cobalt k classroom.



Figure: 0276

Flooring in the cobalt k classroom. Showing stain and patching.



Figure: 0277

Ceiling in the cobalt k classroom.



Figure: 0278

Ceiling in the cobalt k classroom.



Figure: 0279

Ceiling in the cobalt k classroom.



Figure: 0280

General view of the entrance to ruby k classroom.



Figure: 0281

East wall in the entrance to ruby k classroom.



Figure: 0282

East wall in the entrance to ruby k classroom. Showing nailing marks and hole.



Figure: 0283

North wall in the entrance to ruby k classroom. Showing nailing marks.



Figure: 0284

North wall in the entrance to ruby k classroom.



Figure: 0285

North wall in the entrance to ruby k classroom.



Figure: 0286

North wall in the entrance to ruby k classroom.



Figure: 0287

West wall in the entrance to ruby k classroom.



Figure: 0288

West wall in the entrance to ruby k classroom.



Figure: 0289

South wall in the entrance to ruby k classroom.



Figure: 0290

South wall in the entrance to ruby k classroom.



Figure: 0291

Flooring in the entrance to ruby k classroom. Showing staining.



Figure: 0292

Flooring in the entrance to ruby k classroom.



Figure: 0293

Ceiling in the entrance to ruby k classroom.



Figure: 0294

Ceiling in the entrance to ruby k classroom.



Figure: 0295

Fine cracking in the window sill in the southwest corner in the entrance to ruby k classroom.



Figure: 0296

Crazing in the south wall in the entrance to ruby k classroom, west side.



Figure: 0297

Patched cracking in the northwest corner in the ceiling in the entrance to ruby k classroom.



Figure: 0298

Fine cracking in the middle window sill in the north wall in the entrance to ruby k classroom.



Figure: 0299

East wall in the west entrance.




Figure: 0300

South wall in the west entrance.



Figure: 0301

South wall in the west entrance.



Figure: 0302

West wall in the west entrance.



Figure: 0303

West wall in the west entrance.



Figure: 0304

Damage in the door
in the west wall in the
west entrance.



Figure: 0305

Chipping in the door
in the west wall in the
west entrance.



Figure: 0306

Chipping in the door
in the west wall in the
west entrance.



Figure: 0307

East wall in the stairway.



Figure: 0308

East wall in the stairway.



Figure: 0309

North wall in the west entrance, outside the toilet.



Figure: 0310

North wall in the stairway, outside the toilet.



Figure: 0311

Ceiling in the stairway.



Figure: 0312

Ceiling in the stairway.



Figure: 0313

General view of the entrance to the toilet.




Figure: 0314

General view in the toilet.



Figure: 0315

General view in the toilet.



Figure: 0316

General view in the toilet.



Figure: 0317

General view in the toilet.



Figure: 0318

General view in the toilet.



Figure: 0319

General view in the toilet.




Figure: 0320

General view in the toilet.



Figure: 0321

General view in the toilet.



Figure: 0322

General view in the toilet.



Figure: 0323

Tile floor in the toilet.



Figure: 0324

Tile floor in the toilet.




Figure: 0325

Chipping in the steps
in the toilet.



Figure: 0326

East wall in the
storeroom.



Figure: 0327

North wall in the
storeroom.

Figure: 0328

North wall in the storeroom.



Figure: 0329

North wall in the storeroom. Showing patching.



Figure: 0330

North wall in the storeroom. Showing patching.





Figure: 0331

West wall in the storeroom. Showing patching.



Figure: 0332

South wall in the storeroom.



Figure: 0333

South wall in the storeroom.



Figure: 0334

South wall in the storeroom.



Figure: 0335

Fine cracking above the door in the south wall in the storeroom.



Figure: 0336

Fine cracking above the door in the south wall in the storeroom.



Figure: 0337

Flooring in the storeroom.



Figure: 0338

Flooring in the storeroom.



Figure: 0339

Ceiling in the storeroom.



Figure: 0340

Ceiling in the storeroom.



Figure: 0341

Patching in the ceiling in the storeroom, east side.



Figure: 0342

Fine cracking in the east wall in the storeroom, north side.



Figure: 0343

Separation in the northeast corner in the storeroom.



Figure: 0344

Separation in the northeast corner in the storeroom.



Figure: 0345

Scratching in the door in the storeroom.



Figure: 0346

Scratching in the door in the storeroom.



Figure: 0347

General view of the entrance to the cleaners room.



Figure: 0348

West wall in the cleaners room. Showing peeling paint.



Figure: 0349

West wall in the cleaners room. Showing peeling paint.



Figure: 0350

North wall in the cleaners room.



Figure: 0351

North wall in the cleaners room. Showing cracking.



Figure: 0352

North wall in the
cleaners room.



Figure: 0353

North wall in the
cleaners room.



Figure: 0354

East wall in the
cleaners room.



Figure: 0355

East wall in the
cleaners room.



Figure: 0356

South wall in the
cleaners room.



Figure: 0357

South wall in the
cleaners room.



Figure: 0358

South wall in the cleaners room. Showing fine cracking.



Figure: 0359

South wall in the cleaners room. Showing peeling paint.



Figure: 0360

Ceiling in the cleaners room.



Figure: 0361

Ceiling in the cleaners room.



Figure: 0362

General view in the sub floor area in the cleaners room.



Figure: 0363

General view in the sub floor area in the cleaners room.




Figure: 0364

General view in the stairway.



Figure: 0365

General view in the stairway.




Figure: 0366

East wall in the landing area in the stairway.




Figure: 0367

East wall in the landing area in the stairway.




Figure: 0368

East wall in the landing area in the stairway.



Figure: 0369

Chipping in the east wall in the landing area in the stairway.



Figure: 0370

North wall in the stairway.




Figure: 0371

North wall in the stairway. Showing peeling paint.



Figure: 0372

North wall in the stairway.




Figure: 0373

Fine cracking in the east wall in the stairway.



Figure: 0374

South wall in the stairway.




Figure: 0375

South wall in the stairway.



Figure: 0376

South wall in the stairway.



Figure: 0377

General view in the stairway.



Figure: 0378

General view in the stairway.



Figure: 0379

General view in the stairway.



Figure: 0380

Ceiling in the stairway.



Figure: 0381

Ceiling in the stairway.




Figure: 0382

East wall in the stairway.




Figure: 0383

LEVEL 1

General view in the stairway.




Figure: 0384

South wall in the stairway.




Figure: 0385

South wall in the stairway.



Figure: 0386

South wall in the stairway.



Figure: 0387

South wall in the ground floor corridor, outside the kitchen.



Figure: 0388

South wall in the ground floor corridor, outside the kitchen.




Figure: 0389

North wall in the ground floor corridor, outside the kitchen.




Figure: 0390

North wall in the ground floor corridor, outside the kitchen.



Figure: 0391

North wall in the ground floor corridor, outside the kitchen.




Figure: 0392

North wall in the ground floor corridor, outside the kitchen.



Figure: 0393

Cracking in the ceiling in the ground floor corridor, outside the kitchen.



Figure: 0394

Ceiling in the ground floor corridor, outside the kitchen.



Figure: 0395

Ceiling in the ground floor corridor, outside the kitchen. Showing staining.



Figure: 0396

Timber floor in the ground floor corridor, outside the kitchen.



Figure: 0397

Timber floor in the ground floor corridor, outside the kitchen.




Figure: 0398

West wall in the ground floor corridor, outside the kitchen.



Figure: 0399

West wall in the ground floor corridor, outside the kitchen.



Figure: 0400

General view of the entrance to the kitchen.




Figure: 0401

East wall in the kitchen.



Figure: 0402

East wall in the kitchen. Showing peeling paint.



Figure: 0403

North wall in the kitchen.



Figure: 0404

North wall in the kitchen.




Figure: 0405

West wall in the kitchen.



Figure: 0406

West wall in the kitchen.



Figure: 0407

Peeling paint in the west wall in the kitchen.



Figure: 0408

Nail holes in the west wall in the kitchen.



Figure: 0409

South wall in the kitchen. Showing peeling paint.



Figure: 0410

South wall in the kitchen. Showing peeling paint.



Figure: 0411

Ceiling in the kitchen.



Figure: 0412

Ceiling in the kitchen.



Figure: 0413

Timber floor in the kitchen.



Figure: 0414

Timber floor in the kitchen.



Figure: 0415

Timber floor in the kitchen. Showing scratching in the skirting.



Figure: 0416

General view of the entrance to the south toilet.



Figure: 0417

General view in the south toilet.



Figure: 0418

General view in the south toilet.



Figure: 0419

General view in the south toilet.



Figure: 0420

Peeling paint and cracking in the west wall in the south toilet.



Figure: 0421

Peeling paint and cracking in the west wall in the south toilet.



Figure: 0422

Peeling paint and crazing in the west wall in the south toilet.



Figure: 0423

Peeling paint and crazing in the west wall in the south toilet.



Figure: 0424

West wall in the south toilet.



Figure: 0425

General view in the south toilet.




Figure: 0426

General view in the south toilet.



Figure: 0427

Peeling paint in the east wall in the south toilet.



Figure: 0428

Tile floor in the south toilet.




Figure: 0429

Tile floor in the south toilet.



Figure: 0430

General view in the level 1 corridor.



Figure: 0431

General view in the level 1 corridor.




Figure: 0432

East wall in the level 1 corridor, outside the citrine classroom.



Figure: 0433

East wall in the level 1 corridor, outside the citrine classroom.



Figure: 0434

East wall in the level 1 corridor, outside the citrine classroom.



Figure: 0435

East wall in the level 1 corridor, outside the citrine classroom.



Figure: 0436

Fine cracking in the east wall in the level 1 corridor, outside the citrine classroom.



Figure: 0437

West wall in the level 1 corridor, outside the citrine classroom.



Figure: 0438

West wall in the level 1 corridor, outside the citrine classroom.



Figure: 0439

West wall in the level 1 corridor, outside the citrine classroom.



Figure: 0440

West wall in the level 1 corridor, outside the citrine classroom.



Figure: 0441

Timber floor in the level 1 corridor, outside the citrine classroom.



Figure: 0442

Ceiling in the level 1 corridor, outside the citrine classroom.



Figure: 0443

General view of the entrance to the citrine classroom.



Figure: 0444

East wall in the citrine classroom.



Figure: 0445

East wall in the citrine classroom.



Figure: 0446

East wall in the citrine classroom.



Figure: 0447

East wall in the citrine classroom.




Figure: 0448

Fine cracking in the east wall in the citrine classroom.



Figure: 0449

Peeling paint in the east wall in the citrine classroom.




Figure: 0450

North wall in the citrine classroom.



Figure: 0451

North wall in the citrine classroom.



Figure: 0452

West wall in the citrine classroom.



Figure: 0453

West wall in the citrine classroom.



Figure: 0454

West wall in the citrine classroom.



Figure: 0455

South wall in the citrine classroom. Showing nail markings.



Figure: 0456

South wall in the citrine classroom. Showing nail markings.



Figure: 0457

South wall in the citrine classroom. Showing nail markings.



Figure: 0458

Flooring in the citrine classroom.



Figure: 0459

Flooring in the citrine classroom.



Figure: 0460

Ceiling in the citrine classroom.



Figure: 0461

Ceiling in the citrine classroom.



Figure: 0462

General view in the level 1 corridor, outside the cleaners room.



Figure: 0463

General view in the level 1 corridor, outside the cleaners room.



Figure: 0464

General view in the level 1 corridor, outside the cleaners room.



Figure: 0465

General view in the level 1 corridor, outside the cleaners room.

Figure: 0466

West wall in the level 1 corridor, outside the cleaners room.



Figure: 0467

West wall in the level 1 corridor, outside the cleaners room.



Figure: 0468

East wall in the level 1 corridor, outside the cleaners room.





Figure: 0469

East wall in the level 1 corridor, outside the cleaners room.



Figure: 0470

East wall in the level 1 corridor, outside the cleaners room.



Figure: 0471

East wall in the level 1 corridor, outside the cleaners room.



Figure: 0472

General view of the entrance to the cleaners room.



Figure: 0473

General view in the cleaners room.



Figure: 0474

General view in the cleaners room. Showing patching and missing skirting.



Figure: 0475

General view in the cleaners room.



Figure: 0476

General view in the cleaners room.



Figure: 0477

Timber floor in the cleaners room.




Figure: 0478

Ceiling in the cleaners room.



Figure: 0479

General view of the entrance to the maths resources room.




Figure: 0480

East wall in the maths resources room.



Figure: 0481

East wall in the maths resources room.



Figure: 0482

South wall in the maths resources room. Showing peeling paint.



Figure: 0483

South wall in the maths resources room.



Figure: 0484

North wall in the maths resources room.



Figure: 0485

North wall in the maths resources room.



Figure: 0486

West wall in the maths resources room.



Figure: 0487

West wall in the maths resources room.



Figure: 0488

Cracking in the window sill in the west wall in the maths resources room.



Figure: 0489

Cracking in the window sill in the west wall in the maths resources room.



Figure: 0490

Missing access hole in the ceiling in the maths resources room.



Figure: 0491

Ceiling in the maths resources room.



Figure: 0492

Flooring in the maths resources room.



Figure: 0493

General view of the entrance to room 2.




Figure: 0494

East wall in room 2.



Figure: 0495

East wall in room 2.




Figure: 0496

East wall in room 2.



Figure: 0497

East wall in room 2.




Figure: 0498

North wall in room 2.



Figure: 0499

North wall in room 2.



Figure: 0500

West wall in room 2.



Figure: 0501

West wall in room 2.



Figure: 0502

South wall in room 2.



Figure: 0503

South wall in room 2.



Figure: 0504

Ceiling in room 2.
Showing peeling paint.



Figure: 0505

Ceiling in room 2.
Showing peeling paint.



Figure: 0506

Ceiling in room 2.



Figure: 0507

Ceiling in room 2.



Figure: 0508

Ceiling in room 2.



Figure: 0509

Flooring in room 2.



Figure: 0510

General view in the level 1 corridor, looking from the stairway.



Figure: 0511

General view in the level 1 corridor, looking from the stairway.



Figure: 0512

West wall in the level 1 corridor, looking from the stairway.



Figure: 0513

West wall in the level 1 corridor, looking from the stairway.



Figure: 0514

West wall in the level 1 corridor, looking from the stairway.



Figure: 0515

West wall in the level 1 corridor, looking from the stairway.



Figure: 0516

East wall in the level 1 corridor, looking from the stairway.



Figure: 0517

East wall in the level 1 corridor, looking from the stairway.



Figure: 0518

East wall in the level 1 corridor, looking from the stairway.



Figure: 0519

East wall in the level 1 corridor, looking from the stairway.



Figure: 0520

West wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0521

West wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0522

West wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0523

West wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0524

West wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0525

West wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0526

West wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0527

Water damage in the level 1 corridor, looking from the emerald classroom.




Figure: 0528

East wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0529

East wall in the level 1 corridor, looking from the emerald classroom.




Figure: 0530

East wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0531

East wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0532

North wall in the level 1 corridor, looking from the emerald classroom.



Figure: 0533

North wall in the level 1 corridor.



Figure: 0534

East wall in the level 1 corridor, north side.



Figure: 0535

East wall in the level 1 corridor, north side.



Figure: 0536

East wall in the level 1 corridor, north side. Showing cracking.



Figure: 0537

East wall in the level 1 corridor, north side.



Figure: 0538

West wall in the level 1 corridor, north side.



Figure: 0539

West wall in the level 1 corridor, north side.



Figure: 0540

West wall in the level 1 corridor, north side.



Figure: 0541

Ceiling in the level 1 corridor.



Figure: 0542

General view of the entrance to the emerald classroom.



Figure: 0543

East wall in the emerald classroom. Showing nail markings.



Figure: 0544

East wall in the emerald classroom.




Figure: 0545

East wall in the emerald classroom.



Figure: 0546

East wall in the emerald classroom.



Figure: 0547

North wall in the emerald classroom.



Figure: 0548

North wall in the emerald classroom.



Figure: 0549

North wall in the emerald classroom.



Figure: 0550

North wall in the emerald classroom.



Figure: 0551

West wall in the emerald classroom.



Figure: 0552

West wall in the emerald classroom.



Figure: 0553

West wall in the emerald classroom.



Figure: 0554

South wall in the emerald classroom.



Figure: 0555

South wall in the emerald classroom.



Figure: 0556

South wall in the emerald classroom.



Figure: 0557

Staining in the ceiling cornice in the northeast corner in the emerald classroom.



Figure: 0558

Flooring in the emerald classroom.



Figure: 0559

Flooring in the emerald classroom.



Figure: 0560

Ceiling in the emerald classroom.




Figure: 0561

Ceiling in the emerald classroom.



Figure: 0562

Ceiling in the emerald classroom.



Figure: 0563

Water damage in the emerald classroom, west side.



Figure: 0564

Fine cracking in the west wall in the emerald classroom. Also showing water damage.



Figure: 0565

General view of the entrance to the lime classroom.




Figure: 0566

East wall in the lime classroom.



Figure: 0567

East wall in the lime classroom.



Figure: 0568

East wall in the lime classroom.



Figure: 0569

East wall in the lime classroom.



Figure: 0570

North wall in the lime classroom.



Figure: 0571

North wall in the lime classroom.



Figure: 0572

West wall in the lime classroom.



Figure: 0573

West wall in the lime classroom.



Figure: 0574

South wall in the lime classroom.



Figure: 0575

Fine cracking in the west wall in the lime classroom.



Figure: 0576

Ceiling in the lime classroom.



Figure: 0577

Ceiling in the lime classroom.



Figure: 0578

Crazing in the ceiling in the lime classroom.



Figure: 0579

Flooring in the lime classroom.



Figure: 0580

Flooring in the lime classroom. Showing staining.



Figure: 0581

Fine cracking in the west wall in the lime classroom, adjacent to the door.



Figure: 0582

Fine cracking in the west wall in the lime classroom, adjacent to the door.




Figure: 0583

General view in the stairway.



Figure: 0584

General view in the stairway.



Figure: 0585

General view in the stairway.



Figure: 0586

Peeling paint and crazing in the west wall in the stairway.



Figure: 0587

Peeling paint and crazing in the west wall in the stairway.




Figure: 0588

Peeling paint and crazing in the west wall in the stairway.



Figure: 0589

West wall in the stairway.




Figure: 0590

North wall in the stairway.




Figure: 0591

North wall in the stairway.




Figure: 0592

South wall in the stairway.




Figure: 0593

South wall in the stairway.




Figure: 0594

General view in the stairway.



Figure: 0595

General view in the stairway.




Figure: 0596

General view in the stairway.




Figure: 0597

East wall in the stairway.



Figure: 0598

East wall in the stairway.



Figure: 0599

South wall in the stairway.



Figure: 0600

South wall in the stairway.



Figure: 0601

GROUND LEVEL

Ceiling in the stairway.




Figure: 0602

Ceiling in the stairway.



Figure: 0603

General view of the entrance to the boys and girls toilet.



Figure: 0604

South wall in room 15.



Figure: 0605

South wall in room 15.



Figure: 0606

Fine cracking in the south wall in room 15.

Figure: 0607

East wall in room 15.



Figure: 0608

East wall in room 15. Showing peeling paint.



Figure: 0609

East wall in room 15. Showing peeling paint.





Figure: 0610

East wall in room 15.




Figure: 0611

East wall in room 15.




Figure: 0612

North wall in room 15.



Figure: 0613

Fine cracking in the north wall in room 15.



Figure: 0614

Fine cracking in the north wall in room 15.



Figure: 0615

Fine cracking in the north wall in room 15.



Figure: 0616

Chipping in the north wall in room 15, adjacent to the door.



Figure: 0617

East wall in room 15.



Figure: 0618

East wall in room 15.



Figure: 0619

East wall in room 15. Showing peeling paint and crazing.



Figure: 0620

Floor slab in room 15.



Figure: 0621

Floor slab in room 15. Showing scoring.



Figure: 0622

Floor slab in room 15.



Figure: 0623

Ceiling in room 15.



Figure: 0624

Ceiling in room 15.

Figure: 0625

South wall in room 14.



Figure: 0626

South wall in room 14.



Figure: 0627

Fine cracking in the south wall in room 14.





Figure: 0628

Fine cracking in the south wall in room 14.



Figure: 0629

Fine cracking in the south wall in room 14.



Figure: 0630

Separation in the window frame in the south wall in room 14.



Figure: 0631

General view in the toilet in room 14.



Figure: 0632

General view in the toilet in room 14.



Figure: 0633

General view in the toilet in room 14.



Figure: 0634

General view in the toilet in room 14.



Figure: 0635

General view in the toilet in room 14.



Figure: 0636

General view in the toilet in room 14.



Figure: 0637

General view in the toilet in room 14.



Figure: 0638

General view in the toilet in room 14.



Figure: 0639

North wall in room 14.



Figure: 0640

North wall in room 14.



Figure: 0641

Fine cracking in the north wall in room 14.



Figure: 0642

Fine cracking in the north wall in room 14.



Figure: 0643

Fine cracking in the north wall in room 14.



Figure: 0644

Crazeing in the north wall in room 14.



Figure: 0645

West wall in room 14.

Figure: 0646

West wall in room 14.



Figure: 0647

West wall in room 14.



Figure: 0648

Ceiling in room 14.
Showing staining.





Figure: 0649

Ceiling in room 14.
Showing staining.



Figure: 0650

Tile floor in room 14.



Figure: 0651

Tile floor in room 14.



Figure: 0652

Tile floor in room 14.



Figure: 0653

Peeling paint and crazing in the north wall in room 14.



Figure: 0654

South wall in room 13.



Figure: 0655

South wall in room 13.



Figure: 0656

General view in the toilet in room 13.



Figure: 0657

General view in the toilet in room 13.



Figure: 0658

Peeling paint in the east wall in the toilet in room 13.



Figure: 0659

General view in the toilet in room 13.



Figure: 0660

General view in the toilet in room 13.



Figure: 0661

General view in the toilet in room 13.



Figure: 0662

General view in the toilet in room 13.



Figure: 0663

General view in the toilet in room 13.



Figure: 0664

General view in the toilet in room 13.



Figure: 0665

General view in the toilet in room 13.



Figure: 0666

General view in the toilet in room 13.



Figure: 0667

General view in the toilet in room 13.



Figure: 0668

General view in the toilet in room 13.



Figure: 0669

General view in the toilet in room 13.



Figure: 0670

General view in the toilet in room 13.



Figure: 0671

North wall in room 13.




Figure: 0672

North wall in room 13.



Figure: 0673

Fine cracking in the north wall in room 13.



Figure: 0674

Tile floor in room 13.



Figure: 0675

Tile floor in room 13.



Figure: 0676

West wall in room
13.



Figure: 0677

West wall in room
13.



Figure: 0678

West wall in room
13.



Figure: 0679

West wall in room 13.



Figure: 0680

Ceiling in room 13.



Figure: 0681

Ceiling in room 13.



Figure: 0682

South wall in room 12.




Figure: 0683

South wall in room 12.



Figure: 0684

East wall in room 12.



Figure: 0685

East wall in room 12.



Figure: 0686

East wall in room 12.




Figure: 0687

East wall in room 12.



Figure: 0688

North wall in room
12.



Figure: 0689

North wall in room
12.




Figure: 0690

West wall in room
12.



Figure: 0691

West wall in room
12.



Figure: 0692

West wall in room
12.



Figure: 0693

West wall in room
12.



Figure: 0694

Floor slab in room 12.



Figure: 0695

Floor slab in room 12.



Figure: 0696

Ceiling in room 12.



Figure: 0697

Ceiling in room 12.



Figure: 0698

EXTERNAL

North wall of building A, outside the girls and boys toilet.



Figure: 0699

North wall of building A, outside room 15.



Figure: 0700

North wall of building A, outside room 15.



Figure: 0701

Slight stepped cracking in the mortar joint in the north wall of building A, outside room 15.



Figure: 0702

Erosion in the mortar joints in the north wall of building A, outside room 15.



Figure: 0703

Erosion in the mortar joints in the north wall of building A, outside room 15.




Figure: 0704

Chipping in the brick in the north wall of building A, outside room 15.



Figure: 0705

North wall of building A, outside room 15.



Figure: 0706

North wall of building A, outside room 15.



Figure: 0707

Mold on the soffit on the north side of building A, outside room 15.



Figure: 0708

Mold on the soffit on the north side of building A, outside room 15.

Figure: 0709

North wall of building A, outside room 14.



Figure: 0710

North wall of building A, outside room 14. Showing chipping and nail markings.



Figure: 0711

General view of the wall on the north side of room 14.





Figure: 0712

General view of the wall on the north side of room 14.



Figure: 0713

Wide cracking in the wall on the north side of room 14.



Figure: 0714

Erosion in the mortar joints in the wall on the north side of room 14.



Figure: 0715

Erosion in the mortar joints in the wall on the north side of room 14.



Figure: 0716

Cracking in the paving on the north side of room 14.



Figure: 0717

Cracking in the paving on the north side of room 14.



Figure: 0718

Cracking in the paving on the north side of room 14.



Figure: 0719

Cracking in the paving on the north side of room 15.



Figure: 0720

Cracking in the paving on the north side of room 15.



Figure: 0721

General view of the wall on the north side of building A, outside the toilets.



Figure: 0722

General view of the wall on the north side of building A, outside the toilets. Showing wide cracking and movement.



Figure: 0723

General view of the wall on the north side of building A, outside the toilets.




Figure: 0724

North wall of building A, outside room 13.



Figure: 0725

North wall of building A, outside room 13.
Showing chipping.



Figure: 0726

North wall of building A, outside room 12.



Figure: 0727

North wall of building A, outside room 12.



Figure: 0728

Erosion in the mortar joints in the north wall of building A, outside room 12.




Figure: 0729

General view of the paving on the north side of building A, looking from room 12.



Figure: 0730

General view of the paving on the north side of building A, looking from room 12.



Figure: 0731

General view of the paving on the north side of building A, looking from room 12.



Figure: 0732

West wall of building A, looking from room 12.



Figure: 0733

West wall of building A, looking from room 12.




Figure: 0734

West wall of building A, looking from room 12. Showing missing brick.



Figure: 0735

Movement and erosion in the west wall of building A.

Figure: 0736

West wall of building
A.



Figure: 0737

West wall of building
A.



Figure: 0738

West wall of building
A.





Figure: 0739

General view of the paving on the north side of building A.



Figure: 0740

General view of the paving on the north side of building A. Showing scoring and cracking.



Figure: 0741

General view of the paving on the north side of building A. Showing cracking.



Figure: 0742

General view of the paving on the north side of building A. Showing cracking.



Figure: 0743

General view of the fence on the north side of building A.




Figure: 0744

General view of the fence on the north side of building A.



Figure: 0745

General view of the fence on the north side of building A.



Figure: 0746

General view of the fence on the north side of building A.



Figure: 0747

North wall of building A.



Figure: 0748

North wall of building A.




Figure: 0749

North wall of building A.



Figure: 0750

Chipping in the north wall of building A, outside the auditorium kitchenette.



Figure: 0751

Chipping in the north wall of building A, outside the drama room.



Figure: 0752

North wall of building A.



Figure: 0753

North wall of building A.



Figure: 0754

North wall of building A. Showing peeling paint and dent in the down pipe.



Figure: 0755

North wall of building A.



Figure: 0756

North wall of building A.

Figure: 0757

North wall of building A.



Figure: 0758

North wall of building A.



Figure: 0759

East wall of building A, outside the auditorium.





Figure: 0760

North wall of building A, outside the auditorium.




Figure: 0761

North wall of building A, outside the auditorium.



Figure: 0762

North wall of building A, outside the auditorium.



Figure: 0763

Paving on the north side of building A.



Figure: 0764

Cracking in the paving on the north side of the auditorium.



Figure: 0765

Paving on the north side of building A.



Figure: 0766

General view in the playground on the north side of building A.



Figure: 0767

General view in the playground on the north side of building A.



Figure: 0768

General view in the playground on the north side of building A.



Figure: 0769

General view in the playground on the north side of building A.



Figure: 0770

Rusting above the window in the north wall of building A.



Figure: 0771

Rusting above the window in the north wall of building A.



Figure: 0772

Rusting above the window in the north wall of building A.



Figure: 0773

North wall of building A.



Figure: 0774

West wall of building A, looking from the playground.



Figure: 0775

West wall of building A, looking from the playground.



Figure: 0776

West wall of building A, looking from the playground.



Figure: 0777

West wall of building A, looking from the playground.



Figure: 0778

West wall of building A, looking from the playground.



Figure: 0779

West wall of building A, looking from the playground.



Figure: 0780

West wall of building A, looking from the playground.



Figure: 0781

Nail marking in the north wall of building A.



Figure: 0782

General view of the soffit at the entrance on the west side of building A. Showing peeling paint.



Figure: 0783

General view of the soffit at the entrance on the west side of building A.

Figure: 0784

South wall of building A, looking from the west entrance.



Figure: 0785

South wall of building A, looking from the west entrance.



Figure: 0786

South wall of building A, looking from the west entrance.





Figure: 0787

Chipping above the window in the south wall of building A, looking from the west entrance.



Figure: 0788

General view of the aircon cage on the west side of building A.



Figure: 0789

General view of the aircon cage on the west side of building A.

Figure: 0790

West wall of building A, looking from the playground.



Figure: 0791

West wall of building A, looking from the playground.



Figure: 0792

West wall of building A, looking from the playground.





Figure: 0793

West wall of building A, looking from the playground.



Figure: 0794

Nail markings in the west wall of building A, looking from the playground.



Figure: 0795

West wall of building A, looking from the playground.



Figure: 0796

West wall of building A, looking from the playground.



Figure: 0797

West wall of building A, looking from the playground.



Figure: 0798

West wall of building A, looking from the playground.



Figure: 0799

West wall of building A, looking from the playground.



Figure: 0800

West wall of building A, looking from the playground.




Figure: 0801

West wall of building A, looking from the playground.



Figure: 0802

General view of the fence on the north side of the property.



Figure: 0803

General view of the fence on the north side of the property.



Figure: 0804

General view of the pathway on the north side of building A.

Figure: 0805

North wall of building A, outside room 23.



Figure: 0806

North wall of building A, outside room 23.



Figure: 0807

North wall of building A, outside room 23.





Figure: 0808

North wall of building A, outside room 23.



Figure: 0809

Rusting and cracking above the window in the north wall of building A.



Figure: 0810

Rusting above the window in the north wall of building A.



Figure: 0811

Rusting above the window in the north wall of building A.



Figure: 0812

Rusting above the window in the north wall of building A.



Figure: 0813

Rusting above the window in the north wall of building A.



Figure: 0814

North wall of building A. Showing erosion in the mortar joints.



Figure: 0815

North wall of building A.



Figure: 0816

North wall of building A.



Figure: 0817

North wall of building A.



Figure: 0818

Cracking in the brick in the north wall of building A, outside room 23.



Figure: 0819

Peeling paint in the north wall of building A, outside the entrance.



Figure: 0820

North wall of building A, looking from the north entrance.



Figure: 0821

North wall of building A, looking from the north entrance.



Figure: 0822

North wall of building A, looking from the north entrance.



Figure: 0823

Chipping in the steps at the north entrance.



Figure: 0824

Chipping in the north wall of building A, outside the entrance.



Figure: 0825

General view of the fence on the north side of the property.



Figure: 0826

General view of the fence on the north side of the property.



Figure: 0827

General view of the fence on the north side of the property.




Figure: 0828

North wall of building A, east side.



Figure: 0829

North wall of building A, east side.



Figure: 0830

North wall of building A, east side.



Figure: 0831

Cracking in the paving on the north side of building A.

Figure: 0832

North wall of building A, east side.



Figure: 0833

North wall of building A, east side.



Figure: 0834

North wall of building A, east side.






Figure: 0835

North wall of building A, east side. Showing erosion in the mortar joints.



Figure: 0836

North wall of building A, east side.



Figure: 0837

North wall of building A, east side.



Figure: 0838

North wall of building A, east side.



Figure: 0839

North wall of building A, east side. Showing corrosion.



Figure: 0840

North wall of building A, east side. Showing corrosion.



Figure: 0841

North wall of building A, east side. Showing corrosion.



Figure: 0842

Chipping in the brick at the northeast corner of building A.



Figure: 0843

Slight, vertical cracking in the east wall of building A, north side



Figure: 0844

Slight, vertical cracking in the east wall of building A, north side.



Figure: 0845

General view of the paving on the north side of building A.



Figure: 0846

General view of the fence on the north side of building A, east side.



Figure: 0847

General view of the fence on the north side of building A, east side.



Figure: 0848

General view of the fence on the north side of building A, east side.



Figure: 0849

General view of the fence on the north side of building A, east side.



Figure: 0850

General view of the playground on the east side of building A.



Figure: 0851

General view of the playground on the east side of building A.



Figure: 0852

General view of the sail shade on the east side of building A.



Figure: 0853

General view of the sail shade on the east side of building A.



Figure: 0854

General view of the sail shade on the east side of building A.



Figure: 0855

General view of the sail shade on the east side of building A.



Figure: 0856

East wall of building A, north side.



Figure: 0857

East wall of building A.



Figure: 0858

East wall of building A, north side.



Figure: 0859

East wall of building A, north side.
Showing slight stepped cracking in the mortar joints.



Figure: 0860

East wall of building A, north side.



Figure: 0861

East wall of building A, north side.
Showing chipping above the window.



Figure: 0862

East wall of building A.



Figure: 0863

East wall of building A.



Figure: 0864

East wall of building A.



Figure: 0865

Cracking above the second window from the north in the brick in the east wall of building A.



Figure: 0866

Cracking above the third window from the north in the brick in the east wall of building A.



Figure: 0867

Cracking above the fourth window from the north in the brick in the east wall of building A.



Figure: 0868

East wall of building A.



Figure: 0869

East wall of building A.



Figure: 0870

East wall of building A.



Figure: 0871

East wall of building A.



Figure: 0872

General view of the garden bed on the east side of building A.



Figure: 0873

General view of the garden bed on the east side of building A.



Figure: 0874

General view of the garden bed on the east side of building A. Showing chipping.



Figure: 0875

East wall of building A.



Figure: 0876

East wall of building A.



Figure: 0877

Cracking and chipping above the third window from the north in the east wall of building A.



Figure: 0878

Cracking and chipping above the fifth window from the north in the east wall of building A.



Figure: 0879

East wall of building A, looking from the sixth window from the north.



Figure: 0880

East wall of building A, looking from the sixth window from the north.



Figure: 0881

East wall of building A, looking from the sixth window from the north.



Figure: 0882

East wall of building A, looking from the sixth window from the north. Showing damage above the window.



Figure: 0883

East wall of building A, looking from the seventh window from the north.



Figure: 0884

East wall of building A, looking from the seventh window from the north.



Figure: 0885

East wall of building A, looking from the eighth window from the north.



Figure: 0886

East wall of building A, looking from the eighth window from the north. Showing chipping above the window.



Figure: 0887

East wall of building A, looking from the eighth window from the north.



Figure: 0888

East wall of building A, looking from the ninth window from the north.

Figure: 0889

East wall of building A, looking from the ninth window from the north. Showing chipping above the window.



Figure: 0890

East wall of building A, looking from the ninth window from the north.



Figure: 0891

East wall of building A.






Figure: 0892

East wall of building A.



Figure: 0893

East wall of building A.



Figure: 0894

General view of the playground on the east side of building A.

Figure: 0895

General view of the playground on the east side of building A.



Figure: 0896

General view of the playground on the east side of building A.



Figure: 0897

North wall of building A.





Figure: 0898

North wall of building A.



Figure: 0899

North wall of building A.



Figure: 0900

North wall of building A.



Figure: 0901

East wall of building
A.



Figure: 0902

East wall of building
A.



Figure: 0903

East wall of building
A.




Figure: 0904

East wall of building A.



Figure: 0905

Chipping in the brick in the east wall of building A.



Figure: 0906

Chipping in the brick in the east wall of building A.



Figure: 0907

General view of the timber decking at the southeast corner of building A.



Figure: 0908

General view of the timber decking at the southeast corner of building A.



Figure: 0909

General view of the timber decking at the southeast corner of building A.



Figure: 0910

Damage in the timber decking at the southeast corner of building A.



Figure: 0911

East wall of building A, outside the main entrance.



Figure: 0912

East wall of building A, outside the main entrance.



Figure: 0913

East wall of building A, outside the main entrance.



Figure: 0914

East wall of building A, south side.




Figure: 0915

East wall of building A, south side.

Figure: 0916

East wall of building A, outside the main entrance.



Figure: 0917

Ceiling on the east side of building A, outside the main entrance.



Figure: 0918

General view of the steps on the east side of building A, outside the main entrance. Showing chipping.





Figure: 0919

General view of the steps on the east side of building A, outside the main entrance. Showing chipping.



Figure: 0920

General view of the steps on the east side of building A, outside the main entrance. Showing chipping.



Figure: 0921

General view of the steps on the east side of building A, outside the main entrance. Showing chipping.



Figure: 0922

South wall of building A, outside the main entrance.



Figure: 0923

South wall of building A, outside the main entrance.




Figure: 0924

South wall of building A, outside the main entrance.



Figure: 0925

South wall of building A, outside the main entrance.



Figure: 0926

South wall of building A, outside the main entrance.



Figure: 0927

South wall of building A, outside the main entrance.



Figure: 0928

West wall of building A, outside the main entrance.



Figure: 0929

West wall of building A, outside the main entrance.



Figure: 0930

West wall of building A, outside the main entrance.



Figure: 0931

West wall of building A, outside the main entrance.



Figure: 0932

Chipping in the paving at the main entrance.



Figure: 0933

Slight cracking in the paving at the entrance.



Figure: 0934

Tile paving at the main entrance.



Figure: 0935

Tile paving at the main entrance.



Figure: 0936

Tile paving at the main entrance.
Showing cracking.



Figure: 0937

South wall at the main entrance.



Figure: 0938

South wall at the main entrance.



Figure: 0939

South wall at the main entrance.



Figure: 0940

Ceiling at the main entrance.



Figure: 0941

Ceiling at the main entrance.



Figure: 0942

Damage in the steps at the main entrance.



Figure: 0943

Cracking in the south wall at the entrance.



Figure: 0944

Cracking in the south wall at the entrance.



Figure: 0945

Cracking in the south wall at the entrance.



Figure: 0946

Paving at the southeast corner of building A.



Figure: 0947

Paving at the southeast corner of building A.



Figure: 0948

Cracking in the paving at the southeast corner of building A.



Figure: 0949

Paving at the southeast corner of building A. Showing cracking and movement.



Figure: 0950

General view of the fig tree at the south east corner of building A.



Figure: 0951

General view of the fig tree at the south east corner of building A.



Figure: 0952

General view of the fig tree at the south east corner of building A.



Figure: 0953

General view of the fig tree at the south east corner of building A.



Figure: 0954

General view of the fig tree at the south east corner of building A.



Figure: 0955

General view of the fig tree at the south east corner of building A.



Figure: 0956

General view of the fig tree at the south east corner of building A.



Figure: 0957

General view of the fig tree at the south east corner of building A.



Figure: 0958

General view of the fig tree at the south east corner of building A.



Figure: 0959

General view of the fig tree at the south east corner of building A.



Figure: 0960

General view of the fig tree at the south east corner of building A.



Figure: 0961

General view of the fig tree at the south east corner of building A.




Figure: 0962

General view of the fig tree at the south east corner of building A.



Figure: 0963

General view of the fig tree at the south east corner of building A.



Figure: 0964

General view of the fig tree at the south east corner of building A.



Figure: 0965

General view of the fig tree at the south east corner of building A.



Figure: 0966

General view of the fig tree at the south east corner of building A.




Figure: 0967

General view of the fig tree at the south east corner of building A.



Figure: 0968

General view of the fig tree at the south east corner of building A.



Figure: 0969

General view of the fig tree at the south east corner of building A.



Figure: 0970

General view of the fig tree at the south east corner of building A.



Figure: 0971

General view of the fig tree at the south east corner of building A.




Figure: 0972

General view of the fig tree at the south east corner of building A.



Figure: 0973

General view of the fig tree at the south east corner of building A.



Figure: 0974

General view of the fig tree at the south east corner of building A.



Figure: 0975

General view of the fig tree at the south east corner of building A.



Figure: 0976

General view of the fig tree at the south east corner of building A.



Figure: 0977

General view of the fence on the north side of the playground.



Figure: 0978

General view of the fence on the north side of the playground.



Figure: 0979

General view of the timber deck on the east side of the property.



Figure: 0980

General view of the timber deck on the east side of the property. Showing damage.



Figure: 0981

General view of the timber deck on the east side of the property.



Figure: 0982

General view of the timber deck on the east side of the property.



Figure: 0983

General view of the steps on the timber deck on the east side of the property.



Figure: 0984

General view of the steps on the timber deck on the east side of the property.



Figure: 0985

General view of the timber deck on the east side of the property. Showing damage.



Figure: 0986

General view of the timber deck on the east side of the property. Showing damage.



Figure: 0987

General view of the timber deck on the east side of the property.



Figure: 0988

General view of the timber deck on the east side of the property.



Figure: 0989

General view of the school sign on the east side of the property.



Figure: 0990

General view of the school sign on the east side of the property.



Figure: 0991

General view of the north boundary fence.



Figure: 0992

South wall of the ventilation shed.



Figure: 0993

South wall of the ventilation shed.



Figure: 0994

Rusting in the south wall of the ventilation shed.



Figure: 0995

Fence on the east side of the property.




Figure: 0996

Fence on the east side of the property.



Figure: 0997

Fence on the east side of the property.



Figure: 0998

Missing top in the fence on the east side of the property.



Figure: 0999

Fence on the east side of the property.



Figure: 1000

Fence on the east side of the property.



Figure: 1001

Fence on the east side of the property.



Figure: 1002

General view of the gate on the east side of the property. Showing rusting.



Figure: 1003

General view of the gate on the east side of the property.



Figure: 1004

General view of the gate on the east side of the property.



Figure: 1005

General view of the gate on the east side of the property.



Figure: 1006

General view of the gate on the east side of the property.




Figure: 1007

Fence on the east side of the property.



Figure: 1008

Fence on the east side of the property.



Figure: 1009

Fence on the east side of the property.




Figure: 1010

Fence on the east side of the property.




Figure: 1011

Fence on the east side of the property.



Figure: 1012

General view of the timber decking on the east side of building A.




Figure: 1013

General view of the timber decking on the east side of building A.




Figure: 1014

Fence on the east side of building A.



Figure: 1015

Fence on the east side of building A.




Figure: 1016

Fence on the east side of building A.




Figure: 1017

Fence on the east side of building A.



Figure: 1018

Fence on the east side of building A.



Figure: 1019

Timber decking on the east side of building A.



Figure: 1020

Timber decking on the east side of building A.

Figure: 1021

Fence on the south side of building A, east side.



Figure: 1022

Fence on the south side of building A, east side.



Figure: 1023

Chipping in the base of the fence on the south side of building A, east side.





Figure: 1024

Chipping in the fence on the south side of building A, east side.



Figure: 1025

Chipping in the fence on the south side of building A, east side.



Figure: 1026

Cracking in the fence on the south side of building A, east side.



Figure: 1027

Fence on the south side of building A.



Figure: 1028

Fence on the south side of building A.



Figure: 1029

Fence on the south side of building A.



Figure: 1030

Cracking in the base of the fence on the south side of building A.



Figure: 1031

Fence on the south side of building A.



Figure: 1032

Fence on the south side of building A.



Figure: 1033

Fence on the south side of building A.



Figure: 1034

Fence on the south side of building A.



Figure: 1035

General view of the gate on the south side of building A.



Figure: 1036

Fence on the south side of building A.



Figure: 1037

Fence on the south side of building A.



Figure: 1038

Fence on the south side of building A.



Figure: 1039

Fence on the south side of building A.



Figure: 1040

Fence on the south side of building A.



Figure: 1041

Fence on the south side of building A.



Figure: 1042

Cracking in the base of the fence on the south side of building A.



Figure: 1043

Cracking in the base of the fence on the south side of building A.



Figure: 1044

Cracking in the base of the fence on the south side of building A.




Figure: 1045

General view of the pathway on the south side of building A.



Figure: 1046

Subsidence in the paving on the south side of building A.



Figure: 1047

South wall of building A, outside the entrance.



Figure: 1048

South wall of building A, outside the entrance.



Figure: 1049

Fence on the south side of building A.



Figure: 1050

Soffit on the south side of building A.



Figure: 1051

Soffit on the south side of building A.



Figure: 1052

South wall of the building.




Figure: 1053

South wall of the building.



Figure: 1054

General view of the pathway on the south side of building A.



Figure: 1055

Fence on the south side of building A.



Figure: 1056

Fence on the south side of building A.




Figure: 1057

Fence on the south side of building A.



Figure: 1058

Fence on the south side of building A. Showing cracking in the base.




Figure: 1059

General view of the power pole on the south side of building A.



Figure: 1060

General view of the power pole on the south side of building A.



Figure: 1061

General view of the power pole on the south side of building A.



Figure: 1062

General view of the main switchboard on the south side of building A.



Figure: 1063

General view of the main switchboard on the south side of building A.



Figure: 1064

South wall of building A.



Figure: 1065

South wall of building A.



Figure: 1066

South wall of building A.



Figure: 1067

Damage above the window in the south wall of building A.



Figure: 1068

South wall of building A. Showing cracking above the window.



Figure: 1069

Pathway on the south side of building A.



Figure: 1070

Fence on the south side of building A.



Figure: 1071

Fence on the south side of building A.



Figure: 1072

Fence on the south side of building A.



Figure: 1073

Fence on the south side of building A.




Figure: 1074

Fence on the south side of building A.



Figure: 1075

Cracking in the paving on the south side of building A.



Figure: 1076

Chipping in the pit lid on the south side of building A.



Figure: 1077

South wall of building A.

Figure: 1078

South wall of building
A.



Figure: 1079

South wall of building
A.



Figure: 1080

South wall of building
A.





Figure: 1081

South wall of building A.



Figure: 1082

Paving on the south side of building A.



Figure: 1083

Cracking in the paving on the south side of building A.



Figure: 1084

Fence on the south side of building A.



Figure: 1085

Fence on the south side of building A.



Figure: 1086

Fence on the south side of building A.



Figure: 1087

Fence on the south side of building A.



Figure: 1088

Fence on the south side of building A.



Figure: 1089

Fence on the south side of building A.



Figure: 1090

Fence on the south side of building A.



Figure: 1091

Fence on the south side of building A.



Figure: 1092

South wall of building A.



Figure: 1093

South wall of building A.



Figure: 1094

South wall of building A.



Figure: 1095

South wall of building A.



Figure: 1096

South wall of building A.



Figure: 1097

South wall of building A.



Figure: 1098

South wall of building A.



Figure: 1099

South wall of building A.



Figure: 1100

Paving on the south side of building A.



Figure: 1101

Chipping and cracking in the south side of building A.




Figure: 1102

Fence on the south side of building A.



Figure: 1103

Fence on the south side of building A.



Figure: 1104

Fence on the south side of building A.



Figure: 1105

Fence on the south side of building A.



Figure: 1106

Fence on the south side of building A.



Figure: 1107

Fence on the south side of building A.



Figure: 1108

Paving on the south side of building A.



Figure: 1109

Cracking in the paving on the south side of building A.




Figure: 1110

South wall of building A.



Figure: 1111

South wall of building A.



Figure: 1112

South wall of building A.



Figure: 1113

Slight cracking in the south wall of building A.



Figure: 1114

Bowing in the lintel in the south wall of building A, outside room 12.



Figure: 1115

South wall of building A, looking from outside room 12.



Figure: 1116

South wall of building A, looking from outside room 12.



Figure: 1117

Cracking in the doorstep on the south side of building A, outside room 12.



Figure: 1118

Cracking in the paving around the drain on the south side of building A, outside room 12.



Figure: 1119

Fence on the south side of building A, looking from room 12.



Figure: 1120

Fence on the south side of building A, looking from room 12.



Figure: 1121

Fence on the south side of building A, looking from room 12.



Figure: 1122

Fence on the south side of building A, looking from room 12. Showing cracking.



Figure: 1123

Cracking in the base of the fence on the south side of building A, outside room 12.



Figure: 1124

Chipping in the base of the fence on the south side of building A, outside room 12.



Figure: 1125

Cracking in the paving on the south side of building A, outside room 13.



Figure: 1126

South wall of building A, looking from outside room 14.



Figure: 1127

South wall of building A, looking from outside room 14.



Figure: 1128

South wall of building A, looking from outside room 14.



Figure: 1129

South wall of building A, looking from outside room 14.



Figure: 1130

General view of the gate on the south side of building A, outside room 12.




Figure: 1131

Fence on the south side of building A.



Figure: 1132

Fence on the south side of building A.



Figure: 1133

Fence on the south side of building A.



Figure: 1134

Alignment of the fence on the south side of building A, looking from the west.



Figure: 1135

General view of the paving on the south side of building A.



Figure: 1136

Cracking in the paving on the south side of building A, outside room 12.



Figure: 1137

South wall of building A, outside room 12.



Figure: 1138

South wall of building A, outside room 12.



Figure: 1139

Bowing and rusting in the lintel on the south side of building A, outside room 12.



Figure: 1140

Wide separation in the paving on the south side of building A, outside room 12.



Figure: 1141

Wide separation in the paving on the south side of building A, outside room 12.



Figure: 1142

West wall of building A.



Figure: 1143

West wall of building A.



Figure: 1144

West wall of building A.



Figure: 1145

West wall of building A.



Figure: 1146

Wide cracking and movement in the paving at the southwest corner of building A.



Figure: 1147

Wide cracking and movement in the paving at the southwest corner of building A.



Figure: 1148

Wide cracking and movement in the paving at the southwest corner of building A.



Figure: 1149

Scoring in the paving on the west side of building A.

Figure: 1150

Cracking in the paving on the west side of building A.



Figure: 1151

Paving on the west side of building A.



Figure: 1152

Paving on the west side of building A. Showing wide cracking.





Figure: 1153

Cracking in the carpark at the southwest corner of building A.



Figure: 1154

Carpark at the southwest corner of building A.



Figure: 1155

Patching and cracking in the carpark at the southwest corner of building A.

Figure: 1156

Patching in the carpark at the southwest corner of building A.



Figure: 1157

Patching in the carpark at the southwest corner of building A.



Figure: 1158

Carpark at the southwest corner of building A. Showing patching.





Figure: 1159

Carpark at the southwest corner of building A. Showing patching and scoring.



Figure: 1160

Carpark at the southwest corner of building A.



Figure: 1161

Carpark at the southwest corner of building A. Showing patching.



Figure: 1162

Patching in the carpark at the southwest corner of building A.



Figure: 1163

South wall of building A.



Figure: 1164

Fence on the south side of the building.



Figure: 1165

Fence on the south side of the building.



Figure: 1166

Fence on the south side of the building.



Figure: 1167

South wall of building A.

Figure: 1168

South wall of building
A.



Figure: 1169

South wall of building
A.



Figure: 1170

South wall of building
A.



Figure: 1171

South wall of building A.



Figure: 1172

Separation in the base of the fence on the south side of building A.



Figure: 1173

General view of the driveway on the south side of building A. Showing cracking.





Figure: 1174

General view of the driveway on the south side of building A. Showing cracking and patching.



Figure: 1175

Fence on the south side of building A.



Figure: 1176

Fence on the south side of building A.



Figure: 1177

Fence on the south side of building A.



Figure: 1178

Cracking in the base of the fence on the south side of building A.




Figure: 1179

South wall of building A.

Figure: 1180

South wall of building
A.



Figure: 1181

South wall of building
A.



Figure: 1182

South wall of building
A.





Figure: 1183

Cracking in the driveway on the south side of building A.



Figure: 1184

General view of the driveway on the south side of building A. Showing cracking.



Figure: 1185

General view of the storm drain in the driveway on the south side of building A. Showing cracking.



Figure: 1186

General view of the storm drain in the driveway on the south side of building A.



Figure: 1187

General view of the pit lid in the driveway on the south side of building A. Showing cracking in the paving.



Figure: 1188

Fence on the south side of building A.



Figure: 1189

Fence on the south side of building A.



Figure: 1190

Fence on the south side of building A.



Figure: 1191

South wall of building A.



Figure: 1192

South wall of building A.



Figure: 1193

South wall of building A.



Figure: 1194

South wall of building A.



Figure: 1195

Fence on the south side of building A.



Figure: 1196

Cracking in the base of the fence on the south side of building A.



Figure: 1197

Cracking in the base of the fence on the south side of building A.

Figure: 1198

South wall of building
A.



Figure: 1199

South wall of building
A.



Figure: 1200

South wall of building
A.



Figure: 1201

Stepped cracking in the south wall of building A.



Figure: 1202

Stepped cracking in the south wall of building A.



Figure: 1203

Stepped cracking in the south wall of building A.





Figure: 1204

South wall of building A, east side.



Figure: 1205

South wall of building A, east side.



Figure: 1206

South wall of building A, east side.



Figure: 1207

South wall of building A, east side.



Figure: 1208

Fence on the south side of building A.




Figure: 1209

Fence on the south side of building A.



Figure: 1210

Fence on the south side of building A.



Figure: 1211

General view of the driveway on the south side of building A.



Figure: 1212

General view of the driveway on the south side of building A.



Figure: 1213

General view of the driveway on the south side of building A. Showing chipping in the kerb.



Figure: 1214

Fence at the southeast corner of building A.



Figure: 1215

Fence at the southeast corner of building A.



Figure: 1216

Fence at the southeast corner of building A.



Figure: 1217

General view of the gate at the southeast corner of building A.



Figure: 1218

General view of the gate at the southeast corner of building A.

Figure: 1219

General view of the gate at the southeast corner of building A.



Figure: 1220

Cracking in the driveway on the south side of building A.





Figure: 1221

BUILDING B

General view of building B.



Figure: 1222

General view of building F on the west side of building B.



Figure: 1223

General view of building F on the west side of building B.



Figure: 1224

General view of building F on the west side of building B.



Figure: 1225

Slight stepped cracking in the north wall of building F.



Figure: 1226

Erosion in the mortar joints in the north wall of building F.

Figure: 1227

Cracking in the paving on the west side of building B.



Figure: 1228

Cracking in the paving on the west side of building B.



Figure: 1229

Cracking in the paving on the west side of building B.





Figure: 1230

Cracking in the paving on the west side of building B.



Figure: 1231

Northwest corner of building B.



Figure: 1232

Northwest corner of building B.



Figure: 1233

Northwest corner of building B.



Figure: 1234

Northwest corner of building B.



Figure: 1235

Damage in the soffit at the northwest corner of building B.



Figure: 1236

Damage in the soffit on the north side of building B.



Figure: 1237

Damage in the soffit on the north side of building B.



Figure: 1238

Damage in the soffit on the north side of building B.

Figure: 1239

North wall of building B, west side. Showing cracking.



Figure: 1240

North wall of building B, west side.



Figure: 1241

North wall of building B, west side.



Figure: 1242

North wall of building B, west side.



Figure: 1243

North wall of building B, west side. Showing erosion in the mortar joints.



Figure: 1244

North wall of building B. Showing damage in the soffit.





Figure: 1245

North wall of building B. Showing corrosion in the balcony.



Figure: 1246

North wall of building B. Showing erosion in the mortar joints.



Figure: 1247

North wall of building B. Showing erosion in the mortar joints.



Figure: 1248

North wall of building B. Showing erosion in the mortar joints.



Figure: 1249

North wall of building B. Showing erosion in the mortar joints.



Figure: 1250

Cracking on the underside of the balcony, on the north side of building B.



Figure: 1251

Cracking on the underside of the balcony, on the north side of building B.



Figure: 1252

Cracking on the underside of the balcony, on the north side of building B.



Figure: 1253

Cracking on the underside of the balcony, on the north side of building B.



Figure: 1254

General view of the pit lid in the paving at the northwest corner of building B. Showing cracking.



Figure: 1255

General view of the pit lid in the grass area at the northwest corner of building B. Showing cracking.



Figure: 1256

Cracking in the kerb at the northwest corner of building B.



Figure: 1257

Cracking and chipping in the kerb at the northwest corner of building B.



Figure: 1258

Chipping in the kerb at the northwest corner of building B.



Figure: 1259

General view of the grass area on the north side of building B.



Figure: 1260

Chipping in the kerb on the north side of building B.



Figure: 1261

General view of the grass area on the north side of building B.



Figure: 1262

North wall of building B.



Figure: 1263

North wall of building B.



Figure: 1264

North wall of building B.



Figure: 1265

North wall of building B.

Figure: 1266

North wall of building B. Showing damage in the soffit.



Figure: 1267

North wall of building B. Showing cracking in the underside of the balcony.



Figure: 1268

North wall of building B, outside the main entrance. Showing peeling paint.





Figure: 1269

North wall of building B, outside the main entrance. Showing peeling paint.



Figure: 1270

North wall of building B, outside the main entrance. Showing peeling paint.




Figure: 1271

North wall of building B, outside the main entrance. Showing peeling paint.



Figure: 1272

Wide cracking in the steps on the north side of building B, outside the entrance.



Figure: 1273

Crazing and cracking in the steps on the north side of building B, outside the entrance.



Figure: 1274

Crazing and cracking in the steps on the north side of building B, outside the entrance.



Figure: 1275

Crazing in the north wall of building B, outside the entrance.



Figure: 1276

Crazing in the north wall of building B, outside the entrance.



Figure: 1277

Crazing in the north wall of building B, outside the entrance.



Figure: 1278

Chipping in the awning on the south side of building B, outside the entrance.



Figure: 1279

General view of the garden bed on the north side of building B.



Figure: 1280

General view of the grass area on the north side of building B.

Figure: 1281

North wall of building B.



Figure: 1282

North wall of building B.



Figure: 1283

North wall of building B.





Figure: 1284

General view of the power pole at the northeast corner of building B.



Figure: 1285

General view of the power pole at the northeast corner of building B.



Figure: 1286

North wall of building B.



Figure: 1287

North wall of building B.



Figure: 1288

North wall of building B.



Figure: 1289

North wall of building B. Showing erosion in the mortar joints.



Figure: 1290

North wall of building B. Showing erosion in the mortar joints.



Figure: 1291

General view of the garden bed on the north side of building B.



Figure: 1292

General view of the garden bed on the north side of building B.



Figure: 1293

General view of the garden bed on the north side of building B. Showing cracking.



Figure: 1294

General view of the garden bed on the north side of building B. Showing wide cracking.



Figure: 1295

General view of the garden bed on the north side of building B.



Figure: 1296

General view of the garden bed on the north side of building B.



Figure: 1297

General view of the garden bed on the north side of building B. Showing cracking.



Figure: 1298

Wide cracking in the garden bed on the north side of building B, outside the entrance.



Figure: 1299

Wide cracking in the garden bed on the north side of building B, outside the entrance.



Figure: 1300

Wide cracking in the garden bed on the north side of building B, outside the entrance.



Figure: 1301

General view of the garden bed on the north side of building B.



Figure: 1302

General view of the garden bed on the north side of building B.



Figure: 1303

General view of the garden bed on the north side of building B. Showing damage in the garden bed and the north wall.



Figure: 1304

Damage in the garden bed on the north side of building B. Also showing damage in the north wall of building B.



Figure: 1305

Missing brick in the north wall of building B. Also showing erosion in the mortar joints.



Figure: 1306

Leaning in the garden bed fence on the north side of building B.



Figure: 1307

Damage in the garden bed fence at the northeast corner of building B.



Figure: 1308

Damage in the garden bed fence at the northeast corner of building B.



Figure: 1309

General view of the garden bed fence on the north side of building B.



Figure: 1310

Cracking in the paving at the northeast corner of building B.



Figure: 1311

Cracking in the paving at the northeast corner of building B.



Figure: 1312

Cracking in the paving at the northeast corner of building B.



Figure: 1313

Cracking in the paving at the northeast corner of building B. Also showing movement.



Figure: 1314

Northeast corner of building B.



Figure: 1315

Northeast corner of building B.




Figure: 1316

Northeast corner of building B.



Figure: 1317

Northeast corner of building B.



Figure: 1318

General view of the soffit on the north side of building B. Showing weathering and damage.



Figure: 1319

General view of the soffit on the north side of building B. Showing weathering and damage.

Figure: 1320

East wall of building
B, north side.



Figure: 1321

East wall of building
B, north side.



Figure: 1322

East wall of building
B, north side.





Figure: 1323

East wall of building
B, north side.



Figure: 1324

East wall of building
B.



Figure: 1325

East wall of building
B.



Figure: 1326

East wall of building
B.



Figure: 1327

East wall of building
B.



Figure: 1328

East wall of building
B.



Figure: 1329

East wall of building B.



Figure: 1330

East wall of building B. Showing crazing.



Figure: 1331

East wall of building B.



Figure: 1332

East wall of building B.



Figure: 1333

East wall of building B.



Figure: 1334

East wall of building B.



Figure: 1335

East wall of building B, south side. Showing rusting and peeling paint.



Figure: 1336

East wall of building B, south side.



Figure: 1337

Stepped cracking and movement in the east wall of building B, south side.



Figure: 1338

East wall of building B, south side.



Figure: 1339

East wall of building B, south side.



Figure: 1340

Slight stepped cracking in the mortar joints in the east wall of building B, south side. Also showing missing bricks.



Figure: 1341

East wall of the building, south side.



Figure: 1342

Slight cracking in the mortar joints in the east wall of the building, south side. Also showing movement.



Figure: 1343

Cracking in the paving at the southeast corner of building B.



Figure: 1344

Damage in the step at the southeast corner of building B. Also showing cracking in the paving.



Figure: 1345

General view of the heritage wall, looking from the southeast corner of building B.



Figure: 1346

General view of the heritage wall, looking from the southeast corner of building B. Showing erosion in the mortar joints.



Figure: 1347

General view of the heritage wall, looking from the southeast corner of building B. Showing erosion in the mortar joints.



Figure: 1348

General view of the heritage wall, looking from the southeast corner of building B. Showing erosion in the mortar joints.



Figure: 1349

Cracking in the heritage wall, looking from the southeast corner of building B. Also showing erosion in the mortar joints.



Figure: 1350

Erosion in the mortar joints the heritage wall, looking from the southeast corner of building B. Also showing movement.



Figure: 1351

Cracking in the top of the heritage wall, looking from the southeast corner of building B.



Figure: 1352

Cracking and erosion in the top of the heritage wall, looking from the southeast corner of building B.



Figure: 1353

Cracking and erosion in the top of the heritage wall, looking from the southeast corner of building B.



Figure: 1354

Separation between the heritage wall and the south wall of building B.




Figure: 1355

General view of the top of the heritage wall at the southeast corner of building B. Showing cracking and movement.



Figure: 1356

General view of the southwest corner of building B.



Figure: 1357

General view of the southwest corner of building B.




Figure: 1358

General view of the southwest corner of building B.



Figure: 1359

General view of the southwest corner of building B.



Figure: 1360

Damage in the soffit on the west side of building B.




Figure: 1361

Damage in the soffit on the west side of building B.



Figure: 1362

Damage in the soffit on the west side of building B.



Figure: 1363

Damage in the soffit on the west side of building B.



Figure: 1364

South wall of building B, west side.



Figure: 1365

South wall of building B, west side.



Figure: 1366

South wall of building B, west side.



Figure: 1367

West wall of building B, south side.
Showing cracking above the window.



Figure: 1368

West wall of building B, south side.
Showing damage above the window.



Figure: 1369

Slight cracking
above the window in
the west wall of the
building, south side.




Figure: 1370

West wall of building B, south side.



Figure: 1371

West wall of building B, south side.



Figure: 1372

Cracking in the west wall of building B, south side.



Figure: 1373

Cracking in the west wall of building B, south side.



Figure: 1374

General view of the pathway at the southwest corner of building B.



Figure: 1375

General view of the heritage wall, looking from the southwest corner of building B.




Figure: 1376

General view of the heritage wall, looking from the southwest corner of building B.

Figure: 1377

General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.



Figure: 1378

General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.



Figure: 1379

General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.





Figure: 1380

General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.



Figure: 1381

General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.



Figure: 1382

General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.



Figure: 1383

General view of the heritage wall, looking from the southwest corner of building B. Showing erosion in the mortar joints.



Figure: 1384

Cracking in the paving at the southwest corner of building B.



Figure: 1385

Slight stepped cracking in the east wall of building F.



Figure: 1386

Slight stepped cracking in the east wall of building F. Also showing movement.



Figure: 1387

Slight stepped cracking in the east wall of building F.



Figure: 1388

Movement in the heritage wall at the southwest corner of building B.



Figure: 1389

Movement in the heritage wall at the southwest corner of building B.



Figure: 1390

Cracking in the paving on the west side of building B.



Figure: 1391

General view of the pathway and grass area on the south side of building F.



Figure: 1392

General view of the pathway and grass area on the south side of building F.



Figure: 1393

General view of the garden bed on the south side of building F.



Figure: 1394

General view of the heritage wall on the south side of building B.



Figure: 1395

General view of the heritage wall on the south side of building B.



Figure: 1396

General view of the heritage wall on the south side of building B.



Figure: 1397

General view of the heritage wall on the south side of building B.



Figure: 1398

General view of the heritage wall on the south side of building B.



Figure: 1399

General view of the heritage wall on the south side of building B.



Figure: 1400

General view of the heritage wall on the south side of building B.



Figure: 1401

General view of the heritage wall on the south side of building B.



Figure: 1402

General view of the heritage wall on the south side of building B.



Figure: 1403

General view of the heritage wall on the south side of building B.



Figure: 1404

General view of the heritage wall on the south side of building B.



Figure: 1405

General view of the heritage wall on the south side of building B.



Figure: 1406

General view of the heritage wall on the south side of building B.



Figure: 1407

South wall of building
B, west side.



Figure: 1408

South wall of building
B, west side.



Figure: 1409

South wall of building
B, west side.

Figure: 1410

Wide cracking above the window in the south wall of building B.



Figure: 1411

Cracking and movement in the south wall of building B.



Figure: 1412

Cracking in the south wall of building B.





Figure: 1413

South wall of building B.



Figure: 1414

South wall of building B.



Figure: 1415

South wall of building B.



Figure: 1416

South wall of building B.



Figure: 1417

Cracking in the south wall of building B.



Figure: 1418

South wall of building B.



Figure: 1419

South wall of building B.



Figure: 1420

South wall of building B.



Figure: 1421

General view of the heritage wall on the south side of building B.



Figure: 1422

General view of the heritage wall on the south side of building B.



Figure: 1423

General view of the heritage wall on the south side of building B.



Figure: 1424

General view of the heritage wall on the south side of building B.



Figure: 1425

Cracking in the heritage wall on the south side of building B.



Figure: 1426

General view of the heritage wall on the south side of building B.



Figure: 1427

General view of the heritage wall on the south side of building B.



Figure: 1428

General view of the heritage wall on the south side of building B.



Figure: 1429

General view of the heritage wall on the south side of building B.



Figure: 1430

General view of the heritage wall on the south side of building B.



Figure: 1431

General view of the heritage wall on the south side of building B.



Figure: 1432

General view of the heritage wall on the south side of building B.



Figure: 1433

General view of the heritage wall on the south side of building B.

Figure: 1434

General view of the heritage wall on the south side of building B.



Figure: 1435

General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.



Figure: 1436

Mold and signs of water in the soffit on the south side of building B.



Figure: 1437

South wall of building
B.



Figure: 1438

South wall of building
B.



Figure: 1439

South wall of building
B.





Figure: 1440

South wall of building B.



Figure: 1441

South wall of building B.



Figure: 1442

Detached down pipe in the south wall of building B.



Figure: 1443

Movement in the bricks in the south wall of building B.




Figure: 1444

Movement in the bricks in the south wall of building B.



Figure: 1445

Movement in the bricks in the south wall of building B.



Figure: 1446

South wall of building B.



Figure: 1447

Stepped cracking and erosion in the mortar joints in the south wall of building B.



Figure: 1448

General view of the heritage wall on the south side of building B.



Figure: 1449

General view of the heritage wall on the south side of building B.



Figure: 1450

General view of the heritage wall on the south side of building B.



Figure: 1451

General view of the heritage wall on the south side of building B.



Figure: 1452

General view of the heritage wall on the south side of building B.



Figure: 1453

General view of the heritage wall on the south side of building B.



Figure: 1454

General view of the heritage wall on the south side of building B.



Figure: 1455

General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.



Figure: 1456

General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.



Figure: 1457

General view of the heritage wall on the south side of building B.



Figure: 1458

General view of the heritage wall on the south side of building B.



Figure: 1459

General view of the heritage wall on the south side of building B.



Figure: 1460

General view of the heritage wall on the south side of building B.



Figure: 1461

General view of the grass area on the south side of building B.



Figure: 1462

General view of the grass area on the south side of building B.



Figure: 1463

South wall of building B.



Figure: 1464

South wall of building B.



Figure: 1465

General view of the sitting area on the south side of building B.



Figure: 1466

General view of the sitting area on the south side of building B.



Figure: 1467

General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.



Figure: 1468

General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.



Figure: 1469

General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.



Figure: 1470

General view of the heritage wall on the south side of building B. Showing erosion in the mortar joints.



Figure: 1471

General view of the heritage wall on the south side of building B.



Figure: 1472

General view of the heritage wall on the south side of building B.



Figure: 1473

General view of the heritage wall on the south side of building B.



Figure: 1474

General view of the heritage wall on the south side of building B.



Figure: 1475

General view of the heritage wall on the south side of building B.



Figure: 1476

General view of the heritage wall on the south side of building B.



Figure: 1477

Damage in the seats on the south side of building C.



Figure: 1478

Damage in the seats on the south side of building C.



Figure: 1479

General view of the heritage wall on the south side of building C.



Figure: 1480

General view of the heritage wall on the south side of building C. Showing erosion in the mortar joints.



Figure: 1481

General view of the heritage wall on the south side of building C. Showing erosion in the mortar joints.



Figure: 1482

Nail holes the heritage wall on the south side of building C.



Figure: 1483

General view of the heritage wall on the south side of building C.



Figure: 1484

General view of the heritage wall on the south side of building C.



Figure: 1485

Damage in the heritage wall on the south side of building C.



Figure: 1486

General view of the heritage wall on the south side of building C.




Figure: 1487

General view of the heritage wall on the south side of building C.



Figure: 1488

General view of the heritage wall on the south side of building C. Showing obstructed view.



Figure: 1489

General view of the heritage wall on the south side of building C.



Figure: 1490

General view of the heritage wall on the south side of building C.



Figure: 1491

Slight cracking in the heritage wall on the south side of building C.



Figure: 1492

Slight cracking in the heritage wall on the south side of building C.



Figure: 1493

General view of the heritage wall on the south side of building C.



Figure: 1494

General view of the heritage wall on the south side of building C.



Figure: 1495

General view of the heritage wall on the south side of building C.



Figure: 1496

General view of the heritage wall on the south side of building C.




Figure: 1497

General view of the heritage wall on the south side of building C.



Figure: 1498

General view of the heritage wall on the south side of building C.



Figure: 1499

General view of the heritage wall on the south side of building C.



Figure: 1500

General view of the heritage wall on the south side of building C.



Figure: 1501

General view of the heritage wall on the south side of building C.




Figure: 1502

General view of the heritage wall on the south side of building C.



Figure: 1503

General view of the heritage wall on the south side of building C.



Figure: 1504

General view of the heritage wall on the south side of building C.



Figure: 1505

General view of the grass area on the south side of building C.



Figure: 1506

General view of the grass area on the south side of building C.



Figure: 1507

BUILDING C

South wall of building C.



Figure: 1508

South wall of building C.



Figure: 1509

South wall of building C.



Figure: 1510

General view of the chimney on the south side of building C.



Figure: 1511

General view of the chimney on the south side of building C.



Figure: 1512

General view of the chimney on the south side of building C. Showing chipping.



Figure: 1513

General view of the roof on the south side of building C.



Figure: 1514

General view of the roof on the south side of building C.



Figure: 1515

General view of the roof on the south side of building C.



Figure: 1516

General view of the roof on the south side of building C.



Figure: 1517

South wall of building C.



Figure: 1518

General view of the shed at the southwest corner of building C.




Figure: 1519

General view of the heritage wall on the south side of building C.



Figure: 1520

General view of the heritage wall on the south side of building C.



Figure: 1521

West wall of building C.



Figure: 1522

West wall of building C.



Figure: 1523

West wall of building C.



Figure: 1524

General view of the roof on the west side of building C.



Figure: 1525

General view of the roof on the west side of building C.



Figure: 1526

General view of the chimney on the west side of building C.



Figure: 1527

General view of the chimney on the west side of building C.



Figure: 1528

West wall of building C.



Figure: 1529

West wall of building C.



Figure: 1530

West wall of building C.




Figure: 1531

Cracking in the west wall of building C, north side.



Figure: 1532

Rusting damage in the down pipe on the west side of building C.



Figure: 1533

Movement in the retaining wall at the northwest corner of building C.



Figure: 1534

Movement in the retaining wall at the northwest corner of building C. Also showing wide cracking.



Figure: 1535

Movement in the retaining wall on the west side of building C. Also showing slight cracking in the mortar joints.



Figure: 1536

General view of the retaining wall on the west side of building C.



Figure: 1537

General view of the pathway on the west side of building C.



Figure: 1538

General view of the pathway on the west side of building C.



Figure: 1539

General view of the pathway on the west side of building C.



Figure: 1540

General view of the pathway on the west side of building C.



Figure: 1541

Chipping in the retaining wall on the west side of building C.



Figure: 1542

General view of the retaining wall on the west side of building C. Showing damage.



Figure: 1543

General view of the retaining wall on the west side of building C.



Figure: 1544

Paving at the southwest corner of building C.




Figure: 1545

Paving at the southwest corner of building C.



Figure: 1546

West wall of building C.




Figure: 1547

West wall of building C.



Figure: 1548

Cracking in the doorstep on the west side of building C.




Figure: 1549

General view of the heritage wall on the south side of building C.



Figure: 1550

General view of the heritage wall on the south side of building C. Showing erosion in the mortar joints.



Figure: 1551

South wall of building C.



Figure: 1552

South wall of building C. Showing separation in the cladding.



Figure: 1553

Gap below the step in the south wall of building C.



Figure: 1554

General view of the paving at the northwest corner of building C.



Figure: 1555

General view of the paving on the west side of building B.



Figure: 1556

Northwest corner of building C.

Figure: 1557

Northwest corner
of the chimney on
building C.



Figure: 1558

Northwest corner
of the chimney on
building C.



Figure: 1559

General view of the
roof on the north side
of building C.





Figure: 1560

General view of the roof on the north side of building C.



Figure: 1561

General view of the columns on the north side of building C.



Figure: 1562

General view of the columns on the north side of building C.



Figure: 1563

General view of the grass area on the north side of building C.



Figure: 1564

General view of the grass area on the north side of building C.



Figure: 1565

General view of the pit lid in the grass area on the north side of building C.



Figure: 1566

Cracking in the north wall of building C, west side.



Figure: 1567

General view of the paving at the northeast corner of building C.




Figure: 1568

General view of the paving at the northeast corner of building C.



Figure: 1569

General view of the paving on the north side of building C.



Figure: 1570

North wall of building C.



Figure: 1571

North wall of building C.



Figure: 1572

North wall of building C.



Figure: 1573

North wall of building C.



Figure: 1574

Slight cracking in the paving on the north side of building C.



Figure: 1575

North wall of building C.



Figure: 1576

North wall of building C.



Figure: 1577

North wall of building C.



Figure: 1578

North wall of building C.



Figure: 1579

North wall of building C.



Figure: 1580

North wall of building C.



Figure: 1581

Fine cracking in the north wall of building C.



Figure: 1582

Cracking in the paving at the northeast corner of building C.




Figure: 1583

General view of the paving on the east side of building C.



Figure: 1584

Fine cracking in the paving on the east side of building C.



Figure: 1585

East wall of building C.



Figure: 1586

East wall of building C.



Figure: 1587

East wall of building C.



Figure: 1588

East wall of building C.



Figure: 1589

North wall of building C, east side.



Figure: 1590

North wall of building C, east side.



Figure: 1591

General view of the columns on the east side of building C.



Figure: 1592

General view of the columns on the east side of building C.



Figure: 1593

General view of the roof on the east side of building C.



Figure: 1594

General view of the columns on the east side of building C.



Figure: 1595

East wall of building C.



Figure: 1596

East wall of building C.



Figure: 1597

East wall of building C.



Figure: 1598

General view of the grass area on the east side of building C.



Figure: 1599

General view of the grass area on the east side of building C.



Figure: 1600

East wall of building C.




Figure: 1601

East wall of building C.



Figure: 1602

East wall of building C.



Figure: 1603

East wall of building C.



Figure: 1604

Fine cracking in the east wall of building C.



Figure: 1605

Separation between the fascia and east wall of building C.



Figure: 1606

Separation between the fascia and east wall of building C.




Figure: 1607

General view of the heritage wall on the south side of building C.



Figure: 1608

General view of the heritage wall on the south side of building C.



Figure: 1609

General view of the water tanks at the southeast corner of building C.




Figure: 1610

General view of the water tanks at the southeast corner of building C.



Figure: 1611

General view of the tree at the southeast corner of building C.



Figure: 1612

Damage in the window sill on the east side of building C.



Figure: 1613

General view of the north side of building C.



Figure: 1614

General view of the east side of building C.



Figure: 1615

General view of the power pole at the northeast corner of building C.



Figure: 1616

General view of the power pole at the northeast corner of building C.



Figure: 1617

General view of the paving at the northeast corner of building C.



Figure: 1618

General view of the paving at the northeast corner of building C.



Figure: 1619

General view of the fence on the east side of building C.



Figure: 1620

General view of the fence on the east side of building C.



Figure: 1621

General view of the fence on the east side of building C.



Figure: 1622

INTERNAL

General view of the office sign on building C.

Figure: 1623

South wall in reception.




Figure: 1624

East wall in reception.



Figure: 1625

East wall in reception.





Figure: 1626

North wall in reception.



Figure: 1627

North wall in reception.




Figure: 1628

North wall in reception.



Figure: 1629

West wall in reception.



Figure: 1630

Ceiling in reception.



Figure: 1631

Ceiling in reception.



Figure: 1632

Timber floor in reception.



Figure: 1633

Timber floor in reception.




Figure: 1634

Timber floor in reception.



Figure: 1635

General view of the fireplace in the west wall in reception.



Figure: 1636

General view of the fireplace in the west wall in reception.



Figure: 1637

South wall in office 1.



Figure: 1638

East wall in office 1.



Figure: 1639

East wall in office 1.




Figure: 1640

North wall in office 1.



Figure: 1641

North wall in office 1.



Figure: 1642

West wall in office 1.



Figure: 1643

West wall in office 1.

Figure: 1644

Timber floor in office
1.



Figure: 1645

Timber floor in office
1.



Figure: 1646

Timber floor in office
1.





Figure: 1647

Ceiling in office 1.



Figure: 1648

Peeling paint and staining in the ceiling in office 1.



Figure: 1649

Patching in the ceiling in office 1.



Figure: 1650

General view in the hallway, outside the bathroom.



Figure: 1651

Timber floor in the hallway, outside the bathroom.



Figure: 1652

General view in the hallway, outside the bathroom.



Figure: 1653

General view in the hallway, outside the bathroom.



Figure: 1654

General view in the hallway, outside the bathroom.



Figure: 1655

General view in the hallway, outside the bathroom.



Figure: 1656

General view in the hallway, outside the bathroom.



Figure: 1657

West wall in the bathroom.




Figure: 1658

West wall in the bathroom.



Figure: 1659

South wall in the bathroom.



Figure: 1660

Separation in the cladding in the south wall in the bathroom.



Figure: 1661

East wall in the bathroom.



Figure: 1662

North wall in the bathroom.



Figure: 1663

North wall in the bathroom.



Figure: 1664

North wall in the bathroom.



Figure: 1665

Tile floor in the bathroom.




Figure: 1666

Tile floor in the bathroom.



Figure: 1667

Tile floor in the bathroom.

Figure: 1668

Ceiling in the bathroom. Showing separation between cladding.



Figure: 1669

Ceiling in the bathroom. Showing separation between cladding.



Figure: 1670

Ceiling in the bathroom.





Figure: 1671

Ceiling in the bathroom. Showing separation between cladding.




Figure: 1672

South wall in office 2.



Figure: 1673

South wall in office 2.



Figure: 1674

South wall in office 2.



Figure: 1675

South wall in office 2.



Figure: 1676

East wall in office 2.



Figure: 1677

East wall in office 2.



Figure: 1678

North wall in office 2.




Figure: 1679

North wall in office 2.



Figure: 1680

West wall in office 2.



Figure: 1681

Timber floor in office 2.



Figure: 1682

Timber floor in office 2.



Figure: 1683

Ceiling in office 2.



Figure: 1684

General view in the hallway, outside the kitchen.



Figure: 1685

General view in the hallway, outside the kitchen.



Figure: 1686

General view in the hallway, outside the kitchen.



Figure: 1687

General view in the hallway, outside the kitchen.



Figure: 1688

General view in the hallway, outside the kitchen.



Figure: 1689

Ceiling in the hallway, outside the kitchen.



Figure: 1690

South wall in the kitchen.



Figure: 1691

South wall in the kitchen.

Figure: 1692

East wall in the kitchen.



Figure: 1693

East wall in the kitchen.



Figure: 1694

North wall in the kitchen.





Figure: 1695

North wall in the kitchen.



Figure: 1696

North wall in the kitchen.



Figure: 1697

West wall in the kitchen.

Figure: 1698

Ceiling in the kitchen.
Showing separation
between cladding.



Figure: 1699

Ceiling in the kitchen.
Showing separation
between cladding.



Figure: 1700

Ceiling in the
kitchen.





Figure: 1701

North wall in office 3.



Figure: 1702

North wall in office 3.



Figure: 1703

East wall in office 3.

Figure: 1704

South wall in office 3.



Figure: 1705

West wall in office 3.



Figure: 1706

Timber floor in office 3.





Figure: 1707

Timber floor in office 3.



Figure: 1708

Ceiling in office 3.



Figure: 1709

Ceiling in office 3.



Figure: 1710

Separation between the counter and the west wall in the kitchen.



Figure: 1711

Separation between the counter and the west wall in the kitchen.



Figure: 1712

General view in the toilet.



Figure: 1713

General view in the toilet.



Figure: 1714

General view in the toilet.



Figure: 1715

EXTERNAL

General view of the ceiling on the north porch on building C.



Figure: 1716

General view of the ceiling on the north porch on building C.



Figure: 1717

General view of the ceiling on the north porch on building C. Showing cracking.



Figure: 1718

General view of the ceiling on the north porch on building C.



Figure: 1719

Separation above the column on the north porch on building C.



Figure: 1720

General view of the heritage wall on the south side of building C.



Figure: 1721

General view of the heritage wall on the south side of building C. Showing erosion in the mortar joints.



Figure: 1722

General view of the heritage wall on the south side of building C.



Figure: 1723

General view of the heritage wall on the south side of building C.



Figure: 1724

General view of the heritage wall on the south side of building C.



Figure: 1725

General view of the heritage wall on the south side of building C.



Figure: 1726

General view of the heritage wall on the south side of building C. Showing erosion in the mortar joints.



Figure: 1727

General view of the pit lid in the grass area at the southeast corner of the property.



Figure: 1728

Cracking in the heritage wall at the southeast corner of the property.



Figure: 1729

East boundary fence.



Figure: 1730

East boundary fence.



Figure: 1731

East boundary fence.



Figure: 1732

East boundary fence.



Figure: 1733

Fence on the south side of the driveway.



Figure: 1734

Fence on the south side of the driveway.



Figure: 1735

Fence on the south side of the driveway.



Figure: 1736

General view of the pit lid in the grass area on the east side of building C.



Figure: 1737

General view of the grass area on the east side of building C.



Figure: 1738

General view of the grass area on the east side of building C.



Figure: 1739

General view of the power pole on the south side of the driveway.



Figure: 1740

General view of the power pole on the south side of the driveway.



Figure: 1741

Damage in the base of the fence on the south side of the driveway.



Figure: 1742

General view of the heritage post on the south side of the driveway.



Figure: 1743

General view of the heritage post on the south side of the driveway.



Figure: 1744

General view of the heritage post on the south side of the driveway.



Figure: 1745

General view of the fence on the south side of the driveway.



Figure: 1746

General view of the fence on the south side of the driveway.



Figure: 1747

General view of the fence on the south side of the driveway.



Figure: 1748

General view of the heritage post on the south side of the driveway. Showing cracking in the mortar joints.



Figure: 1749

General view of the heritage post on the south side of the driveway. Showing cracking in the mortar joints.



Figure: 1750

General view of the heritage post on the south side of the driveway. Showing cracking in the mortar joints.



Figure: 1751

General view of the heritage post on the south side of the driveway. Showing erosion in the mortar joints.



Figure: 1752

General view of the heritage post on the south side of the driveway. Showing erosion in the mortar joints.



Figure: 1753

General view of the paving on the south side of the driveway.



Figure: 1754

General view of the paving on the south side of the driveway.



Figure: 1755

General view of the paving on the south side of the driveway. Showing cracking.



Figure: 1756

General view of the fence on the south side of the property.



Figure: 1757

General view of the fence on the south side of the property.

Figure: 1758

General view of the fence on the south side of the property.



Figure: 1759

General view of the fence on the south side of the property.



Figure: 1760

General view of the fence on the north side of the driveway.





Figure: 1761

General view of the fence on the north side of the driveway.



Figure: 1762

General view of the fence on the north side of the driveway.



Figure: 1763

Chipping in the base of the fence on the north side of the driveway.



Figure: 1764

Cracking in the base of the fence on the north side of the driveway.



Figure: 1765

Cracking in the driveway.



Figure: 1766

General view of the garden bed on the south side of the driveway.



Figure: 1767

General view of the garden bed on the south side of the driveway.



Figure: 1768

General view of the garden bed on the south side of the driveway.



Figure: 1769

General view of the roadway, looking from the driveway.



Figure: 1770

General view of the roadway, looking from the driveway.



Figure: 1771

General view of the roadway, looking from the driveway.



Figure: 1772

General view of the fence on the north side of the driveway.



Figure: 1773

General view of the fence on the north side of the driveway.




Figure: 1774

General view of the fence on the north side of the driveway.



Figure: 1775

General view of the fence on the north side of the driveway. Showing chipping in the base.



Figure: 1776

General view of the fence on the north side of the driveway.



Figure: 1777

General view of the fence on the north side of the driveway.



Figure: 1778

General view of the fence on the north side of the driveway.



Figure: 1779

General view of the fence on the north side of the driveway.



Figure: 1780

General view of the fence on the north side of the driveway. Showing cracking in the base.



Figure: 1781

General view of the fence on the east side of the property.



Figure: 1782

General view of the fence on the east side of the property.



Figure: 1783

Cracking in the base of the fence on the east side of the property.



Figure: 1784

Cracking in the base of the fence on the east side of the property.



Figure: 1785

Cracking in the base of the fence on the east side of the property.



Figure: 1786

Cracking in the base of the fence on the east side of the property.



Figure: 1787

General view of the fence on the east side of the property.



Figure: 1788

General view of the gate on the east side of the property. Showing leaning.



Figure: 1789

General view of the footpath on the east side of the property. Showing chipping.



Figure: 1790

General view of the footpath on the east side of the property.



Figure: 1791

General view of the fence on the east side of the property.



Figure: 1792

General view of the fence on the east side of the property.



Figure: 1793

Cracking in the base of the fence on the east side of the property.



Figure: 1794

Cracking in the base of the fence on the east side of the property.



Figure: 1795

General view of the fence on the east side of the property.



Figure: 1796

Cracking in the base of the fence on the east side of the property.



Figure: 1797

General view of the fence on the east side of the property. Showing missing top.



Figure: 1798

East wall of the ventilation shed.



Figure: 1799

East wall of the ventilation shed.



Figure: 1800

East wall of the ventilation shed. Showing bubbling paint.



Figure: 1801

East wall of the ventilation shed. Showing bubbling paint.



Figure: 1802

East wall of the ventilation shed. Showing bubbling paint.

Figure: 1803

East wall of the ventilation shed. Showing bubbling paint.



Figure: 1804

East wall of the ventilation shed.



Figure: 1805

East wall of the ventilation shed.





Figure: 1806

East wall of the ventilation shed.



Figure: 1807

General view of the footpath on the east side of the ventilation shed.



Figure: 1808

Cracking in the footpath on the east side of the ventilation shed.



Figure: 1809

Cracking in the footpath on the east side of the ventilation shed.



Figure: 1810

East wall of the ventilation shed.



Figure: 1811

East wall of the ventilation shed.



Figure: 1812

North wall of the ventilation shed.




Figure: 1813

North wall of the ventilation shed.



Figure: 1814

North wall of the ventilation shed.



Figure: 1815

North wall of the ventilation shed.



Figure: 1816

General view of the paving on the north side of the ventilation shed. Showing patching.



Figure: 1817

CYCLE WAY

General view of the grass area on the east side of Upper Fort Street.



Figure: 1818

General view of the grass area on the east side of Upper Fort Street.



Figure: 1819

General view of the grass area on the east side of Upper Fort Street. Showing chipping in the kerb.



Figure: 1820

General view of the grass area on the east side of Upper Fort Street. Showing chipping in the kerb.



Figure: 1821

General view of the cycle way on the east side of Upper Fort Street.



Figure: 1822

General view of the power pole on the east side of Upper Fort Street, adjacent to the cycle way.



Figure: 1823

General view of the power pole on the east side of Upper Fort Street, adjacent to the cycle way.



Figure: 1824

General view of the power pole on the east side of Upper Fort Street, adjacent to the cycle way. Showing leaning.



Figure: 1825

General view of the cycle way on the east side of Upper Fort Street.



Figure: 1826

General view of the cycle way on the east side of Upper Fort Street.



Figure: 1827

General view of the cycle way on the east side of Upper Fort Street.



Figure: 1828

General view of the fence on the east side of Upper Fort Street.



Figure: 1829

General view of the fence on the east side of Upper Fort Street.



Figure: 1830

General view of the fence on the east side of Upper Fort Street.



Figure: 1831

General view of the cycle way. Showing cracking.



Figure: 1832

General view of the cycle way. Showing cracking.



Figure: 1833

General view of the grass area on the west side of the cycle way.



Figure: 1834

General view of the grass area on the west side of the cycle way.



Figure: 1835

General view of the grass area on the west side of the cycle way.



Figure: 1836

General view of the grass area on the west side of the cycle way.



Figure: 1837

General view of the cycle way.



Figure: 1838

General view of the cycle way.



Figure: 1839

General view of the cycle way.



Figure: 1840

General view of the cycle way.



Figure: 1841

General view of the cycle way.



Figure: 1842

Cracking in the cycle way.



Figure: 1843

Cracking in the kerb on the east side of the cycle way.



Figure: 1844

Cracking in the kerb on the east side of the cycle way.



Figure: 1845

General view of the cycle way.



Figure: 1846

Damage in the street sign in the cycle way.




Figure: 1847

General view of the cycle way.



Figure: 1848

General view of the cycle way.



Figure: 1849

Cracking in the cycle way.



Figure: 1850

Cracking in the cycle way.



Figure: 1851

Cracking in the cycle way.



Figure: 1852

Cracking in the cycle way.



Figure: 1853

General view of the fence on the north side of the cycle way.



Figure: 1854

General view of the fence on the south side of the cycle way.



Figure: 1855

General view of the cycle way.



Figure: 1856

General view of the cycle way.



Figure: 1857

General view of the cycle way.



Figure: 1858

General view of the pathway, looking from the east side of building C.



Figure: 1859

General view of the garden on the east side of the property.



Figure: 1860

General view of the garden on the east side of the property.



Figure: 1861

General view of the garden on the east side of the property.



Figure: 1862

General view of the fence on the east side of the property. Showing obstructed view.



Figure: 1863

General view of the fence on the east side of the property. Showing obstructed view.



Figure: 1864

General view of the pathway on the east side of building G.



Figure: 1865

General view of the fence on the south side of building G.



Figure: 1866

General view of the fence on the south side of building G.



Figure: 1867

General view of the fence on the south side of building G.



Figure: 1868

Separation in the base of the fence on the south side of building G.




Figure: 1869

General view of the fence on the south side of building G.




Figure: 1870

General view of the fence on the south side of building G.



Figure: 1871

General view of the fence on the south side of building G.



Figure: 1872

General view of the fence on the south side of building G.



Figure: 1873

General view of the fence on the south side of building G.



Figure: 1874

General view of the fence on the south side of building G.



Figure: 1875

General view of the fence on the south side of building G. Showing cracking in the base.



Figure: 1876

General view of the paving on the south side of building G. Showing cracking and patching.



Figure: 1877

General view of the paving on the south side of building G.



Figure: 1878

General view of the pedestrian bridge on the south side of building G.



Figure: 1879

Cracking in the post on the east side of the pedestrian bridge on the south side of building G.



Figure: 1880

Cracking in the post on the east side of the pedestrian bridge on the south side of building G.

Figure: 1881

Cracking in the post on the east side of the pedestrian bridge on the south side of building G.



Figure: 1882

Cracking in the post on the east side of the pedestrian bridge on the south side of building G.



Figure: 1883

Crazing in the post on the west side of the pedestrian bridge on the south side of building G.





Figure: 1884

Crazing in the post on the west side of the pedestrian bridge on the south side of building G.



Figure: 1885

Cracking in the pedestrian bridge on the south side of building G.



Figure: 1886

Cracking in the pedestrian bridge on the south side of building G.



Figure: 1887

Cracking in the pedestrian bridge on the south side of building G.



Figure: 1888

Cracking in the pedestrian bridge on the south side of building G.



Figure: 1889

Cracking in the pedestrian bridge on the south side of building G.



Figure: 1890

General view of the pedestrian bridge on the south side of building G.




Figure: 1891

General view of the steps on the south side of the pedestrian bridge on the south side of building G.



Figure: 1892

General view of the steps on the south side of the pedestrian bridge on the south side of building G. Showing chipping.

Figure: 1893

Crazing in the wing wall of the steps on the south side of the pedestrian bridge on the south side of building G.



Figure: 1894

Crazing in the wing wall of the steps on the south side of the pedestrian bridge on the south side of building G.



Figure: 1895

Crazing in the wing wall of the steps on the south side of the pedestrian bridge on the south side of building G.



Figure: 1896

General view of the post on the south side of the pedestrian bridge on the south side of building G.



Figure: 1897

General view of the post on the south side of the pedestrian bridge on the south side of building G.



Figure: 1898

General view of the post on the south side of the pedestrian bridge on the south side of building G.



Figure: 1899

General view of the post on the south side of the pedestrian bridge on the south side of building G.



Figure: 1900

General view of the cycle way bridge, looking from the pedestrian bridge.



Figure: 1901

General view of the cycle way bridge, looking from the pedestrian bridge.





Figure: 1902

General view of the cycle way bridge, looking from the pedestrian bridge.



Figure: 1903

General view of the retaining wall on the south side of building G, looking from the pedestrian bridge.



Figure: 1904

General view of the retaining wall on the south side of building G, looking from the pedestrian bridge.

Figure: 1905

General view of the retaining wall on the south side of building G, looking from the pedestrian bridge.



Figure: 1906

General view of the retaining wall on the south side of building G, looking from the pedestrian bridge.



Figure: 1907

General view of the roadway, looking from the pedestrian bridge.



Figure: 1908

General view of the retaining wall on the south side of building G, looking from the pedestrian bridge.



Figure: 1909

General view of the retaining wall on the south side of building G, looking from the pedestrian bridge.



Figure: 1910

Cracking in the post on the west side of the pedestrian bridge.






Figure: 1911

Cracking in the post on the west side of the pedestrian bridge.



Figure: 1912

General view of the fence on the south side of building J.



Figure: 1913

General view of the fence on the south side of building J. Showing obstructed view.



Figure: 1914

General view of the pathway on the south side of building J.



Figure: 1915

General view of the fence on the south side of building J. Showing obstructed view.



Figure: 1916

General view of the fence on the south side of building J. Showing obstructed view.



Figure: 1917

General view of the pathway on the south side of building J.



Figure: 1918

General view of the fence on the south side of building J. Showing obstructed view.




Figure: 1919

General view of the fence on the south side of building J.



Figure: 1920

General view of the fence on the south side of building J.



Figure: 1921

General view of the fence on the south side of building J.



Figure: 1922

General view of the fence on the south side of building J.



Figure: 1923

General view of the fence on the south side of building J.



Figure: 1924

General view of the garden on the south side of building J.



Figure: 1925

Cracking in the paving on the west side of building J.



Figure: 1926

General view of the fence on the south side of building J.



Figure: 1927

General view of the fence on the south side of building J.



Figure: 1928

General view of the fence on the south side of building J.



Figure: 1929

General view of the fence on the south side of building J.



Figure: 1930

General view of the fence on the south side of building J.



Figure: 1931

General view of the fence on the south side of building J.



Figure: 1932

General view of the fence on the south side of building J.



Figure: 1933

General view of the fence on the south side of building J. Showing obstructed view.



Figure: 1934

General view of the fence on the west side of the property, looking from building F.



Figure: 1935

General view of the fence on the west side of the property, looking from building F.



Figure: 1936

General view of the fence on the west side of the property, looking from building F.



Figure: 1937

General view of the fence on the west side of the property, looking from building F.



Figure: 1938

General view of the fence on the west side of the property, looking from building F.



Figure: 1939

Cracking in the base of the fence on the west side of the property, looking from building F.



Figure: 1940

Cracking in the base of the fence on the west side of the property, looking from building F.



Figure: 1941

Cracking in the base of the fence on the west side of the property, looking from building F.



Figure: 1942

General view of the fence in the carpark on the west side of the property.



Figure: 1943

General view of the fence in the carpark on the west side of the property.



Figure: 1944

General view of the fence in the carpark on the west side of the property.



Figure: 1945

General view of the fence in the carpark on the west side of the property.



Figure: 1946

General view of the fence in the carpark on the west side of the property.



Figure: 1947

General view of the fence in the carpark on the west side of the property.



Figure: 1948

General view of the fence in the carpark on the west side of the property.



Figure: 1949

General view of the fence in the carpark on the west side of the property.



Figure: 1950

General view of the fence in the carpark on the west side of the property.



Figure: 1951

General view of the fence in the carpark on the west side of the property.




Figure: 1952

General view of the fence in the carpark on the west side of building A.



Figure: 1953

General view of the fence in the carpark on the west side of building A.



Figure: 1954

General view of the fence in the carpark on the north side of building A.



Figure: 1955

General view of the fence in the carpark on the north side of building A.



Figure: 1956

General view of the fence in the carpark on the north side of building A.



Figure: 1957

General view of the fence in the carpark on the north side of building A.



Figure: 1958

General view of the fence in the carpark on the north side of building A.



Figure: 1959

General view of the garden bed in the carpark on the north side of building A.



Figure: 1960

General view of the garden bed in the carpark on the north side of building A.



Figure: 1961

General view of the fence in the carpark on the north side of building A.

Figure: 1962

General view of the fence in the carpark on the north side of building A.



Figure: 1963

General view of the fence in the carpark on the north side of building A.



Figure: 1964

General view of the fence in the carpark on the north side of building A.





Figure: 1965

General view of the garden bed in the carpark on the north side of building A.



Figure: 1966

General view of the fence in the carpark on the north side of building A.



Figure: 1967

General view of the fence in the carpark on the north side of building A.



Figure: 1968

General view of the fence in the carpark on the north side of building A.



Figure: 1969

General view of the garden bed in the carpark on the north side of building A.



Figure: 1970

General view of the fence in the carpark on the north side of building A. Showing obstructed view.



Figure: 1971

General view of the garden bed in the carpark on the north side of building A. Showing movement.



Figure: 1972

General view of the garden bed in the carpark on the north side of building A. Showing movement.



Figure: 1973

General view of the fence in the carpark on the north side of building A.



Figure: 1974

General view of the fence in the carpark on the north side of building A.



Figure: 1975

General view of the fence in the carpark on the north side of building A.



Figure: 1976

General view of the fence in the carpark on the north side of building A.



Figure: 1977

General view of the fence in the carpark on the north side of building A.



Figure: 1978

General view of the fence in the carpark on the north side of building A.




Figure: 1979

General view of the fence in the carpark on the north side of building A.



Figure: 1980

General view of the fence in the carpark on the north side of building A.



Figure: 1981

General view of the fence in the carpark on the north side of building A.



Figure: 1982

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1983

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1984

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1985

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1986

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1987

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1988

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1989

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1990

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1991

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1992

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1993

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.




Figure: 1994

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1995

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1996

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1997

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1998

General view of the fence in the carpark on the north side of the playground. Showing obstructed view.



Figure: 1999

Hole in the artificial grass in the playground, east side.



Figure: 2000

Hole in the artificial grass in the playground, east side.



Figure: 2001

Hole in the artificial grass in the playground, east side.



Figure: 2002

Hole in the artificial grass in the playground, north side.



Figure: 2003

Hole in the artificial grass in the playground, north side.



Figure: 2004

Hole in the artificial grass in the playground.



Figure: 2005

Hole in the artificial grass in the playground, west side.



Figure: 2006

Hole in the artificial grass in the playground, west side.



Figure: 2007

Hole in the artificial grass in the playground, south side.



Figure: 2008

Hole in the artificial grass in the playground, south side.



Figure: 2009

Hole in the artificial grass in the playground, south side.