

Figure: 0181

Bleeding/flushing in the roadway on Barrier Highway.



Figure: 0182

Alligator cracking in the roadway on Barrier Highway.



Figure: 0183

Pot hole in the roadway on Barrier Highway.



Figure: 0184

Longitudinal cracking in the roadway on Barrier Highway.



Figure: 0185

Longitudinal cracking in the roadway on Barrier Highway.



Figure: 0186

Alligator cracking in the roadway on Barrier Highway.



Figure: 0187

Alligator cracking in the roadway on Barrier Highway.



Figure: 0188

Legendary cracking in the roadway on Barrier Highway.



Figure: 0189

Alligator cracking in the roadway on Barrier Highway.



Figure: 0190

Alligator cracking in the roadway on Barrier Highway.



Figure: 0191

Alligator cracking in the roadway on Barrier Highway.



Figure: 0192

Alligator cracking in the roadway on Barrier Highway.



Figure: 0193

Alligator cracking in the roadway on Barrier Highway.



Figure: 0194

Alligator cracking in the roadway on Barrier Highway.



Figure: 0195

Alligator cracking in the roadway on Barrier Highway.



Figure: 0196

Alligator cracking in the roadway on Barrier Highway.



Figure: 0197

Alligator cracking in the roadway on Barrier Highway.



Figure: 0198

Alligator cracking in the roadway on Barrier Highway.



Figure: 0199

Alligator cracking in the roadway on Barrier Highway.



Figure: 0200

Alligator cracking in the roadway on Barrier Highway.



Figure: 0201

Alligator cracking in the roadway on Barrier Highway.



Figure: 0202

Alligator cracking in the roadway on Barrier Highway.



Figure: 0203

Alligator cracking in the roadway on Barrier Highway.



Figure: 0204

Alligator cracking in the roadway on Barrier Highway.



Figure: 0205

Alligator cracking in the roadway on Barrier Highway.



Figure: 0206

## CREEDON STREET, BROKEN HILL

Alligator cracking in the roadway on Creedon Street.



Figure: 0207

## KANADAH ROAD, BROKEN HILL

Porous asphalt and raveling in the roadway on Kanadah Street.



Figure: 0208

Asphalt depression and alligator cracking in the roadway on Kanadah Street.



Figure: 0209

Longitudinal cracking in the roadway on Kanadah Street.



Figure: 0210

Tranverse cracking in the roadway on Kanadah Street.



Figure: 0211

Alligator cracking in the roadway on Kanadah Street.



Figure: 0212

Alligator cracking in the roadway on Kanadah Street.




Figure: 0213

Longitudinal cracking in the roadway on Kanadah Street.



Figure: 0214

Longitudinal cracking in the roadway on Kanadah Street.



Figure: 0215

Longitudinal cracking in the roadway on Kanadah Street.



Figure: 0216

Longitudinal cracking in the roadway on Kanadah Street.



Figure: 0217

Failed patching in the roadway on Kanadah Street.



Figure: 0218

Alligator cracking in the roadway on Kanadah Street.



Figure: 0219

Alligator cracking in the roadway on Kanadah Street.



Figure: 0220

Longitudinal cracking in the roadway on Kanadah Street.



Figure: 0221

Longitudinal cracking in the roadway on Kanadah Street.



## **ANNEXURE 1**

AGL Broken Hill BESS – Dilapidation Survey – Broken Hill Council Consultation

 From:
 Faisal Salah

 To:
 Mehdi Ghorbani

 Cc:
 Nina Fick; Richard Green

Subject: RE: 4017- Broken Hill Battery Storage Project

Date: Thursday, 15 September 2022 2:22:09 PM

Attachments: <u>image001.png</u>

Some people who received this message don't often get email from faisal.salah@brokenhill.nsw.gov.au. Learn why this is important

Hi Mehdi.

I have received the report, no further comments regarding this.

Thank you

Kind regards,

Faisal Salah
Projects Engineer
240 Blende St
PO Box 448
Broken Hill NSW 2880
Phone 08 8080 3394
Mobile 0457939377
Faisal.Salah@brokenhill.nsw.gov.au
www.brokenhill.nsw.gov.au



We acknowledge the traditional owners of the land on which we live and work, and pay our respects to their elders past, present, and emerging.

DISCLAIMER

This e-mail message and any accompanying attachments may contain information that is confidential and subject to legal privilege. If you are not the intended recipient do not read, use, disseminate, distribute or copy this message or attachments.

If you have received this message in error, please notify the sender immediately and delete this message. Views expressed in this e-mail are those of the individual, except where specifically stated otherwise.

Broken Hill City Council does not warrant this message to be free of errors, interference or viruses.

From: Mehdi Ghorbani < Mehdi.Ghorbani@valmecgroup.com.au>

Sent: Tuesday, 13 September 2022 3:25 PM

To: Faisal Salah <Faisal.Salah@brokenhill.nsw.gov.au>

Cc: Nina Fick <Nina.Fick@valmecgroup.com.au>; Richard Green <Richard.Green@valmecgroup.com.au>

Subject: 4017- Broken Hill Battery Storage Project

Hi Faisal,

I hope my email finds you well.

Valmec and Fluence are doing a battery storage project for AGL in Broken Hill. As a part of this project, we

need to prepare a dilapidation report at the beginning of the project and another report at the end of the project.

This report needs to be consulted with the relevant road authority which we think would be the Broken Hill council. Due to file size, you can download it from <a href="https://spaces.hightail.com/receive/KNTZm6bKvy">https://spaces.hightail.com/receive/KNTZm6bKvy</a>

Can you please confirm receipt of this report and let us know your comments, if any, as we need to send it to planning Secretary after that.

I'll give you a call tomorrow to discuss more.

Regards,

Mehdi Ghorbani Project Manager

## **Valmec Australia Pty Ltd**

**M:** 0437 801 458

**E:** Mghorbani@valmec.com.au | **W:** www.valmec.com.au

57 Machinery Street, DARRA QLD 4076 | P: 1300 825 632



Perth | Darwin | Adelaide | Brisbane | Roma | Sydney

Valmec acknowledges the Traditional Custodians of the lands on which we operate. We continue to pay our respects to Elders past, present and emerging.

A Please consider the environment before printing this email.