

Our Ref: PSM3828-006L

25 March 2022

JBS&G
Level 1, 50 Margaret St
Sydney NSW 2000
mhodgins@jbsg.com.au

Attention: Mitchell Hodgins

Dear Mitchell

G3 56 Delhi Road
North Ryde NSW 2113
P +61-2 9812 5000
F +61-2 9812 5001
E mailbox@psm.com.au
www.psm.com.au

RE: GEOTECHNICAL INVESTIGATION FOR THE RYDE HOSPITAL REDEVELOPMENT (CONCEPT AND STAGE 1)

1. Introduction

The attached report (Ref. PSM3828-002R REV 2 dated 13 June 2019) to this letter presents the results of the geotechnical investigation undertaken by Pells Sullivan Meynink (PSM) in 2019 for the proposed Ryde Hospital Redevelopment (Concept and Stage 1).

2. Project Descriptions

The Ryde Hospital site is located at 1 Denistone Road, Denistone and comprises Lots 10-11 DP 1183279 and Lots A-B DP 323458. It has an area of approximately 7.69Ha and currently accommodates the existing Ryde Hospital Campus.

This report accompanies a Concept State Significant Development Application that seeks approval for the establishment of a maximum building envelope and gross floor area to facilitate the development of a new hospital services development, car-park and refurbishment works.

A second SSDA will seek approval for the physical Stage 1 Early Works to prepare the site for the future development. The Stage 1 Early Works application will include the following relevant to the Enabling works construction zone as shown on the architectural drawings:

- Establishing access to the Project site and general establishment;
- Site preparation including environmental clearing;
- Bulk earthworks, including, cut and fill, associated with stage 1 footprint and proposed stage 1 internal roads
- Shoring associated with bulk earthworks
- Establishment of construction access roads;
- Relocation and upgrades of in-ground building services works and utility adjustments to facilitate bulk earthworks.

For a detailed project description refer to the Environmental Impact Statement prepared by Ethos Urban.

3. SEARs Requirements

The following SEARs requirements are relevant for the geotechnical investigation:

Item	SEARs Requirement	Response
13.	Ground and Water Conditions:	
13. i)	Provide an assessment of the potential impacts on soil resources, including related infrastructure and riparian lands on and near the site.	<p>We assess that there is minimum or close to no impact on the soil resource at the site.</p> <p>This assessment is based on the following considerations:</p> <ul style="list-style-type: none">• The site has been used for hospital for many decades.• The proposed re-development does not change the site use. <p>We understand that the stormwater system, surface gradients and landscaping have been and or will be designed to control surface flows and minimise soil erosion and the effects of soil erosion on waterways.</p> <p>The vast majority of the site have been and will be sealed by the proposed development (eg. paved) and appropriate surface runoff collection and disposal systems have been included. We understand that appropriate erosion control will also be included during construction.</p>

Should you have further queries, please do not hesitate to contact the undersigned.

Yours Sincerely



GREG FAZZONE
GEOTECHNICAL ENGINEER



AGUSTRIA SALIM
PRINCIPAL ENGINEER

Encl.

- PSM3828-002R REV 2

Ryde Hospital

Denistone, NSW

Geotechnical Investigation

PSM3828-002R 14 June 2019




Table of Contents

1	Introduction	4
2	Proposed Development	4
3	Geotechnical Investigation	4
3.1	Fieldwork	4
3.2	Geotechnical Laboratory Testing	5
3.2.1	California Bearing Ratio (CBR)	5
3.2.2	Atterberg Limits	5
3.3	Analytical Soil Testing	6
4	Site Conditions	6
4.1	Geological Setting	6
4.2	Surface Conditions	7
4.3	Subsurface Conditions	7
4.4	Groundwater	8
5	Discussion and Recommendations	8
5.1	Site Classification	8
5.2	Bulk Excavation Conditions	9
5.3	Earthworks and Disposal of Excavated Material	9
5.4	Permanent and Temporary Batters	10
5.5	Excavation Support	11
5.6	Foundations	12
5.6.1	Preamble	12
5.6.2	Shallow pad footings	12
5.6.3	Piles	13
5.7	Pavements	13
5.8	Corrosivity / Aggressivity	13
5.9	Dewatering	13
6	General	14

List of Tables

Table 1 – CBR Test Results	5
Table 2 – Atterberg Limit Results	5
Table 3 - Summary of Aggressivity Testing Results	6
Table 4 – Summary of Inferred Subsurface Conditions Encountered in the Boreholes	7
Table 5 – Approximate Depth to Top of Inferred Geotechnical Units Encountered in the Boreholes	8
Table 6 – Batter Slope Angles	10
Table 7 – Engineering Parameters of Inferred Geotechnical Units	12




List of Figures

- Figure 1: Site Investigation Location Plan
- Figure 2: Selected Site Photos
- Figure 3: Piezometric Level Monitoring Results
- Figure 4: Atterberg Limits – Plasticity Chart

List of Appendices

- Appendix A Geotechnical Engineering Borehole Logs
- Appendix B Core Photos
- Appendix C Point Load Strength Index Test Results
- Appendix D Piezometer Construction Record
- Appendix E CBR Test Results Sheet
- Appendix F Atterberg Limit Test Results sheet
- Appendix G Aggressivity Test Results Sheet
- Appendix H Ryde Hospital Sketches



1 Introduction

This report presents the results of the geotechnical investigation undertaken by Pells Sullivan Meynink (PSM) for the proposed re-development of Ryde Hospital, Denistone. The investigation was undertaken in accordance with our proposal PSM3828-001L, dated 9 April 2019. Approval to proceed was provided in an email from Mitchell Hodgins dated 2 May 2019.

The aim of the geotechnical investigation was to assess the subsurface conditions and provide geotechnical advice for the proposed development. The investigation involved assessment and classification of subsurface conditions for the purpose of providing advice on excavation conditions, permanent and temporary batters, retention and foundations.

2 Proposed Development

Based on architectural drawings provided by JBS&G (Ref: Ryde Sketches Staging.pdf, attached as Appendix H), we understand that the site is located at Ryde Hospital, Denistone. The site is currently occupied by existing buildings with internal roads and carparking areas.

The proposed re-development comprises:

- Three buildings with up to six (6) storeys above ground (Stage 1 and Stage 2) with up to two (2) basement levels
- A new multistorey carpark with no basement
- A new community health building with no basement.

A site locality plan is presented in Figure 1.

3 Geotechnical Investigation

3.1 Fieldwork

The fieldwork was undertaken from 14 to 19 May 2019 under the full-time supervision of a PSM Geotechnical Engineer, who undertook the following tasks:


- Setting out the investigation locations
- Directing the reinstatement of concrete and asphalt surfaces where required
- Preparing engineering logs of the materials encountered
- Collection of disturbed samples for laboratory testing
- Point load testing of recovered core samples.

Prior to the investigation, on-site service location “scans” were undertaken by a licenced service locator under the direction of PSM.

Fourteen (14) boreholes (BH01 to BH14) were drilled at the site, locations presented on Figure 1. Drilling was undertaken by Rockwell Drilling using a tracked drilling rig. The investigation locations of boreholes were recorded with a hand-held GPS unit with a horizontal accuracy of approximately +/- 5 m. Borehole collar levels cannot be estimated as a survey of the site had not been made available. The logs can be updated to included elevations if a survey plan is provided or survey completed.

Boreholes were drilled to depths of between 3.0 m and 11.27 m, with augering in soils and low strength rock and coring in rock. Rock coring was undertaken for boreholes BH01 to BH08, BH13 and BH14.

Two (2) standpipe piezometer were installed within BH03 and BH07 upon completion to allow ongoing monitoring of groundwater levels. The geotechnical borehole logs prepared as part of the investigation together with core photos are included in Appendix A and Appendix B. Explanation sheets to allow interpretation of the logs are also provided. Point load strength index testing was performed on the recovered core at approximately 1 m intervals with results tabulated in Appendix C and presented on the logs. Piezometer construction records are presented in Appendix D.



Figures 2.1 and 2.2 presents selected photos showing the general conditions of the existing site at the time of the fieldwork and typical drilling rig setup.

3.2 Geotechnical Laboratory Testing

3.2.1 California Bearing Ratio (CBR)

Six (6) bulk soil samples from the site were recovered for California Bearing Ratio (CBR) testing at an accredited geotechnical laboratory.

The following sample preparation was undertaken for the CBR testing:

- Compact to 98% standard MDD, at optimum moisture content (OMC);
- Four (4) day-soaked sample; and
- 4.5 kg surcharge.

Table 1 presents a summary of the CBR test results. The test result sheets are included in Appendix E.

Table 1 – CBR Test Results

Sample ID (depth)	Material Description	Soaked CBR (%)	OMC (%)	Standard Maximum Dry Density (t/m ³)	Swell (%)
BH01 (0.5 m – 3.0 m)	Silty clay	1.5*	18.5	1.69	1.5
BH03 (0.5 m – 1.9 m)	Silty clay	3.0*	19.6	1.70	2.0
BH04 (0.5 m – 1.3 m)	Silty clay	1.5*	23.3	1.63	4.5
BH07 (0.5 m – 3.0 m)	Silty clay	7.0*	16.0	1.81	0.0
BH10 (0.1 m – 2.9 m)	Silty sand	7.0*	15.0	1.79	1.0
BH13 (0.3 m – 3.5 m)	Silty clay	6.0*	17.4	1.79	0.5

Note: * Indicates Soaked CBR value at 2.5 mm penetration

3.2.2 Atterberg Limits

Six (6) bulk soil samples from the site were recovered for Atterberg Limits testing at an accredited geotechnical laboratory. Table 2 presents a summary of the test results. The results all plot above the A-line on Casagrande's plasticity chart (Figure 4), ranging from low to high plasticity (i.e., CL to CH), with majority of the samples indicating medium to high plasticity.

The test result sheets are included in Appendix F.

Table 2 – Atterberg Limit Results

Sample ID (depth)	Sample Description	Liquid Limit (%)	Plastic Limit (%)	Plasticity Index (%)	Linear Shrinkage (%)
BH01 (0.5 m – 3.0 m)	Silty clay	50	21	29	14
BH03 (0.5 m – 1.9 m)	Silty clay	76	24	52	19
BH04 (0.5 m – 1.3 m)	Silty clay	54	23	31	15
BH07 (0.5 m – 3.0 m)	Silty clay	30	17	13	7.5
BH10 (0.1 m – 2.9 m)	Silty sand	35	20	15	1.0
BH13 (0.3 m – 3.5 m)	Silty clay	39	19	20	0.5



3.3 Analytical Soil Testing

Analytical laboratory testing for soil aggressivity was carried out on six (6) samples. The results are presented in Appendix G and summarised in Table 3.

Table 3 - Summary of Aggressivity Testing Results

Sample ID	Sample Depth	pH	Moisture Content (%)	Chloride by Discrete Analyser (mg/kg)	Soluble Sulfate by ICPAES (mg/kg)
BH01	1.0 m	4.7	17.2	10	50
BH03	0.5 m	8.7	5.1	<10	90
BH04	1.0 m	5.1	20.1	20	40
BH07	0.5 m – 1.0 m	6.8	18.3	<50	180
BH11	0.5 m	4.7	17.4	30	110
BH13	0.5 m – 1.0 m	9.5	19.7	<10	240

4 Site Conditions

4.1 Geological Setting

The 1:100,000 Sydney Geological Map indicates the site is underlain by Ashfield Shale of the Wianamatta group (Rwa) which consist of black to dark-grey Shale and Laminite. The published information is consistent with the subsurface conditions encountered in the field investigation.

Inset 1 presents an indicative site locality on the geological map.



Inset 1: Sydney geological map indicating approximate site location



4.2 Surface Conditions

The site is currently occupied by existing buildings, internal roads and various carparking areas with an asphalt or concrete pavement surface.

The site is bound by Fourth Ave to the north, Denistone Rd to the east, and Ryedale Rd to the west (Figure 1). The site is sloped from the northeast boundary towards the southwest (based on the supplied architectural drawings).

At the time of the fieldwork, the ground surface was dry with minimal traffic. The boreholes were drilled through asphalt, concrete and topsoil surface.

4.3 Subsurface Conditions

The subsurface conditions are summarised in Table 4 and the depth at which each unit was encountered are summarised in Table 4.

We note that it is difficult to discriminate between fill and natural insitu material in augered boreholes where the fill is composed of locally excavated natural material; it is possible that the fill is thicker than interpreted. The laminite/siltstone bedrock unit has been classified using the system developed by Pells et al (1998). The rock mass classification system is based on rock strength, defect spacing and allowable seams.

Table 4 – Summary of Inferred Subsurface Conditions Encountered in the Boreholes

Inferred Geotechnical Unit		Material Description
Asphalt/Concrete/Topsoil		Current pavement – 100 to 200 mm thick ASPHALT: black and dark grey CONCRETE: pale grey and white TOPSOIL: silty sand with gravel, fine grained sand, dark brown, sub-angular gravel size up to 5mm, some clay. Rootlets and barks observed.
Fill (varying types)		SILTY CLAY with gravel, dark brown, grey and black, low to medium plasticity, sub-angular gravel size up to 10mm, stiff to very stiff consistency, trace of rootlets. CLAY with gravel, dark grey and orange, medium plasticity, sub-angular gravel size up to 5mm, very stiff consistency, trace of rootlets. SILTY SAND with gravel and crushed rocks, brown and yellow, fine to medium grained sand, sub-angular gravel size up to 20 mm, medium dense to dense consistency, trace of rootlets. CLAYEY SAND with gravel, brown and yellow, fine to medium grained sand, sub-angular gravel size up to 15 mm, medium dense to dense consistency, trace of rootlets. SILTY GRAVEL, pale grey and yellow, medium grained size, crushed sandstone rocks – moderately weathered and high strength.
Residual		SILTY CLAY: pale grey, brown and orange, low to medium plasticity, very stiff to hard consistency.
Bedrock	Class IV/V	LAMINITE: pale grey, dark grey and brown with orange banding, thin fine-grained sandstone laminations, rock fabric faint with developed bedding. Extremely to highly weathered. Extremely low to very low strength.
	Class III	LAMINITE: grey and dark grey with occasional orange banding, thin fine-grained sandstone laminations, rock fabric visible with well-developed bedding. Moderately to fresh. Low to medium strength.




Table 5 – Approximate Depth to Top of Inferred Geotechnical Units Encountered in the Boreholes

BH ID	Depth to Top of Inferred Unit (m below surface level)					
	Asphalt/Concrete Topsoil	Fill	Residual	Bedrock		EOH ⁽¹⁾
				Class IV/V	Class III	
BH01	0	0.20	0.90	3.00	7.65	9.00
BH02	0	0.20	0.50	1.40	6.50	11.27
BH03	0	0.10	1.30	1.90	8.05	9.13
BH04	0	0.20	0.80	1.35	4.30	8.40
BH05	0	0.10	0.50	1.20	3.70	8.45
BH06	0	0.10	1.40	2.00	5.40	8.10
BH07	0	0.10	1.30	2.50	3.50	9.17
BH08	0	0.09	1.40	2.60	8.18	8.80
BH09 ⁽²⁾	N/E	0.00	3.60	4.60	N/E	5.00
BH10 ⁽²⁾	0	0.10	>3.00	N/E	N/E	3.00
BH11 ⁽²⁾	0	0.10	4.00	4.50	N/E	6.00
BH12 ⁽²⁾	0	0.15	2.00	2.80	N/E	3.00
BH13	0	0.18	4.40	5.00	5.80	8.45
BH14	0	0.10	4.50	5.50	6.80	9.58

Note:

1. End of hole
2. Augered borehole
3. N/E – Not encountered

4.4 Groundwater

Spot measurement of the groundwater level was taken on 15 and 17 May 2018 in BH03 and BH07 following completion of the drilling. The measured groundwater level was 3.01 m below surface level in BH03 and was 2.70 m below surface level in BH07.

Continuous measurements of the groundwater level were taken at half hour intervals from 15 May 2019 to 7 June 2019 in BH03 and BH07 (with a HOBO water level logger). The groundwater level in both boreholes had not changed significantly during this period. Figures 3.1 and 3.2 present the results of groundwater level monitoring in both standpipe piezometers and monitoring will continue for the next 3 months.

5 Discussion and Recommendations

5.1 Site Classification

We have classified the site in accordance with Australian Standard AS2870 – 2011, “Residential slabs and footings – Construction”. Based on our field observations the depth of clay in the profile is greater than 1.8 m within most of the boreholes spread across the site, we recommend that structures which are within the scope of AS2870 be designed for a site classification of Class “H1” Highly Reactive.

The site can be re-classified during the works for specific areas where required.



5.2 Bulk Excavation Conditions

We expect excavation to depths of approximately 7 m is required for the proposed development which may comprise up two (2) basement levels for the new buildings.

Based on the geotechnical investigation, excavation in the Asphalt, Concrete, Fill, Residual Soil and highly weathered Bedrock should be achievable using conventional earth moving equipment with minor rock breaking. Excavation of more competent Bedrock may require the use of hydraulic impact breakers, rock saws and/or rock grinders and must be undertaken by contractors with suitable experience in rock excavation close to existing structures..


Prospective contractors should make their own assessment of excavatability based on the borehole logs and their site inspection and experience. It is our experience that excavatability is heavily dependent on both the operator and the plant used. Heavy rock breaking equipment will generate vibrations that may impact on neighbouring structures. Where controls on vibrations are required, the contractor should consider the use of smaller hammers, rock saws and grinders to undertake the excavation. The contractor should recognise that there is a potential for damage to adjacent buildings or infrastructure (if any) and consider this in its planning.

5.3 Earthworks and Disposal of Excavated Material

We anticipate that some earthworks may be required as part of the redevelopment. We consider that topsoil is not suited for reuse as engineered fill (but could be potentially blended in small quantities) but may be reused for landscaping purposes. It is our opinion that most of the remaining cut material (i.e., Fill, Residual Soil and Bedrock) would be suitable for reuse on the site as engineered fill.

We envisage that the earthworks proposed at the site will require the preparation of a detailed fill specification developed following the guidelines in AS3798 (2007), "Guidelines on earthworks for commercial and residential developments". Preparation of this fill specification is outside the scope of this report. We consider that the fill specification should address at least the following:

1. Subgrade preparation and base geometry requirements.
2. Material requirements, including a clear definition of:
 - a. Suitable and unsuitable material.
 - b. Grading or maximum particle size requirements. We note that a conservative definition of maximum particle size may result in some of the materials on site being excluded from reuse as engineered fill. It is our opinion that this restriction may not significantly benefit fill performance.
3. Fill placement requirements, including a clear definition of compacted layer thickness, we suggest 300 mm.
4. Compaction requirements. We suggest that a minimum and maximum density ratio be adopted to control any potential shrink swell of the clayey fill material and to limit the effect of fill material variability on the fill performance, we suggest 98 to 102 % standard.
5. Moisture control requirements. We consider that control on placement moisture variation should be adopted to control any potential shrink swell of the clayey fill material, we suggest moisture variation of +/- 2%.
6. Inspection and testing requirements, including a clear definition of:
 - a. Level of control testing, e.g. Level 1 as per AS3798.
 - b. Lot testing, this is an important aspect of earthworks control but often ignored in acceptance of the works.
 - c. Testing methodology.
 - d. Testing frequency.
7. Responsibilities of the contractor. We envisage that such responsibilities would include:
 - a. Undertake the earthworks in accordance with fill specification.
 - b. Seek approvals by the GITA as required by the fill specification, in particular prior to placing any new fill.
 - c. Responsibilities of the Geotechnical Inspection and Testing Authority (GITA). The fill specification should define:
 - d. The inspection and testing responsibilities of the GITA.
 - e. The reporting responsibilities of the GITA.



- f. The final certification responsibilities of the GITA. We note that the specification should require the GTA to certify that “all the earthworks have been documented and have been undertaken in accordance with the relevant fill specification”. It is not adequate just to refer to AS3798 Level 1.

The majority of the basement excavation material is likely to comprise Virgin Excavated Natural Material (VENM). For disposal purposes, it is likely the Residual Soil and Bedrock units (Laminate and Siltstone) are able to be validated as VENM. However, the Fill unit encountered can either be disposed as General Solid Waste or validated as Excavated Natural Material (ENM). Based on the Fill observed during the geotechnical investigation, we consider it likely that the existing fill will be able to be so validated, but this can only be done once the material is stockpiled on site during construction.

The most economical outcome may be to re-use the existing Fill on site as much as possible and dispose the VENM off site. VENM verification would be required during construction for material disposal.

The existing fill will be suitable for incorporating in any earthworks on site. We note that the earthwork contractor should go to considerable effort to segregate different materials and not dilute/contaminate the VENM with Fill.

5.4 Permanent and Temporary Batters

The excavation to construct the new building will be in proximity to existing buildings, vehicle and pedestrian pavements and utilities. Subject to the sensitivity and proximity of these elements, the excavation may require support and/or protection. This should be assessed on a case by case basis.

The batter slope angles shown in Table 6 are recommended for the design of batters up to a nominal 5 m height subject to the following recommendations:

- The batters shall be protected from erosion. Permanent batters will require face protection such as vegetation or shotcrete.
- Permanent batters shall be drained for a distance behind the faces at least equal to the height.
- Temporary batters shall not be left unsupported for more than 3 months without further advice, and inspection by a suitably experienced geotechnical engineer should be undertaken following significant rain events
- No buildings, surcharge loads or services should be located within 1 batter height of the crest.

If the conditions above cannot be met, further advice should be sought.


Where Fill is not engineered/controlled fill, batter slope angles should be assessed by a suitable experienced geotechnical engineer.

Exposed rock faces should be inspected by a geotechnical engineer or engineering geologist to assess the need for localised rock bolting to control adverse jointing in the Bedrock unit and shotcreting for overall face support and weather protection.

Table 6 – Batter Slope Angles

Unit	Temporary	Permanent
Engineered Fill	2H: 1V	2.5H: 1V
Residual Soil	1.5H: 1V	2H: 1V
Bedrock Class IV/V	0.5H: 1V	1.5H: 1V
Bedrock Class III	0.5H: 1V	1H: 1V

Steeper batters may be possibly subject to further advice, probably including inspection during construction and shotcreting and rock bolting etc.



5.5 Excavation Support

Permanent cuts in the Fill, Residual Soil and Bedrock units steeper than the recommended permanent batter slopes in Table 6 will need to be supported by some form of retaining structure.

The selection of the appropriate retention system is a matter of design. The designer should consider the following factors in making its selection:

- Technical factors
 - Performance
 - Ground conditions (this is addressed below with the design parameters)
 - Surcharge loading and
 - Proximity of structures, buildings and roads, etc.
- Non- technical factors
 - Cost (to build and to maintain)
 - Other constraints such as real estate, neighbouring site / boundary, aesthetics, legislation, etc.

The design of these structures should be based on the following geotechnical properties:

- Effective strength parameters in Table 7 when assessing the earth pressure on retaining structures
- A lateral pressure of 10 kPa for vertical cuts in the Bedrock units (Class III or better). This is to allow for blocks and rock wedges formed due to adverse defects that may exist within the unit.
- Water pressure (depending on the type of structure).

Note that design of retention systems may be based on either K_a or K_o earth pressures. Design using active earth pressures provides the minimum lateral earth pressure that must be supported to avoid failure and requires a wall that can rotate or translate to allow the pressures to reduce to these values (vertical and lateral movements up to 2% of height may occur, typical movements will be much less).

Where the design is based on K_o pressures, construction should be carefully controlled to avoid unwanted effects. It should be noted that designing for K_o pressures do not, of themselves, ensure that movement does not occur. Movements are controlled by the construction method, especially sequence.

Both surface and sub-surface drainage needs to be designed and constructed properly to prevent pore water pressures from building up behind the retaining walls and in the retained material. Otherwise, appropriate water pressures must be included in the design.

Where excavations are proposed in the vicinity of existing structures designers shall consider the effects of the excavation including horizontal and vertical deflections on the neighbouring structures.

If relying on passive support from embedment of piles into the Bedrock units. (e.g. cantilever piled wall or propped or anchored piled wall) the designer shall ignore the support provided in the upper 1.0 m of embedment and can adopt a lateral resistance of one third of the allowable bearing pressure (ABP) in Table 7.




Table 7 – Engineering Parameters of Inferred Geotechnical Units

Inferred Unit	Bulk Unit Weight (kN/m³)	Soil Effective Strength Parameters		Ultimate Bearing Pressure Under Vertical Centric Loading (kPa) ^{1, 2}	Allowable Bearing Pressure (ABP) Under Vertical Centric Loading (kPa) ^{1, 3}	Ultimate Shaft Adhesion (kPa) ⁴	Elastic Parameters	
		c' (kPa)	ϕ (deg)				Long Term Young Modulus (MPa)	Poisson's Ratio
Fill	18	0	30	N/A			10	0.3
Residual soil	18	0	30	450	150	N/A	15	0.3
Bedrock Class IV/V	22	10	30	3000	700	50	50	0.3
Bedrock Class III	22	N.A		6,000	2000	350	200	0.25
Bedrock Class II (or better)	22			30,000	3500	600	700	0.25

Notes: 1. Minimum plan dimension of 1.0 m and a minimum embedment depth of 0.5 m.
2. Ultimate values occur at large settlement (>5% of minimum footing dimensions).
3. End bearing pressure to cause settlement of <1% of minimum footing dimensions).
4. Clean socket of roughness category R2 or better.

5.6 Foundations

5.6.1 Preamble

In general, the designer should note the following with regards to foundation design for both piles and shallow pad footings:

- The bearing capacities provided are contingent on piles or footings being vertically and centrally loaded. Further advice should be sought if the footings are not vertically centrally loaded.
- Where adjacent foundation details differ (e.g. pile and pad, differing loads or ground conditions) differential settlement will need to be assessed.
- Deflections should be checked using the recommended elastic parameters in Table 7.

5.6.2 Shallow pad footings

Pad footings can be proportioned on the basis of an allowable bearing pressure (ABP) for centric vertical loads provided in Table 7.

We note that an allowable bearing pressure (ABP) is not a soil property. It depends on many factors such as the size of the footings, the embedment depth, the load direction and eccentricity, the stiffness of the footing, the adopted factor of safety (FOS), as well as the soil properties. As footings get bigger or deeper the capacity increases rapidly. As the load gains eccentricity or becomes inclined, the capacity reduces rapidly.

Settlements can be estimated using the elastic parameters provided in Table 7. When assessing the settlement of the shallow footings, the designer needs to consider the additional ground settlement due to the total building load on both shallow and deeper units. The differential settlement due to the building load shall also be assessed.

Foundations conditions at the proposed shallow pad footings locations should be inspected by a suitably qualified geotechnical engineer prior to the pouring of concrete.



5.6.3 Piles

We envisage that piles would be founded within the Bedrock unit.

Piles should be designed in accordance with the requirements in AS 2159 (2009), Piling – Design and Installation. The parameters provided in Table 7 may be adopted in the design of piles founded in Bedrock unit.

The designer should note the following with regards to the pile design:

- The ABP needs to be confirmed by a geotechnical engineer through pile inspections prior to pouring concrete
- Under permanent load, the contribution of side adhesion for soils including Fill and Residual Soil should be ignored
- Deflection should be checked using the recommended elastic parameters in Table 7
- Where adjacent foundation details differ (e.g., pile and pad, differing loads or ground conditions), differential settlement should also be assessed.

Should higher bearing capacities be required of the Bedrock, this may be available subject to further advice.

With regards to the pile design we recommend that:

- A geotechnical strength reduction factor, $\Phi_g = 0.60$ (AS2159 CL. 4.3.2) be adopted for a high redundancy system for an assessed average risk rating (ARR) between 2.5 and 3.0. This should be reviewed to suit the specific design and appropriate pile testing proposed by the structural designers in accord with the requirements of AS2159
- It may be possible to increase the pile reduction factors, if the details of the proposed pile installation procedures indicate a high level of quality control with regards to concrete placement, base cleanliness, etc.
- If a geotechnical strength reduction factor, $\Phi_g = 0.40$ is adopted then no pile testing will be required (AS2159 Clause 8.2.4 (b)).

5.7 Pavements

Subgrade CBR for pavement design depends on the material at the finished subgrade levels. Based on the CBR tests undertaken by PSM (refer to Table 1) we recommend a design subgrade CBR of 1.5% be adopted for the pavement design at site. Should a higher design CBR be required, further testing at specific locations may be required and further advice should be sought.

5.8 Corrosivity / Aggressivity

Table 4.8.1 of AS3600-2009 “Concrete Structures” provides criteria for exposure classification for concrete in sulphate soils based on sulphates in soil and groundwater, and pH of soil. According to the sulphate and pH testing completed, we assess the exposure classification for concrete in sulphate soils to be A2.

Table 6.4.2(C) of Australian Standard AS2159:2009, Piling – Design and Installation provides criteria for exposure classification for concrete piles based on sulfates in the soil and groundwater, soil and groundwater pH, and chlorides in groundwater. According to the soil sulfates and pH testing completed we assess the exposure classification for concrete piles in the soil to be mild for the site.


Table 6.5.2(C) of Australian Standard AS2159:2009, Piling – Design and Installation provides criteria for exposure classification for steel piles based on resistivity, soil and groundwater pH, and chlorides in soil and groundwater. On the basis of soil chlorides and pH testing completed we assess the exposure classification for steel piles in the soil to be non-aggressive for the site.

5.9 Dewatering

Where excavation below the water table is proposed for the basement, construction stage dewatering may be required.

We note that recent experience indicates that the New South Wales Office of Water (NoW) have been conditioning approval of basement excavations on the basis of the following:

- Temporary dewatering allowed during excavation. Permits will need to be sought for both extraction of the water and disposal.



- No inflows into the basement allowed in the permanent condition. That is the final basement needs to be watertight, i.e. tanked. Such a requirement results in the basement floor slab, and the walls needing to be designed for the full hydrostatic load below a maximum foreseeable water table. This requirement, if enforced by the regulatory authorities, may influence decisions regarding the feasibility of deep basement excavations. It is our experience that NoW may relax the requirement for tanking where monitoring of groundwater levels in combination with analysis of inflows in the permanent condition indicate yearly inflow into the excavation of less than 3 ML/yr and that the extraction of groundwater has no adverse impact on other groundwater users.
- The developments are usually conditioned on monitoring of groundwater levels, assessment and estimation of temporary inflows during construction, and assessment of effect on neighbouring structures.

Given the topography, we expect that a decent pump out system should suffice for basements excavation on this site.

PSM can provide advice on the above, but this is outside the scope of this report.

6 General

If at any time, the conditions are found to vary from those described in this report, further advice should be sought.

Please do not hesitate to contact the undersigned if you have any questions.

For and on behalf of
PELLS SULLIVAN MEYNINK



NGOC TUAN HOANG
GEOTECHNICAL ENGINEER



BERNARD SHEN
PRINCIPAL

Brisbane


35 Jeays Street
Bowen Hills QLD 4006
+61 7 3220 8300

Sydney

G3-56 Delhi Road
North Ryde NSW 2113
+61 2 9812 5000

Perth

Level 3 22 Delhi Street
West Perth WA 6005
+61 8 9462 8400





LEGEND

- APPROXIMATE CORED BOREHOLE LOCATION
- APPROXIMATE AUGERED BOREHOLE LOCATION
- SITE BOUNDARY



Pells Sullivan Meynink

JBS&G
Ryde Hospital
Denistone Rd, Eastwood NSW
Geotechnical Investigation
LOCALITY PLAN

PSM3828-002R

Figure 1



Photo 1 - Main internal road of the site looking South



Photo 2 - Carpark areas in the South of the site looking North



Pells Sullivan Meynink

**JBS&G
Ryde Hospital
Eastwood, NSW
GEOTECHNICAL INVESTIGATION
GENERAL SITE PHOTOS**

PSM3828-002R

Figure 2.1



Photo 3 - Carpark areas in the West of the site looking North



Photo 4 - Setting up the drilling rig -Hanjin D8




Pells Sullivan Meynink

**JBS&G
Ryde Hospital
Eastwood, NSW
GEOTECHNICAL INVESTIGATION
GENERAL SITE PHOTOS**

PSM3828-002R

Figure 2.2

BH 03



Notes:

1. Instrument elevation: 8.09 m BGL
2. Rainfall data source: BOM Website. SILO Australian Government, Eastwood Bowling Club (No: 66087)
3. Measured water level (using tape measure) on 17/05/2019: 3.01 m BGL
4. Data logger installed on 15/05/2019




Pells Sullivan Meynink

JBS&G
Ryde Hospital
Eastwood, NSW
GEOTECHNICAL INVESTIGATION
GROUNDWATER MONITORING - BH03

PSM3828-002R

Figure 3.1

BH 07



Notes:

1. Instrument elevation: 8.825 m BGL
2. Rainfall data source: BOM Website. SILO Australian Government, Eastwood Bowling Club (No: 66087)
3. Measured water level (using tape measure) on 17/05/2019: 2.70 m BGL
4. Data logger installed on 17/05/2019




Pells Sullivan Meynink

JBS&G
Ryde Hospital
Eastwood, NSW
GEOTECHNICAL INVESTIGATION
GROUNDWATER MONITORING - BH07

PSM3828-002R

Figure 3.2



◆ BH01, 0.5 m - 3.0 m, Silty Clay + BH03, 0.5 m - 1.9 m, Silty Clay - BH04, 0.5 m - 1.3 m, Silty Clay

■ BH07, 0.5 m - 3.0 m, Silty Clay ● BH10, 0.1 m - 2.9 m, Silty Sand ▲ BH13, 0.3 m - 3.5 m, Silty Clay



Pells Sullivan Meynink


JBS&G
Ryde Hospital
Eastwood, NSW
GEOTECHNICAL INVESTIGATION
ATTERBERG LIMITS - PLASTICITY CHART

PSM3828-002R

Figure 4

Appendix A

Geotechnical Engineering Borehole Logs





EXPLANATION SHEET BOREHOLE LOG

GENERAL

Method

Non-Cored Borehole
Auger
Hand Auger
Diamond Rotary
Percussion
Other

Coring Size

Cored Borehole	Nominal Core Diameter (mm)
NMLC	51.9
BQ	36.5
BQ3	33.5
NQ	47.6
NQ3	45.1
HQ	63.5
HQ3	61.1
PQ	85
PQ3	83.1
Diatube	Variable
Other	-





Testing

Symbol	Description
UCS	Uniaxial Compressive Strength
TXL	Triaxial Test
BT	Brazilian Test
DT	Direct Tensile
SD	Slake Durability
Packer	Rock Mass Permeability

Samples

Symbol	Description
U50	50 mm undisturbed tube sample
D	Disturbed sample
Bs	Bulk sample

Water

Symbol	Description
	Water level
	Water inflow
	Complete water loss
	Partial water loss

SOIL DESCRIPTIONS

Unified Soil Classification System (USCS)

Major Divisions			Symbol	Typical Names
Coarse-Grained Soils More than 50% coarser than 0.075mm	Gravels (more than 50% coarser than 2mm)	Clean Gravels	GW	Well-graded gravels and gravel-sand mixtures, little or no fines.
			GP	Poorly graded gravels and gravel-sand mixtures, little or no fines.
		Gravels With Fines	GM	Silty gravels, gravel-sand-silt mixtures.
			GC	Clayey gravels. gravel-sand-clay mixtures.
	Sands (more than 50% of coarse fraction finer than 2mm)	Clean Sands	SW	Well-graded sands and gravelly sands, little or no fines.
			SP	Poorly graded sands and gravelly sands, little or no fines.
		Sand With Fines	SM	Silty sands, sand-silt mixture.
			SC	Clayey sands, sand-clay mixtures.
Fine-Grained Soils 50% or more finer than 0.075mm	Silts and Clays Liquid limit 50% or less		ML	Inorganic silts, very fine sands, rock flour silty or clayey fine sands.
			CL	Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays, lean clays.
			OL	Organic silts and silty clays of low plasticity.
	Silts and Clays Liquid limit greater than 50%		MH	Inorganic silts, micaceous or diatomaceous fine sands or silts, elastic silts.
			CH	Inorganic clays of high plasticity, fat clays.
			OH	Organic clays of medium to high plasticity.
			Highly Organic Soils	

Moisture Condition

Term	Symbol
Dry	D
Moist	M
Wet	W
Wet at Plastic Limit	WP
Wet at Liquid Limit	WL

Strength

COHESIVE SOILS are described in terms of undrained shear strength, colour and structure with comments on minor constituents or apparent special features. Undrained shear strength is measured by hand penetrometer or determined by laboratory testing or estimated from experience. Classification in terms of undrained shear strength is as follows:

Term	Symbol	Description for Field Estimation	Shear Strength (kPa)	UCS (kPa)
Very Soft	VS	Easily penetrated several centimetres by fist.	<12	<25
Soft	S	Easily penetrated several centimetres by thumb. Can be moulded by light finger pressure.	12-25	25-50
Firm	F	Can be penetrated by thumb with moderate effort. Can be moulded by strong finger pressure.	25-50	50-100
Stiff	ST	Readily indented by thumb.	50-100	100-200
Very Stiff	VST	Readily indented by thumbnail.	100-200	200-400
Hard	H	Indented with difficulty by thumbnail	>200	>400

NON-COHESIVE SOILS are described in terms of density, colour, with comments on minor constituents or special features. Density (density index) is generally based on standard penetration testing (AS1289 Method 6.3.1), or other forms of penetration testing. Terms used in describing density are set out below:

Term	Symbol	Density Index	SPT N Values
Very Loose	VL	<15%	<5
Loose	L	15-35 %	5-10
Medium Dense	MD	35-65 %	10-30
Dense	D	65-85 %	30-50
Very Dense	VD	>85 %	>50

ROCK DESCRIPTIONS

Weathering

Term	Symbol	Description
Fresh	FR	Rock substance unaffected by weathering.
Slightly Weathered	SW	Rock substance affected by weathering to the extent that partial staining or partial discolouration of the rock substance usually by limonite has taken place. The colour and texture of the fresh rock is recognisable; strength properties are essentially those of the fresh rock substance.
Moderately Weathered	MW	Rock substance affected by weathering to the extent staining extends throughout whole of the rock substance and the original colour of the fresh rock is no longer recognisable.
Highly Weathered	HW	Rock substance affected by weathering to the extent that limonite staining or bleaching affects the whole of the rock substance and signs of chemical or physical decomposition of individual minerals are usually evident. Porosity and strength may be increased or decreased when compared to the fresh rock substance, usually as a result of the leaching or deposition of iron. The colour and strength of the original fresh rock substance is no longer recognisable.
Extremely Weathered	EW	Rock substance affected by weathering to the extent that the rock exhibits soil properties, i.e. it can be remoulded and can be classified according to the Unified Soil Classification System, but the texture of the original rock is still evident.

Strength

Term	Symbol	Description for Field Estimation	Point Load Index I_{s50} (MPa)
Very Low	VL	Material crumbles under firm blows with sharp end of pick; can be peeled with a knife; pieces up to 30 mm thick can be broken by finger pressure.	<0.1
Low	L	Easily scored with a knife; indentations 1 mm to 3 mm show with firm blows of a pick point; has a dull sound under hammer. Pieces of core 150 mm long by 50 mm diameter may be broken by hand. Sharp edges of core may be friable and break during handling.	0.1 to 0.3
Medium	M	Readily scored with a knife; a piece of core 150 mm long by 50 mm diameter can be broken by hand with difficulty.	0.3 to 1.0
High	H	A piece of core 150mm long by 50mm cannot be broken by hand but can be broken by a pick with a single firm blow; rock rings under hammer.	1 to 3
Very High	VH	Hand specimen breaks after more than one blow of a pick; rock rings under hammer.	3 to 10
Extremely High	EH	Specimen requires many blows with geological pick to break; rock rings under hammer.	>10


Defect Description

Order of description: type, inclination, shape, roughness, infill type, infill thickness, number

Defect Type

Symbol	Description
CL	Clay Seam
FL	Fault - fracture along which displacement is recognisable.
SR	Shear - a fracture along which movement has taken place but no displacement is recognisable. Evidence for movement may be slickensides, polishing and/or clay gouge.
SH	Sheared Zone - zone of multiple closely spaced fracture planes with roughly parallel planar boundaries usually forming blocks of lenticular or wedge shaped intact material. Fractures are typically smooth, polished or slickensided; and curved.
BG	Bedding parting - arrangement in layers of mineral grains or crystals parallel to surface of deposition along which a continuous observable parting occurs.
BSH	Bedding plane shear - a shear formed along a bedding plane
JN	Joint - a single fracture across which rock has little or no tensile strength and is not obviously related to rock fabric.
CN	Contact - surface between two lithologies.
SC	Schistosity - plane formed by the preferred orientation of the constituent minerals in a parallel arrangement in a coarse grained rock which has undergone regional metamorphism (schist).
CV	Cleavage - plane of mechanical fracture in a rock normally sufficiently closely spaced to form parallel-sided slices.
FO	Foliation
CZ	Crushed Zone - zone with roughly parallel, planar boundaries (commonly slickensided) containing disoriented usually angular rock fragments of variable size often in a soil matrix.
VN	Vein - fracture in which a tabular or sheet-like body of minerals have been intruded.
DK	Dyke - Igneous intrusion - often weathered and altered to a clay like substance.
DZ	Decomposed Zone - zone of any shape but commonly with parallel planar boundaries containing moderately to gradational boundaries into fresher rock.
FZ	Fractured Zone - a zone of closely spaced defects (mainly joints, bedding, cleavage and/or schistosity) comprised of core lengths in the order of 50 mm or less.

Standard Defect Symbols



Roughness Colour Code (for summary log)



Shape

Term	Symbol	Description
Planar	PL	Forms a continuous plane without variation in orientation.
Curved	CU	Has a gradual change in orientation.
Undulating	UN	Has a wavy surface shape.
Stepped	ST	Has one or more well defined steps
Irregular	IR	Many changes of orientation.

Roughness

Term	Symbol	Description
Slickensided or polished	Ro1	Very smooth, reflects light.
Smooth	Ro2	Roughness not detected with finger.
Defined ridges	Ro3	Sandpaper feel (fine to medium sandpaper).
Small steps	Ro4	Sandpaper feel (medium to coarse sandpaper).
Very rough	Ro5	Very well defined ridges and/or steps.

Infill Type

Symbol	Description
KL	Clean
CA	Calcite
CB	Carbonaceous
CHL	Chlorite
FE	Iron oxide
QZ	Quartz
MG	Manganese
SU	Sulphides
SE	Sericite
RF	Rock fragments
G	Gravel
S	Sand
Z	Silt
CL	Clay

Infill Thickness

Where infilling is present, the thickness of infill is recorded using the following convention:


ST Iron oxide staining of less than 1 mm
 VN Veneer coating of less than 1 mm

If the infilling is greater than 1 mm, the actual thickness of infill is recorded in millimeters.

If infill is not present, a dash (-) is recorded

Number

Number of defects with similar characteristics.



Project No.: PSM3828

PSM 3.02.1 LIB.GLB Log PSM AU NONCORE BH NZAU PSM3828.GPJ <<DrawingFile>> 13/06/2019 09:59 10.00.00.69 Dataol Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 Pri: PSM 3.02.1 2019-03-06



Borehole ID

BH01

Page 2 of 3

Engineering Log - Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 14/05/2019											
Project Name: Ryde Hospital		Completed: 14/05/2019											
Hole Location: Eastwood, NSW		Logged By: NTH											
Hole Position: 323083.0 m E 6258892.0 m N MGA94 Zone 56		Checked By: BS											
Drill Model and Mounting: Hanjin- D8		Inclination: -90°											
Barrel Type and Length: Triple Tube 3 m		RL Surface: No survey											
		Datum: AHD Operator: Rockwell											
Drilling Information		Rock Substance		Rock Mass Defects									
Method	Water	RQD (%)	Samples and Field Tests	WPT (Lugeons)	RL (m)	Depth (m)	Graphic Log	Material Description ROCK NAME: particle/grain characteristics, colour, fabric/texture, inclusions or minor components, moisture, mineral composition, alteration	Weathering XW HW MW SW FR	Strength Is(50) ● - Axial ○ - Diametral VL 0.1 L 0.3 M 1 H 3 VH 10 EH	Defect Spacing (mm) <20 60 200 600 1000	Defect Descriptions / Comments Description, alpha/beta, infilling or coating, shape, roughness, thickness, other	
						1							
						2							
						3							
								Continued from non-cored borehole sheet					
						4		LAMINITE: pale grey & red, orange banding, bedding fabric visible, well developed, iron staining.					JT, 70°, RF, IR, RF
													SM, 0°, CL, PR, RF, +30 mm
													JT, 23°, FE SN, PR, RF
								NO CORE 370mm					
Method		Water		Weathering		Defect Type		Infilling/Coating		Roughness			
AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore HQ3- Wireline core (63.5 mm) PQ3- Wireline core (85.0 mm) SPT- Standard penetration test PT - Push tube WPT - Water pressure test		▽ Inflow △ Partial Loss ▲ Complete Loss Graphic Log/Core Loss Core recovered (hatching indicates material) No core recovery		XW - Extremely Weathered HW - Highly Weathered MW - Moderately Weathered SW - Slightly Weathered FR - Fresh Strength VL - Very Low L - Low M - Medium H - High VH - Very High EH - Extremely High		FT - Fault SS - Shear Surface SZ - Shear Zone BP - Bedding parting SM - Seam IS - Infilled Seam JT - Joint CO - Contact CZ - Crushed Zone VN - Vein FZ - Fracture Zone BSH - Bedding Shear DB - Drilling Break		CN - Clean SN - Stain VN - Veneer CO - Coating RF - Rock fragments G - Gravel S - Sand Z - Silt CA - Calcite CL - Clay FE - Iron QZ - Quartz X - Carbonaceous		SL - Slickensided POL - Polished S - Smooth RF - Rough VR - Very Rough Shape PR - Planar CU - Curved UN - Undulating ST - Stepped IR - Irregular			



Borehole ID

BH01

Page 3 of 3

Engineering Log - Cored Borehole

Project No.: PSM3828

Client: JBS&G
Project Name: Ryde Hospital
Hole Location: Eastwood, NSW
Hole Position: 323083.0 m E 6258892.0 m N MGA94 Zone 56

Commenced: 14/05/2019
Completed: 14/05/2019
Logged By: NTH
Checked By: BS

Drill Model and Mounting: Hanjin- D8 Inclinometer: -90°
Barrel Type and Length: Triple Tube 3 m Bearing: Datum: AHD Operator: Rockwell

Drilling Information						Rock Substance										Rock Mass Defects									
Method	Water	RQD (%)	Samples and Field Tests	WPT (Lugeons)	RL (m)	Depth (m)	Graphic Log	Material Description	Weathering				Strength Is(50)				Defect Spacing (mm)	Defect Descriptions / Comments							
								ROCK NAME: particle/grain characteristics, colour, fabric/texture, inclusions or minor components, moisture, mineral composition, alteration	XW	HW	MW	SW	FR	VL	L	M	H	VH	EH	<20	200	600	1000		
NMLC	Not Observed	67						LAMINITE: pale grey & red, orange banding, bedding fabric visible, well developed, iron staining.																	BP, 21°, FE SN, CU, RF
			5.85m Is(50) d=0 a=0.1 MPa			6																			JT, 14°, CN, PR, RF
		61	6.46m Is(50) d=0 a=0 MPa			7		LAMINITE: dark grey & orange, white banding, well developed, 70%-80% siltstone, 20%-30% sandstone, thin fine-grained sandstone laminations. Some clay bands (dark grey & black and medium plasticity), iron staining.																	SM, 0°, CL, PR, S, +50 mm BP, 10°, Fe & Clay, UN, RF CZ, 0°, RF, +20 mm SM, 0°, CL, PR, S, +50 mm SM, 0°, CL, PR, S, +40 mm CO, 0°, FE, PR, RF SM, 0°, CL, PR, S, +20 mm SM, 0°, CL, PR, S, +20 mm BP, 3°, FE SN, PR, S
		59	7.64m Is(50) d=0.1 a=0.1 MPa			8																			JT, 79°, FE SN, PR, RF BP, 3°, FE SN, PR, RF SM, 0°, CL, RPR, S, +20 mm SM, 0°, Fe & Clay SN, PR, RF, +30 mm SM, 0°, CL, PR, S, +40 mm CZ, 5°, RF, +20 mm JT, 52°, FE SN, PR, RF JT, 21°, FE SN, PR, S JT, 62°, FE SN, PR, RF JT, 47°, FE SN, PR, S BP, 3°, FE SN, PR, S SM, 7°, CL, PR, S, +10 mm FZ, 0°, RF, PR, S, +20 mm SM, 0°, SM, PR, S, +20 mm BP, 4°, FE SN, PR, RF SM, 5°, CL, PR, S, +10 mm SM, 0°, CL, PR, S, +20 mm SM, 0°, CL, PR, S, +30 mm BP, 0°, FE SN, PR, RF BP, 12°, CL, PR, S BP, 7°, FE SN, PR, S BP, 4°, RF, PR, S BP, 0°, FE SN, PR, S
			8.86m Is(50) d=0.3 a=0.1 MPa			9		8.3m - Becomes pale grey & black with black banding, 60%-70% siltstone, 30%-40% sandstone.																	BP, 0°, CN, PR, S
								Hole Terminated at 9.00 m Target depth, hole grouted to surface and reinstated																	JT, 23°, FE SN, PR, RF
Method			Water			Weathering			Defect Type			Infilling/Coating			Roughness										
AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore HQ3- Wireline core (63.5 mm) PQ3- Wireline core (85.0 mm) SPT- Standard penetration test PT - Push tube WPT - Water pressure test			▽ Inflow △ Partial Loss ▲ Complete Loss			XW - Extremely Weathered HW - Highly Weathered MW - Moderately Weathered SW - Slightly Weathered FR - Fresh Strength VL - Very Low L - Low M - Medium H - High VH - Very High EH - Extremely High			FT - Fault SS - Shear Surface SZ - Shear Zone BP - Bedding parting SM - Seam IS - Infilled Seam JT - Joint CO - Contact CZ - Crushed Zone VN - Vein FZ - Fracture Zone BSH - Bedding Shear DB - Drilling Break			CN - Clean SN - Stain VN - Veneer CO - Coating RF - Rock fragments G - Gravel S - Sand Z - Silt CA - Calcite CL - Clay FE - Iron OZ - Quartz X - Carbonaceous			SL - Slickensided POL - Polished S - Smooth RF - Rough VR - Very Rough Shape PR - Planar CU - Curved UN - Undulating ST - Stepped IR - Irregular										
			Graphic Log/Core Loss																						
			Core recovered (hatching indicates material) No core recovery																						

Logged in accordance with AS 1726:2017 Geotechnical site investigations



Borehole ID

BH02

Page 1 of 4

Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client:	JBS&G	Commenced:	14/05/2019
Project Name:	Ryde Hospital	Completed:	14/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323120.0 m E 6258898.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Hole Diameter:	125 mm	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information				Soil Description						Observations				
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
AD/V		N		SPT 1.00-1.45 m 18,13,Refusal			1		CI-ML	ASPHALT - 200m : black & dark grey	D			0.00: PAVEMENT
									CI-ML	Silty CLAY with gravel: medium plasticity, dark brown & red; gravel sub-angular up to 5mm.	St to VSt			0.20: INFERRED FILL
AD/T		N	Not Observed				2			Silty CLAY: medium plasticity, pale grey & red.	VSt			0.50: INFERRED RESIDUAL SOIL
										LAMINITE: pale grey, brown & orange, extremely weathered, extremely low strength, iron staining.				1.00: SPT recovery 260mm
							3			LAMINITE: pale grey & orange, highly weathered, very low strength to low strength, orange banding, bedding fabric visible, well developed, iron staining.	D			1.20: V-bit refusal
														1.40: INFERRED BEDROCK
							4				H			4.00: Rootlets observed
										4.5m - Becomes dark brown				

Method AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	Penetration No resistance Refusal	Water Inflow Partial Loss Complete Loss	Samples and Tests U - Undisturbed Sample D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	Moisture Condition D - Dry M - Moist W - Wet	Consistency/Relative Density VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact
---	--	---	---	--	--



Borehole ID

BH02

Page 2 of 4

Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 14/05/2019												
Project Name: Ryde Hospital		Completed: 14/05/2019												
Hole Location: Eastwood, NSW		Logged By: NTH												
Hole Position: 323120.0 m E 6258898.0 m N MGA94 Zone 56		Checked By: BS												
Drill Model and Mounting: Hanjin- D8		Inclination: -90°												
Hole Diameter: 125 mm		RL Surface: No survey												
		Bearing: Datum: AHD Operator: Rockwell												
Drilling Information				Soil Description				Observations						
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
AD/T	N	Not Observed					6			LAMINITE: pale grey & orange, highly weathered, very low strength to low strength, orange banding, bedding fabric visible, well developed, iron staining. (continued)	D			
							6.4m - Becomes dark grey & brown			H				
							LAMINITE: dark grey & brown, moderately weathered to slightly weathered, very low strength to low strength, white banding, well developed, 80%-90% siltstone, 10%-20% sandstone, thin fine-grained sandstone laminations, iron staining.							
							7.3m to 8.5m - Multiple clay bands (dark brown, black & high plasticity)	M						
							9			Continued on cored borehole sheet				

Method
AD/T - Auger drilling TC bit
AD/V - Auger drilling V bit
WB - Washbore
SPT - Standard penetration test
PT - Push tube
AS - Auger Screwing


Penetration
 No resistance
 Refusal

Water
 Inflow
 Partial Loss
 Complete Loss

Samples and Tests
U - Undisturbed Sample
D - Disturbed Sample
SPT - Standard Penetration Test
ES - Environmental Sample
TW - Thin Walled
LB - Large Disturbed Sample

Moisture Condition
D - Dry
M - Moist
W - Wet

Consistency/Relative Density
VS - Very soft
S - Soft
F - Firm
St - Stiff
VSt - Very stiff
H - Hard
VL - Very loose
L - Loose
MD - Medium dense
D - Dense
VD - Very dense
Ce - Cemented
C - Compact



Project No.: PSM3828

```
PSM 3.02.1 LIB GLB Log PSM AU CORE BH PSM3828.GPJ <<DrawingFile>> 13/06/2019 10:02 10.00.00.69 DataGel Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 PSM 3.02.1 2019-03-06
```



Borehole ID

BH02

Page 4 of 4

Engineering Log - Cored Borehole

Project No.: PSM3828

Client:	JBS&G	Commenced:	14/05/2019
Project Name:	Ryde Hospital	Completed:	14/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323120.0 m E 6258898.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Barrel Type and Length:	Triple Tube 3 m	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information							Rock Substance													Rock Mass Defects						
Method	Water	RQD (%)	Samples and Field Tests	WPT (Lugeons)	RL (m)	Depth (m)	Graphic Log	Material Description	Weathering				Strength Is(50)					Defect Spacing (mm)			Defect Descriptions / Comments					
								ROCK NAME: particle/grain characteristics, colour, fabric/texture, inclusions or minor components, moisture, mineral composition, alteration	XW	HW	MW	SW	FR	VL	0.1	0.3	1	3	10	EH	<20	60	200	600	1000	
NMLC	Not Observed	98	10.11m Is(50) d=0.1 a=0.5 MPa 10.79m Is(50) d=0.1 a=0.1 MPa			11		LAMINITE: pale grey & black, black banding, very well developed, 60%-70% siltstone, 30%-40% sandstone, thin fine-grained siltstone laminations.(continued)																		BP, 7°, CN, PR, S CZ, 0°, RF, +50 mm BP, 0°, CN, PR, S BP, 0°, CL, PR, S
						12		Hole Terminated at 11.27 m Target depth, hole grouted to surface and reinstated																		
						13																				
						14																				

Method	Water	Weathering	Defect Type	Infilling/Coating	Roughness
AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore HQ3- Wireline core (63.5 mm) PQ3- Wireline core (85.0 mm) SPT- Standard penetration test PT - Push tube WPT - Water pressure test	▽ Inflow △ Partial Loss ▲ Complete Loss Graphic Log/Core Loss	XW - Extremely Weathered HW - Highly Weathered MW - Moderately Weathered SW - Slightly Weathered FR - Fresh Strength VL - Very Low L - Low M - Medium H - High VH - Very High EH - Extremely High	FT - Fault SS - Shear Surface SZ - Shear Zone BP - Bedding parting SM - Seam IS - Infilled Seam JT - Joint CO - Contact CZ - Crushed Zone VN - Vein FZ - Fracture Zone BSH - Bedding Shear DB - Drilling Break	CN - Clean SN - Stain VN - Veneer CO - Coating RF - Rock fragments G - Gravel S - Sand Z - Silt CA - Calcite CL - Clay FE - Iron QZ - Quartz X - Carbonaceous	SL - Slickensided POL - Polished S - Smooth RF - Rough VR - Very Rough Shape PR - Planar CU - Curved UN - Undulating ST - Stepped IR - Irregular



Borehole ID

BH03

Page 1 of 3

Engineering Log - Non Cored Borehole


Project No.: PSM3828

Client:	JBS&G	Commenced:	15/05/2019
Project Name:	Ryde Hospital	Completed:	15/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323214.0 m E 6258884.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Hole Diameter:	125 mm	Bearing:		Datum:	AHD	Operator:	Rockwell


Drilling Information							Soil Description							Observations		
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations		
AD/V	N	Not Observed		CBR 0.50-1.90 m SPT 1.00-1.45 m 2,4,5 N=17			1		CI-CH	ASPHALT - 100m : black & dark grey	D			0.00: PAVEMENT 0.10: INFERRED FILL 0.90: Rootlets observed 1.00: SPT recovery 380mm 1.30: INFERRED RESIDUAL SOIL 1.85: SPT recovery 150mm 1.90: INFERRED BEDROCK		
										Silty CLAY with gravel: medium to high plasticity, dark brown & black; gravel sub-angular up to 5mm.					St	
										Silty CLAY: high plasticity, dark brown, black & orange; trace of rootlets.						M
										1.8m - Becomes pale grey						
				SPT 1.85-2.00 m 17,Refusal			2		CH-MH	LAMINITE: pale grey, orange & red, extremely weathered, extremely low strength., iron staining.	H					
										Continued on cored borehole sheet						
							3									
							4									

Method	Penetration	Water	Samples and Tests	Moisture Condition	Consistency/Relative Density
AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	No resistance Refusal	Inflow Partial Loss Complete Loss	U - Undisturbed Sample D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	D - Dry M - Moist W - Wet	VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact



Project No.: PSM3828

```
PSM 3.02.1 LIB GLB Log PSM AU CORE BH PSM3828.GPJ <<DrawingFile>> 13/06/2019 10:02 10.00.00.69 DataGel Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 PSM 3.02.1 2019-03-06
```

Project No.: PSM3828

```
PSM 3.02.1 LIB GLB Log PSM AU CORE BH PSM3828.GPJ <<DrawingFile>> 13/06/2019 10:02 10.00.00.69 DataGel Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 PSM 3.02.1 2019-03-06
```




Borehole ID

BH04

Page 1 of 3

Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client:	JBS&G	Commenced:	16/05/2019
Project Name:	Ryde Hospital	Completed:	16/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323192.0 m E 6258865.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Hole Diameter:	125 mm	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information							Soil Description							Observations
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
AD/V		N	Not Observed	CBR 0.50-1.30 m SPT 1.00-1.45 m 5,32,Refusal			1			ASPHALT - 200m : black & dark grey	D			0.00: PAVEMENT
									CI-ML	Silty CLAY with gravel: medium plasticity, dark brown, red & black; gravel sub-angular up to 5mm; trace of rootlets.		St		0.20: INFERRED FILL
									CI-CH	Silty CLAY: medium to high plasticity, dark brown, red & orange; trace of rootlets.	M	VSt	x	0.80: INFERRED RESIDUAL SOIL 1.00: SPT recovery 340mm 1.10: Rootlets observed
								1.3m - Becomes pale grey & orange LAMINITE: pale grey, orange & red, extremely weathered, extremely low strength., iron staining. Continued on cored borehole sheet			H		x	1.35: INFERRED BEDROCK
							2							
							3							
							4							

Method
AD/T - Auger drilling TC bit
AD/V - Auger drilling V bit
WB - Washbore
SPT - Standard penetration test
PT - Push tube
AS - Auger Screwing


Penetration

Water
▽ Inflow
▽ Partial Loss
◄ Complete Loss

Samples and Tests
U - Undisturbed Sample
D - Disturbed Sample
SPT - Standard Penetration Test
ES - Environmental Sample
TW - Thin Walled
LB - Large Disturbed Sample

Moisture Condition
D - Dry
M - Moist
W - Wet

Consistency/Relative Density
VS - Very soft
S - Soft
F - Firm
St - Stiff
VSt - Very stiff
H - Hard
VL - Very loose
L - Loose
MD - Medium dense
D - Dense
VD - Very dense
Ce - Cemented
C - Compact



Project No.: PSM3828

```
PSM 3.02.1 LIB GLB Log PSM AU CORE BH PSM3828.GPJ <<DrawingFile>> 13/06/2019 10:02 10.00.00.69 DataGel Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 PSM 3.02.1 2019-03-06
```



Borehole ID

BH04

Page 3 of 3

Engineering Log - Cored Borehole

Project No.: PSM3828

Client:	JBS&G	Commenced:	16/05/2019
Project Name:	Ryde Hospital	Completed:	16/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323192.0 m E 6258865.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Barrel Type and Length:	Triple Tube 3 m	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information						Rock Substance										Rock Mass Defects										
Method	Water	RQD (%)	Samples and Field Tests	WPT (Lugeons)	RL (m)	Depth (m)	Graphic Log	Material Description ROCK NAME: particle/grain characteristics, colour, fabric/texture, inclusions or minor components, moisture, mineral composition, alteration	Weathering					Strength Is(50) ● - Axial ○ - Diametral					Defect Spacing (mm)			Defect Descriptions / Comments Description, alpha/beta, infilling or coating, shape, roughness, thickness, other				
NMLC	Not Observed	70	5.25m Is(50) d=0 a=0.1 MPa					LAMINITE: pale grey & orange, orange banding, bedding fabric visible, well developed. Some clay bands (pale & dark grey and medium plasticity), iron staining. (continued)	XW	HW	MW	SW	FR	VL	L	M	H	VH	EH	<20	80	200	600	1000	BP, 0°, RF, +20 mm BP, 0°, FE SN, PR, S	
		81	6.79m Is(50) d=0.1 a=0.2 MPa			6	5.7m - Becomes dark grey LAMINITE: dark grey & orange, orange banding & white banding, well developed, 80%-90% siltstone, 10%-20% sandstone, thin fine-grained sandstone laminations, iron staining.																	BP, 0°, FE SN, PR, S BP, 3°, FE SN, PR, S BP, 0°, Fe & Clay SN, PR, S BP, 0°, FE SN, PR, S JT, 27°, FE SN, PR, S JT, 87°, FE SN, PR, S		
																										BP, 13°, FE SN, PR, S JT, 29°, FE SN, PR, S
			7.53m Is(50) d=0.1 a=0.2 MPa			7	6.5m - Becomes pale grey & black with black banding, 70%-80% siltstone, 20%-30% sandstone																	BP, 0°, FE SN, PR, S JT, 49°, FE SN, PR, S BP, 0°, FE SN, PR, S		
			8.30m Is(50) d=0.2 a=0.3 MPa			8																			SM, 0°, CL, PR, S, +20 mm SM, 0°, CL, PR, S, +10 mm CZ, 0°, RF, +10 mm BP, 0°, FE SN, PR, S CO, 0°, CL, PR, S	
						9		Hole Terminated at 8.40 m Target depth, hole grouted to surface and reinstated																		

Method
AD/T - Auger drilling TC bit
AD/V - Auger drilling V bit
WB - Washbore
HQ3- Wireline core (63.5 mm)
PQ3- Wireline core (85.0 mm)
SPT- Standard penetration test
PT - Push tube

WPT - Water pressure test

Water
▽ Inflow
△ Partial Loss
▲ Complete Loss

Graphic Log/Core Loss
Core recovered (hatching indicates material)
No core recovery

Weathering
XW - Extremely Weathered
HW - Highly Weathered
MW - Moderately Weathered
SW - Slightly Weathered
FR - Fresh

Strength
VL - Very Low
L - Low
M - Medium
H - High
VH - Very High
EH - Extremely High

Defect Type
FT - Fault
SS - Shear Surface
SZ - Shear Zone
BP - Bedding parting
SM - Seam
IS - Infilled Seam
JT - Joint
CO - Contact
CZ - Crushed Zone
VN - Vein
FZ - Fracture Zone
BSH - Bedding Shear
DB - Drilling Break

Infilling/Coating
CN - Clean
SN - Stain
VN - Veneer
CO - Coating
RF - Rock fragments
G - Gravel
S - Sand
Z - Silt
CA - Calcite
CL - Clay
FE - Iron
QZ - Quartz
X - Carbonaceous

Roughness
SL - Slickensided
POL - Polished
S - Smooth
RF - Rough
VR - Very Rough

Shape
PR - Planar
CU - Curved
UN - Undulating
ST - Stepped
IR - Irregular



Borehole ID

BH05

Page 1 of 3


Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 16/05/2019	
Project Name: Ryde Hospital		Completed: 16/05/2019	
Hole Location: Eastwood, NSW		Logged By: NTH	
Hole Position: 323107.0 m E 6258857.0 m N MGA94 Zone 56		Checked By: BS	
Drill Model and Mounting: Hanjin- D8		Inclination: -90°	
Hole Diameter: 125 mm		RL Surface: No survey	
		Datum: AHD	
		Operator: Rockwell	

Drilling Information				Soil Description						Observations				
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
AD/V	N	N	Not Observed				1		CL-ML	ASPHALT - 100m : black & dark grey	D			0.00: PAVEMENT
									CL-ML	Silty CLAY with gravel: low plasticity, dark brown & grey; gravel sub-angular up to 10mm; trace of rootlets.	St		0.10: INFERRED FILL	
AD/T	N	N	Not Observed				2		CL-ML	Silty CLAY: low plasticity, dark brown & grey; ripped siltstone, iron stone & trace of rootlets.	M	VSt		0.50: INFERRED RESIDUAL SOIL
										0.9m - Becomes pale grey & orange			0.60: Rootlets observed	
							3			LAMINITE: pale grey & orange, extremely weathered, extremely low strength, iron staining.	D	H		0.90: V-bit refusal
							4			Continued on cored borehole sheet				1.20: INFERRED BEDROCK

Method AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	Penetration No resistance Refusal	Water Inflow Partial Loss Complete Loss	Samples and Tests U - Undisturbed Sample D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	Moisture Condition D - Dry M - Moist W - Wet	Consistency/Relative Density VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact
---	--	---	---	--	--



Project No.: PSM3828

PSM 3.02.1 LIB GLB Log PSM AU CORE BH PSM3828.GPJ <<DrawingFile>> 13/06/2019 10:02 10.00.00.69 DatGel Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 Pri: PSM 3.02.1 2019-03-06



Borehole ID

BH05

Page 3 of 3

Engineering Log - Cored Borehole

Project No.: PSM3828

Client:	JBS&G	Commenced:	16/05/2019
Project Name:	Ryde Hospital	Completed:	16/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323107.0 m E 6258857.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Barrel Type and Length:	Triple Tube 3 m	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information						Rock Substance										Rock Mass Defects					
Method	Water	RQD (%)	Samples and Field Tests	WPT (Lugeons)	RL (m)	Depth (m)	Graphic Log	Material Description	Weathering				Strength Is(50)				Defect Spacing (mm)	Defect Descriptions / Comments			
								ROCK NAME: particle/grain characteristics, colour, fabric/texture, inclusions or minor components, moisture, mineral composition, alteration	XW	HW	MW	SW	FR	VL 0.1	L 0.3	M 1	H 3	VH 10	EH		
NMLC	Not Observed	94						LAMINITE: pale grey & brown, white banding, well developed, 60%-70% siltstone, 30%-40% sandstone, fine-grained sandstone laminations, iron staining.(continued)													
			5.54m Is(50) d=0.1 a=0.5 MPa			6															
		100	6.43m Is(50) d=0.2 a=0.2 MPa			7		7.2m - Becomes dark grey & black with white banding, 80%-90% siltstone, 10%-20% sandstone													
			7.83m Is(50) d=0.1 a=0.5 MPa			8															
			8.34m Is(50) d=0.1 a=0.2 MPa					Hole Terminated at 8.45 m Target depth, hole grouted to surface and reinstated													
						9															

Method

AD/T - Auger drilling TC bit
AD/V - Auger drilling V bit
WB - Washbore
HQ3- Wireline core (63.5 mm)
PQ3- Wireline core (85.0 mm)
SPT- Standard penetration test
PT - Push tube

WPT - Water pressure test

Water

▽ Inflow
△ Partial Loss
▲ Complete Loss

Graphic Log/Core Loss

Core recovered (hatching indicates material)
No core recovery

Weathering

XW - Extremely Weathered
HW - Highly Weathered
MW - Moderately Weathered
SW - Slightly Weathered
FR - Fresh

Strength

VL - Very Low
L - Low
M - Medium
H - High
VH - Very High
EH - Extremely High

Defect Type

FT - Fault
SS - Shear Surface
SZ - Shear Zone
BP - Bedding parting
SM - Seam
IS - Infilled Seam
JT - Joint
CO - Contact
CZ - Crushed Zone
VN - Vein
FZ - Fracture Zone
BSH - Bedding Shear
DB - Drilling Break

Infilling/Coating

CN - Clean
SN - Stain
VN - Veneer
CO - Coating
RF - Rock fragments
G - Gravel
S - Sand
Z - Silt
CA - Calcite
CL - Clay
FE - Iron
QZ - Quartz
X - Carbonaceous

Roughness

SL - Slickensided
POL - Polished
S - Smooth
RF - Rough
VR - Very Rough

Shape

PR - Planar
CU - Curved
UN - Undulating
ST - Stepped
IR - Irregular



Borehole ID

BH06

Page 1 of 3


Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 17/05/2019	
Project Name: Ryde Hospital		Completed: 17/05/2019	
Hole Location: Eastwood, NSW		Logged By: NTH	
Hole Position: 323155.0 m E 6258826.0 m N MGA94 Zone 56		Checked By: BS	
Drill Model and Mounting: Hanjin- D8		Inclination: -90°	
Hole Diameter: 125 mm		RL Surface: No survey	
		Datum: AHD	
		Operator: Rockwell	

Drilling Information					Soil Description					Observations				
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
ADV		N							SM	ASPHALT - 100m : black & dark grey	D			0.00: PAVEMENT
							1			Silty SAND with gravel: fine grained, yellow, brown & pale grey; gravel sub-angular up to 10mm; trace of rootlets.	M	D		0.10: INFERRED FILL
							2		CL-ML	Silty CLAY: low plasticity, pale brown & grey; trace of rootlets.		VSt		0.25: V-bit refusal
							3			LAMINITE: pale grey, red & orange, extremely weathered, extremely low strength. Some clay bands (pale grey & medium plasticity), iron staining.	D			1.40: INFERRED RESIDUAL SOIL
							4			LAMINITE: dark grey & orange, highly weathered, very low to low strength. Some clay bands (pale grey & medium plasticity), iron staining.	H			1.90: Rootlets observed
										Continued on cored borehole sheet				2.00: INFERRED BEDROCK

Method AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	Penetration No resistance Refusal	Water ▽ Inflow ▽ Partial Loss ◄ Complete Loss	Samples and Tests U - Undisturbed Sample D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	Moisture Condition D - Dry M - Moist W - Wet	Consistency/Relative Density VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact
---	--	---	---	--	--



Project No.: PSM3828

```
PSM 3.02.1 LIB GLB Log PSM AU CORE BH PSM3828.GPJ <<DrawingFile>> 13/06/2019 10:02 10.00.00.69 DataGel Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 PSM 3.02.1 2019-03-06
```




Borehole ID

BH07

Page 1 of 3

Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client:	JBS&G	Commenced:	17/05/2019
Project Name:	Ryde Hospital	Completed:	17/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323213.0 m E 6258823.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Hole Diameter:	125 mm	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information							Soil Description							Observations
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
AD/V		N		CBR 0.50-3.00 m			1		CI-ML	ASPHALT - 100m : black & dark grey	D			0.00: PAVEMENT 0.10: INFERRED FILL
									SM	Silty CLAY with gravel: medium plasticity, dark brown & black; gravel sub-angular up to 10mm.	St			
AD/T		N	Not Observed			2			CL-ML	Silty SAND with gravel: fine grained, brown & pale grey; gravel sub-angular up to 20mm; trace of rootlets.	D			0.90: V-bit refusal
									CL-ML	Silty CLAY: low plasticity, dark brown & grey.	M			1.20: Rootlets observed 1.30: INFERRED RESIDUAL SOIL
						3				LAMINITE: pale grey, red & orange, extremely weathered, extremely low strength, iron staining.	D	H		2.50: INFERRED BEDROCK
									Continued on cored borehole sheet					
							4							

Method
AD/T - Auger drilling TC bit
AD/V - Auger drilling V bit
WB - Washbore
SPT - Standard penetration test
PT - Push tube
AS - Auger Screwing

Penetration
 No resistance
 Refusal

Water
 Inflow
 Partial Loss
 Complete Loss

Samples and Tests
U - Undisturbed Sample
D - Disturbed Sample
SPT - Standard Penetration Test
ES - Environmental Sample
TW - Thin Walled
LB - Large Disturbed Sample

Moisture Condition
D - Dry
M - Moist
W - Wet

Consistency/Relative Density
VS - Very soft
S - Soft
F - Firm
St - Stiff
VSt - Very stiff
H - Hard
VL - Very loose
L - Loose
MD - Medium dense
D - Dense
VD - Very dense
Ce - Cemented
C - Compact



Borehole ID

BH07

Page 2 of 3

Engineering Log - Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 17/05/2019	
Project Name: Ryde Hospital		Completed: 17/05/2019	
Hole Location: Eastwood, NSW		Logged By: NTH	
Hole Position: 323213.0 m E 6258823.0 m N MGA94 Zone 56		Checked By: BS	
Drill Model and Mounting: Hanjin- D8		Inclination: -90°	
Barrel Type and Length: Triple Tube 3 m		Bearing:	
		RL Surface: No survey	
		Datum: AHD	
		Operator: Rockwell	

Drilling Information						Rock Substance										Rock Mass Defects									
Method	Water	RQD (%)	Samples and Field Tests	WPT (Lugeons)	RL (m)	Depth (m)	Graphic Log	Material Description ROCK NAME: particle/grain characteristics, colour, fabric/texture, inclusions or minor components, moisture, mineral composition, alteration	Weathering				Strength Is(50)						Defect Spacing (mm)				Defect Descriptions / Comments Description, alpha/beta, infilling or coating, shape, roughness, thickness, other		
									XW	HW	MW	SW	FR	VL	L	M	H	VH	EH	<20	60	200	600	1000	
						1																			
						2																			
						3		Continued from non-cored borehole sheet																	
			3.48m Is(50) d=0 a=0 MPa			4		LAMINITE: pale grey, orange & red, orange banding, bedding fabric visible, well developed. Some clay bands (pale grey & medium plasticity), iron staining.																	
			4.82m Is(50) d=0.2 a=0.1 MPa					LAMINITE: pale grey & orange, white & orange banding, well developed, 80%-90% siltstone, 10%-20% sandstone, thin fine-grained sandstone laminations, iron staining.																	

Method AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore HQ3- Wireline core (63.5 mm) PQ3- Wireline core (85.0 mm) SPT- Standard penetration test PT - Push tube WPT - Water pressure test	Water ▽ Inflow △ Partial Loss ▲ Complete Loss Graphic Log/Core Loss Core recovered (hatching indicates material) No core recovery	Weathering XW - Extremely Weathered HW - Highly Weathered MW - Moderately Weathered SW - Slightly Weathered FR - Fresh Strength VL - Very Low L - Low M - Medium H - High VH - Very High EH - Extremely High	Defect Type FT - Fault SS - Shear Surface SZ - Shear Zone BP - Bedding parting SM - Seam IS - Infilled Seam JT - Joint CO - Contact CZ - Crushed Zone VN - Vein FZ - Fracture Zone BSH - Bedding Shear DB - Drilling Break	Infilling/Coating CN - Clean SN - Stain VN - Veneer CO - Coating RF - Rock fragments G - Gravel S - Sand Z - Silt CA - Calcite CL - Clay FE - Iron OZ - Quartz X - Carbonaceous	Roughness SL - Slickensided POL - Polished S - Smooth RF - Rough VR - Very Rough Shape PR - Planar CU - Curved UN - Undulating ST - Stepped IR - Irregular
--	---	--	--	---	---

Logged in accordance with AS 1726:2017 Geotechnical site investigations



Borehole ID

BH07

Page 3 of 3

Engineering Log - Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 17/05/2019	
Project Name: Ryde Hospital		Completed: 17/05/2019	
Hole Location: Eastwood, NSW		Logged By: NTH	
Hole Position: 323213.0 m E 6258823.0 m N MGA94 Zone 56		Checked By: BS	
Drill Model and Mounting: Hanjin- D8		Inclination: -90°	
Barrel Type and Length: Triple Tube 3 m		RL Surface: No survey	
		Datum: AHD	
		Operator: Rockwell	



Borehole ID

BH08

Page 1 of 3

Engineering Log - Non Cored Borehole


Project No.: PSM3828

Client:	JBS&G	Commenced:	17/05/2019
Project Name:	Ryde Hospital	Completed:	18/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323226.0 m E 6258801.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Hole Diameter:	125 mm	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information							Soil Description							Observations
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
AD/V		N	Not Observed				1		CI-ML	CONCRETE - 90m : Pale grey & white Silty CLAY with gravel: medium plasticity, dark grey & black; gravel sub-angular up to 5mm.	D	St		0.00: PAVEMENT 0.09: INFERRED FILL 0.50: V-bit refusal 1.20: Rootlets observed 1.40: INFERRED RESIDUAL SOIL
		SM							Silty SAND with gravel: fine grained, dark brown & red; gravel sub-angular up to 15mm; trace of rootlets.	M	D			
AD/T		N					2		CL-ML	Silty CLAY: low plasticity, pale grey & orange; ripped iron stone encountered at 2.3m. LAMINITE: pale grey, red & orange, extremely weathered, extremely low strength, iron staining.		VSt		2.60: INFERRED BEDROCK
							3		D	H				
							4			Continued on cored borehole sheet				

Method	Penetration	Water	Samples and Tests	Moisture Condition	Consistency/Relative Density
AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	No resistance Refusal	▽ Inflow ▽ Partial Loss ◀ Complete Loss	U - Undisturbed Sample D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	D - Dry M - Moist W - Wet	VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact



Project No.: PSM3828

```
PSM 3.02.1 LIB GLB Log PSM AU CORE BH PSM3828.GPJ <<DrawingFile>> 13/06/2019 10:02 10.00.00.69 DataGel Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 PSM 3.02.1 2019-03-06
```



Borehole ID

BH08

Page 3 of 3

Engineering Log - Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 17/05/2019	
Project Name: Ryde Hospital		Completed: 18/05/2019	
Hole Location: Eastwood, NSW		Logged By: NTH	
Hole Position: 323226.0 m E 6258801.0 m N MGA94 Zone 56		Checked By: BS	
Drill Model and Mounting: Hanjin- D8		Inclination: -90°	
Barrel Type and Length: Triple Tube 3 m		RL Surface: No survey	
		Datum: AHD	
		Operator: Rockwell	



Borehole ID

BH09


















Page 1 of 1

Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client:	JBS&G	Commenced:	18/05/2019
Project Name:	Ryde Hospital	Completed:	18/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323178.0 m E 6258799.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Hole Diameter:	125 mm	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information							Soil Description							Observations												
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations												
AD/V		N	Not Observed				0.00 0.20 1.00 2.00 3.00 4.00 5.00		SW	SAND with gravel: fine to medium grained, dark brown & grey; gravel angular up to 20mm; trace of rootlets.	M	MD		0.00: INFERRED FILL 0.20: Concrete fragments observed												
									SW-SC	Clayey SAND with gravel: fine to medium grained, brown & yellow; gravel sub-angular up to 15mm.		D		1.00: Bricks observed												
									CI	CLAY with gravel: medium plasticity, dark brown & black; gravel sub-angular up to 10mm.		St to VSt		3.00: Bricks observed												
									CH	CLAY: high plasticity, dark brown & black.		VSt		3.60: INFERRED RESIDUAL SOIL												
AD/T		Z								SILTSTONE: pale grey & brown, extremely weathered, extremely low strength, iron staining. Hole Terminated at 5.0m. Target depth, hole grouted to surface and reinstated	D	H		4.55: V-bit refusal 4.60: INFERRED BEDROCK												
<table><tr><th>Method</th><th>Penetration</th><th>Water</th><th>Samples and Tests</th><th>Moisture Condition</th><th>Consistency/Relative Density</th></tr><tr><td>AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing</td><td> No resistance  Refusal</td><td> Inflow  Partial Loss  Complete Loss</td><td>D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample</td><td>D - Dry M - Moist W - Wet</td><td>VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact</td></tr></table>															Method	Penetration	Water	Samples and Tests	Moisture Condition	Consistency/Relative Density	AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	 No resistance  Refusal	 Inflow  Partial Loss  Complete Loss	D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	D - Dry M - Moist W - Wet	VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact
Method	Penetration	Water	Samples and Tests	Moisture Condition	Consistency/Relative Density																					
AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	 No resistance  Refusal	 Inflow  Partial Loss  Complete Loss	D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	D - Dry M - Moist W - Wet	VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact																					

Logged in accordance with AS 1726:2017 Geotechnical site investigations.



Borehole ID

BH10

Page 1 of 1

Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 18/05/2019	
Project Name: Ryde Hospital		Completed: 18/05/2019	
Hole Location: Eastwood, NSW		Logged By: NTH	
Hole Position: 323214.0 m E 6258775.0 m N MGA94 Zone 56		Checked By: BS	
Drill Model and Mounting: Hanjin- D8		Inclination: -90°	
Hole Diameter: 125 mm		RL Surface: No survey	
		Datum: AHD	
		Operator: Rockwell	

Drilling Information				Soil Description						Observations					
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations	
AD/V	N	Not Observed	CBR 0.30-2.90 m				1		SC	ASPHALT - 100m : black & dark grey	D			0.00: PAVEMENT	
										SAND with gravel: fine to medium grained, dark brown & grey; gravel angular up to 10mm; trace of rootlets.				0.10: INFERRED FILL	
										SAND with gravel: fine to medium grained, dark brown & grey; gravel angular up to 20mm; trace of rootlets.				0.50: Rootlets observed	
														1.00: Rootlets observed	
							2								1.50: Plastics and electricity wires observed
							3		GM	Silty GRAVEL: medium grained, pale grey & yellow; crushed sandstone gravel - moderately weathered, high strength.	D	VD			2.00: Bricks observed
										Hole Terminated at 3.00 m Target depth, hole grouted to surface and reinstated					2.95: V-bit refusal
							4								

Method
AD/T - Auger drilling TC bit
AD/V - Auger drilling V bit
WB - Washbore
SPT - Standard penetration test
PT - Push tube
AS - Auger Screwing

Penetration
 No resistance
 Refusal

Water
▽ Inflow
▽ Partial Loss
◀ Complete Loss

Samples and Tests
U - Undisturbed Sample
D - Disturbed Sample
SPT - Standard Penetration Test
ES - Environmental Sample
TW - Thin Walled
LB - Large Disturbed Sample

Moisture Condition
D - Dry
M - Moist
W - Wet

Consistency/Relative Density
VS - Very soft
S - Soft
F - Firm
St - Stiff
VSt - Very stiff
H - Hard
VL - Very loose
L - Loose
MD - Medium dense
D - Dense
VD - Very dense
Ce - Cemented
C - Compact

Logged in accordance with AS 1726:2017 Geotechnical site investigations



Borehole ID

BH11

Page 1 of 2


Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 18/05/2019	
Project Name: Ryde Hospital		Completed: 18/05/2019	
Hole Location: Eastwood, NSW		Logged By: NTH	
Hole Position: 323254.0 m E 6258797.0 m N MGA94 Zone 56		Checked By: BS	
Drill Model and Mounting: Hanjin- D8		Inclination: -90°	
Hole Diameter: 125 mm		RL Surface: No survey	
		Datum: AHD	
		Operator: Rockwell	

Drilling Information				Soil Description						Observations				
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
ADV		N					1		CI-CH	ASPHALT - 100m : black & dark grey	D			0.00: PAVEMENT
										CLAY with gravel: medium to high plasticity, pale grey & red; gravel sub-angular up to 5mm.	M	VSt	0.10: INFERRED FILL	
AD/T		N	Not Observed				2		GM	Silty GRAVEL: medium grained, pale grey & red; crushed sandstone gravel - moderately weathered, high strength.				1.30: V-bit refusal
							3					VD		
							4		CL-ML	Silty CLAY: low plasticity, pale grey & red; ripped iron stone encountered at 4.5m.		VSt		4.00: INFERRED RESIDUAL SOIL
										SILTSTONE: pale grey & red, highly weathered, low strength.	H			4.50: INFERRED BEDROCK

Method AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	Penetration No resistance Refusal	Water Inflow Partial Loss Complete Loss	Samples and Tests U - Undisturbed Sample D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	Moisture Condition D - Dry M - Moist W - Wet	Consistency/Relative Density VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact
---	--	---	---	--	--



Project No.: PSM3828

```
PSM 3.02.1 LIB:GLB Log PSM AU NONCORE BH NZAU PSM 3828.GPJ <<DrawingFile>> 14/06/2019 11:07 10.00.00.69 Date| Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 Pri: PSM 3.02.1 2019-03-06
```



Borehole ID

BH12

Page 1 of 1

Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client:	JBS&G	Commenced:	18/05/2019
Project Name:	Ryde Hospital	Completed:	18/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323178.0 m E 6258799.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Hole Diameter:	125 mm	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information							Soil Description							Observations
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
AD/V	N	Not Observed					0.00			ASPHALT - 150m : black & dark grey	D			0.00: PAVEMENT
							0.15		CI	CLAY with gravel: medium plasticity, dark brown & grey; gravel sub-angular up to 10mm.	M	St		0.15: INFERRED FILL
							1.00		SM-SC	Silty SAND with gravel: fine to medium grained, dark brown & black; gravel sub-angular up to 10mm.		D		
							2.00		CI	CLAY: medium plasticity, pale grey & orange.	D	VSt		2.00: INFERRED RESIDUAL SOIL
AD/T	N						2.75			SILTSTONE: pale grey & yellow, extremely weathered, extremely low strength.	H			2.75: V-bit refusal
							2.80			Hole Terminated at 3.00 m Target depth, hole grouted to surface and reinstated				2.80: INFERRED BEDROCK
							3.00							
							4.00							

Method
AD/T - Auger drilling TC bit
AD/V - Auger drilling V bit
WB - Washbore
SPT - Standard penetration test
PT - Push tube
AS - Auger Screwing

Penetration
 No resistance
 Refusal


Water
 Inflow
 Partial Loss
 Complete Loss

Samples and Tests
U - Undisturbed Sample
D - Disturbed Sample
SPT - Standard Penetration Test
ES - Environmental Sample
TW - Thin Walled
LB - Large Disturbed Sample

Moisture Condition
D - Dry
M - Moist
W - Wet

Consistency/Relative Density
VS - Very soft
S - Soft
F - Firm
St - Stiff
VSt - Very stiff
H - Hard
VL - Very loose
L - Loose
MD - Medium dense
D - Dense
VD - Very dense
Ce - Cemented
C - Compact

Logged in accordance with AS 1726:2017 Geotechnical site investigations



Project No.: PSM3828

```

PSM 3.02.1 LIB:GLB Log PSM AU NONCORE BH NZAU PSM 3828.GPJ <<DrawingFile>> 13/06/2019 14:05 10.00.00.69 Dateof Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 Pri: PSM 3.02.1 2019-03-06

```



Borehole ID

BH13

Page 2 of 2

Engineering Log - Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 19/05/2019																												
Project Name: Ryde Hospital		Completed: 19/05/2019																												
Hole Location: Eastwood, NSW		Logged By: NTH																												
Hole Position: 323075.0 m E 6258816.0 m N MGA94 Zone 56		Checked By: BS																												
Drill Model and Mounting: Hanjin- D8		Inclination: -90°																												
Barrel Type and Length: Triple Tube 3 m		RL Surface: No survey																												
		Datum: AHD																												
		Operator: Rockwell																												
Drilling Information							Rock Substance										Rock Mass Defects													
Method	Water	RQD (%)	Samples and Field Tests	WPT (Lugeons)	RL (m)	Depth (m)	Graphic Log	Material Description	Weathering				Strength Is(50)						Defect Spacing (mm)			Defect Descriptions / Comments								
								ROCK NAME: particle/grain characteristics, colour, fabric/texture, inclusions or minor components, moisture, mineral composition, alteration Continued from non-cored borehole sheet	XW	HW	MW	SW	FR	VL	0.1	0.3	L	M	H	3	VH	10	EH	<20	60	200	600	1000	Description, alpha/beta, infilling or coating, shape, roughness, thickness, other	
NMLC	Not Observed	63	5.85m Is(50) d=0 a=0 MPa			6		LAMINITE: pale grey & orange, Some clay bands (dark grey & medium plasticity).																					5.00: INFERRED BEDROCK	
			6.78m Is(50) d=0.5 a=0.8 MPa			7		LAMINITE: pale grey & orange, white, orange & red banding, very well developed, 70-80% siltstone, 20%-30% sandstone, thin fine-grained sandstone laminations. Some clay bands (pale grey & medium plasticity), iron staining.																					+330 mm, Heavily Fractured	
		68	7.29m Is(50) d=0 a=0.2 MPa			8		7.2m - Becomes dark grey & orange with black & orange banding, 80%-90% siltstone, 10%-20% sandstone. Multiple carbonaceous bands.																						CZ, 0°, RF, PR, RF, +70 mm CZ, 0°, RF, PR, RF, +140 mm SM, 0°, CL, PR, S, +20 mm SM, 10°, Fe & Clay SN, PR, S, +10 mm SM, 0°, CL, PR, S, +10 mm SM, 0°, CL, PR, S, +60 mm CZ, 0°, RF, PR, RF, +20 mm SM, 0°, CL, PR, S, +50 mm CZ, 5°, RF & CL, PR, S, +50mm CZ, 0°, RF, PR, RF, +40 mm FZ, 0°, RF & CL, PR, S, +40 +40 mm JT, 80°, FE SN, PR, S JT, 42°, FE SN, PR, S SM, 0°, CL, PR, S, +70 mm CZ, 0°, RF, PR, S, +60 mm JT, 75°, CL, PR, S, +40 mm CZ, 0°, RF, PR, S, +20 mm SM, 0°, CL, PR, S, +70 mm CZ, 0°, RF, PR, S, +10 mm CZ, 0°, RF, PR, S, +30 mm CZ, 0°, RF, PR, S, +10 mm JT, 77°, CL, PR, S SM, 0°, CL, PR, S, +10 mm BP, 12°, FE SN, PR, S BP, 12°, FE SN, PR, S SM, 0°, CL, PR, S, +20 mm SM, 0°, CL, PR, S, +10 mm CZ, 0°, RF & CL, PR, S, +90 mm
			8.36m Is(50) d=0.1 a=0.1 MPa			9		Hole Terminated at 8.45 m Target depth, hole grouted to surface and reinstated																						BP, 0°, X, PR, S BP, 10°, X, PR, S
Method		Water		Weathering		Defect Type		Infilling/Coating		Roughness																				
AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore HQ3- Wireline core (63.5 mm) PQ3- Wireline core (85.0 mm) SPT- Standard penetration test PT - Push tube WPT - Water pressure test		▽ Inflow △ Partial Loss ▲ Complete Loss Graphic Log/Core Loss Core recovered (hatching indicates material) No core recovery		XW - Extremely Weathered HW - Highly Weathered MW - Moderately Weathered SW - Slightly Weathered FR - Fresh Strength VL - Very Low L - Low M - Medium H - High VH - Very High EH - Extremely High		FT - Fault SS - Shear Surface SZ - Shear Zone BP - Bedding parting SM - Seam IS - Infilled Seam JT - Joint CO - Contact CZ - Crushed Zone VN - Vein FZ - Fracture Zone BSH - Bedding Shear DB - Drilling Break		CN - Clean SN - Stain VN - Veneer CO - Coating RF - Rock fragments G - Gravel S - Sand Z - Silt CA - Calcite CL - Clay FE - Iron QZ - Quartz X - Carbonaceous		SL - Slickensided POL - Polished S - Smooth RF - Rough VR - Very Rough Shape PR - Planar CU - Curved UN - Undulating ST - Stepped IR - Irregular																				



Borehole ID

BH14

Page 1 of 3

Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client:	JBS&G	Commenced:	19/05/2019
Project Name:	Ryde Hospital	Completed:	19/05/2019
Hole Location:	Eastwood, NSW	Logged By:	NTH
Hole Position:	323048.0 m E 6258856.0 m N MGA94 Zone 56	Checked By:	BS

Drill Model and Mounting:	Hanjin- D8	Inclination:	-90°	RL Surface:	No survey		
Hole Diameter:	125 mm	Bearing:		Datum:	AHD	Operator:	Rockwell

Drilling Information							Soil Description							Observations
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description SOIL NAME: Plasticity, behaviour or particle characteristics of primary component, colour, secondary components, additional observations	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
AD/T	N	Not Observed							SM	ASPHALT - 100m : black & dark grey	D			0.00: PAVEMENT
									SM	Silty SAND with gravel: fine grained, pale brown & orange; gravel angular up to 20mm.	M	MD		0.10: INFERRED FILL
							1		SM	Silty SAND with gravel: fine grained, pale brown & grey; gravel sub-angular up to 5mm.				
							2							
							3			3.0m - Becomes dark brown with sub-angular gravel up to 10mm	D	D		
							4							

Method	Penetration	Water	Samples and Tests	Moisture Condition	Consistency/Relative Density
AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	No resistance Refusal	▽ Inflow ▽ Partial Loss ◄ Complete Loss	U - Undisturbed Sample D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	D - Dry M - Moist W - Wet	VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact



Borehole ID

BH14

Page 2 of 3


Engineering Log - Non Cored Borehole

Project No.: PSM3828

Client: JBS&G		Commenced: 19/05/2019	
Project Name: Ryde Hospital		Completed: 19/05/2019	
Hole Location: Eastwood, NSW		Logged By: NTH	
Hole Position: 323048.0 m E 6258856.0 m N MGA94 Zone 56		Checked By: BS	
Drill Model and Mounting: Hanjin- D8		Inclination: -90°	
Hole Diameter: 125 mm		RL Surface: No survey	
		Datum: AHD	
		Operator: Rockwell	

Drilling Information				Soil Description						Observations				
Method	Penetration	Support	Water	Samples Tests Remarks	Recovery	RL (m)	Depth (m)	Graphic Log	Classification Symbol	Material Description	Moisture Condition	Consistency / Relative Density	Hand Penetrometer UCS (kPa)	Structure, Zoning, Origin, Additional Observations
AD/T		N	Not Observed				6		CL-ML	Silty CLAY: low plasticity, dark brown & grey; ripped iron stone encountered at 5.0m.	D	VSt	100	5.00: INFERRED RESIDUAL SOIL
										LAMINITE: dark grey & brown, extremely weathered, extremely low strength., iron staining.		H	200	5.50: INFERRED BEDROCK
							7			Continued on cored borehole sheet				
							8							
							9							

Method AD/T - Auger drilling TC bit AD/V - Auger drilling V bit WB - Washbore SPT - Standard penetration test PT - Push tube AS - Auger Screwing	Penetration No resistance Refusal	Water Inflow Partial Loss Complete Loss	Samples and Tests U - Undisturbed Sample D - Disturbed Sample SPT - Standard Penetration Test ES - Environmental Sample TW - Thin Walled LB - Large Disturbed Sample	Moisture Condition D - Dry M - Moist W - Wet	Consistency/Relative Density VS - Very soft S - Soft F - Firm St - Stiff VSt - Very stiff H - Hard VL - Very loose L - Loose MD - Medium dense D - Dense VD - Very dense Ce - Cemented C - Compact
---	--	---	---	--	--



Project No.: PSM3828

```
PSM 3.02.1 LIB GLB Log PSM AU CORE BH PSM3828.GPJ <<DrawingFile>> 13/06/2019 10:02 10.00.00.69 DataGel Fence and Map Tool | Lib: PSM 3.02.1 2019-03-06 PSM 3.02.1 2019-03-06
```


Appendix B

Core Photos





Pells Sullivan Meynink

JBS&G

Ryde Hospital

Eastwood, NSW

GEOTECHNICAL INVESTIGATION

CORE PHOTOGRAPHY - BH01

PSM3828-002R

Appendix B



Pells Sullivan Meynink

JBS&G
Ryde Hospital
Eastwood, NSW
GEOTECHNICAL INVESTIGATION
CORE PHOTOGRAPHY - BH02

PSM3828-002R

Appendix B



Pells Sullivan Meynink

JBS&G

Ryde Hospital

Eastwood, NSW

GEOTECHNICAL INVESTIGATION

CORE PHOTOGRAPHY - BH03

PSM3828-002R

Appendix B



Pells Sullivan Meynink

JBS&G

Ryde Hospital

Eastwood, NSW

GEOTECHNICAL INVESTIGATION

CORE PHOTOGRAPHY - BH04

PSM3828-002R

Appendix B



Pells Sullivan Meynink

JBS&G

Ryde Hospital

Eastwood, NSW

GEOTECHNICAL INVESTIGATION

CORE PHOTOGRAPHY - BH05

PSM3828-002R

Appendix B



Pells Sullivan Meynink

JBS&G

Ryde Hospital

Eastwood, NSW

GEOTECHNICAL INVESTIGATION

CORE PHOTOGRAPHY - BH06

PSM3828-002R

Appendix B



Pells Sullivan Meynink

JBS&G

Ryde Hospital

Eastwood, NSW

GEOTECHNICAL INVESTIGATION

CORE PHOTOGRAPHY - BH07

PSM3828-002R

Appendix B



Pells Sullivan Meynink

JBS&G

Ryde Hospital

Eastwood, NSW

GEOTECHNICAL INVESTIGATION

CORE PHOTOGRAPHY - BH08

PSM3828-002R

Appendix B



Pells Sullivan Meynink

JBS&G

Ryde Hospital

Eastwood, NSW

GEOTECHNICAL INVESTIGATION

CORE PHOTOGRAPHY - BH13

PSM3828-002R

Appendix B



Pells Sullivan Meynink

JBS&G

Ryde Hospital

Eastwood, NSW

GEOTECHNICAL INVESTIGATION


CORE PHOTOGRAPHY - BH14

PSM3828-002R

Appendix B

Appendix C

Point Load Strength Index Test Results





POINT LOAD STRENGTH INDEX TEST RESULTS

Job No.	PSM3828												Sheet	1	of	1				
Project	Ryde Hospital																			
Test Method	AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index							Sampling Technique	NMLC					Sampling Date	14-19/05/2019					
								Storage History	Field					Testing Date	14-19/05/2019					
Test Machine	GSA 6500							Moisture Condition	Field					Tested By	NTH					
Calibration Date	16/8/2018							Loading Rate	< 30 seconds											
Rock Type		Location	Depth	Diametral Tests					Axial, Block, and Irregular Lump Tests							AS 1726				
		(m)	D	L	P	I _{s(50)}	Failure Mode	W	D	L	P	I _s	I _{s(50)}	Failure Mode	Strength					
			(mm)	(mm)	(kN)	(MPa)		(mm)	(mm)	(mm)	(kN)	(MPa)	(MPa)		Class					
Laminite	BH01	5.85	50	50	0.1	0	Parallel to bedding	50	49		0.2	0.1	0.1	Through substance	VL					
Laminite	BH01	6.46	50	60	0.1	0	Parallel to bedding	50	43		0.1	0	0	Through substance	VL					
Laminite	BH01	7.64	50	50.5	0.1	0.1	Parallel to bedding	50	43		0.3	0.1	0.1	Through substance	VL / L					
Laminite	BH01	8.86	50	64.5	0.7	0.3	Parallel to bedding	50	33		0.3	0.2	0.2	Through substance	L					
Laminite	BH02	9.31	50	36	0.3	0.1	Parallel to bedding	50	37		0.7	0.3	0.3	Through substance	L					
Laminite	BH02	10.11	50	52.5	0.2	0.1	Parallel to bedding	50	44		1.5	0.5	0.5	Bad break	VL / M					
Laminite	BH02	10.79	50	51.5	0.3	0.1	Parallel to bedding	50	47		0.3	0.1	0.1	Through substance	L					
Laminite	BH03	2.62	50	50	0.1	0	Parallel to bedding	50	42		0.2	0.1	0.1	Through substance	VL					
Laminite	BH03	3.58	50	55.5	0.1	0	Parallel to bedding	50	37		0.2	0.1	0.1	Through substance	VL					
Laminite	BH03	4.63	50	59	0.1	0	Parallel to bedding	50	43		0.2	0.1	0.1	Through substance	VL					
Laminite	BH03	5.67	50	52.5	0	0	Parallel to bedding	50	37		0.1	0	0	Through substance	VL					
Laminite	BH03	6.30	50	51	0	0	Parallel to bedding	50	33		0.1	0	0	Through substance	VL					
Laminite	BH03	8.52	50	60	0.1	0	Parallel to bedding	50	46		0.1	0	0	Through substance	VL					
Laminite	BH03	9.09	50	57.5	1.2	0.5	Parallel to bedding	50	49		1.3	0.4	0.4	Bad break	M					
Laminite	BH04	1.96	50	56.5	0.1	0	Parallel to bedding	50	41		0.1	0	0	Through substance						
Laminite	BH04	2.24	50	68.5	0.1	0	Parallel to bedding	50	39		0.1	0	0	Through substance						
Laminite	BH04	3.50	50	55.5	0.1	0	Parallel to bedding	50	48		0.4	0.1	0.1	Through substance	L					
Laminite	BH04	4.35	50	50	0.7	0.3	Parallel to bedding	50	44		1.2	0.4	0.5	Through substance	L / M					
Laminite	BH04	5.25	50	51	0.1	0	Parallel to bedding	50	42		0.3	0.1	0.1	Through substance	VL					
Laminite	BH04	6.79	50	74	0.3	0.1	Parallel to bedding	50	42		0.5	0.2	0.2	Through substance	L					
Laminite	BH04	7.53	50	50	0.2	0.1	Parallel to bedding	50	48		0.5	0.2	0.2	Through substance	VL / L					
Laminite	BH04	8.32	50	55	0.4	0.2	Parallel to bedding	50	38		0.8	0.3	0.3	Through substance	L / M					
By:	NTH												Checked:	BS			Date:	14-19/05/2019		



POINT LOAD STRENGTH INDEX TEST RESULTS


Job No.		PSM3828												Sheet		1	of		1		
Project		Ryde Hospital																			
Test Method		AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique		NMLC			Sampling Date		14-19/05/2019		
												Storage History		Field			Testing Date		14-19/05/2019		
Test Machine		GSA 6500										Moisture Condition		Field			Tested By		NTH		
Calibration Date		16/8/2018										Loading Rate		< 30 seconds							
Rock Type		Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests							AS 1726 Strength Class					
				D (mm)	L (mm)	P (kN)	I _{s(50)} (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	I _s (MPa)	I _{s(50)} (MPa)	Failure Mode						
Laminite		BH05	3.71	50	51.5	0.2	0.1	Parallel to bedding	50	46		0.8	0.3	0.3	Through substance	VL / L					
Laminite		BH05	4.48	50	51.5	0.4	0.1	Parallel to bedding	50	48		0.6	0.2	0.2	Through substance	L					
Laminite		BH05	5.54	50	80	0.3	0.1	Parallel to bedding	50	49		1.5	0.5	0.5	Through substance	L / M					
Laminite		BH05	6.43	50	56	0.5	0.2	Parallel to bedding	50	49		0.7	0.2	0.2	Through substance	L					
Laminite		BH05	7.83	50	65	0.3	0.1	Parallel to bedding	50	38		1.2	0.5	0.5	Through substance	L / M					
Laminite		BH05	8.34	50	69	0.2	0.1	Parallel to bedding	50	47		0.5	0.2	0.2	Bad break	VL / L					
Laminite		BH06	5.40	50	55	0.2	0.1	Parallel to bedding	50	42		0.2	0.1	0.1	Through substance	VL					
Laminite		BH06	5.87	50	62.5	0.5	0.2	Parallel to bedding	50	45		0.6	0.2	0.2	Through substance	L					
Laminite		BH06	6.27	50	55.5	1.3	0.5	Parallel to bedding	50	37		1.6	0.7	0.7	Through substance	M					
Laminite		BH06	7.24	50	51	1	0.4	Parallel to bedding	50	47		1.1	0.4	0.4	Through substance	M					
Laminite		BH07	3.48	50	51.5	0.1	0	Parallel to bedding	50	49		0.1	0	0	Through substance	VL					
Laminite		BH07	4.82	50	52.5	0.5	0.2	Parallel to bedding	50	40		0.3	0.1	0.1	Through substance	L					
Laminite		BH07	5.55	50	50	0.2	0.1	Parallel to bedding	50	49		0.3	0.1	0.1	Bad break	VL					
Laminite		BH07	6.49	50	50	0.1	0	Parallel to bedding	50	33		0.1	0.1	0.1	Through substance	VL					
Laminite		BH07	7.66	50	60	0.2	0.1	Parallel to bedding	50	49		0.5	0.2	0.2	Through substance	VL / L					
Laminite		BH07	8.64	50	61	2	0.8	Parallel to bedding	50	37		2.1	0.9	0.9	Through substance	M					
Laminite		BH08	3.77	50	50	0	0	Parallel to bedding	50	42		0	0	0	Through substance						
Laminite		BH08	4.86	50	56	0	0	Parallel to bedding	50	41		0.1	0	0	Through substance						
Laminite		BH08	5.38	50	53.5	0.1	0	Parallel to bedding	50	39		0.2	0.1	0.1	Through substance	VL					
Laminite		BH08	6.64	50	51	0.1	0	Parallel to bedding	50	49		0.1	0	0	Through substance	VL					
Laminite		BH08	7.83	50	57	0.1	0	Parallel to bedding	50	32		0.2	0.1	0.1	Through substance	VL					
Laminite		BH08	8.18	50	58	0.1	0	Parallel to bedding	50	40		0.1	0	0	Through substance						
Laminite		BH08	8.63	50	53.5	0.7	0.3	Parallel to bedding	50	48		0.8	0.3	0.3	Through substance	L					
By:		NTH										Checked: BS					Date:		14-19/05/2019		

**POINT LOAD STRENGTH INDEX TEST RESULTS**

Job No.		PSM3828												Sheet		1	of	1			
Project		Ryde Hospital																			
Test Method		AS 4133.4.1 - 1993 Methods of Testing Rocks for Engineering Purposes, Determination of Point Load Strength Index										Sampling Technique		NMLC				Sampling Date		14-19/05/2019	
												Storage History		Field				Testing Date		14-19/05/2019	
Test Machine		GSA 6500										Moisture Condition		Field				Tested By		NTH	
Calibration Date		16/8/2018										Loading Rate		< 30 seconds							
Rock Type		Location	Depth (m)	Diametral Tests					Axial, Block, and Irregular Lump Tests							AS 1726 Strength Class					
				D (mm)	L (mm)	P (kN)	I _{s(50)} (MPa)	Failure Mode	W (mm)	D (mm)	L (mm)	P (kN)	I _s (MPa)	I _{s(50)} (MPa)	Failure Mode						
Laminite		BH13	5.85	50	50	0	0	Parallel to bedding	50	48		0.1	0	0	Through substance						
Laminite		BH13	6.78	50	60	1.2	0.5	Parallel to bedding	50	49		2.4	0.8	0.8	Bad break	M					
Laminite		BH13	7.29	50	50	0.1	0	Parallel to bedding	50	49		0.7	0.2	0.2	Through substance	VL / L					
Laminite		BH13	8.36	50	65.5	0.2	0.1	Parallel to bedding	50	35		0.3	0.1	0.1	Through substance	VL / L					
Laminite		BH14	7.26	50	64.5	0.3	0.1	Parallel to bedding	50	38		0.4	0.2	0.2	Through substance	L					
Laminite		BH14	7.80	50	72.5	0.5	0.2	Parallel to bedding	50	38		0.5	0.2	0.2	Through substance	L					
Laminite		BH14	8.28	50	59	0.5	0.2	Parallel to bedding	50	47		2.6	0.9	0.9	Through substance	L / M					
Laminite		BH14	8.95	50	50	0.5	0.2	Parallel to bedding	50	39		1.3	0.5	0.5	Through substance	L / M					
Laminite		BH14	9.51	50	56.5	0.8	0.3	Parallel to bedding	50	30		1	0.5	0.5	Through substance	M					
By:		NTH												Checked:		BS		Date:		14-19/05/2019	

Appendix D

Piezometer Construction Record






PIEZOMETER CONSTRUCTION RECORD

HOLE NUMBER: BH03
PIEZOMETER: BH03
COLLAR EASTING: 323214.0 m E
COLLAR NORTHING: 6258884.0 m N
COLLAR RL(m): No Survey

DRILLING CONTRACTOR: Rockwell
RIG: HANJIN - D8
DEPTH OF HOLE (m): 8.3m
BOREHOLE INCLINATION: -90°
PIEZO INSTALLATION DATE: 15/05/2019
SUPERVISED BY: NTH

Tick boxes

Complete dimensions if appropriate

Steel protective well cover	<input checked="" type="checkbox"/>		Height of stickup (m)	<u>NONE</u>
PVC cap	<input checked="" type="checkbox"/>		Diameter of PVC (mm)	<u>60 mm</u>
Concrete collar	<input type="checkbox"/>			
Back fill type: Cement bentonite	<input checked="" type="checkbox"/>			
Soil	<input checked="" type="checkbox"/>			
None	<input type="checkbox"/>			
Seal: Bentonite pellets	<input checked="" type="checkbox"/>		Depth to top of seal	<u>3.1m</u>
Other	<input type="checkbox"/>			
Gravel type: 2-5mm gravel	<input checked="" type="checkbox"/>		Depth to top of gravel pack	<u>5.1m</u>
Other	<input type="checkbox"/>			
Perforation type: Drill holes	<input type="checkbox"/>	Depth to top of screen	<u>5.2m</u>	
Hack saw cuts	<input type="checkbox"/>			
40um machine slots	<input checked="" type="checkbox"/>	Depth to base of screen	<u>8.2m</u>	
		Depth to base of piezo	<u>8.3m</u>	
		Depth to base of gravel	<u>8.3m</u>	

COMMENTS: Water level after installation 15/05/2019- depth 3.01m BLG




PIEZOMETER CONSTRUCTION RECORD

HOLE NUMBER: BH07
PIEZOMETER: BH07
COLLAR EASTING: 323213.0 m E
COLLAR NORTHING: 6258823.0 m N
COLLAR RL(m): No Survey

DRILLING CONTRACTOR: Rockwell
RIG: HANJIN - D8
DEPTH OF HOLE (m): 8.85m
BOREHOLE INCLINATION: -90°
PIEZO INSTALLATION DATE: 17/05/2019
SUPERVISED BY: NTH


Tick boxes

Complete dimensions if appropriate

Steel protective well cover	<input checked="" type="checkbox"/>		Height of stickup (m)	<u>NONE</u>	
PVC cap	<input checked="" type="checkbox"/>		Diameter of PVC (mm)	<u>60 mm</u>	
Concrete collar	<input type="checkbox"/>		Back fill type: Cement bentonite <input checked="" type="checkbox"/> Soil <input checked="" type="checkbox"/> None <input type="checkbox"/>	Depth to top of seal	<u>1.2 m</u>
Seal: Bentonite pellets <input checked="" type="checkbox"/> Other <input type="checkbox"/>			Gravel type: 2-5mm gravel <input checked="" type="checkbox"/> Other <input type="checkbox"/>	Depth to top of gravel pack	<u>5.65 m</u>
Gravel type: 2-5mm gravel <input checked="" type="checkbox"/> Other <input type="checkbox"/>			Perforation type: Drill holes <input type="checkbox"/> Hack saw cuts <input type="checkbox"/> 40um machine slots <input checked="" type="checkbox"/>	Depth to top of screen	<u>5.75 m</u>
Perforation type: Drill holes <input type="checkbox"/> Hack saw cuts <input type="checkbox"/> 40um machine slots <input checked="" type="checkbox"/>				Depth to base of screen	<u>8.75 m</u>
				Depth to base of piezo	<u>8.85 m</u>
				Depth to base of gravel	<u>8.85 m</u>

COMMENTS: Water level after installation 17/05/2019 - depth 2.7m BLG

Appendix E
CBR Test Results Sheet



FOUR DAY SOAKED CALIFORNIA BEARING RATIO TEST REPORT

Client: Pells Sullivan Meynink
PSM Job No.: PSM3828 - Ryde Hospital

Ref No: L4290E
Report: 2
Report Date: 29/05/2019
Page 1 of 1

BOREHOLE NUMBER	BH 1	BH 3	BH 4	BH 7	BH 10	BH 13
DEPTH (m)	0.50 - 3.00	0.50 - 1.90	0.50 - 1.30	0.50 - 3.00	0.10 - 2.90	0.30 - 3.50
Surcharge (kg)	4.5	4.5	4.5	4.5	4.5	4.5
Maximum Dry Density (t/m ³)	1.69 STD	1.70 STD	1.63 STD	1.81 STD	1.79 STD	1.79 STD
Optimum Moisture Content (%)	18.5	19.6	23.3	16.0	15.0	17.4
Moulded Dry Density (t/m ³)	1.66	1.66	1.59	1.78	1.75	1.75
Sample Density Ratio (%)	98	98	98	98	98	98
Sample Moisture Ratio (%)	99	95	100	99	101	101
Moisture Contents						
Insitu (%)	15.7	24.2	23.1	14.2	10.2	17.6
Moulded (%)	18.3	18.5	23.2	15.8	15.2	17.6
After soaking and						
After Test, Top 30mm(%)	27.0	28.1	37.7	18.5	21.4	18.4
Remaining Depth (%)	21.4	26.3	31.4	17.4	17.4	18.0
Material Retained on 19mm Sieve (%)	0	1*	0	0	4*	2*
Swell (%)	1.5	2.0	4.5	0.0	1.0	0.5
C.B.R. value: @2.5mm penetration	1.5	3.0	1.5	7	7	6

NOTES: Sampled and supplied by client.

- Refer to appropriate Borehole logs for soil descriptions
- Test Methods : AS 1289 6.1.1, 5.1.1 & 2.1.1.
- Date of receipt of sample: 20/05/2019.
- * Denotes not used in test sample.



NATA Accredited Laboratory
Number:1327

Accredited for compliance with ISO/IEC 17025 - Testing.
This document shall not be reproduced except in full.


All services provided by STS are subject to our standard terms and conditions. A copy is available on request.

Approved Signatory / Date
(D. Treweek)

[Signature]
29/5/19

Appendix F

Atterberg Limit Test Results sheet





SOIL TEST SERVICES

ABN 43 002 145 173

ATTERBERG LIMIT AND LINEAR SHRINKAGE TEST REPORT

Client: Pells Sullivan Meynink
Project: Ryde Hospital
PSM Job No.: PSM3828

Ref No: L4290E
Report: 1
Report Date: 29/05/2019
Page 1 of 1

AS 1289	TEST METHOD	3.1.2	3.2.1	3.3.1	3.4.1
BOREHOLE NUMBER	DEPTH m	LIQUID LIMIT %	PLASTIC LIMIT %	PLASTICITY INDEX %	LINEAR SHRINKAGE %
1	0.50 - 3.00	50	21	29	14.0
3	0.50 - 1.90	76	24	52	19.0
4	0.50 - 1.30	54	23	31	15.0
7	0.50 - 3.00	30	17	13	7.5 *
10	0.10 - 2.90	35	20	15	9.0
13	0.30 - 3.50	39	19	20	11.0

Notes:

- The test sample for liquid and plastic limit was air-dried & dry-sieved
- The linear shrinkage mould was 125mm
- Refer to appropriate notes for soil descriptions
- Date of receipt of sample: 20/05/2019.
- Sampled and supplied by client.
- * Denotes Linear Shrinkage cracked.



NATA Accredited Laboratory
Number:1327

Accredited for compliance with ISO/IEC 17025 - Testing.
This document shall not be reproduced except
in full.


Authorised Signature / Date
(D. Troweek)

29/5/19

All services provided by STS are subject to our standard terms and conditions. A copy is available on request.

Appendix G

Aggressivity Test Results Sheet



CERTIFICATE OF ANALYSIS

Work Order : **ES1915695**
Client : **PELLS SULLIVAN MEYNINK T/A PSM Admin PTY LTD**
Contact : **NGOC TUAN HOANG**
Address : **G3, 56 DELHI ROAD**
NORTH RYDE NSW, AUSTRALIA 2113
Telephone : **----**
Project : **PSM3828 RYDE HOSPITAL**
Order number : **----**
C-O-C number : **----**
Sampler : **NGOC TUAN HOANG**
Site : **----**
Quote number : **EN/333**
No. of samples received : **6**
No. of samples analysed : **6**

Page : 1 of 4
Laboratory : Environmental Division Sydney
Contact : Customer Services ES
Address : 277-289 Woodpark Road Smithfield NSW Australia 2164
Telephone : +61-2-8784 8555
Date Samples Received : 22-May-2019 15:00
Date Analysis Commenced : 24-May-2019
Issue Date : 28-May-2019 18:00



This report supersedes any previous report(s) with this reference. Results apply to the sample(s) as submitted. This document shall not be reproduced, except in full.

This Certificate of Analysis contains the following information:

- General Comments
- Analytical Results

Additional information pertinent to this report will be found in the following separate attachments: Quality Control Report, QA/QC Compliance Assessment to assist with Quality Review and Sample Receipt Notification.

Signatories

This document has been electronically signed by the authorized signatories below. Electronic signing is carried out in compliance with procedures specified in 21 CFR Part 11.

Signatories	Position	Accreditation Category
Ankit Joshi	Inorganic Chemist	Sydney Inorganics, Smithfield, NSW
Celine Conceicao	Senior Spectroscopist	Sydney Inorganics, Smithfield, NSW



General Comments

The analytical procedures used by the Environmental Division have been developed from established internationally recognized procedures such as those published by the USEPA, APHA, AS and NEPM. In house developed procedures are employed in the absence of documented standards or by client request.

Where moisture determination has been performed, results are reported on a dry weight basis.

Where a reported less than (<) result is higher than the LOR, this may be due to primary sample extract/digestate dilution and/or insufficient sample for analysis.

Where the LOR of a reported result differs from standard LOR, this may be due to high moisture content, insufficient sample (reduced weight employed) or matrix interference.

When sampling time information is not provided by the client, sampling dates are shown without a time component. In these instances, the time component has been assumed by the laboratory for processing purposes.

Where a result is required to meet compliance limits the associated uncertainty must be considered. Refer to the ALS Contact for details.

Key : CAS Number = CAS registry number from database maintained by Chemical Abstracts Services. The Chemical Abstracts Service is a division of the American Chemical Society.
LOR = Limit of reporting
^ = This result is computed from individual analyte detections at or above the level of reporting
ø = ALS is not NATA accredited for these tests.
~ = Indicates an estimated value.

- ED045G: LOR raised for Chloride on sample 4 due to sample matrix.



Analytical Results

Sub-Matrix: SOIL (Matrix: SOIL)				Client sample ID	BH01 1m	BH03 0.5m	BH04 1m	BH07 0.5-1m	BH11 0.5m
Client sampling date / time					14-May-2019 09:00	15-May-2019 10:00	15-May-2019 09:00	17-May-2019 09:00	18-May-2019 11:00
Compound	CAS Number	LOR	Unit		ES1915695-001	ES1915695-002	ES1915695-003	ES1915695-004	ES1915695-005
				Result	Result	Result	Result	Result	Result
EA002: pH 1:5 (Soils)									
pH Value	----	0.1	pH Unit		4.7	8.7	5.1	6.8	4.7
EA055: Moisture Content (Dried @ 105-110°C)									
Moisture Content	----	1.0	%		17.2	5.1	20.1	18.3	17.4
ED040S : Soluble Sulfate by ICPAES									
Sulfate as SO4 2-	14808-79-8	10	mg/kg		50	90	40	180	110
ED045G: Chloride by Discrete Analyser									
Chloride	16887-00-6	10	mg/kg		10	<10	20	<50	30




Analytical Results

Sub-Matrix: SOIL (Matrix: SOIL)				Client sample ID	BH13 0.5-1m	----	----	----	----
				Client sampling date / time	19-May-2019 07:00	----	----	----	----
Compound	CAS Number	LOR	Unit		ES1915695-006	-----	-----	-----	-----
				Result		----	----	----	----
EA002: pH 1:5 (Soils)									
pH Value	----	0.1	pH Unit		9.5	----	----	----	----
EA055: Moisture Content (Dried @ 105-110°C)									
Moisture Content	----	1.0	%		19.7	----	----	----	----
ED040S : Soluble Sulfate by ICPAES									
Sulfate as SO4 2-	14808-79-8	10	mg/kg		240	----	----	----	----
ED045G: Chloride by Discrete Analyser									
Chloride	16887-00-6	10	mg/kg		<10	----	----	----	----

Appendix H

Ryde Hospital Sketches



22/11/2018 2:25:18 PM C:\REVIT\LOCAL2019\10889_RH-CF_DavidCa.rvt

Client



Health
Infrastructure

Project Name
Ryde Hospital Site Evaluation

Project Address
Denistone Road, Eastwood, NSW, 2122

Document Status
For Information


Drawing Title:
Level 1 - Departments

Date:
22.11.2018
Drawing Number:
10889_SK006

Sheet Size:
A3
Issue:
2

Scale:
1:1000
0 20000

nettleontribe



22/11/2018 2:25:18 PM C:\REVIT\LOCAL2019\10889_RH-CF_DavidCa.rvt

Client



Health
Infrastructure

Project Name
Ryde Hospital Site Evaluation

Project Address
Denistone Road, Eastwood, NSW, 2122

Document Status
For Information


Drawing Title:
Level 1 - Departments

Date:
22.11.2018
Drawing Number:
10889_SK006

Sheet Size:
A3
Issue:
2

Scale:
1:1000
0 20000

nettleontribe



22/11/2018 2:25:18 PM C:\REVIT\LOCAL2019\10889_RH-CF_DavidCa.rvt

Client



Health
Infrastructure

Project Name
Ryde Hospital Site Evaluation

Project Address
Denistone Road, Eastwood, NSW, 2122

Document Status
For Information

Drawing Title:
Level 1 - Departments

Date:
22.11.2018

Drawing Number:
10889_SK006

Sheet Size:
A3

Issue:
2


Scale:
1:1000

0 20000



nettletontribe





Client



Health
Infrastructure

Project Name
Ryde Hospital Site Evaluation

Project Address
Denistone Road, Eastwood, NSW, 2122

Document Status
For Information

Drawing Title:
Sections blocking and stacking

Date:

Sheet Size:
A3

Scale:

Drawing Number:
10889_SK019

Issue:

0 20000

nettleontribe