

1. DC30A-CP11 (Ch 2.0)
Cross-connection to parallel channel



2. DC30A-CP11 (Ch 2.0)
Cross-connection to parallel channel



3. DC30A-CP09 to CP10 (Ch 174.0)
Spalling concrete & exposed reo



4. DC30A-CP08 (Ch 226.0)
Deteriorated step-iron



5. DC30A2-CP15 to CP16 (Ch 0.0)
Transition from circular channel



6. DC30A2-CP11 to CP14 (Ch 91.0)
Debris in channel floor



7. DC30A2-CP11 to CP14 (Ch 91.0)
Debris in channel floor



8. DC30A2-CP11 to CP14 (Ch 215.0)
Transition & increased water depth



9. DC30P1-CP07 to CP08 (Ch 118.0)
Spalling concrete & exposed reo



10. DC30P1-CP07 to CP08 (Ch 132.0)
Aluminium sheeting in roof



11. DC30P1-CP06 (Ch 183.0)
Manhole chamber



12. DC30P1-CP05 (Ch 332.0)
Transition & weir across DC30P1



13. DC30P1-CP05 (Ch 332.0)
Weir across DC30P1



14. DC30P1-CP04 (Ch 0.0)
Heavy silt just below waterline




15. DC30P1-CP01 (Ch 104.0)
Exposed steel beams in roof




16. DC30P2-CP01 (Ch 0.0)
Typical channel section




Table A

Likelihood	Defect Characteristics		Examples						
	State (w.r.t. failure mode)	Extent of defect	Spalling concrete	Exposed reinforcement	Steel corrosion	Cracking	Siltation		
Almost certain	Highly advanced	Very extensive	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		
Very likely	Advanced	Extensive	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		No photo yet identified for this defect likelihood. Such a defect should not appear in this report.				
Likely	Established	Large					No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		
Unlikely	Established	Localised	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		No photo yet identified for this defect likelihood. Such a defect should not appear in this report.				
Improbable	Established	Minor	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		No photo yet identified for this defect likelihood. Such a defect should not appear in this report.	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		









33

COPYRIGHT RESERVED SYDNEY WATER 1998
NO WARRANTY IS GIVEN THAT THIS IS COMPLETE OR ACCURATE




SEE SHEET 3
1845-41-12
DIXON
VENT
CPI10
CPI11
CPI12
CPI13
CPI14
CPI15
CPI16
CPI17
CPI18
CPI19
CPI20
CPI21
CPI22
CPI23
CPI24
CPI25
CPI26
CPI27
CPI28
CPI29
CPI30
CPI31
CPI32
CPI33
CPI34
CPI35
CPI36
CPI37
CPI38
CPI39
CPI40
CPI41
CPI42
CPI43
CPI44
CPI45
CPI46
CPI47
CPI48
CPI49
CPI50
CPI51
CPI52
CPI53
CPI54
CPI55
CPI56
CPI57
CPI58
CPI59
CPI60
CPI61
CPI62
CPI63
CPI64
CPI65
CPI66
CPI67
CPI68
CPI69
CPI70
CPI71
CPI72
CPI73
CPI74
CPI75
CPI76
CPI77
CPI78
CPI79
CPI80
CPI81
CPI82
CPI83
CPI84
CPI85
CPI86
CPI87
CPI88
CPI89
CPI90
CPI91
CPI92
CPI93
CPI94
CPI95
CPI96
CPI97
CPI98
CPI99
CPI100



33

COPYRIGHT RESERVED SYDNEY WATER 1998
NO WARRANTY IS GIVEN THAT THIS IS COMPLETE OR ACCURATE



COPYRIGHT RESERVED SYDNEY WATER 1998.
NO WARRANTY IS GIVEN THAT THIS IS COMPLETE OR ACCURATE.

APPENDIX J

MWS&DB, CITY OF SYDNEY DETAIL SHEET 3739, 3740

