

1. DC30A-CP11 (Ch 2.0)
Cross-connection to parallel channel



2. DC30A-CP11 (Ch 2.0)
Cross-connection to parallel channel



3. DC30A-CP09 to CP10 (Ch 174.0)
Spalling concrete & exposed reo



4. DC30A-CP08 (Ch 226.0)
Deteriorated step-iron



5. DC30A2-CP15 to CP16 (Ch 0.0)
Transition from circular channel



6. DC30A2-CP11 to CP14 (Ch 91.0)
Debris in channel floor



7. DC30A2-CP11 to CP14 (Ch 91.0)
Debris in channel floor



8. DC30A2-CP11 to CP14 (Ch 215.0)
Transition & increased water depth



9. DC30P1-CP07 to CP08 (Ch 118.0)
Spalling concrete & exposed reo



10. DC30P1-CP07 to CP08 (Ch 132.0)
Aluminium sheeting in roof



11. DC30P1-CP06 (Ch 183.0)
Manhole chamber



12. DC30P1-CP05 (Ch 332.0)
Transition & weir across DC30P1



13. DC30P1-CP05 (Ch 332.0)
Weir across DC30P1



14. DC30P1-CP04 (Ch 0.0)
Heavy silt just below waterline




15. DC30P1-CP01 (Ch 104.0)
Exposed steel beams in roof




16. DC30P2-CP01 (Ch 0.0)
Typical channel section




Table A

Likelihood	Defect Characteristics		Examples						
	State (w.r.t. failure mode)	Extent of defect	Spalling concrete	Exposed reinforcement	Steel corrosion	Cracking	Siltation		
Almost certain	Highly advanced	Very extensive	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		
Very likely	Advanced	Extensive	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		No photo yet identified for this defect likelihood. Such a defect should not appear in this report.				
Likely	Established	Large					No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		
Unlikely	Established	Localised	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		No photo yet identified for this defect likelihood. Such a defect should not appear in this report.				
Improbable	Established	Minor	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		No photo yet identified for this defect likelihood. Such a defect should not appear in this report.	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.	No photo yet identified for this defect likelihood. Such a defect should not appear in this report.		




1845-41-32 SEE SHEET 5

COPYRIGHT RESERVED SYDNEY WATER 1998
NO WARRANTY IS GIVEN THAT THIS IS COMPLETE OR ACCURATE




COPYRIGHT RESERVED SYDNEY WATER 1998.
NO WARRANTY IS GIVEN THAT THIS IS COMPLETE OR ACCURATE SEE SHEET 2




33

COPYRIGHT RESERVED SYDNEY WATER 1998
NO WARRANTY IS GIVEN THAT THIS IS COMPLETE OR ACCURATE



SEE SHEET 3

COPYRIGHT RESERVED SYDNEY WATER 1998
NO WARRANTY IS GIVEN THAT THIS IS COMPLETE OR ACCURATE



33

COPYRIGHT RESERVED SYDNEY WATER 1998
NO WARRANTY IS GIVEN THAT THIS IS COMPLETE OR ACCURATE

APPENDIX J

MWS&DB, CITY OF SYDNEY DETAIL SHEET 3739, 3740



