

Site Photos



Figure 1: TFI Bourke Entrance Display Board



Figure 2: Front lawns and internal road



Figure 3: Pedestrian walkway



Figure 4: Backside road of the building



Figure 5: Front gate entry and associated signage



Figure 6: Security office at front entrance



Figure 7: Sediment Dam



Figure 8: Car park




Figure 9: Ramp



Figure 10: Livestock chilling area



Figure 11: Safety Signs for LPG filling area



Figure 12: Water dosing chemical stored on a bunding



Figure 13: Chemical Room Signage (a)



Figure 14: Chemical Room Signage (b)



Figure 15: SBR Pond



Figure 16: Balance Tank in WWTP Area



Figure 17: Stock stored in Chemical Room



Figure 18: Gurri tree cuttings taken on 19/09/2023 and being propagated by TFI



Figure 19: Center Pivot Irrigator



Figure 20: Center Pivot Control Panel



Figure 21: Tail-water Pond and Swale Drain



Figure 22: Irrigation Land prepared for Cropping