




Figure 11 – Southern view along Beach Street towards vehicular Site entrance



Figure 12 – Northern view along Beach Street towards vehicular Site entrance



Figure 13 – Eastern view into the Site




Figure 14 – Northern view from within the Site vehicular entry




Figure 15 – Western view towards Site vehicular entry



Figure 16 – Eastern view along driveway towards overland flow weir



Figure 17 – Overland flow weir downstream of the Site vehicular entrance




Figure 18 – Western view of overland flow weir, mound and overflow paths




Figure 19 – Eastern view of mound and overflow paths



Figure 20 – Eastern view of primary overflow path entering vegetation area