

17 – Asbestos Report

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Waitara Public School (3334)


Region : Northern Sydney

State Electorate : Ku-ring-gai

Local Government Area : Hornsby

Initial Survey : Noel Arnold & Associates : 28 - Mar - 2008

Register Issue Date : 03 - Dec - 2015



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00A - Administration/General Learning - 1991 - Brick/Block (Masonry: 1940 - 1950s)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - External Movement (1.48 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos -**B00A - R0003 - General Storeroom (5.03 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	3334/B00A/R0003/Floor Coverings Res/Textile/S15				No Asbestos Detected
-----------------------------	-------------	---	--	--	--	-----------------------------

B00A - R0004 - Library Office/Workroom (18.61 m2)

No Asbestos

B00A - R0005 - Cleaning Distributed Store (2.17 m2)

Floor Coverings Res/Textile	Vinyl Tiles	3334/B00A/R0005/Floor Coverings Res/Textile/S16				No Asbestos Detected
-----------------------------	-------------	---	--	--	--	-----------------------------

B00A - R0006 - Staff Toilet (3.94 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos -**B00A - R0007 - Staff Toilet (7.75 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos -**B00A - R0008 - Duplicating Workroom (8.93 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos -**B00A - R0009 - External Movement (1.78 m2)**

No Asbestos

B00A - R0010 - Practical Activities - 1hb (10.13 m2)

No Asbestos

B00A - R0011 - Movement (4.52 m2)

No Asbestos

B00A - R0012 - External Movement (1.83 m2)

No Asbestos

B00A - R0013 - Home Base (46.78 m2)

Chalk Board	Compressed AC Sheet	4m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00J/R0003/Chalk Board/S13				Chrysotile (white asbestos)		

B00A - R0016 - Staff Room (46.78 m2)

No Asbestos

B00A - R0017 - Deputy Principal (15.45 m2)

No Asbestos

B00A - R0018 - Staff Toilet (3.48 m2)

No Asbestos

B00A - R0019 - General Storeroom (3.5 m2)

No Asbestos

B00A - R0020 - Principal (13.8 m2)

No Asbestos

B00A - R0021 - Security Store (6.36 m2)

No Asbestos

B00A - R0022 - Movement (94.3 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

B00A - R0023 - Staff Room (94.57 m2)

Recently Modified Space Requires Inspection

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00B - General Learning - 1959 - Timber (Timber: Fixed 1947 - 1960s)**Exterior**

Eaves Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00B/Eaves Linings/S4			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00B - R0001 - Withdrawal Space - 1hb (8.57 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00B/R0004/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0002 - Home Base (53.66 m2)

Wall Linings Internal	Flat AC Sheeting	2m2	Adjacent heater South East corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00B/R0002/Wall Linings Internal/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0003 - Home Base (53.51 m2)

Wall Linings Internal	Flat AC Sheeting	2m2	Adjacent heater South East corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00B/R0002/Wall Linings Internal/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0004 - External Movement (22.28 m2)

Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00B/R0004/Ceiling Structures/Linings/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	2m2	South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00B/R0004/Wall Linings Internal/S3			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00C - General Learning - 1963 - Brick/Veneer (PSFS: Vanderstein)**Exterior**

Gable end strips	Flat AC Sheeting	16m	East and West elevations	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos -					
Eaves Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/Eaves Linings/S5					Chrysotile (white asbestos)
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00C - R0001 - Home Base (57.66 m2)**

No Asbestos

B00C - R0002 - Home Base Store (4.56 m2)

No Asbestos

B00C - R0004 - Personal Effects Storage (8.73 m2)

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/R0004/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					
	3334/B00C/R0004/Wall Linings Internal/S7					No Asbestos Detected

B00C - R0005 - Movement (5.82 m2)

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/R0004/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

B00C - R0006 - General Storeroom (0.53 m2)

Floor Coverings Res/Textile	Vinyl Tiles	0.5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/R0004/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

B00C - R0007 - Cleaning Distributed Store (0.53 m2)

Floor Coverings Res/Textile	Vinyl Tiles	0.5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/R0004/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

B00C - R0008 - Home Base Store (4.58 m2)

No Asbestos

B00C - R0009 - Home Base (57.66 m2)

No Asbestos

B00C - R0010 - External Movement (1.69 m2)

No Asbestos

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00D - General Learning - 2006 - Fibre Cement Clad (PSFS: Kits - MDR)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - Movement (38.48 m2)**

No Asbestos

B00D - R0002 - Practical Activities - 1hb (19.4 m2)

No Asbestos

B00D - R0003 - Home Base Store (6.02 m2)Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0004 - Home Base (59.2 m2)**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0005 - Withdrawal Space - 2hb (11.36 m2)**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0006 - Home Base (59.19 m2)**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0007 - Home Base Store (6.02 m2)**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0008 - Practical Activities - 1hb (19.41 m2)**

No Asbestos

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning/Library - 1992 - Brick/Veneer (PSFS: Kits -Rabong)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00E - R0001 - Cleaning Distributed Store (3.41 m2)**

No Asbestos

B00E - R0002 - General Storeroom (1.66 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0003 - Special Programs Room (36.47 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0004 - Plant (3.26 m2)

No Asbestos

B00E - R0005 - Cleaning Distributed Store (1.59 m2)

No Asbestos

B00E - R0006 - External Movement (53.52 m2)

No Asbestos

B00E - R0007 - Reading Area (161.53 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0008 - Library Office/Workroom (28.74 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0009 - Communications Room (14.09 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0010 - External Movement (19.89 m2)

No Asbestos

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00F - Communal Facilities - 1985 - Brick/Veneer (PSFS: Vanderstein)**Exterior**

Wall Cladding	Flat AC Sheeting 3334/B00G/Wall Cladding/S8	No Asbestos Detected				
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00F - R0001 - Cleaning Distributed Store (0.96 m2)**

No Asbestos

B00F - R0002 - Distribution Board (0.88 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0003 - Shower/Change (2.26 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 3334/B00F/R0011/Partition Walls (Cubicles)/S17	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00F - R0004 - Toilets - Girls (10.93 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 3334/B00F/R0011/Partition Walls (Cubicles)/S17	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00F - R0005 - Hall Chair Store (2.57 m2)

No Asbestos

B00F - R0006 - Movement (6.54 m2)

No Asbestos

B00F - R0007 - External Movement (16.81 m2)

No Asbestos

B00F - R0008 - Raised Platform (54.93 m2)

No Asbestos

B00F - R0009 - Movement (6.48 m2)

No Asbestos

B00F - R0010 - Shower/Change (2.8 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 3334/B00F/R0011/Partition Walls (Cubicles)/S17	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00F - R0011 - Toilets - Boys (10.84 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 3334/B00F/R0011/Partition Walls (Cubicles)/S17	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00F - R0012 - Hall Chair Store (2.57 m2)

No Asbestos

B00F - R0013 - Communal Space (135.66 m2)

No Asbestos

B00F - R0014 - External Movement (23.09 m2)

No Asbestos

B00F - R0015 - No Access (2.84 m2)

No Asbestos

B00F - R0016 - P.E. Store (13.11 m2)

No Asbestos

B00F - R0017 - Canteen Office/Store (4.87 m2)

No Asbestos

B00F - R0019 - Canteen Office/Store (3.84 m2)

No Asbestos

B00F - R0020 - Music Store (10.58 m2)

No Asbestos

B00F - R0021 - Canteen (27.57 m2)

No Asbestos

B00F - R0022 - External Movement (76.11 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00F - R0023 - Distribution Board (1.26 m2)				Note: No inspection of live electrical installation.		

No Asbestos

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00G - General Learning - 1963 - Brick/Veneer (PSFS: Vanderstein)**Exterior**

Gable verge lining	Flat AC Sheeting	15m	East and West elevations	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos -						
Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3334/B00C/Eaves Linings/S5				Chrysotile (white asbestos)	
Wall Cladding	Flat AC Sheeting	No Asbestos Detected				
	3334/B00G/Wall Cladding/S8					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00G - R0001 - Staff Toilet (3.17 m2)**

Wall Linings Internal	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00G/R0001/Wall Linings Internal/S9				Chrysotile (white asbestos)		

B00G - R0002 - Special Programs Room (21.03 m2)

No Asbestos

B00G - R0003 - Special Programs Room (21.39 m2)

No Asbestos

B00G - R0004 - General Storeroom (7.2 m2)

Non Accessible Requires Inspection

B00G - R0005 - Toilets - Boys/Girls (3.11 m2)

Wall Linings Internal	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00G/R0001/Wall Linings Internal/S9				Chrysotile (white asbestos)		

B00G - R0006 - Personal Effects Storage (10.4 m2)

No Asbestos

B00G - R0007 - Movement (16.59 m2)

No Asbestos

B00G - R0008 - Home Base (78.85 m2)

No Asbestos

B00G - R0009 - Special Programs Room (46.47 m2)

No Asbestos

B00G - R0010 - Practical Activities - 1hb (22.8 m2)

No Asbestos

B00G - R0011 - External Movement (5.54 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00G/R0011/Ceiling Structures/Linings/S10				Chrysotile (white asbestos)		

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00H - Other-Regional Use - 1951 - Steel (PSFS: Kits - Hawkesly)**Exterior**

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior**B00H - R0001 - Uniform Shop (5.86 m2)**

No Asbestos

B00H - R0002 - External Movement (23.11 m2)

No Asbestos

B00H - R0003 - General Storeroom (5.86 m2)

No Asbestos

B00H - R0004 - No Access (53.82 m2)Floor Coverings Vinyl Tiles
Res/Textile

3334/B00H/R0004/Floor Coverings Res/Textile/S11

No Asbestos Detected**B00H - R0005 - No Access (52.61 m2)**Floor Coverings Vinyl Tiles
Res/Textile

3334/B00H/R0004/Floor Coverings Res/Textile/S11

No Asbestos Detected

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00I - General Learning - 1991 - Timber (Timber: Fixed 1947 - 1960s)**Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior**B00I - R0001 - Home Base (46.98 m2)**

No Asbestos

B00I - R0002 - External Movement (11.96 m2)

No Asbestos

B00I - R0003 - General Storeroom (0.4 m2)

No Asbestos

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00J - General Learning - 1991 - Timber (Masonry: 1940 - 1950s)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00J - R0001 - General Storeroom (19.48 m2)**

No Asbestos

B00J - R0002 - Home Base Store (7.48 m2)

No Asbestos

B00J - R0003 - Home Base (47.54 m2)

Chalk Board	Compressed AC Sheet	10m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00J/R0003/Chalk Board/S13					Chrysotile (white asbestos)	

B00J - R0004 - Home Base (47.54 m2)

Chalk Board	Compressed AC Sheet	10m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00J/R0003/Chalk Board/S13					Chrysotile (white asbestos)	

B00J - R0005 - Personal Effects Storage (47 m2)

Floor Coverings Res/Textile	Vinyl Tiles
3334/B00J/R0005/Floor Coverings Res/Textile/S12	

No Asbestos Detected**B00J - R0006 - Distribution Board (0.1 m2)**

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0007 - Practical Activities - 1hb (21.85 m2)

No Asbestos

B00J - R0008 - Home Base (47.54 m2)

Chalk Board	Compressed AC Sheet	11m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00J/R0003/Chalk Board/S13					Chrysotile (white asbestos)	

B00J - R0009 - General Storeroom (0.71 m2)

No Asbestos

B00J - R0010 - Movement (1.65 m2)

No Asbestos

B00J - R0011 - Staff Toilet (3.58 m2)

No Asbestos

B00J - R0012 - General Storeroom (0.7 m2)

No Asbestos

B00J - R0013 - Library Office/Workroom (13.23 m2)

No Asbestos

B00J - R0014 - Staff Room Annexe (4.36 m2)

No Asbestos

B00J - R0015 - External Movement (1.04 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00G/R0011/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00K - Storage - 1951 - Steel (PSFS: Kits - Hawkesly)**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior**B00K - R0001 - Special Programs Room (53.29 m2)**

No Asbestos

B00K - R0002 - General Storeroom (53.29 m2)

No Asbestos

B00K - R0003 - Cleaning Supplies (2.17 m2)

Wall Linings Internal	Flat AC Sheeting	8m2	East and North walls	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00K/R0003/Wall Linings Internal/S14					Chrysotile (white asbestos)	

B00K - R0004 - External Movement (22.21 m2)

Wall Linings Internal	Flat AC Sheeting	2m2	East and North walls	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00K/R0003/Wall Linings Internal/S14					Chrysotile (white asbestos)	

B00K - R0005 - Personal Effects Storage (4.93 m2)

Wall Linings Internal	Flat AC Sheeting	6m2	East and North walls	Good Condition (1)	Low (1)	Low Priority (2-3)
3334/B00K/R0003/Wall Linings Internal/S14					Chrysotile (white asbestos)	

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00L - Pupil Facilities - 1991 - Brick/Block (Masonry: 1940 - 1950s)**Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

Interior**B00L - R0001 - Toilets - Girls (21.86 m2)**

No Asbestos

B00L - R0002 - General Assistant/Bulk Store (9.32 m2)

No Asbestos

B00L - R0003 - Toilets - Boys (21.76 m2)

No Asbestos

B00L - R0004 - External Movement (15.01 m2)

No Asbestos

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00M - General Learning/Pupil Facilities - 2011 - Brick/Veneer**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00M - R0001 - Home Base (61.25 m2)**

No Asbestos

B00M - R0002 - Home Base (61.25 m2)

No Asbestos

B00M - R0003 - Home Base Store (6.28 m2)

No Asbestos

B00M - R0004 - Practical Activities/Movement - 1hb (18.55 m2)

No Asbestos

B00M - R0005 - Withdrawal Space - 2hb (11.43 m2)

No Asbestos

B00M - R0006 - Practical Activities/Movement - 1hb (18.55 m2)

No Asbestos

B00M - R0007 - Home Base Store (6.28 m2)

No Asbestos

B00M - R0008 - General Assistant/Bulk Store (20.05 m2)

No Asbestos

B00M - R0009 - Toilets - Girls (23.03 m2)

No Asbestos

B00M - R0010 - Toilets - Boys (16.35 m2)

No Asbestos

B00M - R0011 - Access Shower/Toilet/Change (5.9 m2)

No Asbestos

B00M - R0012 - General Storeroom (4.57 m2)

No Asbestos

B00M - R0013 - General Storeroom (4.57 m2)

No Asbestos

B00M - R0014 - External Movement (104.5 m2)

No Asbestos

B00M - R0015 - External Stairs (10.91 m2)

No Asbestos

B00M - R0016 - External Stairs (10.91 m2)

No Asbestos

B00M - R1001 - Home Base (61.25 m2)

No Asbestos

B00M - R1002 - Home Base (61.04 m2)

No Asbestos

B00M - R1003 - Home Base (58.81 m2)

No Asbestos

B00M - R1004 - Home Base Store (6.28 m2)

No Asbestos

B00M - R1005 - Practical Activities/Movement - 1hb (18.55 m2)

No Asbestos

B00M - R1006 - Withdrawal Space - 2hb (11.43 m2)

No Asbestos

B00M - R1007 - Practical Activities/Movement - 1hb (18.55 m2)

No Asbestos

B00M - R1008 - Home Base Store (6.28 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00M - R1009 - Withdrawal Space - 1hb (9.12 m2)						
No Asbestos						
B00M - R1010 - Home Base Store (6.01 m2)						
No Asbestos						
B00M - R1011 - Practical Activities/Movement - 1hb (19.49 m2)						
No Asbestos						
B00M - R1012 - External Movement (75.21 m2)						
No Asbestos						
B00M - R1013 - External Stairs (18.58 m2)						
No Asbestos						
B00M - R1014 - External Stairs (18.58 m2)						
No Asbestos						

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

Demountables

Demountable details as per the AMS records as of 30 Nov 2015.

OS 602 - D10265 - Learning Unit - Standard With P.A.A. : Placement Date - 29/09/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D11409 - Learning Unit - Standard/Withdrawal : Placement Date - 29/05/1998

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D11618 - Learning Unit - Standard/Withdrawal : Placement Date - 2/09/1999

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 602 - D12132 - Learning Unit - Standard With P.A.A. : Placement Date - 20/02/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 750 - D12469 - Learning Unit - ESL : Placement Date - 13/03/1996						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				5.76 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Esl						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
OS 601 - D12609 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 840 - D12678 - Girls Toilet : Placement Date - 29/10/1998						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				2.88 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Toilets-Girls						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
End wall panel	Flat AC Sheet	Assumed Asbestos				36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2
OS 602 - D13138 - Learning Unit - Standard With P.A.A. : Placement Date - 2/02/2011						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
OS 601 - D13630 - Learning Unit - Standard/Withdrawal : Placement Date - 19/01/2015						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D13760 - Learning Unit - Standard/Withdrawal : Placement Date - 6/06/2007						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 602 - D14254 - Learning Unit - Standard With P.A.A. : Placement Date - 18/09/2008						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 841 - D14539 - Boys Toilet : Placement Date - 29/10/1998						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				2.88 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Toilets-Boys						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				6 m2
End wall panel	Flat AC Sheet	Assumed Asbestos				36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

OS 602 - D14580 - Learning Unit - Standard With P.A.A. : Placement Date - 29/12/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D14959 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995**Exterior**

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior**R1 - Entry**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 840 - D15571 - Girls Toilet : Placement Date - 29/10/1998**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2

Interior**R1 - Toilets-Girls**

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	4 m2
End wall panel	Flat AC Sheet	Assumed Asbestos	36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

2015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 30/11/2015

There are no asbestos related file attachment(s) for this school.

2015

