


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Fairvale High School (8456)  
**Region :** South Western Sydney  
**State Electorate :** Fairfield  
**Local Government Area :** Fairfield

**Initial Survey :** Noel Arnold & Associates : 14 - Jan - 2010  
**Reviewed By :** Grencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Computer Learning/General Learning - 1969 - Brick/Block (Brick/Block)****Exterior**

Wall Cladding	Galbestos	200m2	Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction - Approx. 7m</b>						

Ceiling Voids	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2	<b>No Asbestos Detected</b>				
---------------	--	-----------------------------	--	--	--	--

Underfloor Voids - Slab on Ground	No Asbestos Found					
-----------------------------------	-------------------	--	--	--	--	--

**Interior****B00A - R0001 - Staff - Toilet**

No Asbestos

**B00A - R0002 - Plant**

Door linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00A/R0002/Door linings/S1 <b>Chrysotile (white asbestos)</b>						

**B00A - R0003 - Cleaning Supplies Store**

No Asbestos

**B00A - R0004 - External Stairs**

No Asbestos

**B00A - R0005 - Senior Learning Centre**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2	<b>No Asbestos Detected</b>				
----------------------------	--	-----------------------------	--	--	--	--

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8456/B00A/R0006/Floor Coverings Res/Textile/S3	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						

**B00A - R0006 - Ancillary Staff**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2	<b>No Asbestos Detected</b>				
----------------------------	--	-----------------------------	--	--	--	--

**B00A - R0009 - Staff - Toilet**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2	<b>No Asbestos Detected</b>				
----------------------------	--	-----------------------------	--	--	--	--

**B00A - R0010 - Staff - Toilet**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2	<b>No Asbestos Detected</b>				
----------------------------	--	-----------------------------	--	--	--	--

**B00A - R0011 - External Stairs**

No Asbestos

**B00A - R0018 - General Storeroom**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2	<b>No Asbestos Detected</b>				
----------------------------	--	-----------------------------	--	--	--	--

**B00A - R0019 - Staff - Toilet**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2	<b>No Asbestos Detected</b>				
----------------------------	--	-----------------------------	--	--	--	--

**B00A - R0022 - Archive Store**

No Asbestos

**B00A - R0024 - Plant**

Door linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00A/R0002/Door linings/S1 <b>Chrysotile (white asbestos)</b>						

**B00A - R0025 - Resources Store**

No Asbestos

**B00A - R0026 - General Learning Space**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00A/R0006/Floor Coverings Res/Textile/S3	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0027 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00A/R0006/Floor Coverings Res/Textile/S3	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0029 - Office/Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00A/R0006/Floor Coverings Res/Textile/S3	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0030 - Laboratory L.S.</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00A/R0006/Floor Coverings Res/Textile/S3	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0031 - Preparation - Science</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00A/R0006/Floor Coverings Res/Textile/S3	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0032 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00A/R0006/Floor Coverings Res/Textile/S3	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0033 - Laboratory L.S.</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
<b>B00A - R0035 - Public Reception</b>						
No Asbestos						
<b>B00A - R0036 - Administration - Clerical</b>						
No Asbestos						
<b>B00A - R0037 - Administration - Clerical</b>						
No Asbestos						
<b>B00A - R0038 - Principal Office</b>						
No Asbestos						
<b>B00A - R0039 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0040 - Administration - Clerical</b>						
No Asbestos						
<b>B00A - R0041 - Administration - Clerical</b>						
No Asbestos						
<b>B00A - R0042 - Pupil Entry</b>						
No Asbestos						
<b>B00A - R0043 - Printing/Photocopying</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
<b>B00A - R0044 - Interview/Office - Type 1</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0045 - Interview/Office - Type 1</b>						
No Asbestos						
<b>B00A - R0046 - Office/Store</b>						
No Asbestos						
<b>B00A - R0047 - Movement</b>						
No Asbestos						
<b>B00A - R0048 - Administration - Clerical</b>						
No Asbestos						
<b>B00A - R0049 - Deputy Principal Office</b>						
No Asbestos						
<b>B00A - R0050 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0051 - Archive Store</b>						
No Asbestos						
<b>B00A - R0052 - General Storeroom</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00A/R0028/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0053 - Cleaning Supplies Store</b>						
No Asbestos						
<b>B00A - R0054 - Handwashing Facilities</b>						
No Asbestos						
<b>B00A - R0055 - External Movement</b>						
Wall Linings Internal	Flat AC Sheeting 8456/B00A/R0055/Wall Linings Internal/S40					<b>No Asbestos Detected</b>
<b>B00A - R1001 - Staff - Toilet</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					<b>No Asbestos Detected</b>
<b>B00A - R1002 - Distribution Board Cupboard</b>						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	8456/B00A/R1002/Ceiling Structures/Linings/S36					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Door linings	Flat AC Sheeting	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00A/R0002/Door linings/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1003 - External Stairs</b>						
No Asbestos						
<b>B00A - R1004 - Computer Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					<b>No Asbestos Detected</b>
<b>B00A - R1005 - System Administrators Office</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					<b>No Asbestos Detected</b>
<b>B00A - R1006 - Computer Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					<b>No Asbestos Detected</b>
<b>B00A - R1007 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00A/R0006/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1008 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00A/R0005/Ceiling Structures/Linings/S2						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00A/R0006/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1009 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00A/R0005/Ceiling Structures/Linings/S2						
<b>B00A - R1010 - Materials Learning Space - Type 1</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00A/R0005/Ceiling Structures/Linings/S2						
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8456/B00A/R1014/Floor Coverings Res/Textile/S43						
<b>B00A - R1014 - Materials Learning Space - Type 1</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00A/R0005/Ceiling Structures/Linings/S2						
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8456/B00A/R1014/Floor Coverings Res/Textile/S43						
<b>B00A - R1015 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00A/R0005/Ceiling Structures/Linings/S2						
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8456/B00A/R1014/Floor Coverings Res/Textile/S43						
<b>B00A - R1016 - Cleaning Store - Distributed</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00A/R0005/Ceiling Structures/Linings/S2						
<b>B00A - R1017 - Distribution Board Cupboard</b>						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
8456/B00A/R1002/Ceiling Structures/Linings/S36					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Door linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00A/R0002/Door linings/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1018 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00A/R0005/Ceiling Structures/Linings/S2						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00A/R0006/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1019 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00A/R0005/Ceiling Structures/Linings/S2						
<b>B00A - R1020 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00A/R0005/Ceiling Structures/Linings/S2						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00A/R0006/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1021 - Toilets-Girls</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet 8456/B00A/R0028/Partition Walls (Cubicles)/S4	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

**B00A - R1022 - General Learning Space**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

**B00A - R1023 - General Learning Space**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8456/B00A/R1032/Floor Coverings Res/Textile/S41					No Asbestos Detected
-----------------------------	--	--	--	--	--	----------------------

**B00A - R1027 - Computer Resource**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

**B00A - R1028 - External Stairs**

No Asbestos

**B00A - R1029 - Staff Study**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

**B00A - R1030 - Computer Learning Space**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8456/B00A/R1030/Floor Coverings Res/Textile/S42					No Asbestos Detected
-----------------------------	--	--	--	--	--	----------------------

**B00A - R1031 - Staff Study**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8456/B00A/R0006/Floor Coverings Res/Textile/S3	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------------	---	------	------------	--------------------	---------	--

**B00A - R1032 - Tea Room**

Ceiling Structures/Linings	Vermiculite 8456/B00A/R0005/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

Floor Coverings Res/Textile	Vinyl Tiles 8456/B00A/R1032/Floor Coverings Res/Textile/S41					No Asbestos Detected
-----------------------------	--	--	--	--	--	----------------------

**B00A - R1033 - Handwashing Facilities**

No Asbestos

**B00A - R1034 - External Movement**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Technological & Applied Studies/Music/Art - 1969 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	Vermiculite					No Asbestos Detected
	8456/B00B/R0002/Ceiling Structures/Linings/S7					

**Interior****B00B - R0002 - Laundry**

Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	8456/B00B/R0002/Ceiling Structures/Linings/S7					

**B00B - R0006 - Kitchen - Type 2**

No Asbestos

**B00B - R0010 - Resources Store**

Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	8456/B00B/R0002/Ceiling Structures/Linings/S7					

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R0006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0011 - Resources Store**

Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	8456/B00B/R0002/Ceiling Structures/Linings/S7					

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R0006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0012 - General Storeroom**

No Asbestos

**B00B - R0013 - Plant**

Door linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R0013/Door linings/S9					Chrysotile (white asbestos)

**B00B - R0014 - Staff - Toilet**

No Asbestos

**B00B - R0020 - Music Store**

Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	8456/B00B/R0002/Ceiling Structures/Linings/S7					

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R0006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0021 - Music Learning Space**

Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	8456/B00B/R0002/Ceiling Structures/Linings/S7					

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R0006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0022 - Resources Store**

Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	8456/B00B/R0002/Ceiling Structures/Linings/S7					

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R0006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0023 - Plant**

Door linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R0013/Door linings/S9					Chrysotile (white asbestos)

**B00B - R0024 - Cleaning Store - Distributed**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00B - R0027 - General Storeroom</b>						
No Asbestos						
<b>B00B - R0029 - Welding Area</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
<b>B00B - R0030 - Metal Technology Bay</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	8456/B00B/R0035/Floor Coverings Res/Textile/S37					No Asbestos Detected
<b>B00B - R0032 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Cannot sample without excess</b>						
<b>B00B - R0033 - Food Technology L.S.</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
<b>B00B - R0034 - External Stairs</b>						
No Asbestos						
<b>B00B - R0035 - Materials Learning Space - Type 1</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	8456/B00B/R0035/Floor Coverings Res/Textile/S37					No Asbestos Detected
<b>B00B - R0036 - Welding/Hot Metals Area</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
<b>B00B - R0037 - Welding/Hot Metals Area</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
<b>B00B - R0038 - Materials Learning Space - Type 1</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	8456/B00B/R0035/Floor Coverings Res/Textile/S37					No Asbestos Detected
<b>B00B - R0039 - External Stairs</b>						
No Asbestos						
<b>B00B - R0043 - Kitchen - Type 2</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	8456/B00B/R0043/Floor Coverings Res/Textile/S38					No Asbestos Detected
<b>B00B - R0044 - Laundry</b>						
No Asbestos						
<b>B00B - R0045 - Food Technology L.S.</b>						
No Asbestos						
<b>B00B - R0046 - Change</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00B - R0047 - Movement</b>						
No Asbestos						
<b>B00B - R0048 - Preparation</b>						
No Asbestos						
<b>B00B - R0049 - Pantry</b>						
No Asbestos						
<b>B00B - R0050 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R0051 - Handwashing Facilities</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R0052 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R0053 - Handwashing Facilities</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R0006/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>
<b>B00B - R0054 - Handwashing Facilities</b>						
No Asbestos						
<b>B00B - R0055 - External Movement</b>						
No Asbestos						
<b>B00B - R1001 - External Stairs</b>						
No Asbestos						
<b>B00B - R1002 - Distribution Board Cupboard</b>						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	8456/B00B/R0013/Door linings/S9					<b>Chrysotile (white asbestos)</b>
Door linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R0013/Door linings/S9					<b>Chrysotile (white asbestos)</b>
<b>B00B - R1003 - Cleaning Store - Distributed</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R1004 - Art Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R1004/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
<b>B00B - R1005 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R1004/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
<b>B00B - R1006 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00B/R1004/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1007 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00B/R0002/Ceiling Structures/Linings/S7						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00B/R1004/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1008 - Art Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00B/R0002/Ceiling Structures/Linings/S7						
<b>B00B - R1009 - Art Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00B/R0002/Ceiling Structures/Linings/S7						
Floor Coverings Res/Textile	Vinyl Tiles	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00B/R1004/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1010 - Kiln Space</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00B/R0002/Ceiling Structures/Linings/S7						
Floor Coverings Res/Textile	Vinyl Tiles	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00B/R1004/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
Kiln	Encapsulated Insulation material within unit	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Not sampled - Live</b>						
<b>B00B - R1011 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00B/R0002/Ceiling Structures/Linings/S7						
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00B/R1004/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1014 - Music Store</b>						
No Asbestos						
<b>B00B - R1015 - Music Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00B/R0002/Ceiling Structures/Linings/S7						
<b>B00B - R1016 - Dust Extraction Space</b>						
No Asbestos						
<b>B00B - R1017 - Distribution Board Cupboard</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
8456/B00B/R0013/Door linings/S9					<b>Chrysotile (white asbestos)</b>	
Door linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00B/R0013/Door linings/S9					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1018 - Staff - Toilet</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00B/R0002/Ceiling Structures/Linings/S7						
<b>B00B - R1019 - Computer Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00B/R0002/Ceiling Structures/Linings/S7						
<b>B00B - R1021 - Wood Technology Bay</b>						
Ceiling Structures/Linings	Vermiculite					<b>No Asbestos Detected</b>
8456/B00B/R0002/Ceiling Structures/Linings/S7						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive					
	8456/B00B/R0035/Floor Coverings Res/Textile/S37					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	3m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00B/R1004/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
<b>B00B - R1023 - Materials Learning Space - Type 1</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Adhesive					
	8456/B00B/R0035/Floor Coverings Res/Textile/S37					<b>No Asbestos Detected</b>
<b>B00B - R1024 - Music Store</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R1025 - Printing/Photocopying</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R1026 - Music Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R1029 - Materials Learning Space - Type 1</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Adhesive					
	8456/B00B/R0035/Floor Coverings Res/Textile/S37					<b>No Asbestos Detected</b>
<b>B00B - R1030 - Dust Extraction Space</b>						
No Asbestos						
<b>B00B - R1031 - External Stairs</b>						
No Asbestos						
<b>B00B - R1032 - Staff Study</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R1033 - Materials Store</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R1034 - Class Tools Storage</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00B/R0002/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R1035 - Handwashing Facilities</b>						
No Asbestos						
<b>B00B - R1036 - External Movement</b>						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities/Building Services - 1969 - Brick/Block (Brick/Block)****Exterior**

Wall Cladding	Galbestos	200m2	Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction - Approx. 7m</b>						

Underfloor Voids - Slab on Ground	No Asbestos Found
-----------------------------------	-------------------

Ceiling Voids	Lagging 8456/B00C/R0001/Insulation to Pipework/S50	<b>No Asbestos Detected</b>				
---------------	---	-----------------------------	--	--	--	--

**Interior****B00C - R0001 - Sport Equipment Store**

Insulation to Pipework	Lagging 8456/B00C/R0001/Insulation to Pipework/S50	<b>No Asbestos Detected</b>				
------------------------	---	-----------------------------	--	--	--	--

**B00C - R0003 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

Door linings	Flat AC Sheeting	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0003/Door linings/S13						<b>Chrysotile (white asbestos)</b>

**B00C - R0004 - Student Canteen**

Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0004/Ceiling Structures/Linings/S15						<b>Chrysotile (white asbestos)</b>

**B00C - R0005 - Pantry**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0004/Ceiling Structures/Linings/S15						<b>Chrysotile (white asbestos)</b>

**B00C - R0006 - Staff - Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0004/Ceiling Structures/Linings/S15						<b>Chrysotile (white asbestos)</b>

**B00C - R0007 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0004/Ceiling Structures/Linings/S15						<b>Chrysotile (white asbestos)</b>

**B00C - R0008 - Office/Store**

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0004/Ceiling Structures/Linings/S15						<b>Chrysotile (white asbestos)</b>

Floor Coverings Res/Textile	Vinyl Tiles
-----------------------------	-------------

8456/B00C/R0008/Floor Coverings Res/Textile/S51						<b>No Asbestos Detected</b>
---	--	--	--	--	--	-----------------------------

**B00C - R0010 - General Assistants**

No Asbestos

**B00C - R0012 - Sport Equipment Store**

Insulation to Pipework	Lagging 8456/B00C/R0001/Insulation to Pipework/S50	<b>No Asbestos Detected</b>				
------------------------	---	-----------------------------	--	--	--	--

**B00C - R0013 - Machine Storage**

No Asbestos

**B00C - R0014 - Staff - Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0004/Ceiling Structures/Linings/S15						<b>Chrysotile (white asbestos)</b>

Infill panel	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0004/Ceiling Structures/Linings/S15						<b>Chrysotile (white asbestos)</b>

**B00C - R0015 - General Storeroom**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00C/R0004/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
Infill panel	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00C/R0004/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)
<b>B00C - R0017 - Main Switchroom</b>						
No Asbestos						
<b>B00C - R0019 - Multi-Purpose Space</b>						
No Asbestos						
<b>B00C - R0021 - Stairs</b>						
No Asbestos						
<b>B00C - R0022 - Movement</b>						
No Asbestos						
<b>B00C - R0023 - External Movement</b>						
No Asbestos						
<b>B00C - R0024 - Movement</b>						
No Asbestos						
<b>B00C - R0025 - Movement</b>						
No Asbestos						
<b>B00C - R0026 - Movement</b>						
No Asbestos						
<b>B00C - R0027 - Movement</b>						
No Asbestos						
<b>B00C - R0028 - Stairs</b>						
No Asbestos						
<b>B00C - R0029 - General Storeroom</b>						
No Asbestos						
<b>B00C - R0030 - General Assistants</b>						
No Asbestos						
<b>B00C - R1001 - Sport Equipment Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00C/R1011/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)
<b>B00C - R1002 - Staff Shower</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00C/R1011/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00C/R0004/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)
<b>B00C - R1003 - Movement</b>						
No Asbestos						
<b>B00C - R1004 - General Storeroom</b>						
Door linings	Flat AC Sheeting	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00C/R1012/Door linings/S17					Chrysotile (white asbestos)
<b>B00C - R1005 - Toilets-Girls</b>						
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00C/R1011/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)
<b>B00C - R1006 - Shower</b>						
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00C/R1011/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R1007 - Shower</b>						
Infill panels	Flat AC Sheeting	5m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0004/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1008 - Toilets-Boys</b>						
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R1011/Ceiling Structures/Linings/S16					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1009 - Staff Shower</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R1011/Ceiling Structures/Linings/S16					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R0004/Floor Coverings Res/Textile/S14					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1010 - Movement</b>						
No Asbestos						
<b>B00C - R1011 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R1011/Ceiling Structures/Linings/S16					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1012 - General Storeroom</b>						
Door linings	Flat AC Sheeting	4m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00C/R1012/Door linings/S17					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1013 - Stairs</b>						
No Asbestos						
<b>B00C - R1014 - Stairs</b>						
No Asbestos						
<b>B00C - R1015 - Plant</b>						
No Asbestos						
<b>B00C - R1016 - Plant</b>						
No Asbestos						
<b>B00C - R1017 - Plant</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00D - Science Learning/General Learning/Support Unit - 1975 - Brick/Block (Brick/Block)****Exterior**

Wall Cladding	Galbestos	200m2	Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction - Approx. 7m Assumed same as 8456/Build+2/Wall Cladding/S33 -</b>						
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					

**Interior****B00D - R0001 - Toilets-Boys**

Ceiling Structures/Linings	Vermiculite	8456/B00D/R0001/Ceiling Structures/Linings/S23			<b>No Asbestos Detected</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0001/Partition Walls (Cubicles)/S25				<b>Chrysotile (white asbestos)</b>		

**B00D - R0003 - Staff Study**

Ceiling Structures/Linings	Vermiculite	8456/B00D/R0001/Ceiling Structures/Linings/S23			<b>No Asbestos Detected</b>	
----------------------------	-------------	--	--	--	-----------------------------	--

**B00D - R0004 - Plant**

Door linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0004/Door linings/S26				<b>Chrysotile (white asbestos)</b>		

**B00D - R0005 - Preparation - Science**

Ceiling Structures/Linings	Vermiculite	8456/B00D/R0001/Ceiling Structures/Linings/S23			<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0002/Floor Coverings Res/Textile/S24				<b>Chrysotile (white asbestos)</b>		

**B00D - R0006 - General Storeroom**

Ceiling Structures/Linings	Vermiculite	8456/B00D/R0001/Ceiling Structures/Linings/S23			<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0002/Floor Coverings Res/Textile/S24				<b>Chrysotile (white asbestos)</b>		

**B00D - R0007 - Laboratory L.S.**

Ceiling Structures/Linings	Vermiculite	8456/B00D/R0001/Ceiling Structures/Linings/S23			<b>No Asbestos Detected</b>	
----------------------------	-------------	--	--	--	-----------------------------	--

**B00D - R0008 - Chemical Store**

Ceiling Structures/Linings	Vermiculite	8456/B00D/R0001/Ceiling Structures/Linings/S23			<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0002/Floor Coverings Res/Textile/S24				<b>Chrysotile (white asbestos)</b>		

**B00D - R0009 - Toilets-Girls**

Ceiling Structures/Linings	Vermiculite	8456/B00D/R0001/Ceiling Structures/Linings/S23			<b>No Asbestos Detected</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0001/Partition Walls (Cubicles)/S25				<b>Chrysotile (white asbestos)</b>		

**B00D - R0010 - Special Learning Space**

Ceiling Structures/Linings	Vermiculite	8456/B00D/R0001/Ceiling Structures/Linings/S23			<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0002/Floor Coverings Res/Textile/S24				<b>Chrysotile (white asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R0011 - Plant</b>						
Door linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0004/Door linings/S26					Chrysotile (white asbestos)	
<b>B00D - R0012 - Staff - Toilet</b>						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
8456/B00D/R0001/Ceiling Structures/Linings/S23						
<b>B00D - R0013 - Cleaning Store - Distributed</b>						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
8456/B00D/R0001/Ceiling Structures/Linings/S23						
<b>B00D - R0014 - Laboratory L.S.</b>						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
8456/B00D/R0001/Ceiling Structures/Linings/S23						
<b>B00D - R0017 - Laboratory L.S.</b>						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
8456/B00D/R0001/Ceiling Structures/Linings/S23						
Floor Coverings Res/Textile	Vinyl Tiles	93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0002/Floor Coverings Res/Textile/S24					Chrysotile (white asbestos)	
<b>B00D - R0018 - Special Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
8456/B00D/R0001/Ceiling Structures/Linings/S23						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0002/Floor Coverings Res/Textile/S24					Chrysotile (white asbestos)	
<b>B00D - R0019 - Interview/Office - Type 1</b>						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
8456/B00D/R0001/Ceiling Structures/Linings/S23						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0002/Floor Coverings Res/Textile/S24					Chrysotile (white asbestos)	
<b>B00D - R0020 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
8456/B00D/R0001/Ceiling Structures/Linings/S23						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0002/Floor Coverings Res/Textile/S24					Chrysotile (white asbestos)	
<b>B00D - R0021 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
8456/B00D/R0001/Ceiling Structures/Linings/S23						
Floor Coverings Res/Textile	Vinyl Tiles	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00D/R0002/Floor Coverings Res/Textile/S24					Chrysotile (white asbestos)	
<b>B00D - R0023 - Cleaning Store - Distributed</b>						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
8456/B00D/R0001/Ceiling Structures/Linings/S23						
<b>B00D - R0024 - External Stairs</b>						
No Asbestos						
<b>B00D - R0025 - External Stairs</b>						
No Asbestos						
<b>B00D - R0026 - Darkroom Space</b>						
No Asbestos						
<b>B00D - R0027 - Dark Room</b>						
No Asbestos						
<b>B00D - R0028 - Movement</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R0029 - Preparation - Science</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R0030 - External Movement</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1001 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1002 - External Stairs</b>						
No Asbestos						
<b>B00D - R1003 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00D/R0004/Door linings/S26					Chrysotile (white asbestos)
Door linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00D/R0004/Door linings/S26					Chrysotile (white asbestos)
<b>B00D - R1004 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00D - R1006 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1007 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive 8456/B00D/R1025/Floor Coverings Res/Textile/S49					No Asbestos Detected
<b>B00D - R1008 - Seminar</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1009 - Office/Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00D/R1009/Floor Coverings Res/Textile/S29	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
<b>B00D - R1011 - Handwashing Facilities</b>						
Ceiling Structures/Linings	Flat AC Sheeting 8456/B00D/R0004/Door linings/S26	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
<b>B00D - R1013 - General Storeroom</b>						
No Asbestos						
<b>B00D - R1014 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1015 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	8456/B00D/R0004/Door linings/S26					Chrysotile (white asbestos)
Door linings	Flat AC Sheeting	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00D/R0004/Door linings/S26					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R1017 - External Movement</b>						
No Asbestos						
<b>B00D - R1018 - Staff - Toilet</b>						
No Asbestos						
<b>B00D - R1019 - Computer Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1020 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles					
	8456/B00D/R1021/Floor Coverings Res/Textile/S47					No Asbestos Detected
<b>B00D - R1021 - Resources Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8456/B00D/R1021/Floor Coverings Res/Textile/S47					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1022 - Seminar</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8456/B00D/R1022/Ceiling Structures/Linings/S34					No Asbestos Detected
<b>B00D - R1023 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles					
	8456/B00D/R1021/Floor Coverings Res/Textile/S47					No Asbestos Detected
<b>B00D - R1024 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles					
	8456/B00D/R1021/Floor Coverings Res/Textile/S47					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles					
	8456/B00D/R1024/Floor Coverings Res/Textile/S48					No Asbestos Detected
<b>B00D - R1025 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	8456/B00D/R1025/Floor Coverings Res/Textile/S49					No Asbestos Detected
<b>B00D - R1026 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	8456/B00D/R1025/Floor Coverings Res/Textile/S49					No Asbestos Detected
<b>B00D - R1027 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	8456/B00D/R1025/Floor Coverings Res/Textile/S49					No Asbestos Detected
<b>B00D - R1028 - Resources Store</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1029 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1030 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1031 - External Stairs</b>						
No Asbestos						
<b>B00D - R1032 - Movement</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00D/R1009/Floor Coverings Res/Textile/S29					Chrysotile (white asbestos)
<b>B00D - R1033 - Staff Study</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1034 - Tea Room</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1035 - Staff Study</b>						
Ceiling Structures/Linings	Vermiculite					
	8456/B00D/R0001/Ceiling Structures/Linings/S23					No Asbestos Detected
<b>B00D - R1036 - Tea Room</b>						
Floor Coverings Res/Textile	Adhesive					
	8456/B00D/R1025/Floor Coverings Res/Textile/S49					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning/Administration/Science Learning - 1975 - Brick/Block (Brick/Block)****Exterior**

Wall Cladding	Galbestos	200m2	Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction - Approx. 7m</b>						

Underfloor Voids - Slab on Ground	No Asbestos Found					
-----------------------------------	-------------------	--	--	--	--	--

Ceiling Voids	Vermiculite					
	8456/B00E/R0001/Ceiling Structures/Linings/S18					<b>No Asbestos Detected</b>

**Interior****B00E - R0001 - Computer Learning Space**

Ceiling Structures/Linings	Vermiculite					
	8456/B00E/R0001/Ceiling Structures/Linings/S18					<b>No Asbestos Detected</b>

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00E/R0026/Floor Coverings Res/Textile/S19					<b>Chrysotile (white asbestos)</b>

**B00E - R0003 - Administration - Clerical**

No Asbestos

**B00E - R0004 - Deputy Principal Office**

No Asbestos

**B00E - R0005 - Student Waiting**

No Asbestos

**B00E - R0006 - Student Waiting**

No Asbestos

**B00E - R0007 - Deputy Principal Office**

No Asbestos

**B00E - R0008 - Administration - Clerical**

No Asbestos

**B00E - R0009 - Staff Study**

Ceiling Structures/Linings	Vermiculite					
	8456/B00E/R0001/Ceiling Structures/Linings/S18					<b>No Asbestos Detected</b>

**B00E - R0010 - General Storeroom**

Ceiling Structures/Linings	Vermiculite					
	8456/B00E/R0001/Ceiling Structures/Linings/S18					<b>No Asbestos Detected</b>

**B00E - R0011 - Staff Study**

Ceiling Structures/Linings	Vermiculite					
	8456/B00E/R0001/Ceiling Structures/Linings/S18					<b>No Asbestos Detected</b>

**B00E - R0013 - Resources Store**

Ceiling Structures/Linings	Vermiculite					
	8456/B00E/R0001/Ceiling Structures/Linings/S18					<b>No Asbestos Detected</b>

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00E/R0026/Floor Coverings Res/Textile/S19					<b>Chrysotile (white asbestos)</b>

**B00E - R0014 - Toilets-Boys**

Ceiling Structures/Linings	Vermiculite					
	8456/B00E/R0001/Ceiling Structures/Linings/S18					<b>No Asbestos Detected</b>

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00E/R0024/Partition Walls (Cubicles)/S20					<b>Chrysotile (white asbestos)</b>

**B00E - R0015 - Cleaning Store - Distributed**

Ceiling Structures/Linings	Vermiculite					
	8456/B00E/R0001/Ceiling Structures/Linings/S18					<b>No Asbestos Detected</b>

**B00E - R0016 - Resources Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00E - R0018 - Dark Room</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
<b>B00E - R0022 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
<b>B00E - R0023 - Archive Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00E - R0024 - Toilets-Girls</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Partition Walls (Cubicles)	Compressed AC Sheet 8456/B00E/R0024/Partition Walls (Cubicles)/S20	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
Incinerator	Encapsulated Insulation material within unit <b>Assumed Asbestos - Assumed asbestos incased in unit</b>	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>B00E - R0025 - Cleaning Store - Distributed</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
<b>B00E - R0026 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						
<b>B00E - R0027 - External Movement</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
<b>B00E - R0028 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00E - R0029 - General Storeroom</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
<b>B00E - R0030 - Staff Study</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
<b>B00E - R0031 - Darkroom Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
<b>B00E - R0032 - External Stairs</b>						
No Asbestos						
<b>B00E - R0033 - Careers Advisers Office</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
<b>B00E - R0034 - Leading Teacher</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
<b>B00E - R0035 - External Stairs</b>						
No Asbestos						
<b>B00E - R0036 - Performing Arts Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
<b>B00E - R0037 - General Storeroom</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
<b>B00E - R0038 - Movement Studio</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
<b>B00E - R0039 - Movement</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
<b>B00E - R0041 - Staff Study</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8456/B00E/R0026/Floor Coverings Res/Textile/S19	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00E - R0042 - Tea Room</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
<b>B00E - R0043 - Staff Study</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
<b>B00E - R0044 - Tea Room</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
<b>B00E - R1001 - Laboratory L.S.</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
<b>B00E - R1002 - Preparation - Science</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00E - R1003 - Apparatus Storage</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00E - R1004 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00E - R1005 - Laboratory L.S.</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R1006 - Computer Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
<b>B00E - R1007 - Cleaning Store - Distributed</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1008 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1009 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1010 - Distribution Board Cupboard</b>						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting 8456/B00E/R1010/Door linings/S22	2m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Door linings	Flat AC Sheeting 8456/B00E/R1010/Door linings/S22	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1011 - External Movement</b>						
No Asbestos						
<b>B00E - R1012 - Staff - Toilet</b>						
No Asbestos						
<b>B00E - R1013 - External Stairs</b>						
No Asbestos						
<b>B00E - R1014 - Staff Study</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1015 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1016 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8456/B00E/R0026/Floor Coverings Res/Textile/S19	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1017 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite 8456/B00E/R0001/Ceiling Structures/Linings/S18				<b>No Asbestos Detected</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00E/R0026/Floor Coverings Res/Textile/S19					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1018 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite				<b>No Asbestos Detected</b>	
8456/B00E/R0001/Ceiling Structures/Linings/S18						
Floor Coverings Res/Textile	Vinyl Tiles	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00E/R0026/Floor Coverings Res/Textile/S19					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1019 - Interview/Office - Type 1</b>						
Ceiling Structures/Linings	Vermiculite				<b>No Asbestos Detected</b>	
8456/B00E/R0001/Ceiling Structures/Linings/S18						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00E/R0026/Floor Coverings Res/Textile/S19					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1020 - Resources Store</b>						
Ceiling Structures/Linings	Vermiculite				<b>No Asbestos Detected</b>	
8456/B00E/R0001/Ceiling Structures/Linings/S18						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00E/R0026/Floor Coverings Res/Textile/S19					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1021 - General Learning Space</b>						
Ceiling Structures/Linings	Vermiculite				<b>No Asbestos Detected</b>	
8456/B00E/R0001/Ceiling Structures/Linings/S18						
Floor Coverings Res/Textile	Vinyl Tiles	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00E/R0026/Floor Coverings Res/Textile/S19					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1022 - Distribution Board Cupboard</b>						
				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
8456/B00E/R1010/Door linings/S22					<b>Chrysotile (white asbestos)</b>	
Door linings	Flat AC Sheeting	6m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00E/R1010/Door linings/S22					<b>Chrysotile (white asbestos)</b>	
Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00E - R1023 - Cleaning Store - Distributed</b>						
Door linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00E/R1010/Door linings/S22					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1024 - Staff - Toilet</b>						
No Asbestos						
<b>B00E - R1025 - External Stairs</b>						
No Asbestos						
<b>B00E - R1026 - Cleaning Store - Distributed</b>						
Door linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00E/R1010/Door linings/S22					<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Library - 1993 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab  
on Ground

Ceiling Voids                      Non Accessible Area  
- No accessible access points to ceiling void

**Interior****B00F - R0001 - Seminar**

No Asbestos

**B00F - R0002 - Seminar**

No Asbestos

**B00F - R0003 - Seminar/Study**

No Asbestos

**B00F - R0004 - Main Entry**

No Asbestos

**B00F - R0005 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0006 - Cleaning Store - Distributed**

No Asbestos

**B00F - R0007 - Staff - Toilet**

No Asbestos

**B00F - R0008 - Audio Visual Workroom**

No Asbestos

**B00F - R0009 - Library Administration**

No Asbestos

**B00F - R0010 - Librarian**

No Asbestos

**B00F - R0011 - Main Area**

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

**B00F - R0012 - External Movement**

No Asbestos

**B00F - R0013 - External Movement**

No Asbestos

**B00F - R0015 - Senior Study**

No Asbestos

**B00F - R0016 - Tea Room**

No Asbestos

**B00F - R0017 - General Storeroom**

No Asbestos

**B00F - R0018 - Access Student Shower/Toilet/Change**

No Asbestos

**B00F - R0019 - General Learning Space**

No Asbestos

**B00F - R0020 - Plant**

No Asbestos

**B00F - R0021 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00G - Multi Purpose Facilities - 1973 - Concrete (Concrete)****Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Under stage	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00G/Underfloor Voids - Packing to Floor Joists/S45			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Window beading	Mastic					No Asbestos Detected
	8456/B00G/Window beading/S46					

**Interior****B00G - M0001 - Control Room**

Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	8456/B00G/R0023/Ceiling Structures/Linings/S32					

**B00G - M0002 - Stairs**

Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	8456/B00G/R0023/Ceiling Structures/Linings/S32					

**B00G - R0001 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00G/R0004/Ceiling Structures/Linings/S30			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0002 - Chair Store**

No Asbestos

**B00G - R0003 - Cleaning Store - Distributed**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00G/R0004/Ceiling Structures/Linings/S30			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Infill panel	Flat AC Sheeting	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00G/R0004/Ceiling Structures/Linings/S30			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0004 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8456/B00G/R0004/Ceiling Structures/Linings/S30			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00G/R0004/Floor Coverings Res/Textile/S31			<b>Chrysotile (white asbestos)</b>		

**B00G - R0006 - Fitness Laboratory**

No Asbestos

**B00G - R0008 - Staff Kitchen**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00G/R0004/Ceiling Structures/Linings/S30			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	8456/B00G/R0008/Floor Coverings Res/Textile/S44					

**B00G - R0009 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00G/R0004/Ceiling Structures/Linings/S30			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0019 - Stage</b>						
No Asbestos						
<b>B00G - R0020 - Sport Equipment Store</b>						
No Asbestos						
<b>B00G - R0022 - Stairs</b>						
No Asbestos						
<b>B00G - R0023 - Multi-Purpose Space</b>						
Ceiling Structures/Linings	Vermiculite					
8456/B00G/R0023/Ceiling Structures/Linings/S32				<b>No Asbestos Detected</b>		
<b>B00G - R0024 - Toilet - Lobby</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0025 - Change</b>						
Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0026 - Toilet - Lobby</b>						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0027 - Change</b>						
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0028 - Toilet - Lobby</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0029 - Toilets-Boys</b>						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0030 - Music Store</b>						
No Asbestos						
<b>B00G - R0031 - Toilet - Lobby</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Floor Coverings Res/Textile/S31					Chrysotile (white asbestos)	
<b>B00G - R0032 - Toilets-Girls</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30					Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00G - R0033 - External Movement</b>						
No Asbestos						
<b>B00G - R0034 - External Movement</b>						
No Asbestos						
<b>B00G - R0035 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30					Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00G - R0036 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00G/R0004/Ceiling Structures/Linings/S30					Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Language Centre - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00H - R0001 - Computer Learning Space**

No Asbestos

**B00H - R0002 - Seminar - Type 2**

No Asbestos

**B00H - R0003 - Resources Store**

No Asbestos

**B00H - R0004 - Computer Store**

No Asbestos

**B00H - R0005 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00Y - Building Services - 1968 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00Y - R0001 - Plant**

Gas Valve	Gasket material	1Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8456/B00Y/R0001/Gas Valve/S39					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00Z - Building Services - 1968 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids - Flat Roof      No Asbestos Found

**Interior**

**B00Z - R0001 - Plant**

Gas Valve	Gasket material	1Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8456/B00Y/R0001/Gas Valve/S39					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BOWS - Storage - 2008 - Steel (Steel)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**BOWS - R0002 - Wood Technology Bay**

No Asbestos

**BOWS - R0003 - Materials Store - Type 1**

No Asbestos

**BOWS - R0004 - Movement**

No Asbestos

**BOWS - R0005 - Project Store - Type 1**

No Asbestos

**BOWS - R0006 - Project Store - Type 1**

No Asbestos

**BOWS - R0007 - Dust Extraction Space**

No Asbestos

**BOWS - R0008 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+1 - Covered walkway Block E-A**

**Exterior**

No Asbestos

**Interior**

**Build+1 - Room+1 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+2 - Covered walkway Block B-A**

**Exterior**

No Asbestos

**Interior**

**Build+2 - Room+1 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+3 - GA Shed**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**Build+3 - Room+1 - Lunch Room**

No Asbestos

**Build+3 - Room+2 - Garage**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 601 - D11015 - Learning Unit - Standard/Withdrawal : Placement Date - 4/01/2012**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Entry

No Asbestos Found.

#### R2 - General Learning Space

No Asbestos Found.

#### R3 - Store

No Asbestos Found.

**OS 600 - D11038 - Learning Unit - Small : Placement Date - 22/12/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - General Learning Space

No Asbestos Found.

**NS 200 - D11728 - Art Learning Space/Workshop/Bulk Store : Placement Date - 30/06/1995**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Art Learning Space

No Asbestos Found.

#### R2 - Workshop

No Asbestos Found.

#### R3 - Bulk Store

No Asbestos Found.

**OS 601 - D11734 - Learning Unit - Standard/Withdrawal : Placement Date - 30/12/2011**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Entry

No Asbestos Found.

#### R2 - General Learning Space

No Asbestos Found.

#### R3 - Store

No Asbestos Found.

**OS 601 - D11781 - Learning Unit - Standard/Withdrawal : Placement Date - 19/12/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 601 - D11853 - Learning Unit - Standard/Withdrawal : Placement Date - 23/12/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 751 - D11903 - Learning Unit - ESL : Placement Date - 22/02/1996**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2

**Interior**

**R1 - Esl**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2

**R2 - Esl**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2

**OS 601 - D12427 - Learning Unit - Standard/Withdrawal : Placement Date - 22/12/2011**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 601 - D12900 - Learning Unit - Standard/Withdrawal : Placement Date - 28/12/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
<b>Interior</b>						
<b>R1 - Entry</b>						
No Asbestos Found.						
<b>R2 - General Learning Space</b>						
No Asbestos Found.						
<b>R3 - Store</b>						
No Asbestos Found.						
<b>NS 200 - D13067 - Art Learning Space/Workshop/Bulk Store : Placement Date - 19/12/2011</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Art Learning Space</b>						
No Asbestos Found.						
<b>R2 - Workshop</b>						
No Asbestos Found.						
<b>R3 - Bulk Store</b>						
No Asbestos Found.						
<b>NS 200 - D13345 - Art Learning Space/Workshop/Bulk Store : Placement Date - 20/12/2011</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Art Learning Space</b>						
No Asbestos Found.						
<b>R2 - Workshop</b>						
No Asbestos Found.						
<b>R3 - Bulk Store</b>						
No Asbestos Found.						
<b>OS 601 - D13611 - Learning Unit - Standard/Withdrawal : Placement Date - 7/01/2012</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Entry</b>						
No Asbestos Found.						
<b>R2 - General Learning Space</b>						
No Asbestos Found.						
<b>R3 - Store</b>						
No Asbestos Found.						
<b>OS 601 - D14171 - Learning Unit - Standard/Withdrawal : Placement Date - 7/01/2012</b>						
<b>Exterior</b>						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 601 - D14228 - Learning Unit - Standard/Withdrawal : Placement Date - 13/12/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 601 - D14342 - Learning Unit - Standard/Withdrawal : Placement Date - 23/12/2011**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 601 - D14654 - Learning Unit - Standard/Withdrawal : Placement Date - 4/01/2012**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 601 - D14890 - Learning Unit - Standard/Withdrawal : Placement Date - 30/12/2011**

**Exterior**

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
No Asbestos Found.						
<b>R2 - General Learning Space</b>						
No Asbestos Found.						
<b>R3 - Store</b>						
No Asbestos Found.						
<b>OS 751 - D16098 - Learning Unit - ESL : Placement Date - 11/02/2015</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Esl</b>						
No Asbestos Found.						
<b>R2 - Esl</b>						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017