Rev	Date completed	CHANGELOG Change	Documents	Initials
		PLRP-TRNSW-APP-CORR-000263: The HRW trees have the impact written in the IA column (cell AP) but is not always in the Contractor (cell AR) column Issue fixed	PLRP-TFNSW-APP-CORR-000263	GG
	6/05/2019	PLRP-TFNSW-APP-CORR-000263: Update Tree 1035, 1036 and 1037 as being as outside the heritage curtilage (this has been updated since submission based on heritage specialist advice) - Updated	PLRP-TFNSW-APP-CORR-000263	GG
	6/05/2019	Delete text against TN 5572 as this is no longer applicable (Suggest rename to 5572 as there are two		GG
	6/05/2019		PLRP-TFNSW-APP-CORR-000263	
		Update tree data based on form - Update text for tree 2102 to be as written in the tree form (currently has HAC have put in an individual tree removal form. Approval acknowledgement provided by IA on 8 April 2019 (PLRP-APP-TFNSWCORR-000223). Confirmed would put in overarching register) Updated, agreement date added	PLRP-TFNSW-APP-CORR-000263	GG
	6/05/2019 6/05/2019	TN 1037 updated E105(c) Alternative Options to reflect that it is not being harmed by root pruning	PLRP-TFNSW-APP-CORR-000263	GG
	,,,,,	: Tree 3184 - this tree is no longer present (damaged in storm on 8/2) but all of the information on why it needs to be removed etc is still in the table. Inconsistency – eg it states in column AH that the crown overhangs travel lane – but it also says only a stump is remaining - Strikethrough text to show it is no longer applicable but maintain history of tree.	PLRP-TFNSW-APP-CORR-000263	GG
	14/05/2019	status change: 3168, 3221, 3228-3230,	PLRP-TFNSW-APP-CORR-000275	
		5 577 - Damage to Tree - 3567 & 3568 - Added tree info for new Trees -		
04		3228, 3229, 3230 - Updated		GG
04		Barney - Dunlop: 3106, 3107, 3108, 3109, 3110, 3111, 3112, 3113, 3114, 3115, 3116, 3117, 3118.		00
		Dunlop - Factory: 3170, 3180, 3185, 3186, 3187, 3188, 3222, 3218.		
		4009 has had the test excavation within approx. 18% of the TPZ, which is "Minor root pruning"		
04	14/05/2019	Added Columns IA status, Contractor status There are an additional 3 small trees within the private property 55 O'Connell Street which meet the		GG
04		definition of tree as listed in the report (3m+ height) - 2 x 4m high Camellia and 1x 3m high Backhousia along the Factory Street boundary	PLRP-TFNSW-APP-CORR-000275	
04		Changes to formatting Existing assesment agreements added with Y/N (future agreements to have date added)		GG
04		Adjusted compensatory vegetation columns, relabelled "If pruning req. (maintenance)" as E104 (f) Added TeamBinder ref column and Separated contractor comments and assessment into contractors columns (Meeting Richard Farmer, Danny Draper, Andrew Bennet, Peter		GG
04		Monsted, Gavin Gunawan)		GG
04	, ,	Added trees from Mons Road compound - under HAC trees 1-25. Need to give Tree ID to these trees. (Amenity - Heritage curtilage) and (Ecological value - threatened species) , need to find better columns ??	PLRP-TFNSW-TX-001041	GG
04 05		Changed HRW to HAC Added notes from Danny Draper for inspection of Mons Rd TN 1-25 on 7/6/19 (retain)	PLRP-TFNSW-TX-001041 PLRP-TFNSW-TX-001041	GG GG
05	18/06/2019	Added tree updates from transmittal attachment excel file received 17/06/19	PLRP-TFNSW-TX-001098	GG
05 06		Added information from word file in attachments received 17/06/19 (speak to Danny - added as % enroachment and comments) Addded legend tab to clarify column data	PLRP-TFNSW-TX-001098 PLR-APP-PJT-PE-REG-000001	GG GG
06 06	9/07/2019	Removed SRIV column (redundant as different requirements specified for contracts) TN 5215, 5217, 5218, 5226, 5232 updated as (action) pruned , TN 5224, 6225, 5227, 5228 Confirmed previously removed (status)	PLR-APP-PJT-PE-REG-000001 inspection	GG DD
07	30/07/2019	HAC updates received 22/07/19 (PLR-HAC-HRW-BI-FRM-0000020803). Trees 1345, 1346 added. HAC Tree Protection and Pruning Specification columns added	PLRP-TFNSW-TX-001187	JC
07	1/08/2019	IA Assessment updated following discussions with HAC Contractor. Verified on site, Tree Numbers TN8509, TN8510, TN8511 are double ups of TN1138, TN1139, TN1141,	IA email 31/7/19	JC
08	9/08/2019	respectively. IA Assessment for removal of TN 5216 updated	PLRP-APP-CORR-000108	JC
09	17/09/2019	HAC updates: HRW Pruning specifications updated for Trees 1137, 2101	IA email 16/9/19	JC
10	3/10/2019	Several Changes from received Tree register covering T6 bus stop trees due to existing TN overlapping on carlingford line 11510 >> 9269 11511 >> 9270 11513 >> 9272 11514 >> 9154 11515 >> 9155 11516 >> 9153 11517 >> 9156 11518 >> 9157 11519 >> 9177 11519 >> 9177 11520 >> 9083 11526 >> 9622 (awaiting geolocation data for trees not overlaping existing TN 11501-11509, 11521-11525)	PLR-PLR1ALL-APP-CPBD-CORR-000009	GG
10	3/10/2019	Several changes from Jemina gas relocation due to overlapping TN 1= 26 2= 1033	PLR-PLROALL-APP-APP-CORR-000005	GG
11	4/10/2019	3= 1032 EN (Newleaf) have been allocated TN 50-999	Email 4/10/19	GG
	1,710,2013	and the second s		
11	21/10/2019	TN 10395, 10396 reserved for trees @11 Grand Avenue Camellia	Text from IA	GG
11 11	24/10/2019 29/10/2019	TN 10397-10406 reserved for trees for Adrian Swain by IA Updates to register from Diona Ward register (Filter Last updated column 29/10/19 Rev 11)	Text from IA PLRP-APP-APP-CORR-000137	GG GG
11 11	30/10/2019	TN 6029, 10395 updated	PLRM-CPBD-APP-TX-000015	GG
11	4/11/2019 7/11/2019	Aboreport has Reserved TN 10407-10444 Updated register Tree Survey Data for the Dundas Ancillary Facility	email 4/11/2019 PLRM-CPBD-APP-TX-000020	GG GG
11	7/11/2019	Updated register Tree Survey Data: Fleet St and Factory St Parramatta	PLR1INF-CPBD-A03-EO-REG-000003 PLRM-CPBD-APP-TX-000019	GG
11	7/11/2019	Updated register Tree Survey Data: Ross St and Church St in Parramatta	PLR1INF-CPBD-A03-EO-REG-000002 PLRM-CPBD-APP-TX-000018	GG
11			PLR1INF-CPBD-A01-EO-REG-000003 PLRM-CPBD-APP-TX-000017	GG
	7/11/2019	Updated register Tree Survey Data: Jemena Condition Assessments – Grand Avenue Camellia	PLR1INF-CPBD-A03-EO-REG-000004 PLRM-CPBD-APP-TX-000016	
11	7/11/2019	Updated register Tree Survey Data: November 2019 Possession	PLR1INF-CPBD-A03-EO-REG-000002 PLRM-CPBD-APP-TX-000014	GG
11	7/11/2019 8/11/2019	Tree survey data at 13 Grand Avenue Aboreport has Reserved TN 10445-11000	PLR1INF-CPBD-A03-EO-REG-000001	GG GG
12	8/11/2019	Tree Protection Plan: Telstra Works - Darcy Rd and Hawkesbury Rd Westmead (note: 1046 double up contract)	Email 8/11/2019 PLRM-CPBD-APP-TX-000022	GG
12 12	8/11/2019 11/11/2019	Tree Survey Data: Utility Investigations at Macquarie and Harris Street Intersection Parramatta (TN 4679 = 7469) (5417 double up contract) Tree Protection Plan and Tree Survey Data for the Optus Relocation – Kissing Point Road (TN 10445-10456)	PLRM-CPBD-APP-TX-000023 PLRM-CPBD-APP-TX-000024	GG GG
12	12/11/2019	Tree Survey Data: Jemena Condition Assessments – Hainsworth St (note: 2027 double up contract)	PLRM-CPBD-APP-TX-000025	GG
12 12	19/11/2019 19/11/2019	Tree Survey Data: Phillip Street Temporary Bus Stop (TN 5283) Tree Survey Data: Victoria Road Temporary Bus Stop	PLRM-CPBD-APP-TX-000028 PLRM-CPBD-APP-TX-000029	GG GG
12	19/11/2019	Updated IA tree removal confirmation status (TN 45,-49, 3217, 3219, 3228-3230, 3567)	PLRP-APP-APP-CORR-000141	DD
13	28/11/2019	Tree Survey Data for the Jemena Relocation works on Harris Street	PLRM-CPBD-APP-TX-000031 PLR1INF-CPBD-A02-EO-REG-000001.A.S2.A.01	GG
13	28/11/2019	TN 5417 double up from 8/11/19 corrected. INF TN 5417 from this transmittal should be TN 7439	PLRM-CPBD-APP-TX-000023	GG
17	28/11/2019 10/12/2019	INF (Birds) updated and added TN PLR - Tree Survey Data: Utility Relocations in Parramatta CBD	PLR1INF-CPBD-A03-EO-RPT-000007 PLRM-CPBD-APP-TX-000035	GG GG
13		Tree Survey Data: Utility Investigations South of Lennox Bridge (TN 10481)	PLR1INF-CPBD-A02-EO-REG-000005 PLRM-CPBD-APP-TX-000034	GG
13			PLR1INF-CPBD-A02-EO-REG-000007	ou .
13 13	10/12/2019	not updated: require excel register in addition to rpt		_
13 13 13	10/12/2019	not updated: require excel register in addition to rpt. Updated with PLRM-CPBD-APP-TX-000040 23/01/2020	PLRM-CPBD-APP-TX-000032	GG
13 13 13 13	10/12/2019 10/12/2019 10/12/2019	Not updated: require excel register in addition to rpt Updated with PLRM-CPBD-APP-TX-000040 23/01/2020 Updated IA tree removal confirmation status (TN 4748-4752, 4772, 4773, 4775, 4776, 9455-4960, 11126-11143, 11163-11169, 11181-11183, 11186 and 11187)		GG DD
13 13 13 13 14*	10/12/2019 10/12/2019 10/12/2019 tbc	not updated: require excel register in addition to rpt. Updated with PLRM-CPBD-APP-TX-000040 23/01/2020 Updated IA tree removal confirmation status (TN 4748-4752, 4772, 4773, 4775, 4776, 9455-4960, 11126-11143, 11163-11169, 11181-11183, 11186 and 11187) changes after 10/12/19 to be updated in the new year (in rev 14) Updated Tree Survey Data for the January 2020 Possession	PLRM-CPBD-APP-TX-000032 PLR-PLR1ALL-APP-APP-CORR-000006 PLRM-CPBD-APP-TX-000037	DD
13 13 13 13 14* 14	10/12/2019 10/12/2019 10/12/2019 tbc 8/01/2020	not updated: require excel register in addition to rpt Updated with PLRM-CPBD-APP-TX-000040 23/01/2020 Updated IA tree removal confirmation status (TN 4748-4752, 4772, 4773, 4775, 4776, 9455-4960, 11126-11143, 11163-11169, 11181-11183, 11186 and 11187) changes after 10/12/19 to be updated in the new year (in rev 14) Updated Tree Survey Data for the January 2020 Possession (TN 4744-4745, 9247, 9449, 9538-9539, 0616, 9623-9624, 9661, 9779-9781, 9784, 9793, 10397-10417, 10426-10443, 10492-10518)	PLRM-CPBD-APP-TX-000032 PLR-PLR1ALL-APP-APP-CORR-000006	DD GG
13 13 13 14* 14 14	10/12/2019 10/12/2019 10/12/2019 tbc	not updated: require excel register in addition to rpt. Updated with PLRM-CPBD-APP-TX-000040 23/01/2020 Updated IA tree removal confirmation status (TN 4748-4752, 4772, 4773, 4775, 4776, 9455-4960, 11126-11143, 11163-11169, 11181-11183, 11186 and 11187) changes after 10/12/19 to be updated in the new year (in rev 14) Updated Tree Survey Data for the January 2020 Possession	PLRM-CPBD-APP-TX-000032 PLR-PLR1ALL-APP-APP-CORR-000006 PLRM-CPBD-APP-TX-000037 PLR1INF-CPBD-A03-EO-REG-000007	DD
13 13 13 13 14* 14	10/12/2019 10/12/2019 10/12/2019 tbc 8/01/2020 8/01/2020	Default of the second register in addition to rpt Updated with PLRM-CPBD-APP-TX-000040 23/01/2020 Updated IA tree removal confirmation status (TN 4748-4752, 4772, 4773, 4775, 4776, 9455-4960, 11126-11143, 11163-11169, 11181-11183, 11186 and 11187) changes after 10/12/19 to be updated in the new year (in rev 14) Updated Tree Survey Data for the January 2020 Possession (TN 4744-4745, 9247, 9449, 9538-9539, 0616, 9623-9624, 9661, 9779-9781, 9784, 9793, 10397-10417, 10426-10443, 10492-10518) Updated IA tree removal confirmation status (TN 47, 48, 49, 3568) IA Tree status of TN 48 & 49 corrected (switched) (TN 49 retained) (INF) updated Tree Survey Data for the AAPT Works at Hassall and Charles St	PLRM-CPBD-APP-TX-000032 PLR-PLR1ALL-APP-APP-CORR-000006 PLRM-CPBD-APP-TX-000037 PLR1INF-CPBD-A03-EO-REG-000007 PLRP-APP-APP-CORR-000141 PLR-PLR0ALL-TFNSW-APP-CORR-000016 PLRM-CPBD-APP-TX-000043	DD GG GG
13 13 13 13 14* 14 14 15	10/12/2019 10/12/2019 10/12/2019 tbc 8/01/2020 8/01/2020 9/01/2020	not updated: require excel register in addition to rpt. Updated with PLRM-CPBD-APP-TX-000040 23/01/2020 Updated IA tree removal confirmation status (TN 4748-4752, 4772, 4773, 4775, 4776, 9455-4960, 11126-11143, 11163-11169, 11181-11183, 11186 and 11187) changes after 10/12/19 to be updated in the new year (in rev 14) Updated Tree Survey Data for the January 2020 Possession (TN 4744-4745, 9247, 9449, 9538-9539, 0616, 9623-9624, 9661, 9779-9781, 9784, 9793, 10397- 10417, 10426-10443, 10492-10518) Updated IA tree removal confirmation status (TN 47, 48, 49, 3568) IA Tree status of TN 48 & 49 corrected (switched) (TN 49 retained) (INF) updated Tree Survey Data for the AAPT Works at Hassall and Charles St (TN 3557, 3562, 7426, 7458, 7467, 7559, 10480, 10520) Updated Status of trees from previous report	PLRM-CPBD-APP-TX-000032 PLR-PLR1ALL-APP-APP-CORR-000006 PLRM-CPBD-APP-TX-000037 PLR1INF-CPBD-A03-EO-REG-000007 PLRP-APP-APP-CORR-000141 PLR-PLR0ALL-TFNSW-APP-CORR-000016	GG GG DD
13 13 13 14* 14 14 15 16 16	10/12/2019 10/12/2019 10/12/2019 tbc 8/01/2020 8/01/2020 9/01/2020 10/01/2020 13/01/2020 13/01/2020	not updated: require excel register in addition to rpt Updated with PLRM-CPBD-APP-TX-000040 23/01/2020 Updated IA tree removal confirmation status (TN 4748-4752, 4772, 4773, 4775, 4776, 9455-4960, 11126-11143, 11163-11169, 11181-11183, 11186 and 11187) changes after 10/12/19 to be updated in the new year (in rev 14) Updated Tree Survey Data for the January 2020 Possession (TN 4744-4745, 9247, 9449, 9538-9539, 0616, 9623-9624, 9661, 9779-9781, 9784, 9793, 10397- 10417, 10426-10443, 10492-10518) Updated IA tree removal confirmation status (TN 47, 48, 49, 3568) IA Tree status of TN 48 & 49 corrected (switched) (TN 49 retained) (INF) updated Tree Survey Data for the AAPT Works at Hassall and Charles St (TN 3557, 3562, 7426, 7458, 7467, 7559, 10480, 10520) Updated Status of trees from previous report (TN 9083, 9153-9157, 9177, 9269-9272, 9622, 11501-11509, 11521-11525) Fixed Trees 9169-9172 >> 9269-9272 (reverted 9169-9172 to rev 8 data)	PLRM-CPBD-APP-TX-000032 PLR-PLR1ALL-APP-APP-CORR-000006 PLRM-CPBD-APP-TX-000037 PLR1INF-CPBD-A03-EO-REG-000007 PLRP-APP-APP-CORR-000141 PLR-PLR0ALL-TFNSW-APP-CORR-000016 PLRM-CPBD-APP-TX-000043 PLR1INF-CPBD-A02-EO-REG-000008	GG GG DD GG
13 13 13 14* 14 14 15 16	10/12/2019 10/12/2019 10/12/2019 tbc 8/01/2020 8/01/2020 10/01/2020 13/01/2020	not updated: require excel register in addition to rpt Updated with PLRM-CPBD-APP-TX-000040 23/01/2020 Updated IA tree removal confirmation status (TN 4748-4752, 4772, 4773, 4775, 4776, 9455-4960, 11126-11143, 11163-11169, 11181-11183, 11186 and 11187) changes after 10/12/19 to be updated in the new year (in rev 14) Updated Tree Survey Data for the January 2020 Possession (TN 4744-4745, 9247, 9449, 9538-9539, 0616, 9623-9624, 9661, 9779-9781, 9784, 9793, 10397- 10417, 10426-10443, 10492-10518) Updated IA tree removal confirmation status (TN 47, 48, 49, 3568) IA Tree status of TN 48 & 49 corrected (switched) (TN 49 retained) (INF) updated Tree Survey Data for the AAPT Works at Hassall and Charles St (TN 3557, 3562, 7426, 7458, 7467, 7559, 10480, 10520) Updated Status of trees from previous report (TN 9083, 9153-9157, 9177, 9269-9272, 9622, 11501-11509, 11521-11525)	PLRM-CPBD-APP-TX-000032 PLR-PLR1ALL-APP-APP-CORR-000006 PLRM-CPBD-APP-TX-000037 PLR1INF-CPBD-A03-EO-REG-000007 PLRP-APP-APP-CORR-000141 PLR-PLR0ALL-TFNSW-APP-CORR-000016 PLRM-CPBD-APP-TX-000043 PLR1INF-CPBD-A02-EO-REG-000008 PLR-PLR1ALL-APP-APP-CORR-000002	GG GG DD GG DD

17	23/01/2020	(INF) Updated AIA and Tree Register - Grand Avenue North TN 4774, 11153-11162 and 11184-11185 are now to be removed.	PLR-PLR1INF-CPBD-APP-CORR-000314	GG
17 18	23/01/2020 11/02/2020	Checks on IA tree status agreements [INF) Section 2 Tree register updated (2500 Urban Design & Arch PDR submission)	PLR1INF-COX-A02-UD-REG-500001.A	DD GG
18	12/02/2020	(INF) Section 3 tree register updated (1016 Tree entries updated)	PLR1INF-CPBD-A03-EO-REG-000009	GG
18	13/02/2020	(INF) Section 1 Tree register updated (1500 Urban Design & Arch PDR submission)	PLR-PLR1INF-CPBD-APP-CORR-000336 PLR1INF-COX-A01-UD-REG-500001.A	GG
18	13/02/2020		PLR1INF-CPBD-ALL-EO-CER-000001	GG
		Tree removal certificate of TN 11503 updated in register (in line with 9155, 9157, 9177)	PLR1INF-CPBD-A03-EO-REG-000007	
18	17/02/2020	(INF) Section 3 tree register updated	PLR-PLR1INF-CPBD-APP-CORR-000327	GG
18	18/02/2020	(INF) Section 2 tree register updated (AIA-Section 2 Rev B)	PLR1INF-CPBD-A02-EO-REG-000009 PLR-PLR1INF-CPBD-APP-CORR-000346	GG
18	18/02/2020	(INF) Area 2 Tree Protection Plan for 198 George Street (TN 5200, 5202, 5204-5206, 7470-7477, 10529-10537)	PLR1INF-CPBD-A02-EO-REG-000010 PLR1INF-CPBD-A02-EO-RPT-000011 PLR-PLR1INF-CPBD-APP-CORR-000347	GG
18	18/02/2020	(EN) reserve 3 x TN (new leaf arborist). 15209, 15210, 15213 (INF) Tree Protection Plan – Cumberland Hospital Archaeological Salvage	PLR1INF-CPBD-A01-EO-RPT-000011	GG
18	24/02/2020 25/02/2020	Update IA endoresement tree status (INF) Tree Protection Plan - Hainsworth St - EE-06 Investigation Works	PLRM-CPBD-APP-TX-000058 PLR1INF-CPBD-A01-EO-RPT-000007	GG GG
18	26/02/2020	Update IA endoresement tree status (EN) Tree Register Updated to January 2020	PLRM-CPBD-APP-TX-000051 PLRP-APP-APP-CORR-000158	GG
18	26/02/2020	Partial IA endorsement of Priority trees for removal (column BU) (TN 9218, 9509-9510, 9463, 9518-9519, 9535-9546, 9705-9706,9711-9714,9744, 11212-11224, 11226-11232, 11384, 11414-11420, 11432)	PLR-PLR1ALL-APP-TFNSW-CORR-000049 PLR1INF-CPBD-A03-EO-RPT-000008	GG
19	28/02/2020	Updated Status of trees from previous report (TN 1 - TN 51, 1006-1008, 1013, 1023 - 1027, 1033, 1034, 1759, 5524, 5525)	PLR-PLR1ALL-APP-APP-CORR-000002, PLR1INF-CPBD-A01-EO RPT-000004	טט
19 19	28/02/2020 28/02/2002	Tree Register updated - TN 3475, 3476, 5422, 5423, 5425 - 5436, 5453 - 5461, 7559, 10479, 10482 - 10491 IA updated 6/1/2020 Tree Protection Plan: AAPT Works Hassall and Charles Street, Parramatta. TN 3557, 5338 - 5340, 7426, 7458, 7467, 7526 - 7552, 7554, 7556, 7559, 7560, 7563, 10461 - 10478, 10480, 10492 - 10520	PLR1INF-CPBD-A02-EO-RPT-000005 PLR1INF-CPBD-A02-EO-RPT-000008	DD DD
19	28/02/2020	10461 - 10476, 10480, 10492 - 10520 Updated Status of trees from previous report TN 4678 - 4680, 7438, 7459, 7460, 7461, 7469, 10480 Updated Status of trees from previous report of 16/12/2019 Tree Protection Plan: January 2020 Possession TN 4744, TN 4745, 9247, 9449, 9538, 9544, 9546, 9779, 9780, 9781,	PLR1INF-CPBD-A02-EO-RPT-000001	DD
19	28/02/2020	9784 , 10421 - 10443	PLR1INF-CPBD-A03-EO-RPT-000008	DD
19	28/02/2020 28/02/2020	IA updated from 25/11/2020 PA AIA Tree Protection Plan - Grand Avenue North UTC -TN 4747 - 4758, 4761 - 4763, 4766, 9455 - 9460, 9528, 10397 - 10417, 11126 - 11171 IA updated 31/10/2019 Tree Protection Plan: Jemena Condition Assessments - Grand Avenue Camellia -TN 4772 - 4776	PLR1INF-CPBD-A03-EO-RPT-000007 PLR1INF-CPBD-A03-EO-RPT-000004	DD DD
19	28/02/2020 28/02/2020 28/02/2020	Tree Register updated - TN 6029 Tree Register updated - TN 6029	PLR-PLR1INF-APP-APP-CORR-000037	DD DD
19	28/02/2020	Updated Status of trees from previous report - Jemena works 21/11/2019 - TN 7462	PLR1INF-CPBD-A02-EO-RPT-000002	DD
19 19	28/02/2020 28/02/2020	Updated Status of trees from previous report - Jemena works 21/11/2019 -TN 7463 Updated Status of trees from previous report - TN 7524	PLR1INF-CPBD-A02-EO-RPT-000003	DD DD
19 19	28/02/2020 28/02/2020	Updated Status of trees from previous report - TN 7525 Updated Status of trees from previous report - TN 9218, 9463, 9518, 9519, 9535 - 9546, 9711 - 9714, 5750, 9744	PLR-PLR1ALL-APP-TFNSW-CORR-000046 PLR-PLR1ALL-APP-TFNSW-CORR-000049	DD DD
19	28/02/2020	IA Updated 10/02/2020 Rev. D, AIA Report (Section 3) Camellia, Carlingford, Maint. Facility and Sandown Line -TN 5750, 5752, 9798 - 9800, 9931, 9932, 9950 - 9961, 11211 - 11232, 14000 - 14013, 14017 - 14021, 14023 - 14028, 14030, 14031, 14034, 14036 - 14039, 14041 - 14049, 14052 - 14058, 14062 - 14064, 14066 - 14075, 14077 - 14079, 14081,	PLR1INF-CPBD-A03-EO-RPT-000010	DD
19	28/02/2020	14083 - 14087, 14089 - 14159, 14161 14163, 14165 Updated Status of trees from previous report - trees removed - Certificate 2 - 13/01/2020 - tree removedTN 9177	PLR1INF-CPBD-ALL-EO-CER-000001	DD
19 19	28/02/2020 28/02/2020	Updated Status of trees from previous report - TN 10395 IA updated 31/10/2019 Tree Protection Plan: Jemena Condition Assessments - Grand Avenue Camellia - TN 10420	PLR1INF-CPBD-A03-EO-RPT-000004	DD DD
19 19	28/02/2020 28/02/2020	Updated Status of trees from previous report - TN 10481, 11181 - 11187 Updated Status of trees from previous report - TN 11180, 11501	PLR1INF-CPBD-A02-EO-RPT-000007	DD DD
19	28/02/2020	IA updated Status of trees from previous report -TN 11502 - 11526 IA updated Status of trees from previous report -TN 4736, 5938 - 5961, 9000 - 9034, 9052, 9053, 9060, 9084, 9086, 9091, 9092, 9097, 9098, 9133 - 9135, 9137 - 9164, 9167, 9168,	PLR-PLR1ALL-APP-APP-CORR-000002	DD
20	4/03/2020	9170 - 9175, 9181 - 9183, 9187, 9189, 9195, 9196, 9203 - 9210, 9212 - 9218, 9220 - 9224, 9235, 9237 - 9246, 9251, 9255 - 9266, 9279 - 9283, 9286 - 9289, 9291 - 9295, 9297, 9298, 9300 - 9305, 9310 - 9314, 9316 - 9319, 9322 - 9327, 9329 - 9332, 9334, 9337 - 9355, 9357 - 9359, 9362 - 9374, 9376 - 9398, 9401 - 9405, 9407 - 9410, 9412 - 9422, 9427, 9428, 9430 - 9435, 9437 - 9442, 9446, 9446 - 9448, 9461, 9462, 9464, 9469 - 9486, 9481 - 9502, 9504 - 9508, 9511 - 9516, 9529, 9531, 9532, 9551, 9552, 9566, 9567, 9571, 9572, 9605, 9610 - 9615, 9617, 9622 - 9656, 9664 - 9671, 9677, 9681 - 9685, 9688, 9690, 9698, 9700, 9701, 9704, 9721, 9722, 9724, 9727 - 9731, 9733, 9735, 9736, 9738, 9739, 9740, 9743, 9746, 9747, 9749, 9756, 9757, 9764 - 9763, 9779, 9780, 9782 - 9790, 9792, 9793, 9811 - 9816, 11188, 11197, 11198, 11202 - 11209, 11233 - 11238, 11240 - 11245, 11247 - 11268, 11277 - 11286, , 11289, 11290, 11291, 11293 - 11298, 11302, 11304, 11306 - 11375 11377 - 13382, 11385 - 11393, 11397 - 11413, 11422 - 11431, 11433 - 11494	PLR1INF-CPBD-A03-EO-RPT-000010	DD
20	4/03/2020	IA Updated 10/02/2020 Rev. D, AIA Report (Section 3) Minor encroachment - Level Changes. Some localised level changes may be required -TN 9054, 9055, 9059,		DD
20 20	4/03/2020 4/03/2020	Updated Status of trees from previous report - TN 9530 Updated Status of trees from previous report - TN 8038	PLR-PLR1ALL-APP-TFNSW-CORR-000046	DD DD
20	12/03/2020	IA updated 12/03/2020 TPP - A2-Area 2 East Site Investigations - TN 3556, 3557, 4407 - 4413, 4420 -4425, 4430 - 4438, 4680, 5269 - 5272, 5411 - 5417, 11086 - 11100, 11144 - 11147, 11171 IA Update 13/03/2020 TPP - 198 George St., Parramatta, Rev. A, Doc TN 5200, 5202, 5204 - 5206, 10529 - 10544	PLR1INF-CPBD-A02-EO-RPT-000013 PLR1INF-CPBD-A02-EO-RPT-000011	DD DD
21	9/04/2020 9/04/2020	A2_Macquarie Street TMP Implementation, TN 2073. Area 1 28 Railway Parade and 149 Hawkesbury demolition TN 4, 5520, 5521, 5522, 5523, 5524, 5525 and 5526.	PLR1INF-CPBD-A01-EO-RPT-000013 CORR-PLR-PLR1INF-CPBD-APP-CORR-000412	DD DD
21	9/04/2020	Area 1 - Fleet and Factory streets, gas relocation -TN 5668, 5669, 5670 and 5673.	CORR-PLR-PLR1INF-CPBD-APP-CORR-000424	DD
21	9/04/2020 9/04/2020	Area 2 - Tree Removal - Root Mapping and interpretation - TN 7545 and 7551. Area 2 - (CBD Utility Works) Market Street to Macquarie Street, Parramatta CBD -TN 3475, 3476, 5453-5461, 7530, 7531, 11045-11047, 11049-11066	CORR-PLR-PLR1INF-CPBD-APP-CORR-000433 CORR-PLR-PLR1INF-CPBD-APP-CORR-000478	DD DD
21	9/04/2020	Area 3 - Tree Determination – Section 3 PLR -TN 9156, 9247, 9296, 9328, 9333, 9360, 9401, 9424, 9429, 9521, 9522, 9566, 9657, 9740, 9749, 9781, 9782, 9783, 11188, 11199, 11201, 11247, 11294, 11302, 11304, 11316-11319, 11322, 11324, 11375 and 11379	CORR-PLR-PLR1INF-CPBD-APP-CORR-000480-Tree Determination - Section 3 PLR (5)	DD
21	9/04/2020 14/04/2020	Area 2 - Tramway Avenue Utilities - TN 11144, 11145 and 11146 Area 2 - Status of trees uncertain subject to redesign review -TN 15228 - 15232	PLR1INF-CPBD-A03-EO-RPT-000018 PLR-PLR1ALL-TFNSW-APP-CORR-000019.	DD DD
21	15/04/2020 21/04/2020	Area 2 - Micro Tunnel - Remove TN 7424 and 7528; Retain TN 7529 and 10486. Area 3 - bridge over Kissing Point Road, Dundas - TN 9433, 11302, 11304, 11307 - 11314, 11316 - 11324, 11495 - 11507, 11529 - 11532	CORR-PLR-PLR1INF-CPBD-APP-CORR-000499-AR PLR1INF-CPBD-A03-EO-RPT-000010	DD DD
22	22/04/2020 22/04/2020	Northings fixed using rev 19 (previous copy duplicate error) - TN 9157-10395 Removed inconsistencies between column 'BR-BS' and Columns AR, AT, AY, BC.	PLR-PLR0ALL-TFNSW-APP-CORR-000030 PLR-PLR0ALL-TFNSW-APP-CORR-000029	GG GG/DD
22	22/04/2020	check inconsistencies TN 4407-4438, 4736 - 4738, 4744, 5412, 5453 - 5461, 7532 - 7552, 7554, 7555, 7559, 7560, 7563, 9721, 9722, 9724, 9727, 9781, 10297, 10298, 10502 - 10504, 11197, 11198, 11203, 11307, 11421 and 11432.		DD
24	24/04/2020 17/04/2020	Area 3 - bridge over Kissing Point Road, Dundas - TN 11509 - 11528. Area 1 - Section 1 - Arboricultural Impact Assessment (AIA) Rev D and Updated Tree Register Submission for review and endorsement -1020, 1021, 1023 - 1029, 1032, 1035 - 1044, 1046, 1051 - 1054, 1088 - 1091, 1103, 1104, 1106-1108, 1132, 1133, 1134, 1136-1139, 1141, 1143, 1144, 1147, 1148, 1150 - 1155, 1160 - 1164, 1166-1168, 1170, 1171, 1173, 1176, 1182, 1183, 1184, 1185, 1187 - 1191, 1193, 1202 - 1207, 1218-1220, 1223, 1225, 1228, 1231, 1234, 1234, 1237, 1238, 1239, 1242, 1243, 1245, 1246, 1248, 1249, 1250, 1254, 1255, 1257, 1258, 1259, 1260, 1265, 1270, 1271, 1272, 1273, 1275, 1277, 1281, 1282, 1286, 1287, 1288, 1293, 1294, 1295, 1299, 1737-1739, 1742, 1743, 1744, 1759, 1774, 1777, 1798, 1843, 1204, 2203, 2025 - 2053, 2056, 2058, 2061, 2062, 2063, 2065 - 2075, 2077 - 2086, 2089 - 2104, 3205 - 3214, 3217, 3219, 3220, 3221, 3223 - 3237, 3239, 3240, 3241, 3246, 3246, 3253-3257, 3317 - 3325, 3327, 4175, 4176, 4184, 4185, 4250 - 4257, 4263, 4264, 4365, 4266, 4268, 4269, 4370, 4271, 4275, 4276, 4277, 4278, 4281, 4282, 4284, 4286, 4287, 4291, 4292, 4294, 4295, 4297, 4299 - 4303, 4309 - 4313, 4315 - 4326, 4328 - 4333, 4335, 4337, 4338, 4339, 4340, 4343-4347, 4361 - 4375, 4379, 4380, 4584, 4664 - 4668, 4672, 5001, 5003 - 5008, 5015 - 5018, 5026, 5027, 5439, 5441, 5442, 5445, 5450, 5456, 5457 - 5464, 5466, 5520 - 5528, 5538, 5540, 5543, 5550, 5552, 5553, 5555, 5557, 5559, 5562, 5664 - 5677, 5692 - 5702, 5708 - 5715, 5718 - 5752, 5737, 5738, 5740, 7541, 5745 - 5752, 5753, 5755, 5756, 7575, 5759 - 5762, 7019 - 7026, 7096 - 7102, 7112, 7113, 7400, 7401, 8038, 8252, 10019, 10035, 10036, 10037, 10039, 10052, 10053, 10064, 10082, 10084, 10093, 10097, 10098, 10106, 10107, 10109, 10110, 101112, 10117, 10119, 10120, 10123, 10130, 10131, 10133, 10157, 10160, 10165, 10166, 10167, 10170, 10186, 10187, 10199, 10200, 10201, 10204, 10208, 10208, 10204, 10208, 10209, 15001, 15013, 15033, 15035, 15037, 15038, 15158 - 15165, 15183, 15190, 15191, 15223, 15224, 15225, 152	PLR1INF-CPBD-A03-EO-RPT-000010 CORR-PLR-PLR1INF-CPBD-APP-CORR-000358-20200219 and PLR-PLR1INF-CPBD-APP-CORR-000555	DD
24	5/05/2020	Clearing of Area 2 Trees with Priority List - Approval required (Urgent trees by 07/05/20) TN3475, 3476, 3563 - 3566, 4677, 4678, 4679, 5417, 5453 - 5455, 5487, 5488, 7424, 7432 - 7437, 7478, 7479, 7480, 7483 - 7487, 7524, 7530 - 7534, 11045 - 11066 and 11081 - 11084.	PLR-PLR1INF-CPBD-APP-CORR-000577	DD
24 25	6/05/2020 8/05/2020	7437, 7478, 7479, 7480, 7483 - 7487, 7324, 7330 - 7334, 11043 - 11064 and 11081 - 11084. Additional comments from Project Arborist regarding transplantation feasibility of Trees 15229 - 15232. Check inconsistencies	PLR-PLR1ALL-CPBD-APP-CORR-000062 PLR-PLR0ALL-APP-TFNSW-CORR-000042	DD DD
25	8/05/2020	Clearing of Area 2 Trees with Priority List - Approval required (Urgent trees by 07/05/20)TN 5489, 5490, 12010, 12011, 12012 and 12013	PLR-PLRUINF-CPBD-APP-CORR-000594	DD
26	12/05/2020	Area 2 - Arboricultural Impact Assessment (AIA) Rev E, Updated to address Condition E105 - TN 3536, 3537, 4403, 4407 - 4413, 4420 - 4425, 4430 - 4438, 4680, 4747 - 4758, 4766, 5200, 5202, 5204, 5205, 5206, 5212, 5269 - 5272, 5411 - 5416, 5433, 5773, 5814, 5817 - 5825, 5827, 5835, 5837, 7425, 7425, 7426 - 2731, 7438 - 7454, 7456, 7457, 7470 - 7477, 7481, 7482, 7488, 7489, 7491, 7493, 7495, 7496, 7497, 7499 - 7509, 7516, 7519, 7521, 7522, 7523, 7525, 7535 - 7544, 7546 - 7550, 7552, 7554, 7555, 7559, 7560 and 7563. Area 3 - Tree Assessment Report - Parramatta River Bridge Campilia NSW - TN 12014, 12015, 12016, 8, 12017.	PLRM-CPBD-APP-TX-000075	DD
26 26	13/05/2020 13/05/2020	Area 3 - Tree Assessment Report – Parramatta River Bridge, Camellia NSW -TN 12014, 12015, 12016 & 12017 Area 3 - Tree Assessment Report – Vineyard Creek, Rydalmere NSW -TN 9419, 9563, 12018, 12019, 12020 and 12021	PLR1INF-CPBD-A03-EO-RPT-000019 PLR1INF-CPBD-A03-EO-RPT-000020 DI RM-CPBD-ADD-TY-000075 and DI R-DI R1INE-CPBD-ADD-	DD DD
27	27/05/2020	Area 2 - Arboricultural Impact Assessment (AIA) Rev E, Updated to address Condition E105 and Area 2 Tree Protection Plan for approval (TPP-A2_006) - works proposed to commence 14/05/20 - Tree Protection Plan (TPP) - A2_006 – UTC 006 Utility Relocations – Harris/Macquarie Streets TN 3556, 3557, 3563 - 3566, 4677 - 4680, 5271, 5272, 5487 - 5490, 7426 - 7453, 7458 - 7463, 7467, 10480, 11081 - 11084, 12007-12016.	PLRM-CPBD-APP-TX-000075 and PLR-PLR1INF-CPBD-APP- CORR-000577. TN 4679 and TN 4680 - PLR1INF-CPBD-A02- EO-RPT-000010. TN 4680 - PLR-PLR1INF-CPBD-APP-CORR- 000667.	DD
27	15/06/2020	Area 2 - TPP - A2_008 for approval - commencing 22/06/20TN 4039, 4040, 4041, 5346, 5347, 5350, 5351, 5352, 5405 - 5410, 5433 - 5436, 5465, 5466, 5471, 10484, 10485, 12022, 12023, 12025 - 12028.	PLR-PLR1INF-CPBD-APP-CORR-000709	DD
27	16/06/2020	Area 3 - Tree Protection Plan - Grand Avenue, Camellia, TN 12038 – 12055.	PLR-PLR1INF-CPBD-APP-CORR-000720 PLR1INF-CPBD-A03-EO-PLN-000002	DD
27 27	17/06/2020 18/06/2020	Check inconsistencies TN 5641, 5642 and 15228 - 15232. (note changelog 6/5 should include 15228) LEGEND tab has been updated to better disambiguate IA and PA inputs	PLR1ALL-CPBD-APP-CORR-000062. PLR-PLR1INF-TFNSW-APP-CORR-000072	DD GG
27 27	18/06/2020 18/06/2020	entry 7469 struck through (previously noted same as 4679) status changed from retain to N/A Column 'AR' added to record instances of trees outside project boundary (will be populated going forward)	PLR-PLR1INF-TFNSW-APP-CORR-000072 PLR-PLR1INF-TFNSW-APP-CORR-000072	GG GG
	18/06/2020	Duplicate TN 120010-12013 struck through (status remove > N/A). Up to date entry 'retain' as agreed by PA and IA		GG
27 28	19/06/2020	Minor corrections to 4677 and 4679	ļ.	GG

20	22/05/2020	Average March 1997 Annual Control of the Control of	PLR1INF-COX-A02-UD-REG-500001 and PLR1INF-COX-A02-	
29	23/06/2020	Area 2 - AIA Rev. H - 21 June 2020, Revision of status of TN 4679	UD-REG-500003.A.C3.A.01 PLR Tree Register section 3 BTC	DD
29	25/06/2020	Updated georeference data section 3 Consideration and status update of trees for removal of trees within the SPIR Project boundary (EIS Boundary), which is separate to and outside of the permanent design boundary	PLR-PLR1INF-CPBD-APP-CORR-000632	GG
29	25/06/2020	as shown in the AIA Report TN 9469-9473, 11191-11194, 11546-11555		DD
29 29	25/06/2020 25/06/2020	Check inconsistencies for status. Confirmed trees to be retained -TN 12014, 12015, 12016 Status of trees being reassessed by PA - status changed to uncertain - TN 9407-9410.		DD DD
29	26/06/2020	Request to correct discrepancy in tree register 28 for trees 10335, 15015 and 15016	PLR-PLR1INF-TFNSW-APP-CORR-000076	DD
30	2/07/2020	(Now status'd for removal based on review on AIA plan DWG: A07 and 08 REV L) Area 2 - Arboricultural Impact Assessment (AIA) Rev E - update Tree Regsiter Submission for review and endorsement -TN 11067 - 11078, 11085 - 11123, 11126 - 11143, 11147 -	PLR1INF-CPBD-A02-EO-RPT-000010	DD
		11175. Added geolocation data for TN 10297, 10298, 11001-8, 11010, 11012-13, 11016-19, 11028-29, 11033,36,37,38, 11040-42, 11067, 11069-72, 11075, 11078, 11085, 11087-99,	PLRM-CPBD-APP-TX-000075	
30	6/07/2020 28/07/2020	11108, 11114, 11117, 11120, 11129-36, 11139, 11147, 11150, 11170, 11172-75, (Need corrected data for 11160, 11165, 11167) Area 3 - Tree Assessment Report - Rydalmere Retaining Wall - TN 9285, 12005, 12019, 12077 and 12078.	PLR-PLR1INF-CPBD-TFNSW-CORR-002377 PLR-PLR1INF-CPBD-APP-CORR-000873	GG DD
31	13/08/2020	Area 3 - Tree Protection Plan - 55 Kissing Point Road, Dundas NSW - TN 12073.	PLR-PLR1INF-CPBD-APP-CORR-000924	DD
31	13/08/2020	Area 2 - Tree Protection Plan - A2_007-UTC 009 Utility relocations - Area 2 East -TN 4403, 4407, 4411, 4413, 4420, 4421, 4431, 4438, 5202, 5204, 5205, 5212, 5223, 5773, 7476,	PLR-PLR1INF-CPBD-APP-CORR-000711	DD
		7481, 7482, 7489, 7495, 7496, 7497, 7500 - 7509, 7521, 7522, 7523, 7525, 10531, 10532, 10545 - 10548, 11086, 11101, 11103, 11104, 11105, 11107 - 11110, 12000, and 12024. Area 2 - Tree Protection Plan - TPP-A2 009 - TN 4403, 4408 - 4413, 4420 - 4425, 4430 - 4438, 5817, 5818, 5821, 5822 5824, 5827, 5835, 7488, 7491, 7499-7503, 7516, 7519, 10545-		
31	13/08/2020	10548, 11086 - 11123, 11126 - 11131, 11133 - 11143, 12000, 12028 - 12037, 12095 - 12097.	PLR-PLR1INF-CPBD-APP-CORR-000928	DD
31	14/08/2020	Area 1 - TMP - For Review and Approval - Trees proposed to be removed for High Pressure Gas Main and Sewer Construction -TN 10036, 10037, 10082, 10198, 10286, 10287, 10388 and 10389.	PLR-PLR1INF-CPBD-APP-CORR-000931	DD
31	14/08/2020	Area 1 - TMP - For Review and Approval - Trees proposed to be removed for Water Main - TN 7112 and 7113. Area 1 - Correction of discrepencies: Duplicate of TN 5449 was TN 8507, which was struck out. Duplicate of TN 1141 was TN 8508, which was struck out. Duplicate of TN 1138 was	PLR-PLR1INF-CPBD-APP-CORR-000934	
32	24/08/2020	TN 8509, which was struck out. Duplicate of TN 1139 was TN 8510, which was struck out. Duplicate of TN 5450 was TN 8511, which was struck out. Duplicate of TN 1144 was TN		
32	24/08/2020	8512, which was struck out. Area 2 - Change of status from Retain to Remove. TN 7434, 7435 and 7437.	PLRM-CPBD-APP-TX-000075	DD
32	24/08/2020	Area 1 - Trees removed without requiring consent as they were shrubs, struck out -TN 5764 - 5771.		DD
32 32	24/08/2020 24/08/2020	Area 3 - Correction of status of tree is within project boundary and co-ordinates corrected -TN 12018. Area 3 - Correction of status of tree outside project boundary from remove to retain until planning documentation is in place for removal. TN 9206.	PLR-PLR1INF-CPBD-APP-CORR-000611 PLR-PLR1INF-CPBD-TFNSW-CORR-001351	DD DD
32	25/08/2020	Area 1 - Revise status from 'retain/transplant' to 'remove' for Palm Trees - TN 10019, 10096, 4286 and 4287.	PLR-PLR1INF-CPBD-APP-CORR-000955	DD
32 32	26/08/2020 26/08/2020	Area 3 - Arboricultural Impact Assessment Report Area 3, Revision I - TN 9664 - 9670. Area 3 - Tree Protection Plan - Leamington Road, Telopea (UTC-015) - Commencement Date 7 September 2020 -TN 9372, 9440 - 9442, 9446, 9503, 12145 - 12151.	PLR-PLR1INF-CPBD-APP-CORR-000872 PLR-PLR1INF-CPBD-APP-CORR-000949	DD DD
32	1/09/2020	Area 3 - Updated Coordinate for Tree 12018 - PCPLR Section 3 -TN 12018	PLR-PLR1INF-CPBD-APP-CORR-000974	DD
33	3/09/2020	Area 1 - For Review and Approval Rev B - TMP - UTC-023 Works along Church St between Factory St and Albert St., Parramatta -TN 1160 - 1178, 1182 - 1185, 1187 - 1191, 1193, 1194, 1195, 1199 - 1202, 4263, 4272, 4275 - 4281, 4322, 4335 - 4340, 4342 - 4347, 4357 (shrub struck through), 4665 - 4672. 4673 not present and struck out	PLR-PLR1INF-CPBD-APP-CORR-000981	DD
33	4/09/2020	TN 4674, 5439, 11028, 11029, 11031, 11033, 12074, 12152, 12153, 12154 and 12158 Area 2 - Area 2 - Tree Protection Plan for approval - TPP-A2_010 - Proposed commencement 09/09/20 -TN 10481.	PLR-PLR1INF-CPBD-APP-CORR-000984	DD
33	4/09/2020	Area 3 - Tree Management Plan - Kenny Place, Carlingford - Urgent -TN 9663.	PLR-PLR1INF-CPBD-APP-CORR-000989	DD
33	4/09/2020	Area 1 - For Review and Approval - TMP - Trees Proposed to be removed - UTC-019 Cumberland Campus TN 5736, TN 10273. TN 10418, duplicate number 11011 struck out. TN 12108 - 12114. TN 2053, 5445, 5656, 5657, 10019, 10038, 10093, 10097, 10133, 10196, 10198, 10273, 10286, 10287, 10297, 10326, 15191.	PLR-PLR1INF-CPBD-APP-CORR-000995	DD
33	5/09/2020	Area 3 - Tree Protection Plan – Reserve Street, Rydalmere (UTC-014) -TN 9259 and 9262.	PLR-PLR1INF-CPBD-APP-CORR-000994	DD
33	8/09/2020	TN 5643 duplicate number TN 10302 struck out. TN 5646 duplicate number TN 10019 struck out. TN 5644 duplicate number TN 10270 struck out.	PLR-PLR0ALL-TFNSW-APP-CORR-000051	DD
33	8/09/2020	Area 3 - Trees Impacted by Retaining Wall - Camellia (Section 3) - TPP for Approval -TN 9422, 9514, 9515, 9529, 9530, 11197 and 11198. Area 1 - Fennel Street Compound Tree Removal -TN 4314 and TN 10549 - 10555. TN 12074 was a duplicate number with that in IA PLR Register Rev.33, now changed to	PLR-PLR1INF-CPBD-APP-CORR-001001	DD
34	9/09/2020	TN 0052. TN 12075 - 12079. Area 1 - For Review and Approval - TMP - Trees Proposed to be removed - UTC-017 Hawkesbury Road - TN 1051, 1054, 1087, 1088, 1089, 1090, 1091, 1138, 1139, 1148,	PLR-PLR1INF-CPBD-APP-CORR-000840	DD
34	10/09/2020	1150, 2104, 7096, 7401 and 12170	PLR-PLR1INF-CPBD-APP-CORR-001005	DD
34	14/09/2020	Area 3 – Updated Section 3 AIA - Revision I - TfNSW comments (Revision J) - TN 9407-9410 already been removed by PCPLR, Non-Conformance Report (NCR) (reference: INX 213876).	PLR-PLR1INF-TFNSW-APP-CORR-000099	DD
34	14/09/2020	Area 2 - Tree transplanted by PCPLR. Completion of works noted. Columns 'AS', 'AU', 'BS' and 'BT' changed to transplant to reflect this activity. +TN 4749.	PLR-PLR1INF-CPBD-TFNSW-CORR-002728	DD
34 34	14/09/2020 14/09/2020	Area 3 – For Approval - Tree Protection Plan - Robert Street Drainage Works - TN 12163 (dead tree), TN 12168 and 12169. Area 3 - Priority List - Camellia, Carlingford, Maintenance Facility & Sandown - Tree Register Tree Protection Plan – UTC-013B TN 11480, 9341, 9133 and 9670.	PLR-PLR1INF-CPBD-APP-CORR-001008 PLR-PLR1INF-CPBD-APP-CORR-001007	DD DD
34	15/09/2020	Area 1 - Clarifications of tree status - TN 1171, 1173, 1176, 1185, 1187, 1188, 1190, 3210 - 3213, 3221, 3223 - 3227, 4280 - 4282, 4292, 4294, 4295, 4332, 4333, 4335, 4337, 4339, 4340, 4344, 4345, 4664 - 4668, 5439, 5692, 5693, 5694, 5696, 5697, 5757, 5760 - 5763, 11017, 11031 and 11033	PLR-PLR1INF-CPBD-APP-CORR-001022	DD
34	15/09/2020	Area 3 - Priority List - TN 9054, 9055, 9174, 9391-9396, 9482, 9483, 9507, 9508, 11352, 11363 - 11368, 11593 - 11598, 11600, 11602 - 11607, 11613, 11617 - 11631,	PLR-PLR1INF-CPBD-APP-CORR-001009	DD
34	15/09/2020	11633, 11636, 11638-11640 and 11643-11661. Area 3 - Arboricultural Impact Assessment Report, revision J - TN 11700 - 11737.	PLR-PLR1INF-CPBD-TFNSW-CORR-002728	DD
35	21/09/2020	Area 2 - Tree Protection Plan - TPP-A2_009 - Proposed Commencement 28/09/20 -TN 4413, 4421, 5817, 5818, 11098, 11099 & 11100	PLR-PLR1INF-CPBD-APP-CORR-001050	DD
35	22/09/2020	Area 2 - Arboricultural Impact Assessment (AIA) Report – Section 2 - Revision J with Priority Trees - TN 11071 - 11076, 11101, 11109 - 11112, 11117, 11118, 11120, 11144 - 11146. 11738 struck out as duplicate number with TN 10481. TN 11739 - 11750 and 11760 - 11765 and 11769 - 11803. TN 11804 - 11817 struck out as shrubs <3	PLR-PLR1INF-CPBD-APP-CORR-001049	DD
	22/00/2020	high.		
35 35	22/09/2020 24/09/2020	Area 3 - Tree Management Plan - Sandown Line (Area 3) - Urgent Approval Required -TN 14086. Discrepancies - TN 4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - , TN 4261 struck out as duplicate number with 4369. TN 4267 struck out as Shrub	PLR-PLR1INF-CPBD-APP-CORR-001055 PLR-PLR1INF-CPBD-APP-CORR-001022.	DD DD
		Discrepancies - TN 4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - TN 4261 struck out as duplicate number with 4369. TN 4261 struck out as duplicate number with TN 11050. TN 10461 struck out, duplicate number with TN 11050. TN 10461 struck out, duplicate number with TN 11052. TN 10462 struck out, duplicate number with TN 11051. TN 10465 struck out, duplicate number with TN 11051. TN 10465 struck out, duplicate number with TN 11059. TN 10465 struck out, duplicate number with TN 11059. TN 10465 struck out, duplicate number with TN 11056. TN 10467 struck out, duplicate number with TN 11051. TN 10469 struck out, duplicate number with TN 11052. TN 10470 struck out, duplicate number with TN 11055. TN 10470 struck out, duplicate number with TN 11055. TN 10471 struck out, duplicate number with TN 11058. TN 10472 struck out, duplicate number with TN 11059. TN 10473 struck out, duplicate number with TN 11059. TN 10473 struck out, duplicate number with TN 11060. TN 10474 struck out, duplicate number with TN 11061. TN 10475 struck out, duplicate number with TN 11061. TN 10475 struck out, duplicate number with TN 11064. TN 10475 struck out, duplicate number with TN 11066. TN 7494 struck out, duplicate number with TN 11066. TN 7494 struck out, duplicate number with TN 11166. TN 4865 struck out, duplicate number with TN 11166. TN 4865 struck out, duplicate number with TN 11166. TN 4865 struck out, duplicate number with TN 11166. TN 4865 struck out, duplicate number with TN 11166. TN 4865 struck out, duplicate number with TN 11166. TN 686 struck out, duplicate number with TN 11166. TN 686 struck out, duplicate number with TN 11166. TN 686 struck out, duplicate number with TN 11166. TN 769 struck out, duplicate number with TN 11166. TN 769 struck out, duplicate number with TN 11166. TN 769 struck out, duplicate number with TN 11166. TN 769 struck out, duplicate number with TN 11166. TN 769 struck out, duplicate number with TN 11166. TN 769 struck out,		
35 35 35 35 35 35 35	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020	Discrepancies - TN 4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - TN 4295 is truck out as displicate number with TN 11050. TN 4265 struck out as Objected number with TN 11050. TN 10465 struck out, duplicate number with TN 11052. TN 10465 struck out, duplicate number with TN 11053. TN 10465 struck out, duplicate number with TN 11051. TN 10465 struck out, duplicate number with TN 11051. TN 10465 struck out, duplicate number with TN 11051. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10475 struck out, duplicate number with TN 11058. TN 10475 struck out, duplicate number with TN 11058. TN 10475 struck out, duplicate number with TN 11059. TN 10475 struck out, duplicate number with TN 11060. TN 10475 struck out, duplicate number with TN 11060. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with TN 11166. TN 10475 struck out, duplicate number with T	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000968	DD DD DD GG DD
35 35 35 35 35 35 35	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 29/09/2020	Discrepancies - TN-4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - TN-4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - TN-4293 struck out as duplicate number with TN 11050. TN 10460 struck out, duplicate number with TN 11050. TN 10461 struck out, duplicate number with TN 11053. TN 10464 struck out, duplicate number with TN 11053. TN 10464 struck out, duplicate number with TN 11051. TN 10465 struck out, duplicate number with TN 11051. TN 10465 struck out, duplicate number with TN 11052. TN 10465 struck out, duplicate number with TN 11062. TN 10465 struck out, duplicate number with TN 11065. TN 10475 struck out, duplicate number with TN 11065. TN 10475 struck out, duplicate number with TN 11055. TN 10470 struck out, duplicate number with TN 11055. TN 10471 struck out, duplicate number with TN 11058. TN 10473 struck out, duplicate number with TN 11068. TN 10473 struck out, duplicate number with TN 11069. TN 10474 struck out, duplicate number with TN 11060. TN 10475 struck out, duplicate number with TN 11061. TN 10475 struck out, duplicate number with TN 11065. TN 10477 struck out, duplicate number with TN 11065. TN 10477 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11065. TN 10475 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN 11165. TN 10470 struck out, duplicate number with TN	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000968	DD DD DD GG DD GG
35 35 35 35 35 35 35 35 35	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 29/09/2020 30/09/2020 1/10/2020	Discrepancies - TM 4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - TM 4295 struck out as deplicate number with 4389. TM 4267 struck out as Shrub TM 10960 struck out, doublicate number with TM 11050. TM 10960 struck out, doublicate number with TM 11050. TM 10960 struck out, doublicate number with TM 11051. TM 10960 struck out, doublicate number with TM 11051. TM 10960 struck out, doublicate number with TM 11051. TM 10960 struck out, doublicate number with TM 11063. TM 10960 struck out, doublicate number with TM 11063. TM 10960 struck out, doublicate number with TM 11063. TM 10960 struck out, doublicate number with TM 11063. TM 10960 struck out, doublicate number with TM 11063. TM 10960 struck out, doublicate number with TM 11063. TM 10960 struck out, doublicate number with TM 11063. TM 10960 struck out, doublicate number with TM 11063. TM 10960 struck out, doublicate number with TM 11063. TM 10970 struck out, doublicate number with TM 11063. TM 10970 struck out, doublicate number with TM 11063. TM 10970 struck out, doublicate number with TM 11063. TM 10970 struck out, doublicate number with TM 11063. TM 10970 struck out, doublicate number with TM 11063. TM 10970 struck out, doublicate number with TM 11063. TM 10970 struck out, doublicate number with TM 11063. TM 10970 struck out, doublicate number with TM 11063. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with TM 11165. TM 10970 struck out, doublicate number with	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000968	DD DD DD GG DD GG GG GG
35 35 35 35 35 35 35 35 35 36 36	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 29/09/2020 1/10/2020 4/10/2020	Discrepancies - TN 4/293 on private property, status changed to same as adjacent palm 4/294. Discrepancies - TN 14/295 struck out as doubleate number with 4/399. TN 4/267 struck out as doubleate number with 1/305. TN 10/465 struck out, duplicate number with 1/305. TN 10/475	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000968 PLR-PLR0ALL-TFNSW-APP-CORR-000057	DD DD DD GG DD GG GG GG GG DD
35 35 35 35 35 35 35 35 35	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 29/09/2020 30/09/2020 1/10/2020	Decrepancies - TN 4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - Pi 14 256 struck out as duplicate number with 14 369. TN 4265 struck out, duplicate number with 17 11050. TN 10664 struck out, duplicate number with 17 11052. TN 10664 struck out, duplicate number with 17 11053. TN 10664 struck out, duplicate number with 17 11053. TN 10665 struck out, duplicate number with 17 11053. TN 10665 struck out, duplicate number with 17 11054. TN 10665 struck out, duplicate number with 17 11055. TN 10665 struck out, duplicate number with 17 11056. TN 10667 struck out, duplicate number with 17 11056. TN 10667 struck out, duplicate number with 17 11055. TN 10669 struck out, duplicate number with 17 11055. TN 10669 struck out, duplicate number with 17 11055. TN 10670 struck out, duplicate number with 17 11057. TN 10471 struck out, duplicate number with 17 11059. TN 10471 struck out, duplicate number with 17 11059. TN 10472 struck out, duplicate number with 17 11061. TN 10472 struck out, duplicate number with 17 11065. TN 10475 struck out, duplicate number with 17 11065. TN 10475 struck out, duplicate number with 17 11065. TN 10475 struck out, duplicate number with 17 11065. TN 10475 struck out, duplicate number with 17 11065. TN 10475 struck out, duplicate number with 17 11065. TN 10475 struck out, duplicate number with 17 11065. TN 10475 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11165. TN 10485 struck out, duplicate number with 17 11166. TN 10485 struck out, duplicate number with 17 111	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000968	DD DD DD GG DD GG GG GG GG
35 35 35 35 35 35 35 35 36 36 36	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 29/09/2020 4/10/2020 4/10/2020 6/10/2020	Decrepancies - TN 4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - TN 14263 struck out as duplicate number with 4899. TN 4265 struck out, duplicate number with TN 11050. TN 10465 struck out, duplicate number with TN 11052. TN 10465 struck out, duplicate number with TN 11053. TN 10465 struck out, duplicate number with TN 11053. TN 10465 struck out, duplicate number with TN 11054. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11053. TN 10465 struck out, duplicate number with TN 11053. TN 10465 struck out, duplicate number with TN 11055. TN 10475 struck out, duplicate number with TN 11057. TN 10475 struck out, duplicate number with TN 11057. TN 10475 struck out, duplicate number with TN 11056. TN 10475 struck out, duplicate number with TN 11056. TN 10475 struck out, duplicate number with TN 11064. TN 10475 struck out, duplicate number with TN 11064. TN 10475 struck out, duplicate number with TN 11064. TN 10475 struck out, duplicate number with TN 11065. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066.	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-APP-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000968 PLR-PLR0ALL-TFNSW-APP-CORR-000057	DD DD DD GG DD DD GG GG DD DD DD DD DD D
35 35 35 35 35 35 35 36 36 36 36 36 37	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 29/09/2020 1/10/2020 4/10/2020 4/10/2020 6/10/2020 9/10/2020	Discrepancies - TN 4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - TN 4295 struck out as duplicate number with 4895. TN 4267 struck out as Shrub TN 10469 struck out, duplicate number with TN 11092. TN 10465 struck out, duplicate number with TN 11093. TN 10466 struck out, duplicate number with TN 11093. TN 10466 struck out, duplicate number with TN 11095. TN 10466 struck out, duplicate number with TN 11095. TN 10466 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11096. TN 1047 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out duplicate number with TN 11096. TN 1048 struck out duplicate number with TN 11096. TN 1048 struck out duplicate number with TN 11096. TN 1048 struck out as always and paper out with TN 11096. TN 1048 struck out as always and the total of 1048 (now struck out) Georderence TN 11096 fied	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000968 PLR-PLR0ALL-TFNSW-APP-CORR-000057 PLR-PLR0ALL-TFNSW-APP-CORR-000077 PLR-PLR1INF-CPBD-A03-EO-RPT-000010 PLR-PLR1INF-CPBD-APP-CORR-001077 PLR-PLR1INF-CPBD-APP-CORR-001034	DD DD DD GG DD DD DD DD DD DD DD DD DD D
35 35 35 35 35 35 35 35 36 36 36	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 29/09/2020 4/10/2020 4/10/2020 6/10/2020	Decrepancies - TN 4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - TN 14263 struck out as duplicate number with 4899. TN 4265 struck out, duplicate number with TN 11050. TN 10465 struck out, duplicate number with TN 11052. TN 10465 struck out, duplicate number with TN 11053. TN 10465 struck out, duplicate number with TN 11053. TN 10465 struck out, duplicate number with TN 11054. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11055. TN 10465 struck out, duplicate number with TN 11053. TN 10465 struck out, duplicate number with TN 11053. TN 10465 struck out, duplicate number with TN 11055. TN 10475 struck out, duplicate number with TN 11057. TN 10475 struck out, duplicate number with TN 11057. TN 10475 struck out, duplicate number with TN 11056. TN 10475 struck out, duplicate number with TN 11056. TN 10475 struck out, duplicate number with TN 11064. TN 10475 struck out, duplicate number with TN 11064. TN 10475 struck out, duplicate number with TN 11064. TN 10475 struck out, duplicate number with TN 11065. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066. TN 10475 struck out, duplicate number with TN 11066.	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-APP-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000968 PLR-PLR0ALL-TFNSW-APP-CORR-000057	DD DD DD GG DD DD GG GG DD DD DD DD DD D
35 35 35 35 35 35 35 36 36 36 36 36 37	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 29/09/2020 1/10/2020 4/10/2020 4/10/2020 6/10/2020 9/10/2020	Discrepancies - TN 4293 on private property, status changed to same as adjacent palm 4294. Discrepancies - TN 4295 struck out as duplicate number with 4895. TN 4267 struck out as Shrub TN 10469 struck out, duplicate number with TN 11092. TN 10465 struck out, duplicate number with TN 11093. TN 10466 struck out, duplicate number with TN 11093. TN 10466 struck out, duplicate number with TN 11095. TN 10466 struck out, duplicate number with TN 11095. TN 10466 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 10467 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11095. TN 1047 struck out, duplicate number with TN 11096. TN 1047 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out, duplicate number with TN 11096. TN 1048 struck out duplicate number with TN 11096. TN 1048 struck out duplicate number with TN 11096. TN 1048 struck out duplicate number with TN 11096. TN 1048 struck out as always and paper out with TN 11096. TN 1048 struck out as always and the total of 1048 (now struck out) Georderence TN 11096 fied	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000968 PLR-PLR0ALL-TFNSW-APP-CORR-000057 PLR-PLR0ALL-TFNSW-APP-CORR-000077 PLR-PLR1INF-CPBD-A03-EO-RPT-000010 PLR-PLR1INF-CPBD-APP-CORR-001077 PLR-PLR1INF-CPBD-APP-CORR-001034	DD DD DD GG DD DD DD DD DD DD DD DD DD D
35 35 35 35 35 35 35 35 36 36 36 37 37	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 30/09/2020 4/10/2020 4/10/2020 6/10/2020 9/10/2020 15/10/2020	Discrepancies - 1N 4295 on private property, status changed to same as adjacent palm 4294. Discrepancies - 1N 4296 struck out as duplicate number with 4396. 1N 4267 struck out as duplicate number with 1N 11050. 1N 10466 struck out, duplicate number with 1N 11052. 1N 10465 struck out, duplicate number with 1N 11052. 1N 10465 struck out, duplicate number with 1N 11053. 1N 10466 struck out, duplicate number with 1N 11054. 1N 10466 struck out, duplicate number with 1N 11055. 1N 10465 struck out, duplicate number with 1N 11056. 1N 10466 struck out, duplicate number with 1N 11056. 1N 10466 struck out, duplicate number with 1N 11056. 1N 10466 struck out, duplicate number with 1N 11056. 1N 10466 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out of the 1N 10476 struck out of	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000957 PLR-PLR0ALL-TFNSW-APP-CORR-000057 PLR-PLR1INF-CPBD-A03-EO-RPT-000010 PLR-PLR1INF-CPBD-APP-CORR-001077 PLR-PLR1INF-CPBD-APP-CORR-001034 PLR-PLR1INF-CPBD-APP-CORR-001108 PLR-PLR1INF-CPBD-APP-CORR-001103	DD DD DD GG GG DD DD DD GG DD DD DD DD D
35 35 35 35 35 35 35 35 36 36 36 36 37 37	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 4/10/2020 4/10/2020 4/10/2020 6/10/2020 9/10/2020 14/10/2020	Decrepancies - Th 4239 on private property, status changed to same as adjacent palm 4294. The 4267 struck out as duplicate number with 4369. Th 4267 struck out as duplicate number with 4369. Th 4269 struck out, duplicate number with 11052. Th 4269 struck out, duplicate number with Th 11052. Th 4269 struck out, duplicate number with Th 11052. Th 4269 struck out, duplicate number with Th 11052. Th 10469 struck out, duplicate number with Th 11056. Th 10469 struck out, duplicate number with Th 11056. Th 10469 struck out, duplicate number with Th 11056. Th 10469 struck out, duplicate number with Th 11056. Th 10469 struck out, duplicate number with Th 11055. Th 10469 struck out, duplicate number with Th 11055. Th 10469 struck out, duplicate number with Th 11055. Th 10469 struck out, duplicate number with Th 11055. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th 11056. Th 1047 struck out, duplicate number with Th	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000957 PLR-PLR0ALL-TFNSW-APP-CORR-000057 PLR-PLR1INF-CPBD-A03-EO-RPT-000010 PLR-PLR1INF-CPBD-APP-CORR-001074 PLR-PLR1INF-CPBD-APP-CORR-001034 PLR-PLR1INF-CPBD-APP-CORR-001108	DD DD DD GG GG DD DD DD GG DD DD DD DD D
35 35 35 35 35 35 35 35 36 36 36 37 37	24/09/2020 24/09/2020 25/09/2020 25/09/2020 25/09/2020 25/09/2020 29/09/2020 30/09/2020 4/10/2020 4/10/2020 6/10/2020 9/10/2020 15/10/2020	Discrepancies - 1N 4295 on private property, status changed to same as adjacent palm 4294. Discrepancies - 1N 4296 struck out as duplicate number with 4396. 1N 4267 struck out as duplicate number with 1N 11050. 1N 10466 struck out, duplicate number with 1N 11052. 1N 10465 struck out, duplicate number with 1N 11052. 1N 10465 struck out, duplicate number with 1N 11053. 1N 10466 struck out, duplicate number with 1N 11054. 1N 10466 struck out, duplicate number with 1N 11055. 1N 10465 struck out, duplicate number with 1N 11056. 1N 10466 struck out, duplicate number with 1N 11056. 1N 10466 struck out, duplicate number with 1N 11056. 1N 10466 struck out, duplicate number with 1N 11056. 1N 10466 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out, duplicate number with 1N 11056. 1N 10476 struck out of the 1N 10476 struck out of	PLR-PLR1INF-CPBD-APP-CORR-001022. PLR-PLR1INF-CPBD-TFNSW-CORR-002728 PLR-PLR1INF-CPBD-APP-CORR-000969 PLR-PLR1INF-CPBD-APP-CORR-000957 PLR-PLR0ALL-TFNSW-APP-CORR-000057 PLR-PLR1INF-CPBD-A03-EO-RPT-000010 PLR-PLR1INF-CPBD-APP-CORR-001077 PLR-PLR1INF-CPBD-APP-CORR-001034 PLR-PLR1INF-CPBD-APP-CORR-001108 PLR-PLR1INF-CPBD-APP-CORR-001103	DD DD DD GG GG DD DD DD GG DD DD DD DD D

	Г		T	1
37	19/10/2020	Area 3 - Tree Management Plan - Winter Street, Telopea -TN 12132 and 12133 and 12204 – 12221.	PLR-PLR1INF-CPBD-APP-CORR-001122	DD
37	19/10/2020	Area 1 - Revise status from 'retain/transplant' to 'remove' for Palm Tree - TN 5646. TN 10019 struck out as duplicate of TN 5646.	PLR-PLR1INF-CPBD-APP-CORR-000955	DD
37	19/10/2020	Area 2 - Clarification, Revise status, George Street, Parramatta - Trees removed by othersTN 12033 and 12034. TN 5493 was struck out as a duplicate of TN 12033. TN 5494 was struck out as a duplicate of TN 12034.	PLR-PLR1INF-CPBD-APP-CORR-000928	DD
		Struck out as a duplicate of 11 12054.		
37	19/10/2020	Area 1 - Clarification - Subject to assessment and outcome of additional Root Mapping works - status changed from remove to UncertainTN 5724.		DD
37 37	20/10/2020 20/10/2020	Area 1 - TMP Update - TN 12158 Albert St North Parramatta post Root Mapping TN 12158. Struck out duplicate TN 3417 of TN 5258	PLR-PLR1INF-CPBD-APP-CORR-001127	DD GG
37	20/10/2020	Area 1 - Added status 'trees removed by others' to trees identified as removed for Hospital development -TN 10054, 10056, 10091, 10092, 10112, 10113, 10114, 10115, 10116,	PLR-PLR1ALL-TFNSW-APP-CORR-000052	DD
38	23/10/2020	10160, 10161, 10188, 10190, 10191, 10265, 10275, 10282, 10285, 15010, 15011, 15012 and 15013. Area 3 - Area 3 - Tree Management Plan - Jenkins and James Streets, Carlingford -TN 9604, 9605, 12222 – 12237. Dead tree struck out - TN 9604.	PLR-PLR1INF-CPBD-APP-CORR-001128	DD
38	23/10/2020	Area 3 - Area 3 - Tree Protection plan - Sturt street Telopea - TN 9791 and 12108 – 12144. TN 12108 - 12114 already in IA PLR Tree Register - Rev.33 and TN 12132 and 12123 already in IA PLR Tree Register - Rev.37 to be updated with new numbers. Updates completed with - TN 9791 and 12115 - 12122, 12124-12131 and 12133 - 12144.	PLR-PLR1INF-CPBD-APP-CORR-000921	DD
38	23/10/2020	Area 3 - Descrepancy - Updated status of "Tree to be retained", Arboricultural Impact Assessment Report, Doc No.: PLR1INF-CPBD-A03-EO-RPT-000010, Revision Date 31/7/2020,	PLR-PLR1INF-CPBD-TFNSW-CORR-002728	DD
38	23/10/2020	Revision J - TN 9625. Updated status to retain - TN 9774 - 9778. Area 3 - Staus change from tree to shrub as plant <5 m high - TN 9709 and 9716 and struck out.	PLRM-TFNSW-APP-TX-000454	DD
38 38	26/10/2020 26/10/2020	Area 2 - TPP-A2_011 - 200 George Street, Parramatta -TN 11781-11783. Area 1 - TMP Update - TN 12001 O'Connell Street, North Parramatta -TN 12001.	PLR-PLR1INF-CPBD-APP-CORR-001140 PLR-PLR1INF-CPBD-APP-CORR-001137	DD DD
38	27/10/2020	Area 3 - Discrepancy - Grand Avenue North. Tree marked for removal in IA PLR Tree Register Rev.17 24/1/2020 but not marked in register for removal - status updated to removal. TN 4752.	PLR-PLR1INF-TFNSW-APP-CORR-000113 and PLRM-CPBD- APP-TX-000075	DD
38 38	28/10/2020 28/10/2020	Area 3 - Tree Management Plan - Parramatta River South Drainage -TN 11576 - 11588 and 12238 - 12260. Area 3 - Tree Management Plan - Kissing Point Road Retaining Wall and Footpath -TN 12502 - 12507.	PLR-PLR1INF-CPBD-APP-CORR-001144 PLR-PLR1INF-CPBD-APP-CORR-001145	DD DD
38	29/10/2020	Updated Section areas and updated offsets - (offsets for trees with IA status remove, otherwise shown as N/A, all changes higlighted)	PLR-PLR1ALL-APP-APP-CORR-000056	GG
38	3/11/2020	Area 2 - Arthur Phillip High School, Parramatta - trees removed by others. TN 7540, 7546, 7547, 7548, 7549, 7550, 7552 and 7553.	PLR-PLR1ALL-TFNSW-APP-CORR-000056	DD
38	6/11/2020	All Areas - Change of status to 'Uncertain' (except where shown differently) of some trees in consideration of CoA E105 requirements - TN 3223 - 3227* (*5 trees) 1173, 1174, 1176 5697 4282 4664 (already removed - 17/04/2020 IA update, - Agreed. 29/03/19) 11031 11002, (Note: TN 11002 not TN 1102 as TN 1102 already removed), 1033, TN 1032 (duplicate with TN 11002 and TN 1032 struckout) 5439 4439 1051, 1054 7401 1107 (no change from existing 'Uncertain' status), TN 1134 (no change from existing 'Uncertain' status), 1148, 2104 5015 (no change from existing 'Uncertain' status), TN 5017 (duplicate with TN 5015 and and TN 5017 struckout), TN 5018 (no change from existing 'Uncertain' status) 1087 - 1091* (*5 trees), 7096 - 7102* (*7 trees) 5591 - 5599* (*9 trees) 10326, TN 5715 (removed - consent Rev. 24)	PLR-PLROALL-TFNSW-APP-CORR-000066	DD
38	6/11/2020	5724 (no change from existing 'Uncertain' status), 5713 3210 - 3212* (*3 trees) 5692 - 5694* (*3 trees) 3219 (Tree Removed - consent in Rev. 24), 4266 4272 3231 - 3241* (*11 trees) 4286, 4287, 4293, 4294, 4295, 4584, 4263, 4672, 1160, 1164, 1166, 1168, 1170, 1171, 1173, 4339, 4340, 5439, 4335, 4337, 4338, 4343, 4344, 4345 10442 (tree within construction area, removed without consent) 11076, 7538 - 7542* (*5 trees) 11076 - (no change from existing 'Uncertain' status), 7538 - 7542* (*5 trees) - (no change from existing 'Uncertain' status) 11780, 7438 - 7452* (*14 trees) 5818 11776	PLR-PLROALL-TFNSW-APP-CORR-000066	DD
39	13/11/2020 and 24/11/2020	Discrepancies and clarifications from TfNSW workshop #001 22/05/2020 - TN 7556 Removed by others on adjacent development and struckout. TN 5217 struck out as duplicate of TN 10541. TN 5218 struck out as duplicate of TN 10540. TN 5219 struck out as duplicate of TN 10539. TN 4459 struck out as duplicate of TN 11111. TN 4468 struck out as duplicate of TN 11118. TN 4466 struck out as duplicate of TN 111115. TN 4463 struck out as duplicate of TN 111102. TN 4447 struck out as duplicate of TN 11116. TN 4448 struck out as duplicate of TN 11102. TN 4444, street tree Angophora costata removed prior to project. Actual TN 4445 located opposite path within adjacent private property and since TN 11102 was incorrectly given the Geodata data for TN 4444 which has been corrected with that of TN 4445 thus TN 4445 struck out as redundant duplicate. TN 1102 status changed to 'Uncertain'. TN 4455 struck out as duplicate of TN 11106. TN 4448 struck out as duplicate of TN 11105. TN 4454 struck out as duplicate of TN 11107. TN 4440 struck out as duplicate of TN 11107. TN 4449 struck out as duplicate of TN 11107. TN 4450 struck out as duplicate of TN 11203. TN 4448 struck out as duplicate of TN 1105. TN 4487 struck out as duplicate of TN 12030. TN 4488 struck out as duplicate of TN 10545. TN 4487 struck out as duplicate of TN 12030. TN 4488 struck out as duplicate of TN 10547. TN 4488 struck out as duplicate of TN 12031. TN 4440 struck out as duplicate of TN 12037. TN 4485 struck out as duplicate of TN 12031. TN 4442 struck out as duplicate of TN 12037. TN 4485 struck out as 400 struck out as 400 suplicate of TN 12037. TN 4485 struck out as 400 struck out as 400 suplicate of TN 12037. TN 4485 struck out as 400 suplicate of TN 12035. TN 4402 struck out as duplicate of TN 12035. TN 1489 struck out as 400 suplicate of TN 12035. TN 10479 Tree located within Arthur Phillip High School, Parramatta, and removed by others during redevelopment works. TN 5828 struck out as duplicate of TN 1164. TN 4483 struck out as duplicate o	PLRM-TFNSW-APP-TX-000454 and PLR-PLR1ALL-TFNSW-APP-CORR-000056 (TN 10479)	DD
39	19/11/2020	Area 2 - Tree Impact Assessment (TIA) Area 2 - (Camphor Laurel) -TN 11112 removal and replacement with and advanced tree in a similar location adjacent public housing.	19/11/2020 IA update, Ref. No.: PLR-PLR1INF-CPBD-APP-CORR-001150 and PLR-PLR1ALL-CPBD-APP-CORR-000125.	DD
39	19/11/2020	Area 2 - Crown Pruning works for TN 11150 at Tramway Avenue, Rosehill TN 11150.	PLRM-TFNSW-APP-TX-000690	DD
39 39	19/11/2020 19/11/2020	Area 3 - Tree Priority List - Updated 01 October 2020 - TN 9176. Area 3 - Tree Management Plan - Sandown Line, Camelia -TN 14006, 14007, 14043 and 14044.	PLR-PLR1INF-CPBD-APP-CORR-001192 PLR-PLR1INF-CPBD-APP-CORR-001172	DD DD
39 39	19/11/2020 19/11/2020	Tree removal certificates added for area 2 (A2_014 - A2_018) Tree removal certificates added for area 1 (A1-003 - A1-025)	PLR-PLR1INF-CPBD-APP-CORR-001173 PLR-PLR1INF-CPBD-APP-CORR-001176	GG GG
39	19/11/2020	Tree removal certificate added for area 3 (A03.12)	PLR-PLR1INF-CPBD-APP-CORR-001177	GG
39	19/11/2020	Area 1 - updated - incorrectly struckout and former status restored -TN 5740, 5746-5753. BW' Column status changed 'Request for additional infromation.' - TN 1045, 1135, 1138, 5258, 5321, 5450, 5936, 5937, 9426, 9774, 9790, 10503, 11200, 11374, 11383, 11432,	PLR-PLROALL-TFNSW-APP-CORR-000067	DD/GG
	24/11/2020	11480.	PLR-PLROALL-TFNSW-APP-CORR-000067	DD/GG
39	28/11/2020	Area 3 - Tree Assessment Report - Winter Street Water Main Diversion - No encroachment for TN 9073, 9171, 9172, 11372, 11373 and 12238 - 12243.	PLR-PLR1INF-CPBD-APP-CORR-001199	DD
39	28/11/2020	Change of status to 'Uncertain' (except where shown differently) of some trees in consideration of CoA E105 requirements -TN 4664-4669.	PLR-PLR1INF-TFNSW-APP-CORR-000124	DD
40	3/12/2020	Area 3 - Consistency Assessment PCPLR-CA-025 and TFNSW-CA-012 - Condition A24, Consistency Assessment for activities relating to the Infrastructure Package (Package 4), in compliance with Condition of Approval A24 (b). PCPLR-CA-025 Drainage Outside Project Footprint in Camellia PCPLR-CA-012 Carlingford Line Stockpile, - Tree Management Plan – Camellia Stop Retaining Wall -TN 9422, 9514, 9515, 9529, 9530, 11197 and 11198, - Tree Management Plan - Kissing Point Road Retaining Wall and Footpath - TN 12503 - 12507.	PLRM-TFNSW-APP-TX-000719	DD
40	4/12/2020	Area 1 - TMP for IA Approval - Requesting removal of trees 10120, 15017, 15018, 15019 and 15020 as per onsite discussion on 27/11 - TN 10120, 15017, 15018, 15019, 15020 and 12058 and 12059.	PLR-PLR1INF-CPBD-APP-CORR-001225	DD
40	4/12/2020	Area 3 - Tree Assessment Report - TN 9735, 104-106 Adderton Rd, Carlingford - TN 9735.	PLR-PLR1INF-CPBD-APP-CORR-001220 and PLR-PLR1INF-CPBD-APP-CORR-001245	DD
40	10/12/2020	Area 1 - TN 5724 Tree Impact Assessment Report, Minor Crown Pruning being <10% of crown where Damage is not being caused, works status changed from 'Retain' to 'Retain, pr,	PLR-PLR1INF-TFNSW-CPBD-CORR-003187	DD
70		cr' - TN 7524. Area 3 - Tree Viability Assessment by IA and tree status changed from 'Remove' to 'Retain' - TN 9016, 9020, 9124, 9125, 9134, 9170, 9172, 9173, 9184, 9214, 9215, 9235, 9264,		
40	10/12/2020	9265, 9364, 9366, 9372, 9505, 9572, 9735, 9764, 9789, 11241 and 14086.	PLR-PLR1INF-CPBD-APP-CORR-001245	DD
40	10/12/2020	'Change of status to 'Uncertain' (except where shown differently) of some trees in consideration of CoA E105 requirements -TN 3219, 3221 and 4292.	PLR-PLROALL-TFNSW-APP-CORR-000066	DD

40	10/12/2020	Discrepancies and corrections -TN 26 struck out as duplicate of TN 11001, TN 4405 correct location for data for TN 11784. TN 4405 to be struck out and Georeferencing transferred to TN 11784. TN 4406 shrub <3 m high and struck out, TN 4458 shrub <3 m high and struck out, TN 4450 Tree on private property to be retained and not impacted by project. TN 4461 Tree on private property to be retained and not impacted by project. TN 4465 Tree on private property to be retained and not impacted by project. TN 4465 Tree on private property to be retained and not impacted by project. TN 1045 IA approved for removal on 27 April 2020 (PLR-PLR1INF-APP-CPBD-CORR-000477) but did not subsequently reflect in the Tree Register.	PLR-PLROALL-CPBD-APP-CORR-000040 (all other trees), PLR-PLR1INF-CPBD-APP-CORR-000555 (TN 1045).	DD
40	14/12/2020	Discrepancies and corrections - TN 11197 and TN 11198 updated from Geoeferencing cordinates provided in PLR-PLR1INF-CPBD-APP-CORR-001194	PLR-PLR1INF-CPBD-APP-CORR-001194	DD
41	17/12/2020	Discrepancies and corrections - Status changed from Tree to Shrub <3 m high and struck out -TN 12172.	PLR-PLR1INF-CPBD-APP-CORR-001269	DD
41	4/01/2021	Discrepancies and corrections - Age class status changed from Young to Matue - TN 15017 - 15020.	PLR-PLROALL-TFNSW-APP-CORR-000070	DD
41	4/01/2021	Area 1 - Tree Impact Assessment - St Patrick's Cemetery - Urgent Approval Request for removal of treesTN 1229 and 1249. Other trees assessed in the Non-destructive Digging (NDD) root mapping works report of 2 January 2021 to be retained: TN 1319, 1205, 1206, 1207, 1223, 1237, 1238, 1254, 1255, 1259, 1265, 1271, 1272, 1277, 1286 and 1294.	PLR-PLR1INF-CPBD-APP-CORR-001293	DD
41	5/01/2021	Area 3 - Tree Management Plan - Adderton Road Utility Works, negligible impact -TN 12066.	PLR-PLR1INF-CPBD-APP-CORR-001294	DD
41	11/01/2021	Area 2 - Tree Impact Assessment - TIA - TN 5818 (Pruning, crown and roots) - TN 5818.	PLR-PLR1INF-CPBD-APP-CORR-001300	DD
41	11/01/2021	Area 2 - Tree Impact Assessment (TIA) - TIA -TN 11774 and 11775.	PLR-PLR1INF-CPBD-APP-CORR-001305	DD
41	11/01/2021	Area 3 - Tree Assessment Report - Drainage at Reserve Street, Rydalmere - TN 12060 - 12065.	PLR-PLR1INF-CPBD-APP-CORR-001305	DD

			PLR		Rev 4	11.03				IA															
(ur			Area			E	104(a) Georeference Location	d				E104(b) AS49	70 Preliminary	Assessm	ent										
colum							E104(a)						E104(b)											E10	4(c)
Last Updated (filter column)	Tree ID number	Contract	Precinct	Section	NORTHING	EASTING	Latitude	Longitude	RL	Botanical Name	Height (m)	DBH (mm)	Crown Spread (m)	TPZ (m)	DARB (mm)	SRZ (m)	Age Class	Life Expectancy	Condition (Structure)	amenity value	Heritage / Culture Matters	Ecological value	Threatened species assessment	Significance Scale	Retention Value
4/01/2021	1205	INF	Parramatta North Precinct	1	6258052.157	315333.643	-33.80160744	151.0050983	31.191	Corymbia maculata	24	500	10	6	550	2.57	М	2	G	Н	N	М	N	Н	Н
4/01/2021	1206	INF	Parramatta North Precinct	1	6258049.664	315332.96	-33.80162979	151.0050904	31.087	Lophostemon confertus	9	290	3	3.48	340	2.1	М	2	G	Н	N	М	N	Н	Н
4/01/2021	1207	INF	Parramatta North Precinct	1	6258044.295	315334.623	-33.80167847	151.0051072	31.036	Lophostemon confertus	6	240	3	2.88	300	2	M	2	F	Н	N	М	N	М	М
4/01/2021	1223	INF	Parramatta North Precinct	1	6258031.2	315339.774	-33.80179741	151.0051601	30.89	Lophostemon confertus	10	370	8	4.44	450	2.37	M	2	F	Н	N	М	N	М	М
4/01/2021	1229	INF	Parramatta North Precinct	1	6258018.096	315345.331	-33.80191649	151.0052174	30.73	Lophostemon confertus	9	300	4	3.6	320	2.05	M	2	G	Н	N	М	N	М	М
4/01/2021	1237	INF	Parramatta North Precinct	1	6258005.185	315350.675	-33.8020338	151.0052724	30.532	Lophostemon confertus	10	350	5	4.2	380	2.2	M	2	G	Н	N	M	N	М	М
4/01/2021	1238	INF	Parramatta North Precinct	1	6257998.625	315353.462	-33.80209342	151.0053011	30.441	Lophostemon confertus	12	400	6	4.8	420	2.3	M	2	G	Н	N	М	N	М	М
4/01/2021	1249	INF	Parramatta North Precinct	1	6257963.09	315366.66	-33.80241603	151.0054362	29.853	Chamaecyparis funebris	12	540	9	6.48	600	2.67	M	2	G	М	N	М	N	Н	Н
4/01/2021	1254	INF	Parramatta North Precinct	1	6257954.632	315370.876	-33.802493	151.0054799	29.651	Lophostemon confertus	10	290	6	3.48	340	2.1	M	2	G	Н	N	M	N	М	М
4/01/2021	1255	INF	Parramatta North Precinct	1	6257949.815	315372.961	-33.80253679	151.0055014	29.576	Lophostemon confertus	10	240	6	2.88	300	2	М	2	F	Н	N	М	N	М	М
4/01/2021	1259	INF	Parramatta North Precinct	1	6257944.857	315375.053	-33.80258184	151.005523	29.461	Lophostemon confertus	11	390	9	4.68	429	2.32	M	2	G	Н	N	M	N	М	М
4/01/2021	1265	INF	Parramatta North Precinct	1	6258011.527	315348.101	-33.80197619	151.0052459	30.668	Lophostemon confertus	10	310	4	3.72	350	2.13	М	2	G	Н	N	М	N	М	М
4/01/2021	1271	INF	Parramatta North Precinct	1	6257934.492	315379.018	-33.80267596	151.0055636	29.255	Lophostemon confertus	12	485	9	5.82	550	2.57	М	2	G	Н	N	M	N	М	М
4/01/2021	1272	INF	Parramatta North Precinct	1	6257929.38	315380.947	-33.80272238	151.0055834	29.163	Lophostemon confertus	11	265	8	3.18	320	2.05	М	2	G	Н	N	М	N	М	М
4/01/2021	1277	INF	Parramatta North Precinct	1	6257919.123	315385.03	-33.80281554	151.0056253	29.161	Lophostemon confertus	10	330	9	3.96	400	2.25	М	2	G	Н	N	М	N	М	М
4/01/2021	1286	INF	Parramatta North Precinct	1	6257908.22	315388.96	-33.80291451	151.0056655	28.795	Corymbia maculata	17	330	8	3.96	490	2.45	М	2	G	Н	N	М	N	Н	Н
4/01/2021	1294	INF	Parramatta North Precinct	1	6257903.316	315391.979	-33.80295924	151.005697	28.725	Corymbia maculata	19	329	11	3.948	350	2.13	M	2	G	Н	N	М	N	Н	Н
4/01/2021	1319	INF	Parramatta North Precinct	1	6257906.448	315436.936	-33.80293885	151.0061831	28.547	Syncarpia glomulifera	13	500	5	6.48	620	2.707	М	1	F	L	М	Н	N	М	М

11/01/2021	5818	INF	Rosehill and Camellia Precinct	2	6256349.375	316504.803	-33.81715986	151.0173893	5.594	Thuja occidentalis	16	1090	9	13.08	1250	3.63454	M	2	G	М	N	М	N	М	М
11/01/2021	11774	INF	Parramatta CBD Precinct	2	6256331.145	316585.028	-33.81733811	151.0182518	8.88	Morus spp	7	250	6	3	300	2.00	M	2	G	L	N	М	N	М	М
11/01/2021	11775	INF	Parramatta CBD Precinct	2	6256330.044	316589.347	-33.81734878	151.0182982	7.865	Mangifera indica	4	200	3	2.4	250	1.85	M	2	G	М	N	М	N	М	М
11/01/2021	12060	INF	Rydalmere	3	6257451.364	317813.615	-33.80745316	151.0317508		Callistemon Kings Park Special	4.5	320	3	3.84	320	2.05	M	1	Av	L	L	М	N	L	L
11/01/2021	12061	INF	Rydalmere	3	6257455.964	317809.7951	-33.80741104	151.0317105		Ficus benjamina	16	570	14	6.84	570	2.61	M	1	G	М	М	М	N	М	M
11/01/2021	12062	INF	Rydalmere	3	6257460.991	317797.095	-33.80736354	151.0315744		Citharexylum qudrangulare	14	570	9	6.84	570	2.61	M	1	Av	М	М	L	N	M	M
11/01/2021	12063	INF	Rydalmere	3	6257460.098	317788.2315	-33.80737006	151.0314786		Callistemon Kings Park Special	5	250	5	3	250	1.85	M	1	Av	L	L	М	N	L	L
11/01/2021	12064	INF	Rydalmere	3	6257464.794	317774.2085	-33.80732531	151.0313281		Callistemon Kings Park Special	4	320	4	3.48	320	2.05	M	1	Av	L	L	L	N	L	L
11/01/2021	12065	INF	Rydalmere	3	6257469.958	317759.755	-33.80727628	151.0311731		Melia azedarach	4	150	2	2	150	1.50	Υ	1	Av	L	L	L	N	L	L
5/01/2021	12066	INF	Telopea	3	6259204.568	318882.6622	-33.79183	151.04365		Olea europaea	5	354	6	4.248	350	2.20	M	1	G	L	L	L	N	L	L
17/12/2020	12172	INF	Parramatta North Precinct	θ	6258159.159	315219.4736	-33.800623	151.003888		Quercus palustris	2.5	30	0.8	2	30	1.50	¥	1	Av	f	F	F	N	F	F
4/01/2021	15017	INF	Westmead Precinct	1	6257941.359	314497.405	-33.80245974	150.9960462	12.929	Elaeocarpus reticulatus	7	175	3	2.1	200	1.68	M	1	G	М	N	М	N	М	M
4/01/2021	15018	INF	Westmead Precinct	1	6257947.191	314496.309	-33.80240698	150.9960356	12.948	Elaeocarpus reticulatus	7	150	2	2	200	1.68	M	1	G	М	N	М	N	М	M
4/01/2021	15019	INF	Westmead Precinct	1	6257943.791	314497.704	-33.80243787	150.9960499	13.158	Elaeocarpus reticulatus	7	155	2	2	200	1.68	M	1	G	М	N	М	N	М	М
4/01/2021	15020	INF	Westmead Precinct	1	6257949.464	314495.443	-33.80238634	150.9960267	13.427	Elaeocarpus reticulatus	10	185	2	2.22	200	1.68	M	1	G	М	N	М	N	М	М

visual assessment		E04(f) Impact			Offset	comp	ensatory veg	etation			
E104(d)			E104(f)			E104(g)	E	E104(h)	E105(a)	E104(e) E105(b)	E104(e) E105(b)
Outcome (visual assessment)	Reason impact required	% Development Impact / Encroachment	Development Impact	If pruning req. (maintenance)	Removal (Required offsetting ratio)	management, protection, & monitoring	Responsibility	Timing (implementation)	Operational Requirements	Health / Vigour	Ability to survive insitu pruning / transplanting
Retain	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 5 x 40mm and multiple 10-15mm roots removed 16% encroachment was measured and tree should be sustainably retained subject to future	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 16%. 17/04/2020 IA update, PA comment: 100%.	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 5 x 40mm and multiple 10-15mm roots removed 16% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be	N/A	N/A	N/A	INF	N/A	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 5 x 40mm and multiple 10-15mm roots removed 16%	Good	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - No / No.
Retain	works report of 2 January 2021: 1 x 50mm 18% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments.	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 18%. 17/04/2020 IA update, PA comments: 100%.	o4/01/2021 A update, PA comments from NDD foot mapping works report of 2 January 2021: 1 x 50mm 18% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments.	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: 1 x 50mm 18%	Good	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - No / No.
Retain	works report of 2 January 2021: 6 x 10-15mm roots removed 1 x 40mm root retained. 16% encroachment was measured and tree should be sustainably retained subject to future	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 16%. 17/04/2020 IA update, PA comments: 100%.	104/01/2021 TA Update, PA comments from NDD foot mapping works report of 2 January 2021: 6 x 10-15mm roots removed 1 x 40mm root retained. 16% encroachment was measured and tree should be sustainably retained subject to future assessment of additional engragements. Tree	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: 6 x 10-15mm roots	Good	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - No / No.
Retain	u4/01/25 hould be sustainably retained survivor foot mapping works report of 2 January 2021: 1 x 40mm root pruned 11% encroachment was measured and tree should be sustainably retained subject to future assessment of additional	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 11%. 17/04/2020 IA update, PA comments: 100%.	104/01/2021 IA Update, PA comments from NDD foot mapping works report of 2 January 2021: 1 x 40mm root pruned 11% encroachment was measured and tree should be sustainably retained subject to future assessment of additional engranchments. Tree to be retained, 17/04/2020	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: 1 x 40mm root pruned	Fair	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - No / No.
Remove	works report of January 2021: 7 x 20mm roots removed. 25% encroachment was measured. This level of encroachment is not sustainable. Tree 1229 is recommended for removal due to	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 25%. 17/04/2020 IA update, PA comments: 100%.	04/01/2021 A update, PA comments from NDD foot mapping works report of 2 January 2021: 7 x 20mm roots removed. 25% encroachment was measured. This level of encroachment is not sustainable. Tree 1229 is recommended for removal due to the extent of root loss required to enable	N/A	4	N/A	INF	N/A	encroached by excavation for stormwater pipes and new footpath. Amendments to the design of	Good	age, health and vigour are such that this tree is unable to survive insitu butress damage and severing of structural roots 17/04/2020 IA undate No / No.
Retain	works report of 2 January 2021: No roots found 12% encroachment was measured and tree should be sustainably retained subject to future assessment of additional	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 12%. 17/04/2020 IA update, PA comments: 100%.	104/01/2021 A Update, PA comments from NDD foot mapping works report of 2 January 2021: No roots found 12% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained 17/04/2020 IA update PA	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: No roots found 12%	Good	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - No / No.
Retain	04/01/2021 TA update, PA comments from NDD foot mapping works report of 2 January 2021: 1 x 80mm, 1 x 60mm and multiple minus 10mm roots were removed. 18% encroachment was measured and tree should be sustainably retained subject.	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 18%. 17/04/2020 IA update, PA comments: 100%.	104/01/2/21 TA Update, PA comments from NDD foot mapping works report of 2 January 2021: 1 x 80mm, 1 x 60mm and multiple minus 10mm roots were removed. 18% encroachment was measured and tree should be sustainably retained subject to future assessment of additional	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: 1 x 80mm, 1 x 60mm	Good	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - No / No.
Remove	works report of 2 January 2021: 3 x 10mm, 1 x 20mm, 1 x 30mm, 2 x 50mm, 1 x 70mm and numerous 10-15mm roots	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 30%. 17/04/2020 IA update, PA comments: 100%.	report of 2 January 2021: 8 x 10 mm, 1 x 20mm, 1 x 30mm, 2 x 50mm, 1 x 70mm and numerous 10-15mm roots removed, 30% encroachment was measured and tree should be removed as his level of encroachment is	N/A	4	N/A	INF	N/A	Tree SRZ encroached by excavation for stormwater pipes and pits, amendments of operational requirements will not	Good	size, age, health and vigour are such that this tree is unable to survive in situ butress damage and severing of structural roots 17/04/2020 (A undate - No / No
Retain	works report of 2 January 2021: 4% encroachment was measured and tree should be sustainably retained subject to assessment of additional engracements. No root investigation	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 4%. 17/04/2020 IA update, PA comments: 100%.	104/01/2021 A Update: PA comments from NDID foot mapping works report of 2 January 2021: 4% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA.	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: 4% encroachment was	Good	17/04/2021 IA update, NA, tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications. Totally encreached by paying and level
Retain	works report of 2 January 2021: 0% encroachment was measured and tree should be sustainably retained subject to assessment of additional engraphments. No root investigation	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 0%. 17/04/2020 IA update, PA comments: 100%.	104/01/2021 TA Update, PA comments from NDD foot mapping works report of 2 January 2021: 0% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA.	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: 0% encroachment was	Good	17/04/2021 IA update, NA, tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications. Totally encreached by paying and level
Retain	works report of 2 January 2021: 9% encroachment was measured and tree should be sustainably retained subject to assessment of additional engracements. No root investigation	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 9%. 17/04/2020 IA update, PA comments: 100%.	No. not investigation was undertaken Tree to be retained 17/04/2020 A 04/07/2021 9% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments. No not investigation was undertaken Tree to be retained 17/04/2020 A	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: 9% encroachment was	Good	17/04/2021 IA Update, N/A, tree to be retained: 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design
Retain	3540512021 ft additional encoachments in No. 100 to investigating works report of 2 January 2021: 2 x 10-15mm roots pruned. 12% encroachment was measured and tree should be sustainably retained subject to future assessment of additional.	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 12%. 17/04/2020 IA update, PA comments: 100%.	No. 1704 December 2011 1 August 1997 No. 1704 December 2011 1 August 1997 No. 1704 December 2011 2 x 10-15mm roots pruned. 12% encroachment was measured and tree should be sustainably retained subject to future assessment of additional engranchments. Tree to be retained. 17/04/2016	N/A	N/A	N/A	INF	N/A	04/07/252/rA apd tree PA clid linems from NDD root mapping works report of 2 January 2021: 2 x 10-15mm roots 04/07/202174 update: PA continents	Good	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - No / No.
Retain	Sustainably relatined subject to future assessment of additional U4/01/2021 IA update, PA comments from NDD Tool drapping works report of 2 January 2021: No roots found 12% encroachment was measured and tree should be sustainably relatined subject to future assessment of additional	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 12%. 17/04/2020 IA update, PA comments: 100%.	assessment of additional encroachments. Tree to be retained 1.7/04/2021 (4.00) and the comments from NVD foot mapping works report of 2 January 2021: No roots found 12% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained 1.7/04/2020 (A. undate P.A.	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: No roots found 12%	Good	17/04/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications. Totally encroached by paying and level
Retain	บ4/บาร2ปราการ มู่บ่อสะ 1 ค.ส. ประการกระทางการ ค.ส. ประการ works report of 2 January 2021: No roots found 12% encroachment was measured and tree should be sustainably บ4/บาร2ปราการ มู่บ่อสะ 1 ค.ส.ประการทางการครับทางการ	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 0%. 17/04/2020 IA update, PA comments: 100%.	odditional charachers to the retained 1701 M2020 IA works report of 2 January 2021: No roots found 12% encroachment was measured and tree should be sustainably retained subject to future assessment of odditional report of the retained subject to future assessment of odditional report of the retained subject to future assessment of odditional report of the retained subject to future assessment of odditional report of the retained subject to future assessment of odditional report of the retained subject to future assessment of odditional report of the retained subject to future assessment of odditional report of the retained subject to future assessment of odditional retained subject to	N/A	N/A	N/A	INF	N/A	04/07/2020 TA upone, 24/20 and free of 04/07/2020 TA upone, 24/20 and free of 04/2020 TA upone, 24/2020 TA upone, 24/202	Good	modifications. The allocater, N/A, free to be retained and 17/04/2020 TA alphater, PA comments: Viability dependent on further root investigation and design modifications. Totally described by the alphater. N/A, and by the alphater and the sign modifications. Totally described by the alphater.
Retain	works report of 2 January 2021: 5% encroachment was measured and tree should be sustainably retained subject to assessment of additional engraphments. No root investigation	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 5%. 17/04/2020 IA update, PA comments: 100%.	of 2 January 2021: 5% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments. O40012UzY18'lipdiale, YPA contentains from Nob real mapping Works' 2020.	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: 5% encroachment was	Good	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications. Totally engage, N/A, tree to be retained.
Retain	works report of 2 January 2021: Feeder roots only found 3- 5mm 1% encroachment was measured and tree should be	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 1%. 17/04/2020 IA update, PA comments: 100%.	104/01/2021 TA Update, PA comments from NDD foot mapping works report of 2 January 2021: Feeder roots only found 3-5mm 1% encroachment was measured and tree should be sustainably retained subject to assessment u4/01/2021 A update, PA comments from NDD foot mapping Works feborates.	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: Feeder roots only	Good	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications. That update; N/A, ride by or being and level
Retain	works report of 2 January 2021: 1% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 1%. 17/04/2020 IA update, PA comments: 40%.	104/01/2021 TA update, PA comments from NDD foot mapping works report of 2 January 2021: 1% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments. 040/012/j2Y18/inpliate, YPA contributes in Time ND by set already in 17/04/2020 (Walks) 2006.	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: 1% encroachment was	Good	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design
Retain	works report of 2 January 2021: With the exception of tree 1319 the root investigations were undertaken through the existing	04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 9%. High impact (>20%)	of 2 January 2021: With the exception of tree 1319 the root investigations were undertaken through the existing pavement which was comprised of a 50mm enoxy bonded aggregate (5,7mm pea gravel) surface over a 75mm	N/A	N/A	N/A	INF	N/A	from NDD root mapping works report of 2 January 2021: With the exception of tree 1319 the root investigations were	Fair	04/01/2021 IA update, N/A, tree to be retained.

Retain	m from a proposed streetlight pole & underground services to north and 1.8 m from anticipated excavation works for	IA update, PA comments: 20.6%. 21/09/2020 IA update, PA comment: 30%. 13/08/2020 IA update, PA comment: 26.2%. 12/05/2020 IA update, PA	proposed streetlight pole & underground services to north and 1.8 m from anticipated excavation works for underground services to be installed from	N/A	N/A	N/A	INF	N/A	Tree 5818 is located 4.9 m from a proposed streetlight pole & Good	retained. 21/09/2020 IA update, No / No. 13/08/2020 IA update, no change since 12/05/2020. 12/05/2020
	117/01/2021 1A Options, the constalled area area area and axistican	comment: 0%	the nnonteness to constitute and						11/01/2021 A update, PA comment:	11/01/2021 IA update, PA comment:Mature tree not
Remove	to excavation 0.6 m deep excavation works for construcion of a footpath to the north of the trees along the property boundary,	11/01/2021 IA update, PA comment: 45.3%. 21/09/2020 IA update, PA comment: 100%. 100%	excavation 0.6 m deep excavation works for construcion of a footpath to the north of the trees along the property boundary, providing a major (45.3%) cut encroschment into the TP7 and encroschment into the SP7.	N/A	N/A	N/A	INF	N/A	Operational requirements are not sufficient to retain tree largely	suitable to be transplanted. 22/09/2020 IA update: No / No.
Remove	to excavation 0.6 m deep excavation works for construcion of a footpath to the north of the trees along the property boundary, providing a major (43.6%) cut encroschment into the TPZ and	11/01/2021 IA update, PA comment: 43.6%. 21/09/2020 IA update, PA comment: 100%.	excavation 0.6 m deep excavation works for construcion of a footpath to the north of the trees along the property boundary, providing a major (43.6%) cut encroachment into the TPZ and encroachment into the SPZ	N/A	N/A	N/A	INF	N/A	Located directly adjacent to excavation 0.6 m deep excavation works for construction of a footpath to the porth of	11/01/2021 IA update, N/A, tree to be retained. 22/09/2020 IA update, No / No.
Retain	located 700 mm from anticipated cut 50 mm outside of Bok (back of kerb). Drawing shows 0.34 m from near edge of pipe.	11/01/2020 IA update, PA comment: major encroachment.	from anticipated cut 50 mm outside of BoK (back of kerb). Drawing shows 0.34 m from near edge of pipe. Major encroachment within TPZ and	N/A	N/A	N/A	INF	N/A	CoT (centre of trunk) located 700 mm from anticipated cut 50 mm outside of	11/01/2020 IA update, PA comment: N/A, tree to be retained.
Retain	3.41m from near edge of pipe. Major encroachment within TPZ. Ground protection under machinery track path. Located in No.	11/01/2020 IA update, PA comment: major encroachment.	encroachment within SRZ Batain Tunk Protection Cround protection in 1701/2020 TA update, PA comment: Urawing shows Coff 3.41 m from heal edge of pipe. Major encroachment within TPZ. Ground protection under machinery track path. Located in No. 3, 300 mm from front boundary. Exposed lateral roots in road resease. Coff located 4.1 m from Back of	N/A	N/A	N/A	INF	N/A	Prior (1/2001) Proving shows The first of th	11/01/2020 IA update, PA comment: N/A, tree to be retained.
Retain	1.7012 by frau front houndary Expressed lateral roots in 12.1d m from near edge of pipe. Major encroachment within TPZ. 11.9% encroachment assuming 4.13 m offset to excavation.	11/01/2020 IA update, PA comment: 11.9%	near edge of pipe. Major encroachment within TPZ. 11.9% encroachment assuming 4.13 m offset to excavation. Ground protection under machinery	N/A	N/A	N/A	INF	N/A	17/01/2020 IA update, PA comment: Drawing shows CoT 4.13 m from near edge of pipe. Major encroachment within TP7 11.9% encroachment	11/01/2020 IA update, PA comment: N/A, tree to be retained.
Retain	From Puzzote Lippaure Parachiment: Drawnity Showsted in Mas m from near edge of pipe. Major encroachment within TPZ and encroachment within SRZ. Retain. Trunk Protection. Ground	11/01/2020 IA update, PA comment: Major encroachment.	Track 2020 IA Optical in About 18 Comment within TPZ and encroachment within SRZ. Retain. Trunk Protection. Ground protection under machinery track path. All excayation under Project Arborist directions supervision. In	N/A	N/A	N/A	INF	N/A	Drawing shows CoT 0.48 m from near edge of pipe. Major encroachment within TDZ and expressionate within	11/01/2020 IA update, PA comment: N/A, tree to be retained.
Retain	m from near edge of pipe. Major encroachment within TPZ and encroachment within SRZ. Retain. Trunk Protection. Ground	11/01/2020 IA update, PA comment: Major encroachment.	near edge of pipe. Major encroachment within TPZ and encroachment within SRZ. Retain. Trunk Protection. Ground protection under machinery	N/A	N/A	N/A	INF	N/A	Drawing shows CoT 0.40 m from near edge of pipe. Major encroachment	11/01/2020 IA update, PA comment: N/A, tree to be retained.
Retain	m from near edge of pipe. Major encroachment within TPZ. Retain. Trunk Protection. Ground protection under machinery	11/01/2020 IA update, PA comment: Major encroachment.	11/01/2020 IA Update, PA comment: Urawing shows CoT 1.57 m Irom near edge of pipe. Major encroachment within TPZ. Retain. Trunk Protection. Ground protection under machinery track. In road reserve. CoT	N/A	N/A	N/A	INF	N/A	Drawing shows CoT 1.57 m from near edge of pipe. Major encroachment	11/01/2020 IA update, PA comment: N/A, tree to be retained.
Retain	us/or/ztr2/k update, PA comments. Located 3.7km/ from the proposed across-road trenching for UG power providing a minor (1.7%) cut encroachment into the TPZ. Low and sustainable impact. In private property 85 Adderton Road, west	05/01/2021 IA update, PA comments: 1.7%.	across-road trenching for UG power providing a minor (1.7%) cut encroachment into the TPZ. Low and sustainable impact. In private property 85 Added to Poad, west of existing front boundary masonary.	N/A	N/A	N/A	INF	N/A	ustbin 127 Ratio Truck Potentins: Usbin 207 Ratio Truck Profession Located 3.7Mm from the proposed across-road trenching for UG power providing a mipor (1.7%) cut	05/01/2021 IA update, N/A, tree to be retained.
Remove	of excavation for proposed drainage and electrical services and pit inside the property. To be removed. Recent planting <3 m				N/A					
Retain	4/12/2020 IA update, PA comment: Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain. Patain	4/12/2020 IA update, PA comment: 100%. 17/04/2020 IA update, PA comment: 0%.	4/12/2020 IA update, PA comment: Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain Retain.	N/A	4	N/A	INF	N/A	4/12/2020 IA update, PA comment: Stormwater insfrastructure cannot be modified due to proposed sewer	4/12/20/20 IA update, PA comment: Matrue tree cannot be transplanted. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain
Retain	4/12/2020 IA update, PA comment: Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain. Petain	4/12/2020 IA update, PA comment: 100%. 17/04/2020 IA update, PA comment: 0%.	4/12/2020 IA update, PA comment: Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain Retain.	N/A	4	N/A	INF	N/A	4/12/2020 TA Update, PA Comment: Stormwater insfrastructure cannot be modified due to proposed sewer 4/12/2020 TA Update, PA 20 dillielli:	4/12/20/20 IA update; PA comment: Matrue tree cannot be transplanted. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain
Retain	4/12/2020 IA update, PA confinerii: Tree located within excavation works for stormrap units. Tree to be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain. Retain	4/12/2020 IA update, PA comment: 100%. 17/04/2020 IA update, PA comment: 0%.	4/12/2020 IA update, PA comment: Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain Retain.	N/A	4	N/A	INF	N/A	4712720201A Update, PA Confident. Stormwater insfrastructure cannot be modified due to proposed sewer 4712720201A update, PA confident.	4/12/2020 IA update, PA Comment: Matrue tree cannot be transplanted. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain
Retain	4/12/20/20 IA update, PA comment: Tree located within proposed access ramp and demolition works of existing garden bed. Tree to be removed. 17/04/2020 IA update, PA comment:	4/12/2020 IA update, PA comment: 100%. 17/04/2020 IA update, PA comment: 0%.	4/12/2020 IA update, PA comment: Tree located within proposed access ramp and demolition works of existing garden bed. Tree to be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain	N/A	4	N/A	INF	N/A	4/12/2020 IA update, PA comment: Vehicular access required north of the tanks. Tree located within proposed access ramp and demolition works of	4/12/20/20 IA update, PA comment: Mature tree cannot be transplanted. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain

							Determination	ns + comments
Consent Conditions E105							IA	
E105(c)	E105(d)	E105(e)	E105(f)	E105(g)				
Review of construction methodology to minimise impacts to trees	Consideration of footprints	Modification of Design possible	Reduction in Standard Offsets for underground services	Tree sensitive techniques or alternatives to retain tree	Trees Within Project Boundary?	Action	Comments	Outcome / Action
04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Trees on adjacent property substantially encroached by footpath and realigned kerb, Root mapping required.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able	N	Uncertain	04/01/2021 IA update, from PA comments from NDD root mapping works report of 2 January 2021: 5 x 40mm and multiple 10-15mr roots removed 16% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comment: Encroachment by pathway. Viability dependent on paving depth and type with root mapping required. Viability to be determined Uncertain.	THICEHAIN
17/04/2020 IA update, N/A, tree to be retained. 17/04/2020 IA update, PA comments. Trees along St Patrick's Cemetery totally impacted by footbath and relocated korts. Footbath material.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	update, N/A, tree to be retained.	be retained.	N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Encroachment by pathway. Viability dependent on paving depth and typ with root mapping required Viability to be determined Uncertain.	Uncertain
04/01/2021 IA update, NIA, tree to be retained. 17/04/2020 IA update, PA comments: Trees along St Patrick's Cemetery totally impacted by feetnath and relocated korts. Ecotoath material.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	4/01/2/21 IA update, from PA comments from NDD foot mapping works report of 2 January 2/021: 6 x 10-15mm foots removed 1 40mm root retained. 16% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Encroachment by pathway. Viability dependent on paying doubt and type with root mapping required Viability to be determined. Upgettain	Uncertain
04/01/2021 IA Update, N/A, tree to be retained. 17/04/2020 IA update, PA comments: Trees along St Patrick's Cemetery totally impacted by footnath and relocated kerbs. Footnath material	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 TA update, N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	04/01/2021 A Update, from PA comments from NDD foot mapping works report or 2 January 2021: TX 40mm foot pruned T1% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications.	17/04/2020 IA update Uncertain.
Underboring of the stormwater was assessed to determine whether this would avoid or minimise impacts to the tree. However, due to extent of	04/01/2021 IA update, PA comments: The footpath was narrowed from 2.5m to 1.5m to avoid impact to a number of additional trees at this location. Further narrowing or relocation of the footpath would introduce material safety risks	17/04/2021 1A update, PA comments:	04/01/2021 IA update, PA comments: N/A.	PA comments: N/A. 17/04/2020 IA update -	Υ	Remove	the heritage boundary, but due to multiple encroachments and their cummulative adverse impacts from root loss will not be viable o stable and is unsuitable to be retained with no sufficient alternatives available to the required works in this location. Comments from PA-from NDD root mapping works report of 2 January 2021: 7 x 20mm roots removed, 25% encroachment was measured. This leve	Remove
07/01/20/21 TA Update, N/A, Tree! 16 Be Yelaihed. 17/04/2020 IA update, PA comments: Trees along St Patrick's Cemetery totally impacted by	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications.	17/04/2020 IA update Uncertain.
17/04/2020 IA update, N/A, ree to be retained. 17/04/2020 IA update, PA comments: Trees along St Patrick's Cemetery totally impacted by	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	04/01/2021 1A update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 TX Update, N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	04/01/2021 TA update, Irom PA comments from NoD root mapping works report of 2 January 2021: TX 80mm, TX 60mm and multiple minus 10mm roots were removed. 18% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on	Uncertain
comments:Underbor,ing of the stormwater was assessed to determine whether this would avoid	04/01/2021 A update, PA comments: The tootpain was narrowed from 2.5m to 1.5m to avoid impact to a number of additional trees at this location. Further narrowing or coloration of the featable would introduce material safety risks	update, PA comments: An	04/01/2021 IA update, PA comments: N/A	PA comments: N/A. 17/04/2020 IA update -	Υ	Remove	the heritage boundary, but due to multiple encroachments and their cummulative adverse impacts from root loss will not be viable o stable and is unsuitable to be retained with no sufficient alternatives available to the required works in this location. Comments from PA-from NDD root manning works report of 2. January 2021; 3 v 10 mm, 1 v 20mm, 1 v 30mm, 2 v 50mm, 1 v 70mm, and purpersus	Remove
04/01/2021 IA Update, N/A, tree to be retained. 17/04/2020 IA update - Trees on adjacent property substantially encroached by footpath	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	update, N/A, tree to be retained.	04/01/2021 IA	N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design	Uncertain
17/04/2021 IA update, N/A, free to be retained. 17/04/2020 IA update - Trees on adjacent property substantially encroached by footpath	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	be retained.	04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 TA update, N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design	Uncertain
u4rd realigned keek. Prof. magneing seguired. 17/04/2020 IA update - Trees on adjacent property substantially encroached by footpath and realigned kerk. Prof. magning required.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 TA update, N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	U4/U1/2U2TIA Update, from PA comments from NUD root happing works report of 2 Jahuary 2021: 9% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments Viability dependent on further root investigation and design modifications. Totally encroached by paying and level change. Viability to be determined. Uncertain	Uncertain
und realized both. Root manning required. 17/04/2020 IA update, PA comments: Trees along St Patrick's Cemetery totally impacted by footpath and relocated kerbs. Footpath material.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	V4/0 1/2027 1X bpable, N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	u4/01/2021 TA update; from Fatally encorated by naving and level change Viability In the determined Lincortain encorated and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications. Totally encorached by readway. Viability to be determined. Lincortain, ent by pathway.	Uncertain
fortnath and relocated kerbs. Footnath material 04/01/2021 A Update, N/A, tree to be retained. 17/04/2020 IA update - Trees on adjacent property substantially encroached by footpath and realigned kerb. Poot mapping required.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	04/01/2021 IA update, recreased the market with his datermined. Unrefained and by 2021 way encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications.	Uncertain
17/04/2021 IA update, N/A, free to be retained. 17/04/2020 IA update - Trees on adjacent property substantially encroached by footpath	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	04/01/2021 1A update, N/A, tree to be retained. 17/04/2020 IA	04/01/2021 IA	04/01/2021 TA update, N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications.	Uncertain
u4701/2021 The Update, Find, tree to be retained. 17/04/2020 IA update - Trees on adjacent properly substantially encroached by footpath and realigned tests. Post manping required.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	04/01/2021 IA	04/01/2021 IA update, N/A, tree to be retained.	N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	U4/01/2021 IA update, Inchreae both the savion and level chappen Viability to be determined y Lincertain measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments Viability dependent on further root investigation and design modifications. Totally encroached by paying and level change. Viability to be determined. Uncertain	Uncertain
04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Trees on adjacent property substantially encroached by footpath and realizated for Poot mapping required.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	04/01/2021 1A update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	104/01/2021 IA Update, from PA comments from NDD foot mapping works report of 2 January 2021: Feeder roots only round 3-5mm 1% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications.	Uncertain
u4/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Trees on adjacent property substantially encroached by footpath and realigned kerb. Poot mapping required.	04/01/2021 IA update, N/A, tree to be retained. 17/04/2020 IA update - Yes, tree may be able to be retained after review.	04/01/2021 IA	04/01/2021 IA update, N/A, tree to be retained.	N/A, tree to be retained. 17/04/2020 IA update -	N	Uncertain	U4/U1/2/22 IA update, from PA comments from NDD foot mapping works report of 2 January 2/221: 1% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design modifications. Totally encroached by paying and level change. Viability to be determined. Uncertain	Uncertain
04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	04/01/2021 IA update, N/A, tree to be retained.	N	Retain	U4/01/2021 TA DD0316, 31/01 PA CONTINENTS 160 N N D 07 1001 1 13 15 15 15 15 15 15 15 15 15 15 15 15 15	Retain

1 1/0 1/2021 TA update, N/A tree to be retained.	TT/UT/2U2T IA update, N/A tree to be retained. 21/09/2U2U IA	11/01/2021 IA	11/01/2021 IA	11/01/2021 IA update,		1	11/01/2021 IA update, PA comments: Tree 5818 is located 4.9 m from a proposed streetlight pole & underground services to nortr	
21/09/2020 IA update, PA comment: Due to	update, PA comment: Due to extent of encroachment by			V/A tree to be retained.			and 1.8 m from anticipated excavation works for underground services to be installed from the pole to existing services to southeast	
extent of encroachment, alternative construction	installation of shoring boxes, 13/08/2020 IA update, impact of			21/09/2020 IA update.	N	Retain, pr, cr, rt	providing a combined major (20.6%) cut encroachment into the TPZ, encroachment into the SRZ. Crown encroachment is	Retain pr, cr, rt
mothodologies will not suffice to retain tree	ancroachment to be accessed by Project Arborist	21/00/2020 IA 2	21/00/2020 IA	PA comment: Ancillary			anticipated. Within project houndary. Streetlight note must not be located closer than 4.0 m porth of the trunk, i.e. 0.5 m further north	
11/01/2021 IA update, PA comment: Alternative	11/01/2021 IA update, PA comment:Narrowing / moving			PA comment: N/A.			11/01/2021 IA update, and comment: Tree impact Assessment (TIA), TIA – In 11774 & 11775, Figure 2 (page 2/6) shows the	
construction methodology or layout will not lead to retention of tree due to shallow strutural roots	footpaths will not lead to retention of tree due to extent of impact. 22/09/2020 IA update, PA comment: Narrowing /		update, PA nment:Reduction	22/09/2020 IA update,	N	Uncertain	exposed roots painted blue and most structural roots denoted with a red pen, delaminated on their upper sides impacting up to 50% circumference longitudinally and close to the base of the trunk within the Structural Root Zone. This inflicted by the supposedly non-	Remove
required to be pruped for construcion of footnath	moving footpaths will not lead to retention of tree due to		utility offects will	DA comment: Fencing			districtive diaging (NDD) using a water knide and vacuum truck. The pressue of the water knife is expected to have bee applied to	
11/01/2021 IA update, N/A, tree to be retained.	11/01/2021 TA update, N/A, tree to be retained. 22/09/2020 IA		11/01/2021 IA	11/01/2021 IA update,			11/01/2021 IA update, from PA comment: Located directly adjacent to excavation 0.6 m deep excavation works for construction of a	
22/09/2020 IA update, PA comment: Alternative	update, PA comment: Narrowing / moving footpaths will not			V/A, tree to be retained.	N	Retain, pr, cr, rt	footpath to the north of the trees along the property boundary, providing a major (43.6%) cut encroachment into the TPZ and	Retain
construction methodology or layout will not lead	lead to retention of tree due to extent of impact and location of		be retained. :	22/09/2020 IA update,			encroachment into the SRZ. Crown encroachment is anticipated. While this is a major encroachment, it will provide a sustainable	
	II DAII NAMWAY	11/04/2020 IA 1	11/01/2020 IA	11/01/2020 IA update,			Timpact to the tree as, less pats than expected where found during NDD works. Tree located on crivate infronctive To be retained o	
11/01/2020 IA update, PA comment: N/A, tree to	11/01/2020 IA update, PA comment: N/A, tree to be retained.		update, PA	PA comment: N/A, tree	γ	Retain	kerb). Drawing shows 0.34 m from near edge of pipe. Major encroachment within TPZ and encroachment within SRZ. Retain. Trunk	Retain
be retained.			nment: IV/A, tree	to be retained.		rtotairi	Protection. Ground protection under machinery track path. All excavation under Project Arborist direction/ supervision. In road	rotair
		to be retained to	to be retained	11/01/2020 IA update,			reserve. FOR at base spanned. Centre of Trunk (CoT) 700 mm from anticinated excavation. Crown skew to W 11/01/2020 IA update, from PA comment: Drawing shows CoT 3.41m from near edge of pipe. Major encroachment within TPZ.	
11/01/2020 IA update, PA comment: N/A, tree to	11/01/2020 IA update, PA comment: N/A, tree to be retained.	update, PA	lindate PA	PA comment: N/A, tree	N	Retain	Ground protection under machinery track path. Located in No. 3, 300 mm from front boundary. Exposed lateral roots in road reserve	Retain
be retained.	1 1/01/2020 IA apaate, FA confinent. N/A, tree to be retained.	comment: N/A, tree com	mment: N/A, tree	to be retained.	IN	Retaili	CoT located 4.1 m from Back of Kerb (BoK).	Retaili
		to be retained to	10.1/01/20201A					
11/01/2020 IA update, PA comment: N/A, tree to	44/04/000014		undate PA	11/01/2020 IA update,	N.	Dotoin	11/01/2020 IA update, from PA comment: Drawing shows CoT 4.13 m from near edge of pipe. Major encroachment within TPZ.	Datain
be retained.	11/01/2020 IA update, PA comment: N/A, tree to be retained.	comment: N/A, tree com	mment: N/A, tree	PA comment: N/A, tree	N	Retain	11.9% encroachment assuming 4.13 m offset to excavation. Ground protection under machinery track path. Located in No. 3. CoT	Retain
			n he retained	to be retained.			located 4.6 m from back of Kerb.	
11/01/2020 IA update, PA comment: N/A, tree to			undate PA	11/01/2020 IA update,			11/01/2020 IA update, from PA comment: Drawing shows CoT 0.48 m from near edge of pipe. Major encroachment within TPZ and	
be retained.	11/01/2020 IA update, PA comment: N/A, tree to be retained.		mment: N/A, tree	PA comment: N/A, tree	Υ	Retain	encroachment within SRZ. Retain. Trunk Protection. Ground protection under machinery track path. All excavation under Project	Retain
Do Totalliou.		to be retained to	to be retained	to be retained.			Arborist direction/ supervision. In road reserve. Lean to S. 1.4 m E of Power Pole. 0.7 m to (BoK).	
11/01/2020 IA update, PA comment: N/A, tree to			update, PA	11/01/2020 IA update,			encroachment within SRZ. Retain. Trunk Protection. Ground protection under machinery track path. All excavation under Project	
be retained.	11/01/2020 IA update, PA comment: N/A, tree to be retained.	•	mment: N/A, tree	PA comment: N/A, tree	Υ	Retain	Arborist direction/ supervision. Crown tied back where machine cannot avoid crown. In road reserve. Branches/ crown over	Retain
be retained.		to be retained to	to be retained	to be retained.			carriagemay. CaT is 0.85 m from RoV	
11/01/2020 IAd-t- DA			11/01/2020 IA	11/01/2020 IA update,			11/01/0000 IA	
11/01/2020 IA update, PA comment: N/A, tree to	11/01/2020 IA update, PA comment: N/A, tree to be retained.		update, PA	PA comment: N/A, tree	Υ	Retain	11/01/2020 IA update, from PA comment: Drawing shows CoT 1.57 m from near edge of pipe. Major encroachment within TPZ.	Retain
be retained.			mment: N/A, tree	to be retained.			Retain. Trunk Protection. Ground protection under machinery track. In road reserve. CoT is 0.88 m from BoK.	
			05/01/2021 IA				US/U1/2021 TA update, from PA comments: Located 3.7 m from the proposed across-road trenching for UG power providing a minor	
05/01/2021 IA update, N/A, tree to be retained.	05/01/2021 IA update, N/A, tree to be retained.		date N/A tree to	05/01/2021 IA update,	N	Retain	(1.7%) cut encroachment into the TPZ. Low and sustainable impact. In private property 85 Adderton Road, west of existing front	Retain
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			be retained.	V/A, tree to be retained.			boundary masonry fence. Anticipated deflection of roots at wall. Tree to be retained. Retain and protect tree. Restrict machinery	
							hucket movements within crown spread as her TMIPHYA	
					¥	N/A	17/12/2020 IA update, tree located within area of excavation for proposed drainage and electrical services and pit inside the	Remove
					•	14// (property. To be removed. Recent planting <3 m high and is a shrub per definitions in AS4373(2007) and AS4970(2009).	Kemove
4/12/2020 IA update, PA comment: Excavation		4/12/2020 IA update, 4/12/	zrzozo ia update,	4/12/2020 IA update,			4/12/2020 IA undata. Translacated within averagation works for starmtran units. Translation to promoved 47/04/2020 IA undata. DA	
works are required for the installation of tanks	4/12/2020 IA update, PA comment: N/A. 17/04/2020 IA	PA comment: PA c	comment: Due to	PA comment: N/A.	Υ	Remove	4/12/2020 IA update, Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain Retain Field assessment 30/4/2019. Acaulescent, crown comprised of 3 first	Remove
below ground. 17/04/2020 IA update, PA	update, PA comment: No encroachment. Viable to retain.	Consideration was	extent of	17/04/2020 IA update,	•	Kemove	order structural branches (FOSB). Remove.	Kelliove
4/12/2020 IA update, PA comment: Excavation		4/12/2020 TA Update, 4/12/	272020 IA update,	4/12/2020 TA update,				
works are required for the installation of tanks	4/12/2020 IA update, PA comment: N/A. 17/04/2020 IA	· ·	comment: Due to	PA comment: N/A.	\/	Domovo	4/12/2020 IA update, Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020 IA update, PA	Domovo
below ground. 17/04/2020 IA update, PA	update, PA comment: No encroachment. Viable to retain.	Consideration was	extent of	17/04/2020 IA update,	Y	Remove	comment: No encroachment. Viable to retain Retain Field assessment 30/4/2019. Acaulescent, crown comprised of 3 first	Remove
comment: No encreachment Viable to retain 4/12/2020 IA update, PA comment: Excavation		given to modify the 4/12/2020 TA update, 4/12/	encroachment 2/2020 IA update,	PA comment: No. 4/12/2020 TA update,			order structural branches (FOSB). Remove.	
works are required for ehe installation of tanks	4/12/2020 IA update, PA comment: N/A. 17/04/2020 IA	· ·	comment: Due to	PA comment: N/A.		_	4/12/2020 IA update, Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020 IA update, PA	
below ground. 17/04/2020 IA update, PA	update, PA comment: No encroachment. Viable to retain.	Consideration was		17/04/2020 IA update,	Υ	Remove	comment: No encroachment. Viable to retain Retain Field assessment 30/4/2019. Acaulescent, crown comprised of 3 first	Remove
comment: No encreachment. Viable to retain 4/12/2020 IA update, PA comment: Excavation	Table to retain	given to modify the	encroachment	DA comment: No			order structural branches (FOSB). Remove.	
works are required for construcion of access	4/12/2020 IA update, PA comment: N/A. 17/04/2020 IA	' '	comment: Due to	4/12/2020 IA update, PA comment:			4/12/2020 IA update, PA comment: Tree located within proposed access ramp and demolition works of existing garden bed. Tree to	
ramp. 17/04/2020 IA update, PA comment: No	update, PA comment: No encroachment. Viable to retain.	Consideration was	extent of	Consideration was	Υ	Remove	be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain Retain Field assessment 30/4/2019.	Remove
ramp. 17/04/2020 IA upuate, FA comment. No	apadic, i A comment. No encroaciment, viable to retain.	Consideration was	CALCITE OF	Consideration was			Acaulescent, crown comprised of 3 first order structural branches (FOSB). Remove.	

			AGREEMENT			Current Status	
INFRA	(contract with largest impact noted here)	pr = prune cr = crown rt = root					
Contractor	PA Assessment (Contractor)	IA Assessment	IA agreed	TeamBinder ref.	IA Status	Contractor Status (Tree Removal certificate)	date action has been verified completed
04/01/2021 IA update, PA comments from NDD root mapping works report of 2 January 2021: 5 x 40mm and multiple 10 15mm roots removed 16% encroachment was measured and tree should be sustainably retained subject to future assessmen of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comment: Encroachment by pathway. Viability dependent on paving depth and type with root mapping required. Viability to be determined Uncertain. 04/01/2021 IA update, PA comments from NUD root mapping works report of 2 January 2021: 1 x 30mm 18% encroachmen.	Uncertain	Uncertain	Υ	No.: PLR-PLR1INF-CPBD- APP-CORR-001293.			
was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Encroachment by pathway. Viability dependent on paving depth and by the comments of th	Uncertain	Uncertain	Y	04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD- APP-CORR-001293.			
40m root retained. 16% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Encroachment by pathway. Viability 10/04/2021 TA update; PA 2d himewith room was proposed from the pathway of the pathway. Viability 10/04/2021 TA update; PA 2d himewith room was proposed from the pathway of the pathway. Viability	Uncertain	Uncertain	Υ	04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD- APP-CORR-001293.			
encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation an 04/01/2021 IA update, PA comments: Viability to be additional viability to be a comment of additional viability to be a comment of the root investigation and the root of	Uncertain	Uncertain	Y	04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD- APP-CORR-001293. 04/01/2021 IA update, Ref.			
encroachment was measured. This level of encroachment is not sustainable. Tree 1229 is recommended for removal due to the extent of root loss required to enable the installation of the proposed stormwater system. The stormwater pipe is 200 mm diameter, and is to be installed at 3 m deep x 1 m wide open expanded from high storing for work health safety. I crated 0.4/01/2021 IA update, PA comments from wide open expanded from high works report of 2 January 2021: No foots found 12%	Remove	Remove	Y	No.: PLR-PLR1INF-CPBD- APP-CORR-001293. 04/01/2021 IA update, Ref.			
encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation an u4/u1/2021 IA update, PA Comments from Not by 600 Mapping works to port of 20 January 2021; i'x 80M/M, 13 bumm and		Uncertain	Y	No.: PLR-PLR1INF-CPBD- APP-CORR-001293. 04/01/2021 IA update, Ref.			
multiple minus 10mm roots were removed. 18% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability denended to Future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability denended to Future 18/04/2020 IA update, PA comments: Viability to be denended to Future 18/04/2020 IA update, PA comments: Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to be denended to Future 18/04/2020 IA update, PA comments Viability to Be denended to Future 18/04/2020 IA update, PA comments Viability to Be denended to Future 18/04/2020 IA update, PA comments Viability to Be denended to Future 18/04/2020 IA update, PA comments Viability to Be denended to Future 18/04/2020 IA update IA update IA update IA update IA update IA update IA updat	Uncertain	Uncertain	Y	No.: PLR-PLR1INF-CPBD- APP-CORR-001293. 04/01/2021 IA update, Ref.			
30mm, 2 x 50mm, 1 x 70mm and numerous 10-15mm roots removed. 30% encroachment was measured and tree should be removed as this level of encroachment is not sustainable and further encroachment will require removal. Tree 1249 is recommended for removal, the to the extent of root loss required to enable the installation of the proposed stormwater system of an analysis of the proposed stormwater system measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation	Remove	Remove	Y	No.: PLR-PLR1INF-CPBD- APP-CORR-001293. 04/01/2021 IA update, Ref.			
was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation an \[U4/01/2021 TA:Uffication PA Confine Proof the Proof	Uncertain	Uncertain	Y	No.: PLR-PLR1INF-CPBD- APP-CORR-001293. 04/01/2021 IA update, Ref.			
was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation an u4/u1/2021 TA update, PA Comments from NUDV root mapping works report Vir billational encroachments. No root investigation measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation	Uncortain	Uncertain Uncertain	Y 	No.: PLR-PLR1INF-CPBD- APP-CORR-001293. 17/04/2020 IA update - Ref. No.: CORR-PLR-PLR1INF-			
was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation an 04/01/2021 SA production of the production of t	Uncertain	Uncertain	Y	CPBD-APP-CORR-000358- 04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD-			
encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation an udesign modifications. Totally encroached by roadway Viability to be deformined in the root investigation and udesign modifications. Totally encroached by roadway Viability to be deformed and use of the root of the roo	Uncertain	Uncertain	Y	APP-CORR-001293. 04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD-			
u4/015202mAttipatate; PAtchiments from Abur over mapping works report of the standary 2021; not root in 12% encroachment was measured and tree should be sustainably retained subject to future assessment of additional encroachments. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation an	Uncertain	Uncertain	Υ	APP-CORR-001293. 04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD-			
บลกประโภษา Madifications Technilly encreases the device of the subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and the subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and the subject to assessment of additional encroachments.	Uncertain	Uncertain	Υ	APP-CORR-001293. 04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD- APP-CORR-001293.			
U4/01/2021 A update; PA comments from ND from mapping Works report of 2 Jahillary 2021: Feeder from Shift and 3-5mm 1% encroachment was measured and tree should be sustainably retained subject to assessment of additional encroachments Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and design	Uncertain	Uncertain	Y	04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD- APP-CORR-001293.			
04/01/2021 Til update, PA comments from NDD foot mapping works Pool billy to be determined. Upcord in measured and tree should be sustainably retained subject to assessment of additional encroachments. No root investigation was undertaken. Tree to be retained. 17/04/2020 IA update, PA comments: Viability dependent on further root investigation and level change. Viability to be determined Upcortain	Uncertain	Uncertain	Υ	04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD- APP-CORR-001293.			
04/01/2021 Acids modifications. Totally contracted by naving and level change 2 Viability 2021: Withmined exception of the 131s- the root investigations were undertaken through the existing pavement which was common of a 50mm epoxy bonded aggregate (5-7mm pea gravel) surface over a 75mm reinforced no fines concrete sub base with geotextile. The majority of exceptation for tree 1319 was in the existing readway pavement with a small amount excavation behind the kern and gutter	Retain	Retain	Υ	04/01/2021 IA update, Ref. No.: PLR-PLR1INF-CPBD- APP-CORR-001293.			

TI/III//II/ III IIngale PA comments: Tree SXIX IS Incaled // 9 m from a proposed streetling role x. Ungargrafing services to				14404000414 1 0 0 1	
17/01/2021 IA update, PA comments: Tree 5818 is located 4.9 m from a proposed streetlight pole & underground services to north and 1.8 m from anticipated excavation works for underground services to be installed from the pole to existing services to				11/01/2021 IA update, Ref.	
southeast, providing a combined major (20.6%) cut encroachment into the TPZ, encroachment into the SRZ. Crown	Retain, pr, cr, rt	Retain pr, cr, rt	Υ	No.: PLR-PLR1INF-CPBD-	
				APP-CORR-001300.	
encroarboant à apalaie, are Within varei property dans Strentliah draubjeur d'art ba basachet, Assestiment. Procordinent le beunke				11/01/2021 IA update, Ref.	
directly adjacent to excavation 0.6 m deep excavation works for construcion of a footpath to the north of the trees along the	Remove	Uncertain	N	No.: PLR-PLR1INF-CPBD-	
property boundary, providing a major (45.3%) cut encroachment into the TPZ and encroachment into the SRZ. Crown				APP-CORR-001305.	
encroachment is anticipated. This major encroachment is considered to be a significant level of import and unsustainble by the				11/01/2021 IA update, Ref.	
footpath to the north of the trees along the property boundary, providing a major (43.6%) cut encroachment into the TPZ and	Dotoin	Dotoin nr or rt	Υ		
encroachment into the SRZ. Crown encroachment is anticipated. While this is a major encroachment, it will provide a sustainble	Retain	Retain, pr, cr, rt	T	No.: PLR-PLR1INF-CPBD-	
impact to the tree as less roots than expected where found during NDD works. Tree located on private of roperty. To be 17/01/2020 to update, PA comment: Co r (centre or trunk) located 700 mm from anticipated cut so mm outside or box (back o				APP-CORR-001305.	
kerb). Drawing shows 0.34 m from near edge of pipe. Major encroachment within TPZ and encroachment within SRZ. Retain.				11/01/2020 IA update, Ref.	
Trunk Protection. Ground protection under machinery track path. All excavation under Project Arborist direction/ supervision. In	Retain	Retain	Υ	No.: PPLR-PLR1INF-CPBD-	
road reserve. FOR at hase snapped. Centre of Trunk (CoT) 700 mm from anticinated excavation. Crown skew to W				APP-CORR-001263.	
11/01/2020 IA update, PA comment: Drawing shows CoT 3.41m from near edge of pipe. Major encroachment within TPZ.				11/01/2020 IA update, Ref.	
Ground protection under machinery track path. Located in No. 3, 300 mm from front boundary. Exposed lateral roots in road	Retain	Retain	Υ	No.: PPLR-PLR1INF-CPBD-	
reserve. CoT located 4.1 m from Back of Kerb (BoK).			•	APP-CORR-001263.	
				11/01/2020 IA update, Ref.	
11/01/2020 IA update, PA comment: Drawing shows CoT 4.13 m from near edge of pipe. Major encroachment within TPZ.	Retain	Dotoin	Υ	No.: PPLR-PLR1INF-CPBD-	
11.9% encroachment assuming 4.13 m offset to excavation. Ground protection under machinery track path. Located in No. 3.	Retain	Retain	Y		
CoT located 4.6 m from back of Kerb.				APP-CORR-001263.	
11/01/2020 IA update, PA comment: Drawing shows CoT 0.48 m from near edge of pipe. Major encroachment within TPZ and				11/01/2020 IA update, Ref.	
encroachment within SRZ. Retain. Trunk Protection. Ground protection under machinery track path. All excavation under	Retain	Retain	Υ	No.: PPLR-PLR1INF-CPBD-	
Project Arborist direction/ supervision. In road reserve. Lean to S. 1.4 m E of Power Pole. 0.7 m to (BoK).				APP-CORR-001263.	
11/01/2020 IA update, PA comment: Drawing snows CoT 0.40 m from near edge of pipe. Major encroachment within TPZ and				11/01/2020 IA update, Ref.	
encroachment within SRZ. Retain. Trunk Protection. Ground protection under machinery track path. All excavation under	Retain	Retain	Υ	No.: PPLR-PLR1INF-CPBD-	
Project Arborist direction/ supervision. Crown tied back where machine cannot avoid crown. In road reserve. Branches/ crown	rtotam	rtotaiii	•	APP-CORR-001263.	
OVER CATRIAGOWAY. Co.T. is 0.85 m from Ro.K. 11/01/2020 IA update, PA comment: Drawing shows Co.T.1.57 m from near edge of pipe. Major encroachment within TPZ. Retain. Trunk Protection. Ground protection under machinery track. In road reserve. Co.T is 0.88 m from Bo.K.	Retain	Retain	Υ	11/01/2020 IA update, Ref.	
				No.: PPLR-PLR1INF-CPBD-	
105/01/2021 TA update, PA comments: Located 3.7mm from the proposed across-road trenching for UG power providing a mino				APP-CORR-001263.	
(1.7%) cut encroachment into the TPZ. Low and sustainable impact. In private property 85 Adderton Road, west of existing from				05/01/2021 IA update, Ref.	
boundary masonry fence. Anticipated deflection of roots at wall. Tree to be retained. Retain and protect tree. Restrict machiner	Retain	Retain	Υ	No.: PLR-PLR1INF-CPBD-	
hucket movements within crown stread as per TMP02A				APP-CORR-001294.	
47/40/0000 IA 11 DA 17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				17/12/2020 IA update, Ref.	
17/12/2020 IA update, PA comment: Tree located within area of excavation for proposed drainage and electrical services and	Remove	N/A	N/A	No.: PLR PLR1INF-CPBD-	
pit inside the property. To be removed. Recent planting <3 m high.			•	APP-CORR-001269.	
				4/01/2021 IA update, Ref.	
4/12/2020 IA update, PA comment: Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020	Remove	Remove	Υ	No.: PLR-PLR0ALL-TFNSW-	
IA update, PA comment: No encroachment. Viable to retain Retain.	Kemove	Kelliove	Į.		
				APP-CORR-000070.	
4/12/2020 IA update, PA comment: Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020			.,	4/01/2021 IA update, Ref.	
IA update, PA comment: No encroachment. Viable to retain Retain.	Remove	Remove	Υ	No.: PLR-PLR0ALL-TFNSW-	
Trapado, 177 comment. No encreaciment. Viable to retain.				APP-CORR-000070.	
4/10/2000 IA				4/01/2021 IA update, Ref.	
4/12/2020 IA update, PA comment: Tree located within excavation works for stormtrap units. Tree to be removed. 17/04/2020	Remove	Remove	Υ	No.: PLR-PLR0ALL-TFNSW-	
IA update, PA comment: No encroachment. Viable to retain Retain.			•	APP-CORR-000070.	
				4/01/2021 IA update, Ref.	
4/12/2020 IA update, PA comment: Tree located within proposed access ramp and demolition works of existing garden bed.	Remove	Remove	Υ	No.: PLR-PLROALL-TFNSW-	
Tree to be removed. 17/04/2020 IA update, PA comment: No encroachment. Viable to retain Retain.	Remove	Kemove	ı		
				APP-CORR-000070.	