





PHOTOGRAPHIC PLATE No. 1: Path access at beach. Some minor bank stabalisation required using Treemax Recover™ or equivalent and planting in accordance with Vegetation Management Plan (VMP)



PHOTOGRAPHIC PLATE No. 2: Access path across gully. Boardwalk to board and chain accessway will transition at base of photo



PHOTOGRAPHIC PLATE No. 3: Existing eroded minor gully to be rehabilitated - refer to Vegetation Management Plan (VMP)



PHOTOGRAPHIC PLATE No. 4: Boardwalk to be aligned carefully between these two trees



PHOTOGRAPHIC PLATE No. 5: Typical character and width of existing path access. The boardwalk is to be aligned along the path



**PHOTOGRAPHIC PLATE No. 6**: Existing path entry into SEPP 26 Rainforest

KING + CAMPBELL

 
 REV.
 DATE
 DESCRIPTION

 A
 07.07.2010
 ISSUED FOR E.A.
King & Campbell Pty Ltd www.kingcampbell.com.au A: PO Box 243 Port Macquarie NSW 2444 T: 02 6586 2555 F: 02 6583 4064 E: info@kingcampbell.com.au

DATUM: AHD SCALE: 1:500@ A3

© King & Campbell Pty Ltd

	PROJECT NO:	4898	DRAWING TITLE:	EXHIBIT PA06: RAINFOREST BOARDWALK - SHEET 2			
	DA NO.:	-	DRAWING TILE:				
	DESIGNED BY:	DAT	· PROJECT:	LOT 4 DP 615261 & LOT 1 DP 374315			
	DRAWN BY:	PH		OCEAN DRIVE, LAKE CATHIE			
	CHECKED BY:	DAT	CLIENT:	SEAWIDE PTY LTD & MILLAND PTY LTD	DRAWING NO:	SHEET:	REVISIO
	DATE CREATED:	JULY 2010			14898_Exhibit_6_PA_Rainforest_Walk_Sh2.psd	1	А