



PHOTOGRAPHIC PLATE No. 1: Path access at beach. Some minor bank stabilisation required using Treemax Recover™ or equivalent and planting in accordance with Vegetation Management Plan (VMP)



PHOTOGRAPHIC PLATE No. 2: Access path across gully. Boardwalk to board and chain accessway will transition at base of photo



PHOTOGRAPHIC PLATE No. 3: Existing eroded minor gully to be rehabilitated - refer to Vegetation Management Plan (VMP)



PHOTOGRAPHIC PLATE No. 4: Boardwalk to be aligned carefully between these two trees



PHOTOGRAPHIC PLATE No. 5: Typical character and width of existing path access. The boardwalk is to be aligned along the path



PHOTOGRAPHIC PLATE No. 6: Existing path entry into SEPP 26 Rainforest

<div><div>KING + CAMPBELL</div><div><div>King & Campbell Pty Ltd</div><div>www.kingcampbell.com.au</div><div>A: PO Box 243 Port Macquarie NSW 2444</div><div>T: 02 6586 2555</div><div>F: 02 6583 4064</div><div>E: info@kingcampbell.com.au</div></div></div>	REV.	DATE	DESCRIPTION	DATUM: AHD	SCALE: 1:500@ A3	PROJECT NO:	4898	DRAWING TITLE:	EXHIBIT PA06: RAINFOREST BOARDWALK - SHEET 2				
	A	07.07.2010	ISSUED FOR E.A.			DA NO:	-						
						DESIGNED BY:	DAT	PROJECT:	LOT 4 DP 615261 & LOT 1 DP 374315				
						DRAWN BY:	PH		OCEAN DRIVE, LAKE CATHIE				
						CHECKED BY:	DAT	CLIENT:	SEAWIDE PTY LTD & MILLAND PTY LTD				
							NOTE: DO NOT SCALE OFF DRAWINGS. USE FIGURED DIMENSIONS ONLY. REPORT ANY DISCREPANCIES TO THE AUTHOR. THIS DRAWING, BEING THE PROPERTY OF KING & CAMPBELL PTY LTD, IS PROTECTED BY COPYRIGHT AND MUST NOT BE USED, REPRODUCED OR COPIED WHOLLY OR IN PART WITHOUT THE WRITTEN PERMISSION OF KING & CAMPBELL PTY LTD.		DATE CREATED:	JULY 2010	DRAWING NO:	SHEET:	REVISION:
							© King & Campbell Pty Ltd				14898_Exhibit_6_PA_Rainforest_Walk_Sh2.psd	1	A