



CHULLORA
HERITAGE ASSESSMENT, 1990

BUILDING/STRUCTURE

NAME OF ITEM: Returned Material Depot															
No. B54	Map Ref:														
Location: Per Way No. 1, north-west of road, first building.	Precinct G														
Condition: Fair															
Associated Items: Dismantling Yard B55															
<p>Description: The Returned Materials Depot is a store room and has always functioned as such. It is a small (approximately 6x6m) wooden framed corrugated iron clad structure which houses rows of wooden racks for the receipt and consignment of materials. Windows in the store are small casements and are located high on the west face of the building and one is located at eye level on the south face. The southern elevation has a large sliding door. Two corrugated fibreglass panels in the roof provide daylighting.</p>															
<p>SIGNIFICANCE ASSESSMENT</p> <table> <tr><td></td><td>2/5</td></tr> <tr><td>Aesthetic Value</td><td>1/5</td></tr> <tr><td>Historic Association</td><td>3/5</td></tr> <tr><td>Technological Importance</td><td>2/5</td></tr> <tr><td>Structural Integrity</td><td>3/5</td></tr> <tr><td>Interpretive Ability</td><td>1/5</td></tr> <tr><td>Social Significance</td><td>1/5</td></tr> </table>		2/5	Aesthetic Value	1/5	Historic Association	3/5	Technological Importance	2/5	Structural Integrity	3/5	Interpretive Ability	1/5	Social Significance	1/5	<p>INFORMANTS: Theodore</p> <p>REFERENCES:</p>
	2/5														
Aesthetic Value	1/5														
Historic Association	3/5														
Technological Importance	2/5														
Structural Integrity	3/5														
Interpretive Ability	1/5														
Social Significance	1/5														
RECOMMENDATION: Record	<p>PHOTOGRAPHS:</p> <p>B & W: 90-038-5/31 Slides:</p>														
															

CHULLORA
HERITAGE ASSESSMENT, 1990

BUILDING/STRUCTURE

NAME OF ITEM: Equipment Dismantling Yard													
No. B55	Map Ref:												
Location: North-west of Returned Material Depot	Precinct G												
Condition: Poor													
Associated Items: Returned Material Report B54													
<p>Description: This area housed equipment which was intended to be dismantled for the salvage of useful metals. The solid metal frame of the workbench in the foreground is an example. The fire boxes were also stored in this area prior to being cleaned in the pot ash tank (M57) and reused.</p>													
<p>SIGNIFICANCE ASSESSMENT</p> <table> <tr><td>Aesthetic Value</td><td>-/5</td></tr> <tr><td>Historic Association</td><td>2/5</td></tr> <tr><td>Technological Importance</td><td>-/5</td></tr> <tr><td>Structural Integrity</td><td>-/5</td></tr> <tr><td>Interpretive Ability</td><td>-/5</td></tr> <tr><td>Social Significance</td><td>-/5</td></tr> </table>	Aesthetic Value	-/5	Historic Association	2/5	Technological Importance	-/5	Structural Integrity	-/5	Interpretive Ability	-/5	Social Significance	-/5	<p>INFORMANTS:</p> <p>REFERENCES:</p>
Aesthetic Value	-/5												
Historic Association	2/5												
Technological Importance	-/5												
Structural Integrity	-/5												
Interpretive Ability	-/5												
Social Significance	-/5												
RECOMMENDATION: Record	<p>PHOTOGRAPHS:</p> <p>B & W: 90-038-5-32</p> <p>Slides:</p>												
													
<p>Recorded By: D. Godden & J. Sheppard</p> <p>Date: May, 1990</p>													

CHULLORA
HERITAGE ASSESSMENT, 1990

BUILDING/STRUCTURE

NAME OF ITEM: Footwarmers Room		
No. B56	Map Ref:	
Location: South/East corner	Precinct G	
Condition: Poor		
Associated Items:		
<p>Description: The footwarmers room was used for filling sheet steel footwarmers. The building is corrugated iron clad and timber framed. Double gabled, with a series of 10 posts running down the middle. Elevations are in 8 bays with high 16 paned timber framed casement windows. A sliding wooden door of 1/2 one bay width, slides to the side locking against the main central post.</p> <p>The lamp storage room is a lean to on the north elevation. It is skillion roofed, timber framed and corrugated iron clad. The floor is concrete.</p>		
SIGNIFICANCE ASSESSMENT Aesthetic Value Historic Association Technological Importance Structural Integrity Interpretive Ability Social Significance	2/5 2/5 4/5 2/5 1/5 2/5 1/5	INFORMANTS: Theo REFERENCES:
RECOMMENDATION: Record	PHOTOGRAPHS: B & W: 90-038-5/3 4 Slides:	



Recorded By: D. Godden & J. Sheppard


**** Date: May, 1990'

GODDEN MACKAY PTY. LTD.

200 Commonwealth Street, Surry Hills


**CHULLORA
HERITAGE ASSESSMENT, 1990**

MACHINERY/PLANT

NAME OF ITEM: Potash Tank											
No. M57	Map Ref:										
Location: Per Way Workshops No. 1, north-west sector next to electricians room. Precinct G											
Condition: Fair											
Associated Items: Ingot Rooms B53											
<p>Description: The potash tank was used to clean down firecases from the trains, prior to re-use. The metal lined tanks held the pot ash into which the cases were dipped. Fumes were exhausted through the overhead hood. The hood is slung from the roof trusses by flat plate hooks. The hood appears purpose built and was probably made in the Chullora workshops. The tanks are housed in a relatively modern timber and steel framed, corrugated iron clad shed. The shed has a gabled roof with fibreglass panel skylights. The floor is concrete with timbered inserts in standing areas.</p>											
<p>SIGNIFICANCE ASSESSMENT</p> <table> <tr><td>Historic Association</td><td>2/5</td></tr> <tr><td>Technological Importance</td><td>2/5</td></tr> <tr><td>Structural Integrity</td><td>2/5</td></tr> <tr><td>Relative Rarity</td><td>2/5</td></tr> <tr><td>Operational Ability</td><td>2/5</td></tr> </table>	Historic Association	2/5	Technological Importance	2/5	Structural Integrity	2/5	Relative Rarity	2/5	Operational Ability	2/5	<p>INFORMANTS:</p> <p>REFERENCES:</p>
Historic Association	2/5										
Technological Importance	2/5										
Structural Integrity	2/5										
Relative Rarity	2/5										
Operational Ability	2/5										
RECOMMENDATION: Record	<p>PHOTOGRAPHS:</p> <p>B & W: 90-083-5-38</p>										
											
<p>Recorded by: D. Godden & J. Sheppard</p> <p>Date: May 1990</p>											


CHULLORA
HERITAGE ASSESSMENT, 1990

BUILDING/STRUCTURE

NAME OF ITEM: Small Hipped Roof Structure - Possibly a Sub Station		
No. B60	Map Ref:	
Location: Behind Garage Per Way No. 1 - near the timber crane.	Precinct G	
Condition: Good		
Associated Items:		
<p>Description: This small hipped roof structure has twin skillions. The portal frame consists of very heavy RSJs so the building was obviously purpose built in the past. The building frame is timber and steel. The cladding is relatively new corrugated iron. The main entrance door is on the eastern side, consisting of double swing doors. The 8 paned wooden framed windows are located in the northern, southern and eastern elevations.</p>		
SIGNIFICANCE ASSESSMENT Aesthetic Value 2/5 Historic Association 3/5 Technological Importance 2/5 Structural Integrity 3/5 Interpretive Ability 1/5 Social Significance 1/5	INFORMANTS: REFERENCES:	
RECOMMENDATION: Record	PHOTOGRAPHS: B & W: 90-038-4-10 Slides:	
		
Recorded By: D. Godden & J. Sheppard		Date: May, 1990


CHULLORA
HERITAGE ASSESSMENT, 1990

BUILDING/STRUCTURE

NAME OF ITEM: Sigway Platform	
No. B58	Map Ref:
Location: Per way workshops No. 1 beside main line	Precinct G
Condition:	
Associated Items:	
Description: The sigway platform is an earth filled raised platform, sheathed with railway sleepers on its face. There are two small waiting sheds and very few other embellishments.	
SIGNIFICANCE ASSESSMENT Aesthetic Value 2/5 Historic Association 1/5 Technological Importance 3/5 Structural Integrity 1/5 Interpretive Ability 3/5 Social Significance 2/5	INFORMANTS: REFERENCES:
RECOMMENDATION: Record	PHOTOGRAPHS: B & W: 90-038-5-37 Slides:
	
Recorded By: D. Godden & J. Sheppard	Date: May, 1990

CHULLORA
HERITAGE ASSESSMENT, 1990

BUILDING/STRUCTURE

NAME OF ITEM: Garage	
No. B59	Map Ref:
Location: Per way No. 1	Precinct G
Condition: Fair	
Associated Items:	
<p>Description: The garage is a double gable ended, wooden framed corrugated iron clad building with 3 double sliding doors in the Western elevation. Each bay houses 3 cast iron 16 pane casement windows. The top and bottom rows are fixed and the central 8 frame section swivels about its central axis. There is a skillion roofed lean to at the eastern end of the garage. It is timber framed and corrugated iron clad. One double door leads from the lean to to the main building. The roof has standard king post trusses with a ridge pole and 4 purlins.</p>	
SIGNIFICANCE ASSESSMENT Aesthetic Value 2/5 Historic Association 3/5 Technological Importance 2/5 Structural Integrity 2/5 Interpretive Ability 2/5 Social Significance 2/5	INFORMANTS: Col Barclay REFERENCES:
RECOMMENDATION: Record	PHOTOGRAPHS: B & W: 90-038-4/2 Slides:
	
Recorded By: D. Godden & J. Sheppard	Date: May, 1990