

a division of Resolution Response Pty Ltd ABN: 94 154 052 883

> 3.16/55 Miller Street PYRMONT NSW 2009

> > 15 October 2019

Ms Alice Zheng Design Manager, Randwick Campus Redevelopment, Building Level 14, Tower Three, International Towers Sydney Exchange Place, 300 Barangaroo Avenue, BARANGAROO NSW 2000

AVIATION SSDA UPDATE INTEGRATED ASB (IASB) ADDITION V1.4

Dear Alice,

We note the review of the following core scope of elements of the IASB additions:

- UNSW Eastern Extension (Base Building Only)
- Associated modifications within the ASB
- Lowering of Hospital Road
- Landscaping

Following on from the adjusted building scope to include the UNSW considerations, given that the height of the building has not changed and therefore the existing PANS-OPS and OLS approvals remain extant, there is no requirement to engage with the airport and regulatory authorities on this issue. The flight path considerations for SSD 9113 (dated 6th June 2018) remain unchanged.

The GDA94 coordinates of the HLS reference point are:

Easting: 337062.15

Northing: 6245526.54

The MGA94 Coordinates for the building roof area are attached at Annexes A and B.

AviPro has maintained contact with the following organisations concerning crane and main building timings:

Department of Infrastructure, Regional Development and Cities (DIRD)

Civil Aviation Safety Authority (CASA)

Air Services Australia (ASA)

Sydney Airport (SACL)

Sincerely,

Steve Graham Managing Director Tel: 0401 520048 E: s.graham@avipro.com.au

Annexes A & B: Randwick Acute Services Building Roof Plan Coordinates







