




PIC. 6

A diagram illustrating the relationship between True North and Magnetic North. A line labeled 'TRUE NORTH' is shown. Another line, labeled 'MM' (Magnetic North), is shown at an angle to the True North line. The angle between them is labeled '10°57'', representing the magnetic declination. The MM line is marked with a break symbol (two parallel diagonal lines) to indicate it continues beyond the shown angle.