

30 January 2018

Resource Co
144-150 Wingfield Road North,
Wingfield SA 5013

FAO: Bill Hudson
Operations Manager NSW

Re: Consultant Advice Note (CAN) – Baler and Wrapper Structure
Project: Frank Street, Wetherill Park

Dear Bill,

This Consultant Advice Note (CAN) has been produced to outline the fire safety issues with respect to Olsson Fire's Fire Engineering Report S15332 dated 05/10/2017 and fire sprinkler system requirements for the proposed Baler and Wrapper Structure.

OFR have reviewed the below list of documentation; received on 12/01/2018:

- Shed1.jpeg
- YAZ235-01-03 Rev 1
- BA150078 WD-2201 C1
- BA150078 WD-2202 C1

OFR can confirm that the proposed structure has no overall impact on the Fire Engineering Report S15332 dated 05/10/2017. In relation to the requirements of the fire sprinkler system. The awning has been documented as requiring sprinklers, these will provide coverage at high level. Sprinkler protection will be required underneath equipment such as conveyors or the like. Hydrant and Hose reel coverage must be provided.

Yours Sincerely,



Carl Voss

Managing Director, Australia

P: 1300 736 280

E: carl@olssonfire.com