



Level 07 Plan

MOD 4 Drawing with FC2 changes marked up

- 1.Stair revised
- 2.Ramp revised
- 3.BOH layout revised







Level 08 Plan

MOD 4 Drawing with FC2 changes marked up

- 1.Stair and atrium revised
- 2.Ramp revised
- 3.BOH layout revised







Level 09 Plan

MOD 4 Drawing with FC2 changes marked up

- 1.Stair and atrium revised
- 2.BOH layout revised







Level 10 Plan

MOD 4 Drawing with FC2 changes marked up

- 1.Balustrade height increased from 1375mm to 1800mm Change from handrail design to Glazing
- 2. Atrium position changed
- 3. Sliding door replaced by revolving door





Level 10 Plan

MOD4 Drawing with FC2 changes marked up

Level 10 External Balustrade Height Increase

- The external balustrades at Level 10 have increased in height from 1375mm to 1800mm
- Because the change is predominantly additional frameless glazing it is unlikely that there would be any visual impact for external receivers.







Level 11 Plan

MOD 4 Drawing with FC2 changes marked up

- 1.Internal voids added
- 2.Atrium and stair revised







Level 12 Plan

SSD 9270 Plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 13 Plan

SSD 9270 Plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 14 Plan

SSD 9270 Plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 15 Plan

SSD 9270 Plan with FC2 changes marked up

1.BOH layout revised







Level 16 Plan

SSD 9270 Plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 17 Plan

SSD 9270 Plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 18 Plan

MOD 5 plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised






Level 19 Plan

MOD 5 plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 20 Plan

SSD 9270 Plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 21 Plan

MOD 5 plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 22 Plan

MOD 5 plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 23 Plan

SSD 9270 Plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 24 Plan

MOD 5 plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 25 Plan

MOD 5 plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 26 Plan

SSD 9270 plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 27 Plan

SSD 9270 plan with FC2 changes marked up

- 1.Atrium and stair revised
- 2.BOH layout revised







Level 28 Plan

SSD 9270 plan with FC2 changes marked up

1.Plantroom layout revised







Level 29 Plan

MOD 5 plan with FC2 changes marked up

- 1.BOH layout revised
- 2.Columns deleted







Level 30 Plan

MOD 5 plan with FC2 changes marked up

- 1.BOH layout revised
- 2.Columns deleted







Level 31 Plan

MOD 5 plan with FC2 changes marked up

- 1.BOH layout revised
- 2.Columns deleted







Level 32 Plan

MOD 5 plan with FC2 changes marked up

- 1.BOH layout revised
- 2.Columns deleted







Level 33 Plan

MOD 5 plan with FC2 changes marked up

- 1.BOH layout revised
- 2.Columns deleted







Level 34 Plan

MOD 5 plan with FC2 changes marked up

- 1.BOH layout revised
- 2.Columns revised







Level 35 Plan

MOD 5 plan with FC2 changes marked up

1.BOH revised







Level 36 Plan

MOD 5 with FC2 changes marked up

1.BOH revised







Level 37 Plan

MOD 5 plan with FC2 changes marked up

1.BOH revised







Lower Roof Plan

SSD 9270 plan with FC2 changes marked up

1.Plant layout revised







Upper Roof Plan

SSD 9270 plan with FC2 changes marked up


- 1.Plant layout revised
- 2.BMU hatch reduced






East Elevation

MOD 2 drawing with FC2 changes marked up





East Elevation

Kitchen exhaust discharge

