

From: Jake Hausfeld
To: [Isaac Pinkerton](#)
Cc: [John Skaf](#); [Jaron Hoffenberg](#)
Subject: RE: SSD 9354 - D8 - Jordan Springs Public School
Date: Friday, 10 July 2020 3:34:26 PM
Attachments: [image001.png](#)
[image002.png](#)
[image003.png](#)
[image004.jpg](#)
[image005.jpg](#)

Hi Isaac,

Aside from the noted exception of the provision of street lighting, Council confirms that the works listed under condition B22 of SSD 9354 have been completed to the satisfaction of Council, subject to completion of the remaining outstanding works being completed prior to bond refund. Council has no objection to commencement of operation of the school given the minor nature of these remaining works.

I note that since the time of writing of the final inspection slip dated 13/05/2020 the driveway listed to be completed on Lakeside parade has been poured and inspected by Council's engineering inspector. No issues were raised with the construction of this driveway however it is noted from my last inspection in the area that the saw cut into the pavement fronting the driveway had not been crack sealed which is required to be completed. I also note the requirement of our assets team for topsoil backfill to be placed around concrete edges where the turf level has dropped below that of the poured concrete. Could you please add these works to the list of works remaining to be completed.

Thanks

Jake Hausfeld
Development Engineer

E Jake.Hausfeld@penrith.city
T [+61247327876](tel:+61247327876) | F | M -
PO Box 60, PENRITH NSW 2751
www.visitpenrith.com.au
www.penrithcity.nsw.gov.au