

Issue	Area	Request	Outcome	Assessment
1. Non-compliance with UHSC DCP 2015	Cumulative Impact	Remove Turbines	No Response	NOT MET
	Distance from Public roads and boundaries	Remove or relocate Turbines 31,32,33 460M (twice the blade height) from the non-hosted property (BHGP)	No Response WTG 31 has been removed (being impractical to construct). WTG 32 has moved closer to the BHGNP (205m from boundary) and 33 remains (217 m from boundary).	NOT MET
2. Land Capability	Non-disturbance of Class 8 Soils	Assessment of the Steeper slopes be undertaken and erosions control measures warranted	No Response No assessments has been completed of the Soil and associated Erosion impacts on the steep slopes into the Upper Hunter River systems	NOT MET
3. Alleged unauthorised Land clearing	Extensive native vegetation clearing undertaken on the host properties	Investigate	No Response	NOT MET