

## Dust Lift-off – 26<sup>th</sup> January 2021

Current Monitoring locations and proposed location for monitor relocation.



Trench identified as the root cause for the dust lift-off - before and after treatment.

