McPherson Street, Banksmeadow. Cul-de-sac Improvement Works Practical Low Cost solution

> Remove ineffective damaged guard rail as shown in yellow.

Replace kerb &
gutter with roll over
kerb to same area
as new footpathFull width concrete footpath (both
sides) as shown in blue. Specs as
per council Driveway crossing
specs.

Problem - Inadequate turning area for trucks causing:

- Destruction of or damage to kerb, guttering, street drains, footpaths, street trees, street lighting and grass areas.
- Encourages illegal dumping
- Potential to destroy or damage major underground pipelines and services.

Remove or move damaged light Paint & Tidy up pots

=]0////0/0/0

or replace with sandstone blocks Install locked gate.