



Photo 1: Creek bank – damage to Wambo Creek from changes in drainage due to mining.



Photo 2: Creek Bed – creek cut around rocks which were not removed following order of 2003.





Photo 3: Subsidence trench reappeared in December 2013, still awaiting repair.



Photo 4: Subsidence hole, now fenced off but much larger and deeper. Stick is approximately 0.8 m long.





Photo 5: Small subsidence trench



Photo 6: Subsidence hole in cropping paddock.





Photo 7: Subsidence hole