

Ref: 2001186

17th April 2013

Parkview Constructions Pty Ltd
PO Box R1779
Royal Exchange NSW 1225
Australia

Bonacci Group (NSW) Pty Ltd
ABN 29 102 719 352

Consulting Engineers
Structural • Civil • Infrastructure

Level 6, 37 York Street
Sydney NSW 2000 Australia

Tel: +61 2 8247 8400

Fax: +61 2 8247 8444

bons@bonaccigroup.com

www.bonaccigroup.com

Attention: Mr. Gavin Rea

Sydney Olympic Park – Site 3, Australia Towers II Structural Core Slab

Further to our previous advice, we confirm that the slab that joins the lift core and the stair core in both Towers C and D is required structurally to transmit the horizontal diaphragm forces present in these tall buildings. This slab is required in ensuring that the lateral load resisting system for both towers which is predominately compromised of the lift and stair shafts which have been joined together to create an efficient box structure is maintained. See sketch below.



Yours Sincerely

BONACCI GROUP (NSW) PTY LTD

Ryan Campbell
Director