

Hans Sydney Pty Ltd Preliminary Site Investigation

> Stage 2 338 Pitt St, Sydney NSW 2000

19 December 2019 57557/126005 Rev 1 JBS&G



Table of Contents

| Abbr | eviatio | ons | V | | |
|-------|---------------|---|----|--|--|
| Exec | utive S | Summary | vi | | |
| 1. | Intro | Introduction | | | |
| | 1.1 | Objectives | 2 | | |
| | 1.2 | Scope of Work | 2 | | |
| 2. | Site | Condition and Surrounding Environment | 3 | | |
| | 2.1 | Site Identification | 3 | | |
| | 2.2 | Site Description | 3 | | |
| | 2.3 | Surrounding Land Use | 4 | | |
| | 2.4 | Topography | 4 | | |
| | 2.5 | Geology | 4 | | |
| | 2.6 | Acid Sulphate Soils | 4 | | |
| | 2.7 | Hydrology | 5 | | |
| | 2.8 | Hydrogeology | 5 | | |
| 3. | Site History6 | | | | |
| | 3.1 | Aerial Photographs | 6 | | |
| | 3.2 | Title Details | 6 | | |
| | 3.3 | Council Records | 10 | | |
| | 3.4 | EPA Records | 10 | | |
| | 3.5 | Australian and NSW Heritage Register | 11 | | |
| | 3.6 | Integrity Assessment | 11 | | |
| 4. | Asse | essment of Potential Contamination | 12 | | |
| | 4.1 | Potential Areas of Environmental Concern | 12 | | |
| | 4.2 | Potentially Contaminated Media | 12 | | |
| | 4.3 | Potential for Migration | 12 | | |
| 5. | Disc | ussion | 13 | | |
| 6. | Cond | clusions and Recommendations | 14 | | |
| 7. | Limit | tations | 15 | | |
| List | of Ta | ables | | | |
| Table | e 2.1: 9 | Summary of Site Details | 3 | | |
| | | Summary of Historical Title Search | | | |
| | | Areas of Environmental Concern and Contaminants of Potential Concern. | | | |



List of Figures

Figure 1 Site Location
Figure 2 Site Layout

Appendices

Appendix A Groundwater Bore Records

Appendix B Aerial Photographs

Appendix C Title Records

Appendix D Council Records

Appendix E EPA Records

Appendix F Photographic Log



Abbreviations

A list of the common abbreviations used in this report is provided below.

ACM Asbestos containing material

AEC Area of Environmental Concern

AHD Australian Height Datum

COPC Contaminant Of Potential Concern

bgs below ground surface

BTEX Benzene, toluene, ethylbenzene and xylenes

EPA NSW Environment Protection Authority

PESA Preliminary Environmental Site Assessment

Ha Hectare

JBS&G Australia Pty Ltd

OCP Organochlorine Pesticides

OPP Organophosphorus Pesticides

PAHs Polycyclic aromatic hydrocarbons

Pb Lead

PCBs Polychlorinated biphenyls

PSI Preliminary Site Investigation

TPH Total Petroleum Hydrocarbons



Executive Summary

JBS&G Australia Pty Ltd (JBS&G) was engaged by Hans Sydney Pty Ltd (the client) to conduct a Phase 1 / preliminary site investigation (PSI) of Hans 338 project, located at 338 Pitt Street, Sydney NSW (the Site).

This report supports a Stage Significant Development Application (SSDA) for the mixed use redevelopment of 338 Pitt Street, Sydney, which is submitted to the City of Sydney pursuant to Part 4 of the Environmental Planning and Assessment Act 1979 (EP&A Act). China Centre Development Pty Ltd is the proponent of the SSDA. The proposed development comprises of hotel, residential, commercial and retail uses and will include demolition of existing structures, excavation and site preparation including remediation if required and construction of an iconic 258m two-tower building with four basement levels.

The site is located at the corner of Pitt Street and Liverpool Street, within the 'Mid Town' precinct of Sydney's Central Business District (CBD). The site is approximately 150m west of Museum Station and Hyde Park, and approximately 350m from Town Hall Station. The site includes several allotments and constitutes nearly one third of the city block between Bathurst Street, Pitt Street and Liverpool Street. The site is an irregular shape and has a combined area of approximately 5,900m².

This PSI report presents an assessment of potential contamination to address the requirements of State Environmental Planning Policy No. 55 – Remediation of Land (SEPP 55) to support the SSDA.

It is noted that a PSI for the Stage 1 DA portion of the site was previously completed in 2016 (JBS&G 2016¹). Subsequent to the completion of the Stage 1 PSI, the client acquired two additional properties (128 and 130 Liverpool Street) with a total area of 177 m², to be included in the broader development of the site. On this basis, the current PSI is required to update JBS&G (2016) with additional information gathered from the recently acquired properties (128 and 130 Liverpool Street).

Site inspections were completed by one of JBS&G's trained field scientists on the 19 September 2016 and 22 November 2019. The inspection included readily accessible areas of site, the exterior of buildings at ground level, and the two basement car parks (Lot 3 DP 104414 and Lot 10 DP 857070/Lot A DP 4488971). Multistorey commercial buildings occupied the majority of the site, and the remainder of the site was sealed. No evidence of USTs was observed and no odours, staining or hazardous building materials were observed, based on a limited site inspection.

Based on the findings of this investigation and subject to the limitations in **Section 7**, the following conclusions are made:

- From site inspections, the site generally appears well maintained and in good condition.
- While the potential for significant contamination at the site is low, a targeted program of
 intrusive investigations would be necessary to determine if contamination is present at the
 site. An intrusive investigation at the site should target potential fill materials in Dungate
 Lane, and within existing building footprints, with the exception of areas occupied by
 basement carparks.
- It is considered unlikely that activities at the site will have contaminated the land to a degree that would prevent the redevelopment of the site for mixed commercial and residential land-use.

Preliminary Site Investigation, 338 Pitt St Sydney, JBS&G Australia Pty Ltd, 18 October 2016 (JBS&G 2016).



| • | In the event that contamination is identified at the site, it is anticipated that the site can be made suitable for the proposed land uses. |
|---|---|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |



1. Introduction

JBS&G Australia Pty Ltd (JBS&G) was engaged by Hans Sydney Pty Ltd (the client) to conduct a Phase 1 / preliminary site investigation (PSI) of Hans 338 project, located at 338 Pitt Street, Sydney NSW (the Site). The site comprises nine properties (10 Lots), fronting Pitt, Castlereagh and Liverpool Streets.

The site is currently used for commercial purposes, including offices, retail stores and eateries and is currently zoned as B8 Metropolitan Centre.

This report supports a Stage Significant Development Application (SSDA) for the mixed use redevelopment of 338 Pitt Street, Sydney, which is submitted to the City of Sydney pursuant to Part 4 of the Environmental Planning and Assessment Act 1979 (EP&A Act). China Centre Development Pty Ltd is the proponent of the SSDA.

The site is located at the corner of Pitt Street and Liverpool Street, within the 'Mid Town' precinct of Sydney's Central Business District (CBD). The site is approximately 150m west of Museum Station and Hyde Park, and approximately 350m from Town Hall Station. The site includes several allotments and constitutes nearly one third of the city block between Bathurst Street, Pitt Street and Liverpool Street. The site is an irregular shape and has a combined area of approximately 5,900m².

The proposed development comprises of hotel, residential, commercial and retail uses and will include:

- demolition of all existing structures;
- excavation and site preparation, including any required remediation;
- construction and use of a mixed-use development, with an iconic 258m two-tower built form above a podium and internal courtyard;
- four (4) basement levels and a lower ground level accommodating residential, retail and hotel car parking, motorcycle parking, bicycle parking, loading dock, storage and relevant building services;
- improvements to the public domain, including landscaping, pedestrian thoroughfares/connections, and landscaping; and
- augmentation and extension of utilities and services.

A detailed description of development is provided by Ethos Urban within the EIS.

This PSI report presents an assessment of potential contamination to address the requirements of the current State Environmental Planning Policy No. 55 – Remediation of Land (SEPP 55) (and Draft Remediation of Land SEPP) to support the SSDA and in doing so meet the SEARs 'Statutory and Strategic Context' requirement to address SEPP 55.





The Site

It is noted that a PSI for the Stage 1 DA portion of the site was previously completed in 2016 (JBS&G 2016²). Subsequent to the completion of the Stage 1 PSI, the client acquired two additional properties (128 and 130 Liverpool Street) with a total area of 177 m², to be included in the broader development of the site. On this basis, the current PSI updates JBS&G (2016) with additional information gathered from the recently acquired properties (128 and 130 Liverpool Street).

The PSI has been undertaken in accordance with guidelines made or approved by the NSW Environment Protection Authority (EPA) and relevant Australian Standards.

1.1 Objectives

The objectives of the investigation are to review historical site activities and to draw preliminary conclusions regarding the potential contamination status of the site. Recommendations will be made as appropriate for any further actions required to conclude that the site is or can be made suitable for the intended land uses consistent with SEPP 55 requirements.

1.2 Scope of Work

To achieve the objectives of the assessment, the following scope of works was undertaken:

- Review of available Council documentation, aerial photographs, NSW EPA records and Heritage records to identify potential areas of environmental concern (AECs) and associated contaminants of potential concern (COPCs);
- Review of site setting including topography, hydrology, hydrogeology and geology;
- Review of records of environmental incidents or former environmental licences held by the NSW EPA;
- Site inspections to identify potential AECs and COPCs not identified in the historical record review; and
- Preparation of this PSI report in accordance with guidelines made or approved by EPA.

² Preliminary Site Investigation, 338 Pitt St Sydney, JBS&G Australia Pty Ltd, 18 October 2016 (JBS&G 2016).



2. Site Condition and Surrounding Environment

2.1 Site Identification

The site location is shown in **Figure 1**, and current site layout is shown in **Figure 2**. The site details are summarised in **Table 2.1** and described in the following sections.

Table 2.1: Summary of Site Details

| Lot/DP | Lot 3 DP 104414 |
|----------------------------|---|
| | Lot 1 DP 66428 |
| | Lot 10 DP 857070 |
| | Lot A DP 4488971 |
| | Lot B DP 183853 |
| | Lot 1 DP 70702, Lot 1 DP78245 (under the same property) |
| | Lot 1 DP 90016 |
| | Lot B DP 448971 |
| | Lot C DP 448971 |
| Address | 338 Pitt Street, Sydney NSW 2000 |
| Local Government Authority | City of Sydney |
| Easting | 334296.691 (GDA94 - MGA56) |
| Northing | 6250096.635 (GDA94 - MGA56) |
| Site Zoning | B8 Metropolitan Centre (Sydney Local Environmental Plan 2012) |
| Current Use | Commercial – Offices, retail, eateries. |
| Proposed Use | Hotel and residential uses |
| Site Area | Approximately 6,012 m ² |
| | |

2.2 Site Description

Inspection of the greater site area was initially completed by one of JBS&G's qualified and trained environmental consultants on the 19 and 20 September 2016. Photographs taken during the site inspections are included in **Appendix F**. The inspection included readily accessible areas of site, the exterior of buildings at ground level, and the two basement car parks. A summary of general site features is provided below.

The site occupies a portion of a city block occupied by six multistorey buildings. At street level the buildings are predominately occupied by eateries and building foyers. No indications of ACM building materials were noted, from a limited inspection of the exterior of the buildings, and no peeling paint was noted on painted surfaces. An open area between buildings was noted at the end of Dungate Lane, which connects to Castlereagh Street to the east. This area appeared to be in use as a loading zone and as a bin collection area, as well as vehicle access to underground car parking.

Two basement carparks were noted at the site. The basement carpark within the Lots 10 in DP 857070 and A in DP 4488971 was noted to be set into natural materials, with sandstone bedrock observed in the wall of the upper basement level. No exposed soil/bedrock was observed in the other basement carpark, at Lot 3 DP 104414. There was no evidence of underground storage tanks (USTs) in the building basements or other accessible areas of site, with no risers, bowsers or fill/dip points observed. Additionally, there was no evidence of bulk chemical storage within the basement areas. A trade waste pipe and a suspected commercial grease trap or oil-water separator was noted within the basement at Lot 3 DP 104414, and were observed to be in good condition, with no signs of leakage.



Evidence of services were observed frequently at ground level within footpaths, with numerous gatics observed. The ground surface at the site was paved, with tiles on all footpaths, and asphalt roadway within Dungate Lane. No accessible soils were observed within the site.

Overall, the site appeared well maintained and in good condition. There were no odours or significant staining observed on the paved ground surfaces.

In addition, a second site inspection (from the street frontages) was completed by one of JBS&G's qualified and trained environmental consultants on the 22 November 2019. The site appeared consistent with the description provided above. In addition, the two properties located at 128 and 130 Liverpool Street were used as commercial eateries in which the buildings comprised of two-storey brick construction. There were no obvious potential sources of contamination viewed within these two properties from the street frontage.

2.3 Surrounding Land Use

Current land use of adjacent properties or properties across adjacent roads is summarised below:

- North multistorey commercial buildings;
- East Castlereagh Street, followed by multistorey commercial buildings;
- South Liverpool Street, followed by multistorey commercial buildings.
- West Pitt Street, followed by multistorey commercial buildings.

2.4 Topography

Review of the regional topographic data (SixMaps³) indicated that the site has an elevation of between 15 to 20 m Australian Height Datum (AHD). The regional topography slopes gently to the northwest towards Cockle Bay, approximately 800 m from the site.

2.5 Geology

Review of the regional geological map (DMR 1983⁴) indicated the site lies within Ashfield Shale, part of the Wianamatta group of sedimentary rocks. Ashfield shales typically lie on Mittagong formation and comprise of black mudstones, grey silty shales and sideritic clay ironstone bands, often containing high iron and low calcium levels.

Review of the Sydney Soil Landscape series (eSPADE⁵) indicates soils at the site comprise the residual Lucas Heights Landscape. These typically occur on undulating crests and ridges on plateau surfaces of the Mittagong formation, bands of shale and fine-grained sandstones with low relief to 30 m and slopes of less than 10 percent. The soils typically are moderately deep (50-150cm), hardsetting yellow podzolic soils and yellow soloths, and yellow earths on outer edges. This soil landscape group often exhibits stony soil, low fertility and low available water capacity.

2.6 Acid Sulphate Soils

Review of the acid sulphate soil map from Australian Soil Resource Information System (ASRIS⁶) indicates that the site is located in an area of low probability of acid sulphate soils (ASS). As such, management of development activities is unlikely to be required to address the potential for impacts to ASS on the site. In addition, the Council 10.7 certificates provided in **Appendix D**, indicates the site is not situated within a location that has been mapped as Class 1 or 2 ASS.

³ NSW Government Spatial Information Exchange website, http://maps.six.nsw.qov.au/, accessed 15 September 2016

⁴ Sydney 1:100 000 Geological Series Sheet 9130. Department of Mineral resources, 1983 (DMR 1983)

NSW Government Environment & Heritage, NSW soil and land information, eSPADE, http://www.enviornment.nsw.qov.au/eSpadeWebapp/, accessed 15 September 2016

⁶ Australian Soil Resource Information System, <u>http://www.asris.csiro.au/</u>, accessed 15 September 2016



2.7 Hydrology

Rainwater at the site is likely to enter stormwater infrastructure, as buildings occupy the majority of the site and the remaining ground surfaces are paved. The regional topography suggests collected rainwater would then migrate northwest via the city stormwater system towards Cockle Bay. Additionally, an open drain was noted at the site with adjacent painted message "drains to Sydney Harbour" as shown in **Photograph 5** in **Appendix F**.

2.8 Hydrogeology

Review of information obtained from the Office of Water database indicated that there are more than 10 registered groundwater bores within a 500 m radius of the site. As such, data from the 10 closest bores is included in **Appendix A** and summarised below. No data was available for groundwater quality for any of the bores reviewed.

- GW112175 is located approximately 900 m to the east of the site, on Bourke Street, and is registered as a monitoring bore. No Standing Water Level (SWL) data was available.
- GW112179 is located approximately 1.0 km to the southeast of the site, on Flinders Street, and is registered as a monitoring bore. No SWL data was available.
- GW200690 is located approximately 1.0 km to the southeast of the site, on Albion Street, and is registered for domestic purposes. No SWL data was available.
- GW112180 is located approximately 1.2 km to the southeast of the site, on Flinders Street, and is registered as a monitoring bore. No SWL data was available.
- GW109238 is located approximately 1.1 km to the southeast of the site, on Short Place, and
 is registered as a monitoring bore. The bore is located through clay loam and shale to 7.0 m
 bgs and the SWL was recorded at 4.59 m bgs.
- GW109239 is located approximately 1.1 km to the southeast of the site, on Marys Place, and is registered as a monitoring bore. The bore is located through clay loam and shale to 7.45 m bgs and the SWL was recorded at 4.57 m bgs.
- GW109086 is located approximately 1.3 km to the northwest of the site, near Sussex Street, and is registered as a monitoring bore. The bore is located through sand to 5.68 m bgs. No SWL data was available.
- GW113599 is located approximately 1.5 km to the northwest of the site, near Waterman's, Quay and is registered as a monitoring bore. No SWL data was available.
- GW109649 is located approximately 1.2km to the southwest of the site near Wattle Street, and is registered as a monitoring bore. The bore is located through sand then sandstone to 7.20 m bgs and the SWL was recorded at 2.95 m bgs.
- GW109502 is located approximately 1.3km to the southwest of the site, near Abercrombie,
 Street and is registered as a monitoring bore. No SWL data was available.

It is anticipated that shallow groundwater at the site will occur at approximately 3-5 m bgs, based on the reported SWL at nearby bores. Regional groundwater is likely to occur within sandstone/shale bedrock, especially within zones of relatively higher permeability associated with inconsistencies in the bedrock (faults, joints, weathered zones, etc.). Regional topography suggests groundwater migration may move towards Cockle Bay.

Localised, shallow subsoil groundwater seepage may also occur at the site, particularly following periods of significant wet weather. This may result in perched groundwater at the soil-bedrock interface and within highly weathered rock beneath surface soils. Seepage flow is influenced by topography, including local bedrock topography, and is expected to be toward the north-west.



3. Site History

3.1 Aerial Photographs

Copies of aerial photographs obtained from the Department of Lands are included in **Appendix B**. Relevant information from the aerial photograph review is summarised below. It is noted that the angle of the photographs causes the site boundaries to appear offset.

- **1930**: The site appears to be occupied by multistorey buildings. A portion of the north east of the site, adjoining Castlereagh Street, appears to be occupied by two small structures. Other portions of the site may be vacant, however, it is difficult to be certain due to shadows cast by the taller structures at the site.
- **1943**: The site appears mostly unchanged from the 1930 imagery with the exception that the smaller structures in the north east of the site are no longer visible.
- **1961**: The whole site area is occupied by buildings, including the areas between the larger structures which appeared possibly vacant in the 1930 and 1943 images.
- 1975: A new multistorey building has been constructed in the northern portion of the site which is significantly taller than the buildings previously in this location, and has an associated courtyard adjoining Castlereagh Street. This building obscures a large portion of the site due to the angle of the aerial photograph.
- 1986: The site appears mostly unchanged from the 1975 imagery.
- **1994:** A new multistorey building is present in the south-west of the site, at the corner of Pitt Street and Liverpool Street.
- **2005:** A new multistorey building is present in the south-west of the site, at the corner of Pitt Street and Liverpool Street, replacing the building noted in the 1994 aerial.
- **2016:** The site appears mostly unchanged from the 2005 imagery. Dungate Lane is visible, which was previously obscured by the adjoining buildings.
- **2019:** The site appears consistent to the 2016 imagery.

3.2 Title Details

Relevant details from a historical review of the land titles for the site are listed in **Table 3.1**. A copy of title search results is provided in **Appendix C**.

Table 3.1: Summary of Historical Title Search

| | Lot 1 DP 66428 | |
|------------------------------|---|--|
| Date | Registered Proprietor | |
| 20.9.1910 (1910 to 1947) | Louisa Snell (Married Woman) & her deceased estate | |
| 9.10.1947 (1947 to 1951) | Joseph Henry Snell (Gentleman) & his deceased estate (Application by Transmission not investigated) | |
| 11.7.1951 (1951 to 1952) | Mary Lista Hawkins (Married Woman) (Application by Transmission not investigated) | |
| 14.2.1952 (1952 to 1969) | Booth Holdings Pty Limited | |
| 27.11.1969 (1969 to 1972) | 332 Pitt Street (Victoria House) Pty Limited | |
| 30.11.1972 (1972 to 1972) | Loftus Properties Limited | |
| 30.11.1972 (1972 to 1980) | State Superannuation Board | |
| 17.3.1980 (1980 to 1987) | Australian Dental Association (New South Wales Branch) | |



| Lot 1 DP 66428 | |
|----------------|---------------------------------|
| Date | Registered Proprietor |
| 14.10.1987 | Educacia Haldinga Dhi, Lincibad |
| (1987 to Date) | Edremo Holdings Pty Limited |

| | Lot B DP 183853 | |
|-----------------------------|---|--|
| Date | Registered Proprietor | |
| 9.8.1912 (1912 to 1920) | Theodore John Marks (Architect) | |
| 7.5.1920 (1920 to 1929) | Roche and Hampton Motors Limited Now Amalgamated Properties Limited | |
| 4.10.1929 (1929 to 1931) | William Morgan (Gentleman) | |
| 1.9.1931 (1931 to 1977) | Tooth & Co Limited | |
| 20.1.1977 (1977 to 1995) | Holpitt Pty Limited | |
| 5.4.1995 (1995 to 2005) | Evangelos Lekopoulos (Licence) Mary Lekopoulos (Married Woman) | |
| 24.8.2005 (2005 to 2009) | Dencal Pty Limited | |
| 10.6.2009 (2009 to 2014) | Pubcorp Pty Limited | |
| 12.9.2014 (2014 to 2016) | Globalwide Investments Pty Ltd | |
| 12.5.2016 (2016 to Date) | # Han's Sydney Pty Ltd | |

| Lot 1 DP 70702, Lot 1 DP78245 (under the same property) | | |
|---|---|--|
| Date | Registered Proprietor | |
| 19.12.1927 | Castlereagh Properties Limited | |
| (1927 to 1947) | | |
| 7.1.1947 | Edward Gabriel Glass (Furniture Dealer) | |
| (1947 to 1950) | Samuel Bertie Solomon (Furniture Dealer) | |
| 13.11.1950 | E.G. Glass & Company Pty Limited | |
| (1950 to 1953) | Eldi diass a company i ty Emitea | |
| 22.9.1953 | Edels Pty Limited | |
| (1953 to 1958) | Lucis Fty Limited | |
| 26.11.1958 | 245 Castlereagh Street Pty Limited | |
| (1958 to 1964) | 245 Castiereagn Street Pty Limited | |
| 5.11.1964 | Local C. Canaval Assumance Contatu Limited | |
| (1964 to 1981) | Legal & General Assurance Society Limited | |
| 16.12.1981 | Administrative and Clerical Officers' Association Commonwealth Public Service | |
| (1981 to 1983) | (N.S.W. Branch) | |
| 24 44 4002 | Strata Plan No. 20900 | |
| 21.11.1983 | (Common Property Areas only investigated from this date up to 8.11.1993 | |
| 21.11.1983 | | |
| (1983 to 1993) | The Proprietors – Strata Plan No. 20900 | |
| 0.44.4000 | Strata Plan No. 20900 now cancelled | |
| 8.11.1993 | (All land investigated from here on) | |
| 8.11.1993 | Trustees of the Sisters of Mercy (North Sydney) | |
| (1993 to 1996) | | |
| 18.6.1996 | # The Returned and Services League of Australia (New South Wales Branch) | |
| (1996 to Date) | (Trustees for the ANZAC House Trust) | |



| Lot 1 DP 90016 | | |
|------------------------------|---|--|
| Date | Registered Proprietor | |
| 6.10.1920 (1920 to 1980) | Central Property Co Limited Now Central Property Co Pty Limited | |
| 29.9.1980 (1980 to 1981) | United Broadcasting Co Pty Limited | |
| 25.3.1981 (1981 to 1988) | Victor Frankenstein (Surgical Suppliers) Peter Thomas Frankenstein (Surgical Suppliers) | |
| 21.11.1988 (1988 to 1994) | Kiso Holdings Pty Limited Bridgegow Pty Limited Minlor Holdings Pty Limited | |
| 25.11.1994 (1994 to 2003) | Vitalwork Pty Limited | |
| 8.9.2003 (2003 to 2015) | Assets & Properties Pty Limited | |
| 13.8.2015 (2015 to Date) | # Han's Sydney Pty Ltd | |

| Lot 10 DP 857070 | |
|------------------------------|---|
| Date | Registered Proprietor |
| 21.12.1906 (1906 to 1927) | James Paroissien Johnson (Gentleman) |
| 7.6.1927 (1927 to 1932) | Sargents Limited |
| 30.12.1932 (1932 to 1941) | James Paroissien Johnson (Gentleman) & his deceased estate |
| 7.1.1941 (1941 to 1949) | Cecil Paroissien Johnson (Grazier) Theodore Worth Storey (Grazier) (Application by Transmission not investigated) |
| 28.6.1949 (1949 to 1955) | Walter Paroissien Johnson (Student) |
| 24.1.1955 (1955 to 1975) | Australia and New Zealand Bank Limited |
| 18.8.1975 (1975 to 1987) | C.E.C. Investments Pty Limited |
| 5.11.1987 (1987 to 1988) | Paclyn Pty Limited |
| 11.10.1988 (1988 to 2000) | Dindori Holdings Pty Limited Now Prima Developments Pty Limited |

| Lot A DP 448971 | |
|------------------------------|---|
| Date | Registered Proprietor |
| 12.11.1911 (1911 to 1925) | Reginald Campbell Galbraith (Merchant) & his deceased estate |
| 11.12.1925 (1925 to 1931) | Wallace John Carson (Esquire) (Application by Transmission not investigated) |
| 29.4.1931 (1931 to 1959) | The Permanent Trustee Company of New South Wales Limited Now Permanent Trustee Company of New South Wales Limited |
| 5.5.1959 (1959 to 1967) | 126 Liverpool Street Sydney Pty Limited |
| 8.9.1967 (1967 to 1979) | James Sarikas (Milk Bar Proprietor) Mary Sarikas (Married Woman) |
| 8.10.1979 (1979 to 1990) | Peter Maniatis (Restaurant Proprietor) Irene Maniatis (Married Woman) |
| 19.7.1990 (1990 to 2005) | Goodsip Pty Ltd |
| 23.5.2005 (2005 to 2008) | Capital Diamond Pty Limited |



| Lot A DP 448971 | | |
|-----------------|-------------------------------|--|
| Date | Date Registered Proprietor | |
| 26.5.2008 | AMD Conital Investors Limited | |
| (2008 to 2015) | AMP Capital Investors Limited | |
| 17.11.2015 | # VIG-CC Pty Limited | |
| (2015 to Date) | | |

| | Lot 3 DP 1044304 | |
|----------------|--|--|
| Date | Registered Proprietor | |
| 31.7.1915 | George Patrick Dwyer (Gentleman) | |
| (1915 to 1915) | deorge i dener bwyer (dendeman) | |
| 10.12.1915 | Larke Hoskins and Company Limited | |
| (1915 to 1917) | Earke Hoskins and company Emitted | |
| 30.7.1917 | Investments Proprietary Limited | |
| (1917 to 1952) | investments reprictally Elimited | |
| 23.7.1952 | John Danks and Son Proprietary Limited | |
| (1952 to 1955) | John Danks and John Tophetary Elimited | |
| 1.7.1955 | Griffs (N.S.W.) Pty Limited | |
| (1955 to 1963) | Offits (N.S.W.) Tey Enriced | |
| 20.9.1963 | Frank Griff & Sons Pty Limited | |
| (1963 to 1977) | Trunk Griff & 30fi31 ty Elifficed | |
| 11.7.1977 | The Commonwealth of Australia | |
| (1977 to 1985) | The commonwealth of Australia | |
| | Australian Telecommunications Commission | |
| | Now | |
| 20.9.1985 | Australian and Overseas Telecommunications Corporation Limited | |
| (1985 to 2003) | Now | |
| (====== | Australian and Overseas Telecommunications Limited | |
| | Now | |
| | Telstra Corporation Limited | |

| | Lot B DP 448971 |
|----------------|--|
| Date | Registered Proprietor |
| 12.11.1911 | Reginald Campbell Galbraith (Merchant) |
| (1911 to 1925) | |
| 11.12.1925 | Wallace John Carson (Esquire) |
| (1925 to 1931) | (Transmission Application not investigated) |
| 29.04.1931 | The Permanent Trustee Company of New South Wales Limited |
| (1931 to 1959) | |
| 05.05.1959 | 128 Liverpool Street Pty Limited |
| (1959 to 1963) | |
| 06.08.1963 | Louran Investments Pty Limited |
| (1963 to 2018) | |
| 05.07.2018 | # Han's Sydney Pty Limited |
| (2018 to date) | |

| | Lot C DP 448971 | | | | | | |
|----------------|--|--|--|--|--|--|--|
| Date | Registered Proprietor | | | | | | |
| 12.11.1911 | Reginald Campbell Galbraith (Merchant) | | | | | | |
| (1911 to 1925) | | | | | | | |
| 11.12.1925 | Wallace John Carson (Esquire) | | | | | | |
| (1925 to 1931) | (Transmission Application not investigated) | | | | | | |
| 29.04.1931 | The Permanent Trustee Company of New South Wales Limited | | | | | | |
| (1931 to 1959) | | | | | | | |
| 05.05.1959 | 130 Liverpool Street Pty Limited | | | | | | |
| (1959 to 1975) | | | | | | | |
| 26.05.1975 | Insula Australia Pty Limited | | | | | | |



| | Lot C DP 448971 | | | | | | |
|----------------|---------------------------------------|--|--|--|--|--|--|
| Date | Registered Proprietor | | | | | | |
| (1975 to 1981) | | | | | | | |
| 24.03.1981 | Bernard George Appleton (Manager) | | | | | | |
| (1981 to 1984) | Anne Burmond Appleton (Married Woman) | | | | | | |
| 09.04.1984 | Stephen George Rose | | | | | | |
| (1984 to 2012) | Stella Anne Rose | | | | | | |
| 01.03.2012 | Jinlida Investments Pty Ltd | | | | | | |
| (2012 to 2018) | | | | | | | |
| 16.08.2018 | # Han's Sydney Pty Limited | | | | | | |
| (2018 to date) | | | | | | | |

denotes current registered proprietor

3.3 Council Records

A copy of the Planning Certificates for representative properties within the Site were obtained from City of Sydney, and are included in **Appendix D**. Relevant information for the site is summarised below.

- The site is currently zoned B8 Metropolitan Centre under the Sydney Local Environmental Plan (LEP) 2012.
- Under the City of Sydney (LEP) 2012, the site cannot be developed without consent.
- The land is not affected by the Coastal Protection code under the Coastal Protection Act 1979.
- The land is not affected by Section 15 of the Mine Subsidence Compensation Act 1961 proclaiming land to be a Mine Subsidence District.
- The site is partially affected by road widening or road realignment under (a) Roads Act 1993 and (c) any resolution, i.e. Lot B DP 183853.
- The site is not affected by road widening or road realignment under (b) Any Environmental Planning Instrument.
- The land is not affected by policy adopted by the Council which restricts the development of the land because of the likelihood of bush fire, tidal inundation or subsidence.
- The land is not reserved for acquisition.
- The land is not declared to be significantly contaminated land and not subject to any management orders under the *Contaminated Land Management (CLM) Act 1997*. The land is not the subject of an approved voluntary management proposal or site audit statement within the meaning of the *CLM Act 1997*.

3.4 EPA Records

A search of the EPA's public register under the Protection of the Environment Operations Act 1997 was undertaken (**Appendix E**). The search identified that, for the site, there were:

- No prevention, clean-up or prohibition notices; and
- No transfer, variation, suspension, surrender or revocation of an environment protection licence.

A search was also undertaken through the EPA's public contaminated land register (**Appendix E**). The search identified that there have been no notices issued under the Contaminated Land Management Act 1997 (CLM Act) for the site. The site has not been notified to the EPA as containing significant contamination.



3.5 Australian and NSW Heritage Register

A search of the Australian Heritage Trust database and the NSW Heritage Inventory did not reveal any Heritage listed items at the site.

3.6 Integrity Assessment

The information obtained from the historical sources reviewed are in general agreement. Therefore, JBS&G consider that the information provided in this historical assessment has an acceptable level of accuracy.



4. Assessment of Potential Contamination

4.1 Potential Areas of Environmental Concern

Based on the history review and observations of the site, potential AECs and associated COPCs have been identified and are presented in **Table 5.1**.

Table 5.1: Areas of Environmental Concern and Contaminants of Potential Concern

| Area of Environmental Concern (AEC) | Contaminants of Potential Concern (COPC) | | | | | |
|---|--|--|--|--|--|--|
| Fill materials used to create current site levels | Heavy metals, TRH, BTEX, PAHs, OCPs, PCBs and asbestos | | | | | |
| Historical demolition of previous structures | Lead, asbestos | | | | | |

4.2 Potentially Contaminated Media

Surface soils/fill material are potentially contaminated media based upon:

- The unidentified sources of the fill material potentially imported to the site to establish current site levels and/or to backfill service trenches;
- Historical demolition of previous structures that potentially contained hazardous materials (lead, asbestos) which may have impacted underlying soils. It is noted that historical aerials indicate multiple structures at the site were demolished to construct the existing buildings, with the possible exception of the building in Lot B, DP183853, which appears to predate 1930; and
- Potential for a UST to have been abandoned in-situ and now covered by pavement.

Based on the potential leachability of identified contaminants in surface soils/fill material, vertical migration of those contaminants through the soil profile may occur. Consequently, natural soils underlying fill/surface soils are considered to be a potentially contaminated media.

The potential leachability of the identified contaminants of concern indicates groundwater and soil vapour are potentially contaminated media. The potential for contamination of groundwater and/or soil vapour will depend upon the actual nature, occurrence and characteristics of contamination within the overlying fill material and natural soils.

4.3 Potential for Migration

Contaminants generally migrate from site via a combination of windblown dusts, rainwater infiltration, groundwater migration and surface water runoff. The potential for contaminants to migrate is determined by:

- The nature of the contaminants (solid/liquid and mobility characteristics);
- The extent of the contaminants (isolated or widespread);
- The location of the contaminants (surface soils or at depth); and
- The site topography, geology, hydrology and hydrogeology.

The potential contaminant identified as part of the site history review are generally in either a solid form (e.g. heavy metals, asbestos) or liquid form (e.g. TRH from fuel, oil, lubricants etc). Dependent upon concentrations, there is the potential for TRH/VOC impacts to occur in vapour form underlying the site, although this is unlikely in the absence of significant soil/groundwater impacts.

The ground surface of the site is predominantly hardstand. As such, there is low potential for windblown contaminants to migrate from the site.

Migration of contaminants via groundwater is considered possible. Additionally, vapour generation associated with volatile and semi-volatile COPC (TRH, BTEX, VOCs) is identified as a potential migration pathway, particularly where there is evidence of a UST or where impacted fill is identified.



5. Discussion

The site is used for commercial purposes as offices with ground level food outlets and retail stores, and appears well maintained and in good condition. There were no odours or significant staining observed on the ground surfaces and no exposed surface soil. However, AECs were identified as part of the historical review and site inspection and are discussed further below.

Based on review of aerial photographs the site appears to have been used for commercial and/or residential purposes. There are no indications that industrial activities have been carried out at the site. Multiple structures appear to have been demolished historically, which indicates there is potential for contamination associated with hazardous building materials at the site. Historical aerials indicate structures have been demolished in all lots, with the possible exception of Lot B, DP183853, which contains a building appearing to predate the earliest available historical aerial image (1930). Additionally, a large number of underground services were evident at the site and there is a potential for contamination associated with potential importation of materials to backfill service trenches. Two underground carparks exist at the site that appear to have been excavated into natural materials. As such, areas not occupied by basement carparks are considered most likely to be affected by contamination associated with historical demolition of structures.

Additionally, there is potential for historical 'filling' activities associated with levelling of the sites to construct original site structures. The likelihood of this is unknown due to structures occupying the site since before the earliest available historical aerial (1930), and the original site topography being unknown. Redevelopment of the site over time would also likely have led to the removal of some historical impacts to the site.

If present, fill materials at the site would be of an unknown origin, and therefore have the potential to be contaminated. Impacts associated with historical filling may be present in all areas of site, outside of the footprint of basement car parks.



6. Conclusions and Recommendations

Based on the findings of this investigation and subject to the limitations in **Section 7**, the following conclusions are made:

- From a limited site inspection, the site generally appears well maintained and in good condition.
- While the potential for significant contamination at the site is low, a targeted program of
 intrusive investigations would be necessary to determine if contamination is present at the
 site. An intrusive investigation at the site should target potential fill materials in Dungate
 Lane, and within existing building footprints, with the exception of areas occupied by
 basement carparks.
- It is considered unlikely that activities at the site will have contaminated the land to a degree that would prevent the redevelopment of the site for mixed commercial and residential land-use.
- In the event that contamination is identified at the site, it is anticipated that the site can be made suitable for the proposed land uses.



7. Limitations

This report has been prepared for use by the client who has commissioned the works in accordance with the project brief only, and has been based in part on information obtained from the client and other parties.

The advice herein relates only to this project and all results conclusions and recommendations made should be reviewed by a competent person with experience in environmental investigations, before being used for any other purpose.

JBS&G accepts no liability for use or interpretation by any person or body other than the client who commissioned the works. This report should not be reproduced without prior approval by the client, or amended in any way without prior approval by JBS&G, and should not be relied upon by other parties, who should make their own enquiries.

Sampling and chemical analysis of environmental media is based on appropriate guidance documents made and approved by the relevant regulatory authorities. Conclusions arising from the review and assessment of environmental data are based on the sampling and analysis considered appropriate based on the regulatory requirements.


Limited sampling and laboratory analyses were undertaken as part of the investigations undertaken, as described herein. Ground conditions between sampling locations and media may vary, and this should be considered when extrapolating between sampling points. Chemical analytes are based on the information detailed in the site history. Further chemicals or categories of chemicals may exist at the site, which were not identified in the site history and which may not be expected at the site.


Changes to the subsurface conditions may occur subsequent to the investigations described herein, through natural processes or through the intentional or accidental addition of contaminants. The conclusions and recommendations reached in this report are based on the information obtained at the time of the investigations.

This report does not provide a complete assessment of the environmental status of the site, and it is limited to the scope defined herein. Should information become available regarding conditions at the site including previously unknown sources of contamination, JBS&G reserves the right to review the report in the context of the additional information.



Figures





Legend:

Approximate Site Boundary
Cadastre (NSW LPI, 2019)



Job No: 57557

Client: Hans Sydney Pty Ltd

Version: R01 Rev A Date: 22-Nov-2019

Drawn By: CA Checked By: CB

Scale 1:750



Coor. Sys. GDA 1994 MGA Zone 56

metres

338 Pitt Street, Sydney, NSW SITE LAYOUT

FIGURE 2



Appendix A Groundwater Bore Records

NSW Office of Water Work Summary

GW112175

Licence: 10BL158267 Licence Status: ACTIVE

Authorised Purpose(s): MONITORING BORE Intended Purpose(s): MONITORING BORE

Work Type: Bore
Work Status: Equipped

Construct Method:

Owner Type: Private

Commenced Date: Final Depth: Completion Date: 01/03/1999 Drilled Depth:

Contractor Name:

Driller: Unkown Unknown

Assistant Driller:

Property: N/A Standing Water Level: GWMA: Salinity: GW Zone: Yield:

Site Details

Site Chosen By:

CountyParishCadastreForm A: CUMBECUMBE.11//87644

Licensed:

Region: 10 - Sydney South Coast CMA Map:

River Basin: - Unknown Grid Zone: Scale:

Area/District:

 Elevation:
 0.00 m (A.H.D.)
 Northing:
 6250024.0
 Latitude:
 33°52'38.1"S

 Elevation Source:
 Unknown
 Easting:
 335131.0
 Longitude:
 151°13'02.5"E

GS Map: - MGA Zone: 0 Coordinate Source: Unknown

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

| - 3 | Tack, To Troccare Comented, C Camp, CE Contralicore | | | | | | | | | |
|-----|---|------|-----------|------|------|-----|----------|----------|----------|---------|
| Ì | Hole | Pipe | Component | Туре | From | То | Outside | Inside | Interval | Details |
| | | | ' | | (m) | (m) | Diameter | Diameter | | |
| | | | | | | l | (mm) | (mm) | | |

Water Bearing Zones

| From | То | Thickness | WBZ Type | S.W.L. | D.D.L. | Yield | Hole | Duration | Salinity |
|------|-----|-----------|----------|--------|--------|-------|-------|----------|----------|
| (m) | (m) | (m) | | (m) | (m) | (L/s) | Depth | (hr) | (mg/L) |
| 1 | | 1 | | 1 | | l | (m) | | 1 |

Geologists Log Drillers Log

| From To | | Thickness | Drillers Description | Geological Material | Comments | | |
|---------|-----|-----------|----------------------|---------------------|----------|--|--|
| (m) | (m) | (m) | · | _ | | | |

Remarks

17/07/2014: Nat Carling, 17-July-2014; Updated status, drill method & drilled depth.

*** End of GW112175 ***

Warning To Clients: This raw data has been supplied to the NSW Office of Water by drillers, licensees and other sources. The NOW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

NSW Office of Water Work Summary

GW200690

Licence: 20BL171676 Licence Status: ACTIVE

> Authorised Purpose(s): DOMESTIC Intended Purpose(s): DOMESTIC

Work Type: Spear

Work Status:

Construct Method:

Owner Type: Private

Final Depth: Commenced Date: Completion Date: 20/12/2007 Drilled Depth:

Contractor Name:

Driller: Jarrod Ronald Bright

Assistant Driller:

Property: 1/2-4 PACIFIC AVE ETTALONG

BEACH 2257

Salinity: GW Zone: Yield:

Site Details

Site Chosen By:

County **Parish** Cadastre Form A: CUMBÉ CUMBE.1 1//76609

Scale:

Licensed:

CMA Map: Region: 20 - Hunter

River Basin: - Unknown **Grid Zone:**

Area/District:

Latitude: 33°53'00.2"S Elevation: 0.00 m (A.H.D.) **Northing:** 6249340.0 Easting: 334928.0 Elevation Source: Unknown Longitude: 151°12'54.2"E

GS Map: -MGA Zone: 0 Coordinate Source: Map Interpretation

Standing Water Level:

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel

Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

| Hole | Pipe | Component | Type | From | То | Outside | Inside | Interval Details |
|------|------|-----------|------|------|-----|----------|----------|------------------|
| | | | | (m) | (m) | Diameter | Diameter | |
| | | | | | | (mm) | (mm) | |

Water Bearing Zones

| From | То | Thickness | WBZ Type | S.W.L. | D.D.L. | Yield | Hole | Duration | Salinity | ı |
|------|-----|-----------|----------|--------|--------|-------|-------|----------|----------|---|
| (m) | (m) | (m) | | (m) | (m) | (L/s) | Depth | (hr) | (mg/L) | ı |
| | | | | | | | (m) | | | ı |

Geologists Log

Drillers Log

| From | То | Thickness | Drillers Description | Geological Material | Comments |
|------|-----|-----------|----------------------|---------------------|----------|
| (m) | (m) | (m) | · | _ | |

Remarks

*** End of GW200690 ***

Warning To Clients: This raw data has been supplied to the NSW Office of Water by drillers, licensees and other sources. The NOW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

NSW Office of Water Work Summary

GW112180

Licence: 10BL158267 Licence Status: ACTIVE

Authorised Purpose(s): MONITORING BORE Intended Purpose(s): MONITORING BORE

Work Type: Bore
Work Status: Equipped

Construct Method:

Owner Type: Private

Commenced Date: Final Depth: Completion Date: 01/03/1999 Drilled Depth:

Contractor Name:

Driller: Unkown Unknown

Assistant Driller:

Property: N/A Standing Water Level: GWMA: Salinity: GW Zone: Yield:

Site Details

Site Chosen By:

CountyParishCadastreForm A: CUMBECUMBE.55 66692

Licensed:

Region: 10 - Sydney South Coast CMA Map:

River Basin: - Unknown Grid Zone: Scale:

Area/District:

 Elevation:
 0.00 m (A.H.D.)
 Northing:
 6249351.0
 Latitude:
 33°52'60.0"S

 Elevation Source:
 Unknown
 Easting:
 335167.0
 Longitude:
 151°13'03.5"E

GS Map: - MGA Zone: 0 Coordinate Source: Unknown

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

| - 3 | Tack, To Troccare Comented, C Camp, CE Contralicore | | | | | | | | | |
|-----|---|------|-----------|------|------|-----|----------|----------|----------|---------|
| Ì | Hole | Pipe | Component | Туре | From | То | Outside | Inside | Interval | Details |
| | | | ' | | (m) | (m) | Diameter | Diameter | | |
| | | | | | | l | (mm) | (mm) | | |

Water Bearing Zones

| - | | | <u> </u> | | | | | | | |
|-----|------|-----|-----------|----------|--------|--------|-------|-------|----------|----------|
| | From | То | Thickness | WBZ Type | S.W.L. | D.D.L. | Yield | Hole | Duration | Salinity |
| - 1 | (m) | (m) | (m) | | (m) | (m) | (L/s) | Depth | (hr) | (mg/L) |
| - 1 | | | | | | | | (m) | | |

Geologists Log Drillers Log

| From | То | Thickness | Drillers Description | Geological Material | Comments |
|------|-----|-----------|----------------------|---------------------|----------|
| (m) | (m) | (m) | | | |

Remarks

17/07/2014: Nat Carling, 17-July-2014; Updated status, drill method & drilled depth.

*** End of GW112180 ***

Warning To Clients: This raw data has been supplied to the NSW Office of Water by drillers, licensees and other sources. The NOW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

NSW Office of Water Work Summary

GW109238

Licence: 10BL602378 Licence Status: ACTIVE

Authorised Purpose(s): MONITORING BORE Intended Purpose(s): MONITORING BORE

Standing Water Level: 4.590

Work Type: Battery Spears, Filter Pack

Work Status:
Construct.Method: Auger
Owner Type: Private

Commenced Date: Final Depth: 7.50 m
Completion Date: 19/08/2008 Drilled Depth: 7.50 m

Contractor Name: INVIRODRILL

Driller: Lloyd Norman Whitsed

Assistant Driller:

Property: TEPCORP HOLDINGS PTY LTD

350-352 BOURKE STREET SURRY

HILLS 2010 NSW

GWMA: Salinity: Fresh
GW Zone: Yield:

Site Details

Site Chosen By:

CountyParishCadastreForm A: CUMBECUMBE.11//533894

Licensed:

Region: 10 - Sydney South Coast CMA Map:

River Basin: - Unknown Grid Zone: Scale:

Area/District:

Elevation:0.00 m (A.H.D.)Northing:6249391.0Latitude:33°52'58.6"SElevation Source:UnknownEasting:335069.0Longitude:151°12'59.7"E

GS Map: - MGA Zone: 0 Coordinate Source: Unknown

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

| | 0 1 100 | sour o o ormonico | i, o oump, or ochiralist | 5.0 | | | | | |
|------|---------|-------------------|--------------------------|-------------|-----------|------|--------------------|----------|---|
| Hole | Pipe | Component | Туре | From (m) | To (m) | | Inside Diameter | Interval | Details |
| | | | | | | (mm) | (mm) | | |
| 1 | | Hole | Hole | 0.00 | 7.50 | 150 | | | Auger |
| 1 | | Annulus | Waterworn/Rounded | 1.00 | 7.50 | | | | Graded |
| 1 | 1 | Casing | Pvc Class 18 | 0.00 | 1.50 | 50 | | | Seated on Bottom, Screwed |
| 1 | 1 | Opening | Slots - Horizontal | 1.50 | 7.30 | 50 | | | Slotted In Hole, PVC Class 18, SL: 5.8mm, A: 0.20mm |

Water Bearing Zones

| - 1 | | To (m) | Thickness (m) | WBZ Type | S.W.L. (m) | D.D.L. (m) | Yield (L/s) | Depth | Duration (hr) | Salinity (mg/L) |
|-----|------|-----------|------------------|----------|---------------|---------------|----------------|-------|------------------|--------------------|
| ŀ | 4.50 | 7.50 | 0.00 | | 4.50 | | | (m) | | |
| L | 4.50 | 7.50 | 3.00 | Unknown | 4.59 | | | | | |

Geologists Log Drillers Log

| Fr (m | | | Thickness (m) | Drillers Description | Geological Material | Comments |
|----------|------|------|------------------|----------------------|---------------------|----------|
| | 0.00 | 0.10 | 0.10 | ASHPHALT | Ash | |

| 0.10 | 0.40 | 0.30 | FILL,BRICK,SANDSTONE | Fill | | |
|------|------|------|----------------------|------|--------|--|
| 0.40 | 2.50 | 2.10 | CLAY BROWN | Cla | y Loam | |
| 2.50 | 7.50 | 5.00 | SHALE, RED/GREY | Sha | ale | |

Remarks

*** End of GW109238 ***

Warning To Clients: This raw data has been supplied to the NSW Office of Water by drillers, licensees and other sources. The NOW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

NSW Office of Water Work Summary

GW109239

Licence: 10BL602379 Licence Status: ACTIVE

Authorised Purpose(s): MONITORING BORE Intended Purpose(s): MONITORING BORE

Work Type: Bore
Work Status:

Construct.Method: Auger
Owner Type: Private

Commenced Date: Final Depth: 7.45 m **Completion Date:** 19/08/2008 **Drilled Depth:** 7.45 m

Contractor Name: INVIRODRILL

Driller: Lloyd Norman Whitsed

Assistant Driller:

Property: TEPCORP HOLDINGS PTY LTD 4 - **Standing Water Level:** 4.570

12 HILL STREET SURRY HILLS

2010 NSW

GWMA: Salinity: Fresh
GW Zone: Yield:

Site Details

Site Chosen By:

CountyParishCadastreForm A: CUMBECUMBE.12//78252

Licensed:

Region: 10 - Sydney South Coast CMA Map:

River Basin: - Unknown Grid Zone: Scale:

Area/District:

Elevation: 0.00 m (A.H.D.)

Northing: 6249385.0

Elevation Source: Unknown

Northing: 6249385.0

Easting: 335107.0

Latitude: 33°52'58.8"S

Longitude: 151°13'01.2"E

GS Map: - MGA Zone: 0 Coordinate Source: Unknown

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

| . aon, i | | sour o o ormonico | i, o oump, or ochiralist | 5.0 | | | | | |
|----------|------|-------------------|--------------------------|-------------|-----------|------|--------------------|----------|---|
| Hole | Pipe | Component | Туре | From (m) | To (m) | | Inside Diameter | Interval | Details |
| | | | | | | (mm) | (mm) | | |
| 1 | | Hole | Hole | 0.00 | 7.45 | 150 | | | Auger |
| 1 | | Annulus | Waterworn/Rounded | 1.00 | 7.45 | | | | Graded |
| 1 | 1 | Casing | Pvc Class 18 | 0.00 | 1.50 | 50 | | | Seated on Bottom, Screwed |
| 1 | 1 | Opening | Slots - Horizontal | 1.50 | 7.20 | 50 | | | Slotted In Hole, PVC Class 18, SL: 5.7mm, A: 0.20mm |

Water Bearing Zones

| - 1 | From (m) | | Thickness (m) | WBZ Type | S.W.L. (m) | Yield (L/s) | Hole Depth (m) | Duration (hr) | Salinity (mg/L) |
|-----|-------------|------|------------------|----------|---------------|----------------|----------------------|------------------|--------------------|
| İ | 3.00 | 7.40 | 4 40 | Unknown | 4.57 | | ` ′ | | |

Geologists Log Drillers Log

| -11 | From (m) | | Thickness (m) | Drillers Description | Geological Material | Comments |
|-----|-------------|------|------------------|----------------------|---------------------|----------|
| I | 0.00 | 0.10 | 0.10 | ASHPHALT | Ash | |

| L | 0.10 | 0.60 | 0.50 | FILL BROWN,GRAVEL,CLAY | Fill | |
|---|------|------|------|------------------------------------|-----------|--|
| | 0.60 | 2.90 | 2.30 | CLAY BROWN ORANGE, RED, SILT MOIST | Clay Loam | |
| Γ | 2.90 | 7.45 | 4.55 | SHALE RED,GREY, CLAY BANDS | Shale | |

Remarks

*** End of GW109239 ***

Warning To Clients: This raw data has been supplied to the NSW Office of Water by drillers, licensees and other sources. The NOW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

NSW Office of Water Work Summary

GW109086

Licence: 10BL602334 Licence Status: ACTIVE

> Authorised Purpose(s): MONITORING BORE Intended Purpose(s): MONITORING BORE

Work Type: Bore Work Status: Construct Method:

Owner Type: Other Govt

Final Depth: 5.68 m Commenced Date: Completion Date: 22/07/2008 Drilled Depth: 5.68 m

Contractor Name: CH2M HILL

GW Zone:

Driller: Unkown Unknown

Assistant Driller:

Property: SYDNEY WATER 21 - 25 SUSSEX

STREET SYDNEY 2000 NSW

Salinity: Yield:

Standing Water Level:

Site Details

Site Chosen By:

County **Parish** Cadastre Form A: CUMBÉ CUMBE.53 1//87659

Scale:

Licensed:

CMA Map:

Region: 10 - Sydney South Coast River Basin: - Unknown **Grid Zone:**

Area/District:

Northing: 6251262.0 Latitude: 33°51'57.2"S Elevation: 0.00 m (A.H.D.) Elevation Source: Unknown **Easting**: 333781.0 Longitude: 151°12'10.8"E

GS Map: -MGA Zone: 0 Coordinate Source: Unknown

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

| Hole | Pipe | Component | Туре | | To (m) | Diameter | Interval | Details |
|------|------|-----------|--------|------|-----------|----------|--------------|---------|
| 1 | | Hole | Hole | 0.00 | 5.80 | 120 | | Unknown |
| 1 | 1 | Casing | P.V.C. | 0.00 | 3.20 | 40 | | |

Water Bearing Zones

| From | То | Thickness | WBZ Type | S.W.L. | D.D.L. | Yield | Hole | Duration | Salinity |
|------|-----|-----------|----------|--------|--------|-------|-------|----------|----------|
| (m) | (m) | (m) | | (m) | (m) | (L/s) | Depth | (hr) | (mg/L) |
| 1 | l | | | | l | l | (m) | | |

Geologists Log Drillers Loa

| | | ~ 9 | | | |
|-----|---------|-----------|-------------------------------|---------------------|----------|
| | m To | Thickness | Drillers Description | Geological Material | Comments |
| (m) | (m) | (m) | | | |
| 0. | 0.50 | 0.50 | FILL,MEDIUM TO COARSE | Fill | |
| 0. | 50 1.00 | 0.50 | FILL,SILTY SAND | Fill | |
| 1. | 00 1.80 | 0.80 | FILL,CLAYEY SAND FINE GRAINED | Fill | |
| 1. | 80 2.00 | 0.20 | FILL,GRAVELLY SAND | Fill | |
| 2. | 00 3.20 | 1.20 | FILL,SAND WITH SOME SILT | Fill | |
| 3. | 20 3.80 | 0.60 | FILL SILTY SAND | Fill | |

| 3.80 | 4.50 | 0.70 FILL CLAY SILT SAND MIXTURE | Fill | |
|------|------|-----------------------------------|------|--|
| 4.50 | 5.68 | 1.18 SAND, FINE TO MEDIUM GRAINED | Sand | |

Remarks

*** End of GW109086 ***

Warning To Clients: This raw data has been supplied to the NSW Office of Water by drillers, licensees and other sources. The NOW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

NSW Office of Water Work Summary

GW113599

Licence: 10BL604366 Licence Status: ACTIVE

> Authorised Purpose(s): MONITORING BORE Intended Purpose(s): MONITORING BORE

Work Type: Bore Work Status: Equipped

Construct Method:

Owner Type: Private

Commenced Date: Final Depth: Completion Date: 09/02/2010 Drilled Depth:

Contractor Name:

Driller: Unkown Unknown

Assistant Driller:

Property: BARANGAROO DELIVERY Standing Water Level:

AUTHORITY WHARF 8 HICKSON

ROAD BARANGAROO 2000 NSW

GWMA: Salinity: GW Zone: Yield:

Site Details

Site Chosen By:

Parish Cadastre County Form A: CUMBÉ CUMBE.53 5//876514

Licensed:

Region: 10 - Sydney South Coast CMA Map:

River Basin: - Unknown Grid Zone: Scale:

Area/District:

Elevation: 0.00 m (A.H.D.) **Northing:** 6251505.0 Latitude: 33°51'49.2"S Elevation Source: Unknown **Easting:** 333687.0 Longitude: 151°12'07.3"E

GS Map: -MGA Zone: 0 Coordinate Source: Unknown

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

| Hol | e Pipe | Component | Туре | From | То | Outside | Inside | Interval | Details |
|-----|--------|-----------|------|------|-----|----------|----------|----------|---------|
| - | | | | (m) | (m) | Diameter | Diameter | | |
| | | | | | | (mm) | (mm) | | |

Water Bearing Zones

| From | То | Thickness | WBZ Type | S.W.L. | D.D.L. | Yield | Hole | Duration | Salinity |
|------|-----|-----------|----------|--------|--------|-------|-------|----------|----------|
| (m) | (m) | (m) | | (m) | (m) | (L/s) | Depth | (hr) | (mg/L) |
| 1 | | | | | ' ' | | (m) | ' ' | |

Geologists Log

Drillers Loa

| From | То | Thickness | Drillers Description | Geological Material | Comments |
|------|-----|-----------|----------------------|---------------------|----------|
| (m) | (m) | (m) | · | | |

Remarks

31/07/2014: Nat Carling, 31-July-2014; Added status, drill method, depth & updated work type.

*** End of GW113599 ***

Warning To Clients: This raw data has been supplied to the NSW Office of Water by drillers, licensees and other sources. The NOW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

NSW Office of Water Work Summary

GW109649

Licence: 10BL602485 Licence Status: ACTIVE

Authorised Purpose(s): MONITORING BORE Intended Purpose(s): MONITORING BORE

Work Type: Bore Work Status:

Construct.Method: Auger - Hollow Flight

Owner Type: Private

Commenced Date: Final Depth: 7.20 m
Completion Date: 03/05/2008 Drilled Depth: 7.20 m

Contractor Name: ENVIRONMENT INVESTIGATION

SERVICES

Driller: Nicholas Alexander Kontos

Assistant Driller:

Property: WEST APARTMENTS PTY LTD 485 Standing Water Level: 2.950

- 511 WATTLE STREET ULTIMO

2007 NSW

GWMA: Salinity: GW Zone: Yield: 1.000

Site Details

Site Chosen By:

CountyParishCadastreForm A: CUMBECUMBE.451//546296

Licensed:

Region: 10 - Sydney South Coast CMA Map:

River Basin: - Unknown Grid Zone: Scale:

Area/District:

 Elevation:
 0.00 m (A.H.D.)
 Northing:
 6249352.0
 Latitude:
 33°52'58.9"S

 Elevation Source:
 Unknown
 Easting:
 333320.0
 Longitude:
 151°11'51.6"E

GS Map: - MGA Zone: 0 Coordinate Source: Unknown

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

| Hole | Pipe | Component | Туре | | To (m) | | Inside Diameter (mm) | Interval | Details |
|------|------|-----------|--------------------|------|-----------|-----|----------------------------|----------|--|
| 1 | | Hole | Hole | 0.00 | 7.20 | 100 | | | Auger - Hollow Flight |
| 1 | | Annulus | Waterworn/Rounded | 1.00 | 7.20 | | | | Graded |
| 1 | 1 | Casing | Pvc Class 18 | 0.00 | 1.10 | 61 | 51 | | Seated on Bottom, Screwed |
| 1 | 1 | Opening | Slots - Horizontal | 1.10 | 7.20 | 61 | | | Casing - Machine Slotted, PVC Class 18, Screwed, SL: 42,0mm, A: 0,20mm |

Water Bearing Zones

| - 1 | | To (m) | Thickness (m) | WBZ Type | S.W.L. (m) | Yield (L/s) | | Salinity (mg/L) |
|-----|------|-----------|------------------|----------|---------------|----------------|------|--------------------|
| | 3.20 | 6.20 | 3.00 | Unknown | 2.95 | 1.00 | | |

Geologists Log Drillers Log

| From (m) | To (m) | Thickness (m) | Drillers Description | Geological Material | Comments |
|-------------|-----------|---------------|----------------------|---------------------|----------|
| | | | | | |

| | 0.00 | 4.80 | 4.80 | FILL,GREY,BROWN,GRAVEL,CLAY,SILT | Fill | |
|---|------|------|------|-----------------------------------|-----------------|--|
| ſ | 4.80 | 5.90 | 1.10 | SILTY SAND,LT GREY,RED,MED COARSE | Silty Sandstone | |
| L | | | | GRAINED | | |
| ſ | 5.90 | 7.20 | 1.30 | SANDSTONE RED BROWN,WEATHERED | Sandstone | |
| - | | | | WITH CLAY BANDS | | |

Remarks

*** End of GW109649 ***

Warning To Clients: This raw data has been supplied to the NSW Office of Water by drillers, licensees and other sources. The NOW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.



Appendix B Aerial Photographs







Approximate Site Boundary




Job No: 57557

Client: Hans Sydney Pty Ltd

Version: Aerials Date: 22-Nov-2019

Drawn By: CA Checked By: CB

Scale 1:1,500



Coor. Sys. GDA 1994 MGA Zone 56

338 Pitt Street, Sydney, NSW

HISTORICAL AERIAL IMAGERY - 1943



Approximate Site Boundary



Job No: 57557

Client: Hans Sydney Pty Ltd

Version: Aerials Date: 22-Nov-2019

Drawn By: CA Checked By: CB

Scale 1:1.500




Coor. Sys. GDA 1994 MGA Zone 56

338 Pitt Street, Sydney, NSW

HISTORICAL AERIAL IMAGERY - 1961





Approximate Site Boundary



Job No: 57557

Client: Hans Sydney Pty Ltd

Date: 22-Nov-2019 Version: Aerials

Checked By: CB Drawn By: CA


Scale 1:1.500



Coor. Sys. GDA 1994 MGA Zone 56

338 Pitt Street, Sydney, NSW

HISTORICAL AERIAL **IMAGERY - 1986**



Approximate Site Boundary



Job No: 57557

Client: Hans Sydney Pty Ltd

Version: Aerials Date: 22-Nov-2019

Drawn By: CA Checked By: CB

Scale 1:1.500




0 20 40 metres

Coor. Sys. GDA 1994 MGA Zone 56

338 Pitt Street, Sydney, NSW

HISTORICAL AERIAL IMAGERY - 1994



Approximate Site Boundary



Job No: 57557


Client: Hans Sydney Pty Ltd

Version: Aerials Date: 22-Nov-2019

Drawn By: CA Checked By: CB

Scale 1:1.500






Coor. Sys. GDA 1994 MGA Zone 56

338 Pitt Street, Sydney, NSW

HISTORICAL AERIAL IMAGERY - 2005



Approximate Site Boundary




Job No: 57557

Client: Hans Sydney Pty Ltd

Version: Aerials Date: 22-Nov-2019

Drawn By: CA Checked By: CB

Scale 1:1,500



Coor. Sys. GDA 1994 MGA Zone 56

338 Pitt Street, Sydney, NSW

HISTORICAL AERIAL IMAGERY - 2016