The following drawings provide a comparison between the originally submitted DA drawings and the current drawings, by a visual overlay.

Primarily changes comprise of:


- refinements to the internal planning;
- refinment of plant layouts in level 8 effecting roof top exhaust cluster locations;
- minor dimensional adjustments to suit design development detailing.

More significant adjustments include:

- refinment of south-west corner entry stucture (impacts are internal to the building) reducing the bulk of structure on this corner;
- extending width of existing external southern stairs on Level 2 to address proportion of the southern entry properly.


The overall dimension, heights, materials, and facade setout is consistent with the original drawings.

In addition to these drawings, updated shadow diagrams have been provided clearly articulating the shadow projected by the new building compared to existing context.




## Updated DA drawing overlay behind original DA for comparison of changes





## Updated DA drawing overlay behind original DA for comparison of changes










## Updated DA drawing overlay behind original DA for comparison of changes





Cheury Access
Code Compliance
B M - 6 Pty Ltd
Commissionce
B M - 6 Pty Ltd






SCREPANCIES REFER TO ARCHITECT PRIOR TO COMMENCEMENT OF THE WORK.

WINGS MANUALLY OR ELECTRONICALLY.

C1vv(12016)15H LEES 1\_BASE BUILDING\_sameh.hosny@hdrinc.com.nvt



DREPARTIES REPORT OF THE WORK.

C. Invit 2016/15H LEES 1\_BASE BUILDING\_sameh.hosny@hdrinc.com.n.

