

**Subject:** MPW 2 B111 and B112 - RSA and Pedestrian access  
**Date:** Monday, 12 October 2020 at 10:44:24 am Australian Eastern Daylight Time  
**From:** Richard Johnson  
**To:** Shiraz Ahmed  
**CC:** Jake Shackleton, Mathew Williams, Tracy Davey, Steve Ryan  
**Priority:** High  
**Attachments:** image001.png, image002.png, IMG\_8717.HEIC, IMG\_8720.HEIC, IMG\_8723.HEIC, IMG\_8724.HEIC, IMG\_8726.HEIC, IMG\_8727.HEIC, IMG\_8728.HEIC, IMG\_8731.HEIC

Hi Shiraz,

As a follow up to the questions on the RSA findings please see the attached images identifying the absence of pedestrian connectivity across Moorebank Ave and/or Chatham Avenue at the Chatham Avenue construction access.

Note:

- there is no pedestrian access across and over the bridge over the East Hills line to the south.
- There is no pedestrian walkway running north south on the eastern (MPE) side of Moorebank Ave.
- Pedestrian access north of Chatham road (img\_8720) stops at Chatham Ave.

There is therefore no response to the audit improvement opportunity finding re: pedestrian timings on lights at this intersection as there is no pedestrian access utilising this intersection, as previously discussed.

Please close out the RFI as requested.

Regards

Richard Johnson  
Director  
**M: 0409 051 535**

[richard@aspectenvironmental.com.au](mailto:richard@aspectenvironmental.com.au)



Suite 117,  
25 Solent Circuit  
Baulkham Hills  
NSW 2153

[www.aspectenvironmental.com.au](http://www.aspectenvironmental.com.au)





Figure 1 View north Across Chatham from western side of Moorebank Ave showing termination of pedestrian path



Figure 2 View south from Chatham Ave along western side of Moorebank Ave showing no continuity of pedestrian path



*Figure 3 View west along Chatham Ave from eastern side of Moorebank Ave showing termination of pedestrian path*



*Figure 4 View south from Chatham Ave intersection along eastern side of Moorebank Ave showing absence of pedestrian path*



Figure 5 View south from Chatham Ave along eastern side of Moorebank Ave showing absence of pedestrian path



Figure 6 View north from Chatham Ave along eastern side of Moorebank Ave showing absence of pedestrian path



Figure 7 View north from Chatham Ave along western side of Moorebank Ave showing terminating pedestrian path



*Figure 8 View south from northern side of Chatham Ave along western side of Moorebank Ave showing no continuation of pedestrian path*