



File Ref. No: FRN24/2357 BFS25/7150 8000045727
TRIM Doc. No: D25/124124
Contact: Station Officer Chris Naisby

20 October 2025

WALED ELSOUKI
Lehr Consultants International (Australia) Pty Ltd
Level 5, 73 Miller Street
NORTH SYDNEY, NSW 2060

Dear Waled,

Re: Review of Fire Safety Study (FSS) - SYD086 DC01 – 2 GLENDENNING ROAD, GLENDENNING NSW 2761

Fire and Rescue NSW (FRNSW) acknowledge correspondence received on 3 October 2025 requesting review of the submitted FSS (Revision E) for SYD086 DC01 – 2 GLENDENNING ROAD, GLENDENNING NSW 2761. FRNSW note the FSS was to be developed to the satisfaction of FRNSW and in accordance with the Hazardous Industry Planning Advisory Paper (HIPAP) No. 2¹.

FRNSW have reviewed the FSS prepared by LCI Consultants Sydney Office. The current version of the FSS **has been prepared to the satisfaction of FRNSW.**

For further information please contact the Fire Safety Liaison Unit, referencing FRNSW file number BFS25/7150. Please ensure that all correspondence in relation to this matter is submitted electronically to firesafety@fire.nsw.gov.au.

Yours sincerely,

A handwritten signature in black ink, appearing to read "James O'Carroll".

Superintendent James O'Carroll
Manager
Fire Safety Liaison Unit

Cc: waled.elsouki@lciconsultants.com.au

¹ <https://www.planning.nsw.gov.au/sites/default/files/2023-03/hazardous-and-offensive-planning-advisory-paper-no-2-fire-safety-study-guidelines.pdf>