

31 July 2019

Jason Maslen Senior Planning Officer | Social and Infrastructure Assessments Infrastructure Assessments GPO Box 39 Sydney NSW 2000

Dear Mr Maslen,

Re: SSD-8996 - Loreto Normanhurst - 91-93 Pennant Hills Road and 6-12 Mount Pleasant Avenue, Normanhurst.

I refer to the above development proposal and provide the following comments from Council.

Planning

The proposed development is inconsistent with DA/1227/2018 for an 80 place child care centre on the school site which relies on existing car parking within the Loreto School site. Details of the proposed child care centre needs to be considered with the proposed SSD application.

The proposed boarding house building would result in excessive height, bulk and scale when viewed from adjacent properties in Mount Pleasant Avenue.

Heritage

The Loreto Convent Group at 91-93 Pennant Hills Road and 16-22 Mount Pleasant Avenue, Normanhurst is included as a local heritage item (Built, Archaeological and Landscape Item No. 607) in Part 1 - Heritage Items and in Part 3 – Archaeological Sites, in Schedule 5 of the Hornsby Local Environmental Plan 2013 (HLEP).

The site is not located within the vicinity of heritage properties, including No.82 Pennant Hills Road (Item 606) and No.4 Mount Pleasant Avenue (Item 603), Normanhurst listed under Schedule 5 of H LEP.

The Conservation Management Plan (CMP) prepared by Perumal Murphy Alessi dated July 2008 and Heritage Impact Statement (HIS) prepared by Weir Phillips Heritage January 2019 submitted with the documentation has been reviewed and heritage comment is provided in the tables below.

Concept Master Plan

Proposal/Concept	Comment
New Boarding house	Concerns raised under Stage 1 comment below
Upgrade Mary Ward	The limited information provided does not clearly detail the impact of the
Wing building to	proposed changes to the fabric to enable assessment. Change should be limited,
accommodate year 12	reversible and include reinstatement of former floor plan wherever possible and
boarders. Addition of	include interpretation. Existing floor plans and elevations to scale should be
another level above	provided.
existing building.	Concern is raised to the addition of another level to this building as it would alter
	the original form of the building and appearance.
Remove dock to create	No heritage concern raised.
new courtyard	
Early learning centre	Heritage comment provided under separate DA lodged.
(ELC)	

New Primary School	Could be considered on merits, subject to details of proposal, scale and
buildings	assessment of impacts.
All weather field,	Could be considered on merits, subject to details of proposal and assessment of
underground carpark &	impacts.
possible facilities	
management, located	
off Osborn Road.	
Mount Pleasant	Could be considered on merits, subject to details of proposal and assessment of
Pavilion, Stadium,	impacts.
function centre	
possible facilitates	
management or ECO	
centre	
Relocate main	Insufficient detail is provided to enable assessment of impact of proposed
reception, staff and	changes to the original 1897 convent building and Angel wing building.
administration to	These works do not appear to be consistent with the CMP policies for
eastern side of 1897	conservation of the highly significant fabric of the convent. There is also limited
convent building.	proposed conservation works, maintenance, interpretation plans detailed in the
Removal of level 5	Master plan.
toilet block above 1897	The Convent and Angel wing building should not be further altered or lost without
convent building.	detailed assessment of remaining original fabric. Conservation works should
Convent ballang.	include reinstatement of removed original elements and the original spatial
	relationship with the 1897 convent building.
	Subject to detailed information being provided the removal of unsympathetic
	elements would be considered.
	These works should not be supported without adequate detailed plans and fabric analysis. No works should occur that are not consistent with the
Now 2 court gum 9	CMP policies or Burra Charter principles.
New 3 court gym &	Could be considered on merits, subject to details of proposal and assessment of
multi-use hall	impacts.
Reduce roadways	Could be considered on merits subject to detailed landscape heritage report and
within campus, new	assessment to the heritage listed Loreto College grounds.
paths and landscaping.	
Secondary school	The development of this area in proximity to the heritage listed chapel would
expansion adjacent to	have an adverse impact on the setting of the chapel and the relationship with the
the Chapel building	original convent and Angel wing building. The development of this area would
the Chaper building	have an adverse cumulative impact, in addition to the current unsympathetic
	impact of the circa 1980/90s administration wing. No further development should
	occur in this area to maintain the significance of the built items and the
	landscaped grounds. Overall, the front of the school should remain undeveloped
	and landscaped. This component of the master plan should not be
Envolono 2 Futura	supported in heritage terms. The proposed concept development is of a height and scale that would be out of
Envelope 3 – Future	The proposed concept development is of a height and scale that would be out of
development (adjacent	character with the scale of the heritage items on the site. The structure would
Pennant Hills Road;	adversely impact the landscaped setting of the convent and chapel on the
north east of the	northern and eastern sections of the site. The listed grounds would also be
convent and chapel) to	adversely impacted, as well as the original setting of the listed entry and gates.
be determined;	Development in this section should remain largely landscaped as a link to the
underground carpark	original setting and understanding of the site. This development could also
	irreversibly remove potential for historic views of the convent to be revealed. In
	addition, views internally from the Covent and chapel area out of the site would
	be adversely impacted, by the proposed building.
	It is suggested that proposed future buildings for this area be located elsewhere.
	For example, in Mount Pleasant Avenue adjacent the new ELC, and the current
	sports courts in Mount Pleasant Avenue relocated to Envelope 3 and
	landscaped. Alternatively, locate new buildings to Envelope 9, 7 or 6.
	The redevelopment proposed would have an adverse impact and is not
	supported in heritage terms.

Gonzaga Barry Centre auditorium; Amphitheatre; possible ECO centre	Could be considered on merits, subject to details of proposal and assessment of impacts.
Bush Chapel & bush recreational facilities	The CMP 2008 policy states "no new buildings or built elements are permissible within the existing bushland located in the southern portion of the site. No additions or alterations to the cemetery, its size or perimeter walls are permissible." Development of the bushland for a new chapel and the like should not be supported. The addition of further structures would have an adverse impact on the natural heritage values of the bushland and the 'isolated' setting of the listed cemetery.
Upgrade aquatic centre	Could be considered on merits, subject to details of proposal and assessment of impacts.

Stage 1 Application

Proposal Proposal	Comment
Demolition of the Loreto	The buildings to be demolished are documented as having no heritage
Community House and	value. The new boarding house building is of a significantly larger scale
construction of a 3 to 6 story	than the original heritage buildings on the site and appear to be
boarding house for 216	inconsistent with the form and appearance of the original buildings.
students, with underground	A revised form, height and scale should be considered to
car park and new	complement the scale and style of the earliest buildings on the site.
landscaping.	
New Garden area – Removal	The buildings to be demolished are documented as having little heritage
of buildings between Mary	significance due to past alterations and additions. No heritage issues are
Ward Wing and existing	raised to their removal or new garden area, subject to archival
dining room building	photographic recording of all affected areas (internally and externally) prior
(Givendale wing) and	to any demolition or removal of all structures on the site. This would enable
associated works to make	the evolution of the site to be documented.
good the existing.	and dividuality of the olde to be decumented.
New landscaping located in	No heritage concerns raised with the circa 1990s primary school car park
the current primary school	landscaping.
carpark, designed to allow for	idiluscaping.
outdoor assembly of the	
_	
whole school population.	The second of the little Park II have a constitution for the second of
Removal and replacement of	Tree removal should be limited wherever possible and replacement of
approximately 50 trees of	trees removed is supported. No significant trees should be removed, and
varying significance.	the heritage listed grounds as listed on the heritage inventory sheet for the
	grounds should be retained. Comment from Council's Tree Management
	team should be sought.
Augmentation of connection	Should occur only in accordance with the CMP policy for services.
of services and utilities	
infrastructure	

Heritage in the vicinity

The scale of future development in the Master concept plan (Envelope 3) has the potential to adversely alter the residential low scaled setting of the heritage item in the vicinity at No. 4 Mount Pleasant Avenue, Normanhurst.

Summary

Heritage concerns are raised to several proposed works within the State Significant Development application (Stage 1) and concept master plan which would have an adverse impact on the significance and setting of the item. Concern is raised to the form and scale of the boarding house; additional structures within the remnant bushland; redevelopment of the original Covent building, and circa 1920s/1950s buildings on the site. The development of the site to the north and north east of the convent and chapel buildings and area north west of the chapel is not supported due to the adverse impact on the listed grounds and setting of the significant buildings on the site. The proposal should be amended to remove the adverse heritage impacts the proposed redevelopment would have on the listed site as follows:

- 1. The Master plan and stage 1 proposal should be amended to address the heritage concerns raised.
- 2. Archival photographic recording in accordance with Office and Environment and Heritage (OEH) guidelines should be required prior to any demolition works (internal and externally) to any structure on the listed site.
- 3. Augmentation of connection of services and utilities infrastructure is to occur only in accordance with the Conservation Management Plan 2008 (CMP) policy for services.

Trees

Council raises concerns with the loss of high retention value trees on the site.

Traffic and Safety

Council has previously received submissions from residents raising concerns with the following issues:

- a) Traffic generation and volumes in residential streets.
- b) On-street parking in residential streets.
- c) Vehicle access to the site.
- d) Safety concerns at the Pennant Hills Road / Mount Pleasant Avenue intersection.

The Traffic Assessment report (TAR) prepared by Asongroup needs to be updated to include the following:

- a) Existing pick up operation is to be reviewed and improved.
- b) With a 42.5% increase in students it can be argued that there will be a significant increase in queue length, this is not acceptable to the Branch as it would result in the pickup queue extending onto Osborn Road. Council has received many complaints from local residents regarding queuing onto Osborn Road issue during pickup time.
- c) ELC Operational Traffic Management Plan will be impacted by the Master Plan of Loreto. Although the Master Plan excludes the DA of ELC, staff of ELC will rely on car parking areas in Loreto. The TAR needs to have a discussion regarding the future impact to ELC staff parking.
- d) Will there be dedicated bus services for Loreto Normanhurst students?
- e) If so how are the buses to be catered for?
- Date of traffic counts has not been provided and is required.

Please contact me on telephone 9847-6731 or email rpickles@hornsby.nsw.gov.au should you wish to discuss this matter further.

Yours sincerely

R PICKLES

Manager Assessments

Planning Division

TRIM Reference: P2017/02310