

Observation of Proposed Route conducted by Chris and Jackie Neill on Sunday 4th August 2013

Table 1 Audit of submitted route inventory by Mutliquip – Oallen Ford Road – Windellama Road – Brisbane Grove Road.

Distance from Quarry Gates	Local Road Feature
6.5	Causeway; Significant dip in roadway and 5.8 meter carriageway only allows for one way passing traffic.
8.8	Oallen Road Shop; Carriageway 6.1 meters. Traffic hazards of Crest of small hill, Crossroads of Jacqua and Yarralaw Roads, and 2 driveways for incoming and outgoing shop traffic.
10.9	Concealed Driveway with warning sign; very uneven road edge in northbound lane.
15.3	Approaching crest; no centreline
16.2	Approaching crest; no centreline
17.5	Carriageway width 5.9 meters
18.1	Carriageway width 6.0 meters
19.8	Carriageway width 5.7 meters
21	Windellama School; carriageway width 5.6 meters
22.9	Carriageway width 6.6 meters
24.4	Carriageway width 6.3 meters
26.5	Floodway; carriageway width 5.9 meters with significant dip in roadway and water damaged asphalt
31	Carriageway width 6.8 meters and no shoulder
36	Carriageway width 7.3 meters
37	Carriageway width 6.5 meters
39.2	Carriageway width 6.5 meters
41	Carriageway width 7.4 meters
46	Carriageway width 7.3 meters
48	Fife's Bridge at Gundary Creek; carriageway width 6.2 meters with high concrete edges
52.5	Carriageway width 6.5 meters
53.6	Carriageway width 5.7 meters
54.3	Carriageway width 5.7 meters