

05 December 2014

Lend Lease Construction and Infrastructure

Level 4, 30 The Bond 30 Hickson Road Millers Point NSW 2000

Attn: Mr. William Walker

Project: Building C3, Barangaroo South

Dear Mr. Walker,

Please find herein comments regarding the expected wind conditions for the architectural changes to the external podium architectural elements on Building C3, Barangaroo South. The architectural drawings, prepared have been reviewed and from an environmental wind perspective at ground level, the only relevant geometric change is the relatively minor increase in size of the north lobby awning.

These minor changes are expected to have a negligible impact on the local wind conditions at ground level or on the podium. The increase in size of the awning would provide additional protection to wind and wind driven rain. Any major geometric changes to the geometry of the surrounding building would have a greater impact on the environmental wind conditions than the minor alterations proposed to the podium of Building C3. The environmental wind conditions described in the previous wind-tunnel reports are considered valid for the proposed changes to Building C3.

I hope this is of assistance, please do not hesitate to contact me if you have any questions regarding any aspect of this report.

Yours sincerely,

Need.

Graeme Wood Director

CPP Project 6029