

21 October 2020

Jackson Environment and Planning Pty Ltd Suite 102, Level 1, 25 Berry Street

**NORTH SYDNEY NSW 2060** 

**ATTENTION: JILL LETHLEAN** 

RE: RESOURCE RECOVERY FACILITY & TRUCK PARKING DEPOT

21D SCHOOL DRIVE, TOMAGO

**CAPITAL INVESTMENT VALUE ESTIMATE REV 2** 

As per your request dated 18<sup>th</sup> September 2020, Muller Partnership has updated the Capital Investment Value (CIV) Estimate as required by the planning authority for the above development totalling \$8,975,468 (excl. GST) and enclose our report.

This estimate has been prepared in accordance with the EPAA 2000 and SEPP (CIV) 2010 with consideration for the Planning Circular PS10-008.

The purpose of this assessment is to determine the current construction cost value of the development for council purposes only and is not to be used for project budgeting, finance, insurance, sale, mortgage or any other purposes.

Should you wish to discuss any of the above please do not hesitate to contact the undersigned.

Yours faithfully

**MULLER PARTNERSHIP** 


PETER DALLY- DIRECTOR

PD: NW 20235 Resource Recovery Facility & Truck Parking deport - CIV Estimate Rev2



# MULLER partnership

Newcastle | Sydney | Melbourne



#### Disclaimer

Muller Partnership have prepared this report in part on the basis of information supplied to it in the ordinary course of business by Jackson Environment and Planning Pty Ltd.

Whilst all reasonable professional care and skill have been exercised to validate its accuracy and authenticity, Muller Partnership is unable to provide any Guarantee in that regard, and will not be liable to any party for any loss arising as a result of any such information subsequently being found to be inaccurate, lacking authenticity or having been withheld.

This report is only intended for use by the Jackson Environment and Planning Pty Ltd and Muller Partnership accepts no responsibility to other parties who use opinions or information contained herein. They do so at their own risk.

In acting as Quantity Surveyor for Jackson Environment and Planning Pty Ltd, Muller Partnership's liability is limited to the scope of services and value limit, as defined in their Professional indemnity insurance cover. A copy is available on request.

This report covers only the items as contained in this report. Should Jackson Environment and Planning Pty Ltd require additional items or areas of assessment, these should be specifically requested and will be actioned as agreed between the parties.

The construction costs are current as at the date of this assessment only. The values assessed herein may change significantly and unexpectedly over a relatively short period (including as a result of general market movements or factors specific to the particular property). We do not accept liability for losses arising from such subsequent changes in values.

Document history & status

Revision	Date	Description	Ву	Review	Approved
0	01/09/2020	Capital Investment Value Estimate	FW	NW	PD
1	18/09/2020	Capital Investment Value Estimate Rev 1	NW	NW	PD
2	21/10/2020	Capital Investment Value Estimate Rev 2	NW	NW	PD



#### 

#### Capital Investment Value

Capital Investment Value of a development or project includes all costs necessary to establish and operate the project, including the design and construction of buildings, structures, associated infrastructure and fixed or mobile plant and equipment, other than the following costs:

- (a) amounts payable, or the cost of land dedicated or any other benefit provided, under a condition imposed under Division 6 or 6A of Part 4 of the Environmental Planning and Assessment Act or a planning agreement under that Division
- (b) costs relating to any part of the development or project that is the subject of a separate development consent or project approval
- (c) land costs (including any costs of marketing and selling land)
- (d) GST (as defined by A New Tax System (Goods and Services Tax) Act 1999

#### Construction Contingency

The Construction Contingency is a contingency allowance made for unknowns that may occur during construction due to latent conditions or issues with the documentation.

#### Design Development Allowance

The Design Development Allowance is a contingency included within our estimate to allow for unknown costs associated with progressing the development from the initial concept through until the 'For Construction'. At the time of For Construction documentation this contingency should be 0% as the entire project will have been designed and costed accordingly.

#### Preliminaries & Margin

The Preliminaries and Margin Allowance is an allowance for the builders' margin and their establishment and management of the site. This item will therefore include for items such as site fencing & amenities, site foreman, head office overheads, insurances, cranage, site cleaning, OH&S management, QA, etc.



#### **Project Description**

The project located at 21D School Drive, Tomago, NSW involves the following scope of works:

- Building 1: Internal alterations to administration building; new perimeter bund to warehouse; internal concrete block walls; power layout modification and installation of new fixed equipment.
- Building 2: Infill of existing inspection pits; new slab over infilled pits; new perimeter bund to warehouse; internal concrete block walls; power layout modification; new sprinkler system; new roller shutter doors and installation of new fixed equipment.
- Building 3: New perimeter bund to warehouse; new roller shutter door, and installation of fixed equipment.
- External works: New 26m single lane weighbridge, perimeter security fencing; overnight lorry parking area; diesel tank; waste oil tank and associated services.

A summary of the CIV is as follows:

Ref	Description	\$/ Excl. GST
1.0	Demolition & Site Preparation	\$70,000
2.0	Building 1	\$3,504,000
3.0	Building 2	\$3,523,000
4.0	Building 3	\$34,000
5.0	External Works & Services	\$1,029,000
6.0	Preliminaries & Margin (10%)	\$816,000
7.0	TOTAL CONSTRUCTION COST [EXCL. GST]	\$8,976,000
8.0	Identified Risk Items	EXCL
9.0	Design Contingency	EXCL
10.0	Construction Contingency	EXCL
11.0	Professional Fees	EXCL
12.0	Authority Fees & Contributions	EXCL
13.0	TOTAL PROJECT COST [EXCL. GST]	\$8,976,000

We note the attached estimate is for construction costs only and does not allow for items such as property acquisition, finance costs, escalation, planning & authority fees & charges. The above costs are rounded to the nearest thousand. Please refer to the Qualification, Assumptions and Exclusions sections of this report for further details.



#### **Key Notes & Actions:**

- This estimate has been prepared in accordance with the EPAA 2000 and SEPP (CIV) 2010 with consideration for the Planning Circular PS10-008.
- Please note that the purpose of this CIV estimate is to determine the current construction cost value of the development for council purposes only and is not to be used for project budgeting, finance, insurance, sale, or any other purposes.
- Should you require these services Muller Partnership can provide development budgeting, scenario estimating, cost planning, or similar services on request.
- Assumed contractor will have an uninterrupted access and vacant possession of the site.
- Building 2 requires existing inspection pits to be infilled, we have allowed for crushed rock laid in 150mm layers and 120mm reinforced concrete slab with an industrial epoxy finish on top.
- We have allowed a provisional sum for a 26m single lane weighbridge as no specification currently available.
- We have allowed for a 60,000L for both Diesel storage tank and waste oil tank.
- No amplification of existing substations, modifications to existing distribution boards has been allowed.
- We have allowed for sprinkler system to building 2 only. Building 1 has an existing system that is assumed compliant and building 3 is assumed not to require a sprinkler system.
- We have allowed for all new fixed equipment as presented in the FF&E schedule provided. All loose equipment and mobile plant has been excluded.
- Review assumptions and exclusions.



#### 2.0 METHODOLOGY

Muller Partnership has used the following information in compiling our CIV Estimate:

The estimate has been prepared in accordance with the EPAA 2000 and SEPP (CIV) 2010 with consideration for the Planning Circular PS10-008.

All rates used within our CIV have been gathered from our in-house databases as well as being constructed from first principles namely labour, materials and waste to reflect current market and project specific value.

Muller Partnership has used the following plans provided by Jackson Environment and Planning Pty Ltd, dated 05 August 2020, and received on 21st August 2020:

- DA A-001 REV G.
- DA A-020 REV D.
- DA A-100 REV G.
- DA A-102 REV H.
- DA A-103 REV G.

Stormwater Drainage Design Plan by Northrop, dated 1st July 2020, and received on 21st August 2020:

NIL201175 SW Mark-up.

Other information received between 21st August and 18th September 2020:

- Remondis Operational Analysis Tomago Resource RRF and Truck Parking Deport.
- Capital Investment Value RFQ.
- Various emails regarding the Infill of existing pits to Building 2.
- PE200002-01 SSD Fire Safety Study R-01.



#### 3.0 ASSUMPTIONS

We have made the following assumptions in the preparation of our CIV Estimate:

- 1. CIV estimate is to determine the current construction cost value of the development for council purposes only and is not to be used for project budgeting, finance, insurance, sale, or any other purposes.
- 2. The works will be competitively tendered to a number of suitable qualified contractors on a lump sum basis.
- 3. Works will be completed during normal working hours.
- 4. Assumed contractor will have clear access to the work area.
- 5. Contractor will have vacant possession to Building 1, 2 & 3.
- 6. All excavated and demolished materials to be retained on site.
- 7. We have assumed level access between external finished floor level (FFL) and internal slab FFL.
- 8. We have adopted the quantity provided for the infill of existing pits to Building 2 in email from the client dated 28<sup>th</sup> August 2020.
- 9. We have adopted the quantities provided in the Capital Investment Value RFQ for the bund around internal perimeter of each of the buildings.
- 10. We have adopted the FF&E schedule provided by the client.
- 11. We have assumed that all FF&E shown on drawings is included within the FF&E schedule provided.
- 12. We have assumed the infill of pits in building 2 is with imported crushed rock laid in 150mm layers.
- 13. We have allowed 120mm thick concrete reinforced slab with epoxy industrial finish to infill pits in building 2 to tie into existing slab.
- 14. Concrete core filled block walls NE: 4.0m height allowed to separate the different functional areas.
- 15. We have assumed that existing carpet tile is available for replacement.



- 16. We have allowed for the modification of the single phase LV power only to equipment based on revised layout for Buildings 1 & 2. No Distribution board amplification or three phase power allowed.
- 17. Roller doors are all electrically operated.
- 18. New fire sprinkler system to building 2 only.
- 19. Awning over new Diesel tank is assumed lightweight metal roof on steel posts.
- 20. We have allowed for 60,000L diesel tank and waste oil tank as per conversations with Jackson Environmental.
- 21.No specification has been provided for the new weighbridge we have assumed a 26m single lane weighbridge.
- 22. Builder's works in connection with services allowance of 5% has been allowed.
- 23. Preliminaries, Overheads and Profit allowance of 10% has been allowed.



#### 4.0 EXCLUSIONS

Within the following CIV the acronym 'EXCL' means work that has **not** been included in our estimate. We specifically note the following exclusions from the estimated cost:

- 1. Removal of existing FF&E, personal effects, equipment and stored materials.
- 2. Contamination & remediation.
- 3. Disposal of excavated and demolished material as site at local waste facility.
- 4. Services diversions.
- 5. Excavation in rock.
- 6. Grubbing out footings of removed fence.
- 7. Piling or piers to concrete slab.
- 8. Repairs or replacement of roof.
- 9. Replacement of existing doors.
- 10. Replacement of windows.
- 11. Loose equipment and mobile plant (Forklift trucks and loaders etc.)
- 12. Internal hydraulic services.
- 13. New distribution boards.
- 14. New main switchboard.
- 15. New 3 phase power supply.
- 16. Modifications or refurbishment of existing lighting in all buildings.
- 17. Modifications or refurbishment of existing mechanical services.
- 18. Wet sprinkler system to building 1 and 3.



#### 19. Works to other areas:

- 19.1. Security office.
- 19.2. Cooling towers.
- 19.3. Compressors.
- 19.4. Existing employee parking area.

- 19.5. Level 1 to buildings 1 and 3.
- 20. Compressed air.
- 21. New inspection pits.
- 22. Battery storage.
- 23. New loading docks.
- 24. Wheel change facilities.
- 25. Substation.
- 26. Upgrade of water tanks.
- 27. Amplification of existing services.
- 28. Escalation & changes in market conditions.
- 29. Client-side project management.
- 30. Finance costs.
- 31. Works outside normal hours.
- 32. Aboriginal and Heritage impacts.
- 33. Delays resulting from approvals such as Environmental/ Authorities.
- 34. Construction contingency.
- 35. Design contingency.
- 36. Professional Fees.
- 37. Authority Fees.
- 38. Covid-19 programme delays, materials and labour impacts.
- 39. GST.







		Quantity	Unit	Rate	Total
1	DEMOLITION & SITE PREPARATION				\$69,578.00
2	BUILDING 1				\$3,504,435.00
3	BUILDING 2				\$3,523,384.00
4	BUILDING 3				\$33,557.00
5	EXTERNAL WORKS AND SERVICES				\$1,028,562.00
6	PRELIMINARIES & MARGIN				\$815,952.00
7	IDENTIFIED RISK ITEMS				
8	CONSTRUCTION CONTINGENCY				
9	PROFESSIONAL FEES				
10	AUTHORITY FEES AND CONTRIBUTIONS	6			
11	ESCALATION				
12	\$/m2 - GFA - 10,110 m2			\$887.78	
				Subtotal	\$8,975,468.00
				Adjustment	\$0.00
				Total	\$8,975,468.00

		Quantity	Unit	Rate	Total
1	DEMOLITION & SITE PREPARATION				\$69,578.00
1.1	DEMOLITION & ALTERATIONS				\$10,599.00
1.2	SITE PREPARATION				\$58,979.00
2	BUILDING 1				\$3,504,435.00
2.1	DEMOLITION & ALTERATIONS				
2.2	SITE PREPARATION				
2.3	SUBSTRUCTURE				\$21,675.00
2.4	STAIRS				
2.5	UPPER FLOORS				
2.6	COLUMNS				
2.7	ROOF				
2.8	EXTERNAL WALLS				\$3,325.00
2.9	WINDOWS & EXTERNAL DOORS				\$1,000.00
2.10	INTERNAL WALLS				\$143,820.00
2.11	INTERNAL SCREENS & BORROWED LIG	GHTS			
2.12	INTERNAL DOORS				
2.13	WALL FINISHES				\$384.00
2.14	FLOOR FINISHES				\$8,470.00
2.15	CEILING FINISHES				
2.16	JOINERY & METALWORK				
2.17	FITMENTS, FITTINGS & EQUIPMENT				\$2,969,685.00
2.18	HYDRAULIC SERVICES				
2.19	MECHANICAL SERVICES				
2.20	ELECTRICAL SERVICES				\$282,600.00
2.21	FIRE SERVICES				\$56,520.00
2.22	LIFT SERVICES				

	Quantity Unit	Rate	Total
2.23	BUILDERS WORK IN CONNECTION WITH SERVICES		\$16,956.00
2.24	SPECIAL EQUIPMENT		
3	BUILDING 2		\$3,523,384.00
3.1	DEMOLITION & ALTERATIONS		
3.2	SITE PREPARATION		
3.3	SUBSTRUCTURE		\$52,625.00
3.4	STAIRS		
3.5	UPPER FLOORS		
3.6	COLUMNS		
3.7	ROOF		
3.8	EXTERNAL WALLS		\$4,270.00
3.9	WINDOWS & EXTERNAL DOORS		\$34,700.00
3.10	INTERNAL WALLS		\$16,020.00
3.11	INTERNAL SCREENS & BORROWED LIGHTS		
3.12	INTERNAL DOORS		
3.13	WALL FINISHES		
3.14	FLOOR FINISHES		\$22,800.00
3.15	CEILING FINISHES		
3.16	JOINERY & METALWORK		
3.17	FITMENTS, FITTINGS & EQUIPMENT		\$2,807,720.00
3.18	HYDRAULIC SERVICES		
3.19	MECHANICAL SERVICES		
3.20	ELECTRICAL SERVICES		\$192,200.00
3.21	FIRE SERVICES		\$365,180.00
3.22	LIFT SERVICES		
3.23	BUILDERS WORK IN CONNECTION WITH SERVICES		\$27,869.00



	Quantity Unit	Rate	Total
3.24	SPECIAL EQUIPMENT		
4	BUILDING 3		\$33,557.00
4.1	DEMOLITION & ALTERATIONS		
4.2	SITE PREPARATION		
4.3	SUBSTRUCTURE		\$4,250.00
4.4	STAIRS		
4.5	UPPER FLOORS		
4.6	COLUMNS		
4.7	ROOF		
4.8	EXTERNAL WALLS		\$2,940.00
4.9	WINDOWS & EXTERNAL DOORS		\$16,850.00
4.10	INTERNAL WALLS		
4.11	INTERNAL SCREENS & BORROWED LIGHTS		
4.12	INTERNAL DOORS		
4.13	WALL FINISHES		
4.14	FLOOR FINISHES		
4.15	CEILING FINISHES		
4.16	JOINERY & METALWORK		
4.17	FITMENTS, FITTINGS & EQUIPMENT		\$3,070.00
4.18	HYDRAULIC SERVICES		
4.19	MECHANICAL SERVICES		
4.20	ELECTRICAL SERVICES		
4.21	FIRE SERVICES		\$6,140.00
4.22	LIFT SERVICES		
4.23	BUILDERS WORK IN CONNECTION WITH SERVICES		\$307.00
4.24	SPECIAL EQUIPMENT		



		Quantity	Unit	Rate	Total
5	EXTERNAL WORKS AND SERVICES				\$1,028,562.00
5.1	EXTERNAL SERVICES				\$344,021.00
5.2	SITE & LANDSCAPING				\$684,541.00
6	PRELIMINARIES & MARGIN				\$815,952.00
6.1	Allowance for Builders preliminaries, overhead & margin (10%)	1	Item	\$815,952.00	\$815,952.00
7	IDENTIFIED RISK ITEMS				
7.1	Identified risk items	1	Item		EXCL
8	CONSTRUCTION CONTINGENCY				
8.1	Allowance for general construction contingency	1	Item		EXCL
8.2	Design Development allowance	1	Item		EXCL
9	PROFESSIONAL FEES				
9.1	Professional Fees	1	Item		EXCL
10	AUTHORITY FEES AND CONTRIBUTIONS				
10.1	Authority Fees	1	Item		EXCL
11	ESCALATION				
11.1	Escalation	1	item		EXCL
12	\$/m2 - GFA - 10,110 m2			\$887.78	
				Subtotal	\$8,975,468.00
				Adjustment	\$0.00
				Total	\$8,975,468.00

1.1	\$69,578.00 \$10,599.00 EXCL \$2,100.00 EXCL \$1,500.00 \$1,900.00
Removal of existing FFRE, personal effects, equipment, stored materials etc Assumed vacant possession   1	\$2,100.00 EXCL \$1,500.00 \$1,900.00 \$495.00
1.1.1       effects, equipment, stored materials etcAssumed vacant possession       1       Item         1.1.2       Demolish existing control room       28       m2       \$75.00         1.1.3       Tip Fees - Excluded as facility is a waste recovery facility       1       Item         1.1.4       Form opening for single leaf door to external wall       1       No       \$1,500.00         1.1.5       Form openings for roller doors to all buildings       20       m2       \$95.00         1.1.5       Form openings for roller doors to all buildings       33       m2       \$95.00         1.1.6       Carefully remove existing walls in administration building - Assumed       33       m2       \$15.00         1.1.7       Remove existing workstations       3       No       \$300.00         1.1.8       Existing single leaf door       1       No       \$40.00         1.1.9       Make good to walls where internal walls removed [Bid 1 -Administration area]       5.4       m       \$35.00         1.1.10       walls removed [Bid 1 -Administration area]       13       m       \$35.00         1.1.11       walls removed [Bid 1 -Administration area]       13       m       \$35.00         1.1.11       Remove mesh fence       171       m       \$15.00	\$2,100.00 EXCL \$1,500.00 \$1,900.00 \$495.00
1.1.3         Tip Fees - Excluded as facility is a waste recovery facility         1         Item           1.1.4         Form opening for single leaf door to external wall         1         No         \$1,500.00           1.1.5         Form openings for roller doors to all buildings         20         m2         \$95.00           1.1.5         Form openings for roller doors to all buildings         20         m2         \$95.00           1.1.6         Carefully remove existing walls in administration building - Assumed stud partition and plasterboard         33         m2         \$15.00           1.1.7         Remove existing workstations         3         No         \$300.00           1.1.8         Existing single leaf door         1         No         \$40.00           1.1.9         Make good to walls where internal walls removed [Bld 1 -Administration area]         5.4         m         \$35.00           1.1.10         walls removed [Bld 1 -Administration area]         13         m         \$35.00           1.1.11         walls removed [Bld 1 -Administration area]         13         m         \$35.00           1.1.11         walls removed [Bld 1 -Administration area]         1         m         \$15.00           1.2.1         Remove mesh fence         171         m         \$15.00	\$1,500.00 \$1,900.00 \$495.00
1.1.3	\$1,500.00 \$1,900.00 \$495.00
1.1.4       Form opening for single leaf door to external wall       1       No       \$1,500.00         1.1.5       Form openings for roller doors to all buildings       20       m2       \$95.00         1.1.6       Carefully remove existing walls in administration building - Assumed stud partition and plasterboard       33       m2       \$15.00         1.1.7       Remove existing workstations       3       No       \$300.00         1.1.8       Existing single leaf door       1       No       \$40.00         1.1.9       Make good to walls where internal walls removed [Bld 1 -Administration area]       5.4       m       \$35.00         1.1.10       Make good to floor where internal walls removed [Bld 1 -Administration area]       13       m       \$35.00         1.1.11       Make good to ceiling where internal walls removed [Bld 1 -Administration area]       13       m       \$35.00         1.1.11       Remove mesh fence       171       m       \$15.00         1.2       SITE PREPARATION         1.2.1       Evel access between internal building FFL and External areas outside of building       1       Item       \$4,000.00         1.2.2       Cap and protect existing services - 3 Buildings       1       Item       \$4,000.00         1.2.3       Site clearance and levelling - New J	\$1,900.00 \$495.00
1.1.5 Form openings for roller doors to all buildings  Carefully remove existing walls in administration building - Assumed stud partition and plasterboard  1.1.7 Remove existing workstations  3 No \$300.00  1.1.8 Existing single leaf door  1 No \$40.00  1.1.9 Make good to walls where internal walls removed [Bld 1 -Administration area]  Make good to floor where internal walls removed [Bld 1 -Administration area]  1.1.10 Walls removed [Bld 1 -Administration area]  Make good to ceiling where internal walls removed [Bld 1 -Administration area]  1.1.11 Walls removed [Bld 1 -Administration area]  1.1.12 Remove mesh fence  171 m \$15.00  1.2 SITE PREPARATION  1.2.1 Level access between internal building FFL and External areas outside of building  1.2.2 Cap and protect existing services - 3 Buildings  1.2.3 Site clearance and levelling - New lorry parking area  1.1.6 United by client  1.2.7 External existing pits (building 2) - Quantity provided by client  1.2.8 Walls in ma \$3.50  1.2.9 Site clearance and levelling - New Quantity provided by client	\$495.00
Carefully remove existing walls in administration building - Assumed stud partition and plasterboard   33 m² \$15.00	,
1.1.7       Remove existing workstations       3       No       \$300.00         1.1.8       Existing single leaf door       1       No       \$40.00         1.1.9       Make good to walls where internal walls removed [Bld 1 -Administration area]       5.4       m       \$35.00         1.1.10       Make good to floor where internal walls removed [Bld 1 -Administration area]       13       m       \$35.00         1.1.11       Walks removed [Bld 1 -Administration area]       13       m       \$35.00         1.1.12       Remove mesh fence       171       m       \$15.00         1.2       SITE PREPARATION         1.2.1       Level access between internal building FFL and External areas outside of building         1.2.2       Cap and protect existing services - 3 Buildings       1       Item       \$4,000.00         1.2.3       Site clearance and levelling - New lorry parking area       3,451       m2       \$3.50         1.2.4       Infill existing pits (building 2) - Quantity provided by client       180       m3       \$140.00	¢000.00
Make good to walls where internal walls removed [Bld 1 -Administration area] Make good to floor where internal walls removed [Bld 1 -Administration area]  1.1.10 Make good to floor where internal walls removed [Bld 1 -Administration area]  Make good to ceiling where internal walls removed [Bld 1 -Administration area]  1.1.11 Remove mesh fence 171 m \$15.00  1.2 SITE PREPARATION  1.2.1 Level access between internal building FFL and External areas outside of building Diuliding  1.2.2 Cap and protect existing services - 3 Buildings  Site clearance and levelling - New lorry parking area  1.2.4 Infill existing pits (building 2) - Quantity provided by client  Make good to floor where internal areas and areas are	\$900.00
1.1.9 walls removed [Bld 1 -Administration area]  Make good to floor where internal walls removed [Bld 1 -Administration area]  Make good to ceiling where internal walls removed [Bld 1 -Administration area]  1.1.11 walls removed [Bld 1 -Administration area]  1.1.12 Remove mesh fence 171 m \$35.00  1.2 SITE PREPARATION  Level access between internal building FFL and External areas outside of building  1.2.1 Evel access between internal building FFL and External areas outside of building  1.2.2 Cap and protect existing services - 3 Buildings  1.2.3 Site clearance and levelling - New lorry parking area  1.2.4 Infill existing pits (building 2) - Quantity provided by client  180 m3 \$140.00	\$40.00
1.1.10 walls removed [Bld 1 -Administration area]  Make good to ceiling where internal walls removed [Bld 1 -Administration area]  1.1.11 walls removed [Bld 1 -Administration area]  1.1.12 Remove mesh fence 171 m \$15.00  1.2 SITE PREPARATION  1.2.1 Evel access between internal building FFL and External areas outside of building  1.2.2 Cap and protect existing services - 3 Buildings  1.2.3 Site clearance and levelling - New lorry parking area  1.2.4 Infill existing pits (building 2) - Quantity provided by client  180 m3 \$140.00	\$189.00
1.1.11 walls removed [Bld 1 -Administration area]  1.1.12 Remove mesh fence  171 m \$15.00  1.2 SITE PREPARATION  Level access between internal building FFL and External areas outside of building  1.2.1 Cap and protect existing services - 3 Buildings  1.2.2 Site clearance and levelling - New lorry parking area  1.2.3 Site clearance and levelling - New lorry parking area  1.2.4 Infill existing pits (building 2) - Quantity provided by client  1.3 m \$35.00  1.10 m \$4,000.00  1.2.3 Site clearance and levelling - New lorry parking area  1.2.4 Infill existing pits (building 2) - Quantity provided by client	\$455.00
1.2 SITE PREPARATION  Level access between internal building FFL and External areas outside of building  1.2.2 Cap and protect existing services - 3 Buildings  1.2.3 Site clearance and levelling - New lorry parking area  1.2.4 Infill existing pits (building 2) - Quantity provided by client  1.2.5 SITE PREPARATION  1.2.6 Item \$4,000.00  \$4,	\$455.00
Level access between internal building FFL and External areas outside of building  1.2.2 Cap and protect existing services - 3 Buildings  1.2.3 Site clearance and levelling - New lorry parking area  1.2.4 Infill existing pits (building 2) - Quantity provided by client  Level access between internal building  1 Item \$4,000.00  \$4,000.00  \$3,451 m2 \$3.50  m3 \$140.00	\$2,565.00
1.2.1 FFL and External areas outside of building  1.2.2 Cap and protect existing services - 3	58,979.00
1.2.2 Cap and protect existing services - 3 Buildings  1 Item \$4,000.00  1.2.3 Site clearance and levelling - New lorry parking area  1.2.4 Infill existing pits (building 2) - Quantity provided by client  1 Item \$4,000.00  3,451 m2 \$3.50  1 Item \$4,000.00	NOTED
1.2.3 Site clearance and levelling - New lorry parking area 3,451 m2 \$3.50  1.2.4 Infill existing pits (building 2) - Quantity provided by client 180 m3 \$140.00	\$4,000.00
1.2.4 Infill existing pits (building 2) - Quantity provided by client 180 m3 \$140.00	\$12,078.50
	\$25,200.00
Temporary hoarding / Fencing for staging staging 354 m \$50.00	\$17,700.00
1.2.6 Removal and remediation of hazardous 1 Item	EXCL
1.2.7 Service Diversions 1 Item	EXCL
2 BUILDING 1 \$3,	
2.1 DEMOLITION & ALTERATIONS	504,435.00
2.1.1 See Demolition & Site Preparation 1 Item	604,435.00
2.2 SITE PREPARATION	INCL
2.2.1 See Demolition & Site Preparation 1 Item	
2.3 SUBSTRUCTURE	



	1	Quantity	Unit	Rate	Total
2.3.1	10mm bund wall around internal perimeter of external wall and exits - Quantity provided CIV RFQ	51	m3	\$425.00	\$21,674.96
2.4	STAIRS				
2.4.1	Existing stairs to remain	1	Item		EXCL
2.5	UPPER FLOORS				
2.5.1	No works required to Level 1	1	Item		EXCL
2.6	COLUMNS				
2.6.1	No repairs or new columns required	1	Item		EXCL
2.7	ROOF				
2.7.1	Existing roof to remain no repairs required	1	Item		EXCL
2.8	EXTERNAL WALLS				\$3,325.00
2.8.1	Make good to external walls where opening have been formed	95	m	\$35.00	\$3,325.00
2.9	WINDOWS & EXTERNAL DOORS				\$1,000.00
2.9.1	Windows				
2.9.1.1	Existing windows to remain	1	Item		EXCL
2.9.2	External Doors				\$1,000.00
2.9.2.1	Single leaf solid core door	1	No	\$1,000.00	\$1,000.00
2.9.2.2	Existing single leaf door	9	No		EXCL
2.9.2.3	Existing double leaf door	1	pr		EXCL
2.9.2.4	Existing roller shutter doors [6.5m wide x 3.0m high]	2	No		EXCL
2.9.2.5	Existing roller shutter doors [8.0m wide x 5.0m high]	3	No		EXCL
2.10	INTERNAL WALLS				\$143,820.00
2.10.1	4m concrete block walls [Corefilled] - No finish	799	m2	\$180.00	\$143,820.00
2.11	INTERNAL SCREENS & BORROWED LI	GHTS			
2.11.1	Internal screens & borrowed lights	1	Item		EXCL
2.12	INTERNAL DOORS				
2.12.1	Internal doors to remain no works required	1	Item		EXCL
2.13	WALL FINISHES				\$384.00
2.13.1	Paint walls where workstations and internal walls removed	16	m2	\$24.00	\$384.00



		Quantity	Unit	Rate	Total
2.14.1	Localised repairs to existing floor finishes where walls removed in administration building	8	m2	\$30.00	\$240.00
2.14.2	Localised repairs to existing warehouse slab	1	Item		EXCL
2.14.3	Carpet tile - Assumed 500m wide strip requires replacement, match existing	8	m2	\$160.00	\$1,280.00
2.14.4	New pedestrian path delineate line marking	139	m2	\$50.00	\$6,950.00
2.15	CEILING FINISHES				
2.15.1	No works required	1	Item		EXCL
2.16	JOINERY & METALWORK				
2.16.1	Joinery & Metalwork	1	Item		EXCL
2.17	FITMENTS, FITTINGS & EQUIPMENT				\$2,969,685.00
2.17.1	Items shown on drawings assumed form part of FF&E schedule provided by the client				NOTED
2.17.2	Loader [6.0t]	1	No		EXCL
2.17.3	Loader [7.6t]	1	No		EXCL
2.17.4	Material handler	1	No		EXCL
2.17.5	Excavator [23.0t]	1	Item		EXCL
2.17.6	Forklift [2.5t] -Toyota	1	Item		EXCL
2.17.7	Forklift [2.5t] - Linde	1	Item		EXCL
2.17.8	Forklift [2.5t] - Nissan	1	Item		EXCL
2.17.9	Pre-shredder	1	No	\$615,696.00	\$615,696.00
2.17.10	Screen	1	No	\$154,210.00	\$154,210.00
2.17.11	Windshifter	1	No	\$243,720.00	\$243,720.00
2.17.12	Fine-shredder	1	No	\$471,035.00	\$471,035.00
2.17.13	Magnet	1	No	\$136,050.00	\$136,050.00
2.17.14	conveyors	1	No	\$304,037.00	\$304,037.00
2.17.15	Near-Infrared	1	No	\$421,677.00	\$421,677.00
2.17.16	Baler	1	No	\$595,000.00	\$595,000.00
2.17.17	Statutory Signage	5,652	m2	\$5.00	\$28,260.00
2.18	HYDRAULIC SERVICES				
2.18.1	Hydraulic - No changes to existing warehouse or administration area	1	Item		EXCL
2.19	MECHANICAL SERVICES				
2.19.1	Mechanical services - No changes to existing warehouse or administration area	1	Item		EXCL
2.20	ELECTRICAL SERVICES				\$282,600.00
2.20.1	New Distribution boards	1	Item		EXCL



		Quantity	Unit	Rate	Total
2.20.2	New Mainboards	1	Item		EXCL
2.20.3	Modification to existing power and comms layout for new equipment	5,652	m2	\$50.00	\$282,600.00
2.20.4	Existing lighting to remain in current locations	1	Item		EXCL
2.21	FIRE SERVICES				\$56,520.00
2.21.1	Wet sprinkler system to building - Existing sprinklers to remain no modification required	5,652	m2		EXCL
2.21.2	Dry fire services	5,652	m2	\$10.00	\$56,520.00
2.21.3	Internal fire hydrant	1	Item		EXCL
2.22	LIFT SERVICES				
2.22.1	Existing lift to remain	1	Item		EXCL
2.23	BUILDERS WORK IN CONNECTION W	ITH SERVICES			\$16,956.00
2.23.1	Builders work in connection with services 5%	1	Item	\$16,956.00	\$16,956.00
2.24	SPECIAL EQUIPMENT				
2.24.1	Works to existing Inspection Pits or creation of new	1	Item		EXCL
2.24.2	Loading docks	1	Item		EXCL
2.24.3	Battery Storage	1	Item		EXCL
2.24.4	Air compressors	1	Item		EXCL
2.24.5	Wheel change	1	Item		EXCL
3	BUILDING 2				\$3,523,384.00
3.1	DEMOLITION & ALTERATIONS				
3.1.1	See Demolition & Site Preparation heading	1	Item		INCL
3.2	SITE PREPARATION				
3.2.1	See Demolition & Site Preparation heading	1	Item		INCL
3.3	SUBSTRUCTURE				\$52,625.00
3.3.1	Infill Pit				\$30,950.00
3.3.1.1	New concrete slab over infilled pits [assumed concrete slab120mm thick 40Mpa reinforcement at 80kg/m3] [Assumed pit is 1m deep]	180	m2	\$120.00	\$21,600.00
3.3.1.2	Dowels assumed at NE: 300mm to connect to existing slab	187	No	\$50.00	\$9,350.00
3.3.2	16mm bund wall around internal perimeter of external wall and exits Quantity provided CIV RFQ	51	m3	\$425.00	\$21,674.96
3.4	STAIRS				
3.4.1	Stairs	1	Item		EXCL



		Quantity	Unit	Rate	Total
3.5	UPPER FLOORS				
3.5.1	Upper Floors	1	Item		EXCL
3.6	COLUMNS				
3.6.1	No repairs or new columns required	1	Item		EXCL
3.7	ROOF				
3.7.1	Existing roof to remain no repairs required	1	Item		EXCL
3.8	EXTERNAL WALLS				\$4,270.00
3.8.1	Make good to external walls where opening have been formed	122	m	\$35.00	\$4,270.00
3.9	WINDOWS & EXTERNAL DOORS				\$34,700.00
3.9.1	Windows				
3.9.1.1	Existing windows to remain	1	Item		EXCL
3.9.2	External Doors				\$34,700.00
3.9.2.1	Existing single leaf door	9	No		EXCL
3.9.2.2	Existing double leaf door	1	pr		EXCL
3.9.2.3	Single Leaf solid core door	1	No	\$1,000.00	\$1,000.00
3.9.2.4	Existing roller shutter doors [6.5m wide x 3.0m high]	5	No		EXCL
3.9.2.5	New roller shutter doors [8.0m wide x 5.0m high]	2	No	\$16,850.00	\$33,700.00
3.10	INTERNAL WALLS				\$16,020.00
3.10.1	4m concrete block walls [Corefilled] - No finish	89	m2	\$180.00	\$16,020.00
3.11	INTERNAL SCREENS & BORROWED LIGI	HTS			
3.11.1	Internal screens & borrowed lights	1	Item		EXCL
3.12	INTERNAL DOORS				
3.12.1	Existing internal doors to remain	1	Item		EXCL
3.13	WALL FINISHES				
3.13.1	No new wall finishes allowed to driver amenities and operations area	1	Item		EXCL
3.14	FLOOR FINISHES				\$22,800.00
3.14.1	Localised repairs to warehouse	1	Item		
3.14.2	Localised repairs to driver amenities and operations	1	Item		EXCL
3.14.3	Epoxy finish - Industrial warehouse standard where new slab installed	180	m2	\$100.00	\$18,000.00
3.14.4	New pedestrian path delineate line marking	96	m2	\$50.00	\$4,800.00



		Quantity	Unit	Rate	Total
3.15	CEILING FINISHES				
3.15.1	No works required	1	Item		EXCL
3.16	JOINERY & METALWORK				
3.16.1	Joinery & Metalwork	1	Item		EXCL
3.17	FITMENTS, FITTINGS & EQUIPMENT				\$2,807,720.00
3.17.1	Items shown on drawings assumed form part of FF&E schedule provided by the client				NOTED
3.17.2	Food Depackaging Plant				\$700,000.00
3.17.2.1	Feed hopper and conveyor into separator	1	Item	\$700,000.00	\$700,000.00
3.17.2.2	Separator unit	1	Item		INCL
3.17.2.3	Conveyor for emptied packaging	1	Item		INCL
3.17.2.4	Conveyor for solid foods	1	Item		INCL
3.17.2.5	Pump for liquids	1	Item		INCL
3.17.3	Drill Mud Recycling Facility				\$2,000,000.00
3.17.3.1	Initial pit	1	Item	\$2,000,000.00	\$2,000,000.00
3.17.3.2	Pump or filter press	1	Item		INCL
3.17.3.3	Bunkers	1	Item		INCL
3.17.3.4	Buffer tanks	1	Item		INCL
3.17.3.5	Centrifuge	1	Item		INCL
3.17.4	Garden Organics Primary Processing				\$25,000.00
3.17.4.1	Bunker storage walls	1	Item	\$25,000.00	\$25,000.00
3.17.4.2	Loader [6.0t] - shared with Building 1	1	Item		EXCL
3.17.4.3	Material handler - shared with Building 1	1	Item		INCL
3.17.4.4	Shredder - shared with Building 1	1	Item		INCL
3.17.5	Hazardous Waste Recycling Facility				\$21,000.00
3.17.5.1	Pallet racking	1	Item	\$5,000.00	\$5,000.00
3.17.5.2	Pallet scales	1	Item	\$4,000.00	\$4,000.00
3.17.5.3	Elephants foot baler	1	Item	\$12,000.00	\$12,000.00
3.17.5.4	Forklift [2.5t] - Toyota	1	Item		EXCL
3.17.6	Copper Processing Area				\$6,500.00
3.17.6.1	Sorting table	1	Item	\$500.00	\$500.00
3.17.6.2	Storage bins	1	Item	\$6,000.00	\$6,000.00
			_		
3.17.6.3	Hydraulic cable shear	1	Item		EXCL



		Quantity	Unit	Rate	Total
3.17.6.5	Forklift [2.5t] - Toyota	1	Item		EXCL
3.17.7	Metals Recycling Facility				\$36,000.00
3.17.7.1	Existing overhead crane	1	Item		EXCL
3.17.7.2	Material handler - shared with Building 1	1	Item		INCL
3.17.7.3	Material handler - shared with Building 1	1	Item		INCL
3.17.7.4	Forklift [2.5t] - shared with Building 1	1	Item		EXCL
3.17.7.5	Bale press - shared with Building 1	1	Item		INCL
3.17.7.6	Hook lift bins	1	Item	\$36,000.00	\$36,000.00
3.17.7.7	Front end loader - shared with Building 1	1	Item		EXCL
3.17.8	Statutory signage	3,844	m2	\$5.00	\$19,220.00
3.18	HYDRAULIC SERVICES				
3.18.1	Hydraulic - No changes to existing warehouse or driver amenities & operations area	1	Item		EXCL
3.19	MECHANICAL SERVICES				
3.19.1	Mechanical services - No changes to existing warehouse or driver amenities & operations area	1	Item		EXCL
3.20	ELECTRICAL SERVICES				\$192,200.00
3.20.1	New Distribution boards	1	Item		EXCL
3.20.2	New Mainboards	1	Item		EXCL
3.20.3	Modification to existing power and comms layout for new equipment	3,844	m2	\$50.00	\$192,200.00
3.20.4	Existing lighting to remain in current locations	1	Item		EXCL
3.21	FIRE SERVICES				\$365,180.00
3.21.1	Wet sprinkler system to building	3,844	m2	\$85.00	\$326,740.00
3.21.2	Dry fire services	3,844	m2	\$10.00	\$38,440.00
3.21.3	Internal fire hydrant	1	Item		EXCL
3.22	LIFT SERVICES				
3.22.1	Lift Services	1	Item		EXCL
3.23	BUILDERS WORK IN CONNECTION WIT	TH SERVICES			\$27,869.00
3.23.1	Builders work in connection with services 5%	1	Item	\$27,869.00	\$27,869.00
3.24	SPECIAL EQUIPMENT				
3.24.1	New inspection pits	1	Item		EXCL
3.24.2	Loading docks	1	Item		EXCL
3.24.3	Battery Storage	1	Item		EXCL



		Quantity	Unit	Rate	Total
3.24.4	Air compressors	1	Item		EXCL
3.24.5	Wheel change	1	Item		EXCL
4	BUILDING 3				\$33,557.00
4.1	DEMOLITION & ALTERATIONS				
4.1.1	See Demolition & Site Preparation heading	1	Item		INCL
4.2	SITE PREPARATION				
4.2.1	See Demolition & Site Preparation heading	1	Item		INCL
4.3	SUBSTRUCTURE				\$4,250.00
4.3.1	Bund wall around internal perimeter of external wall and exits - No specification on size of bund assumed 16mm	10	m3	\$425.00	\$4,249.99
4.4	STAIRS				
4.4.1	Stairs	1	Item		EXCL
4.5	UPPER FLOORS				
4.5.1	Upper Floors	1	Item		EXCL
4.6	COLUMNS				
4.6.1	Columns	1	Item		EXCL
4.7	ROOF				
4.7.1	Existing roof to remain no repairs required	1	Item		EXCL
4.8	EXTERNAL WALLS				\$2,940.00
4.8.1	Make good to external walls where opening have been formed	84	m	\$35.00	\$2,940.00
4.9	WINDOWS & EXTERNAL DOORS				\$16,850.00
4.9.1	Windows				
4.9.1.1	Existing windows to remain	1	Item		EXCL
4.9.2	External Doors				\$16,850.00
4.9.2.1	Existing single leaf doors to remain	3	No		EXCL
4.9.2.2	Roller shutter doors [8.0m wide x 5.0m high]	1	No	\$16,850.00	\$16,850.00
4.10	INTERNAL WALLS				
4.10.1	4m concrete block walls [Corefilled] - No finish	1	Item		EXCL
4.11	INTERNAL SCREENS & BORROWED LI	GHTS			
4.11.1	Internal screens & borrowed lights	1	Item		EXCL



4.12.1         Existing single leaf doors         2         No         EXCL           4.13.1         WALL FINISHES         Item         EXCL           4.14.1         FLOOR FINISHES         Item         EXCL           4.14.1         Neve pedestrian path delineate line marking marking marking marking marking marking         1         Item         EXCL           4.15.1         Celling Finishes         1         Item         EXCL           4.16.1         Joinery & METALWORK         1         Item         EXCL           4.17.1         FITMENTS, FITTINGS & EQUIPMENT         \$3,070.00         NOTED           4.17.1         Items shown an afrawings assumed form paint of FFRE schedule provided by the clent.         Item         EXCL           4.17.2         Handwash trough to remain         2         Item         EXCL           4.17.2         Handwash trough to remain         1         Item         EXCL           4.17.2         Handwash trough to remain         1         Item         EXCL           4.17.3         Safety, shower to remain         1         Item         EXCL           4.17.4         Handwash trough to remain and provise and beautiful and provised purposes         1         Item         EXCL           4.17.5         Saf			Quantity	Unit	Rate	Total
A.13	4.12	INTERNAL DOORS				
A.13.1   Wall finishes	4.12.1	Existing single leaf doors	2	No		EXCL
4.14   FLOOR FINISHES 4.14.1   New pedestrian path delineate line marking   1   Item   EXCL 4.15   CEILING FINISHES 4.15.1   Ceiling Finishes   1   Item   EXCL 4.16   JOINERY & METALWONK 4.16.1   Joinery & Metalwork   1   Item   EXCL 4.17   FITMENTS, FITTINGS & EQUIPMENT   \$3,070.00 4.17.1   Items shown on drawings assumed form part of FFRE schedule provided by the client form part of FFRE schedule provided by the client form part of FFRE schedule provided by the client   EXCL 4.17.3   Safety shower to remain   1   Item   EXCL 4.17.4   Handwash trough to remain   2   Item   EXCL 4.17.5   Safety shower to remain   1   Item   EXCL 4.17.6   Stardy of drills, grinders, welders,   1   Item   EXCL 4.17.5   Storage or racking for the above equipment - Existing assumed   1   Item   EXCL 4.17.6   Statutory Signage   614   m2   \$5.00   \$3,070.00 4.18   HYDRAULIC SERVICES 4.19   MECHANICAL SERVICES 4.19   MECHANICAL SERVICES 4.20.1   New Distribution boards   1   Item   EXCL 4.20.2   New Mainboards   1   Item   EXCL 4.20.3   Modification to existing power and comms layout for new equipment   580   m2   EXCL 4.20.4   Existing lighting to remain in current   1   Item   EXCL 4.20.5   FIRE SERVICES   \$6,140.00 4.21.1   Westprinkler system to building - Not required   614   m2   \$5.00   \$6,140.00 4.21.2   Dry fire services   614   m2   \$5.00   \$6,140.00	4.13	WALL FINISHES				
4.14.1         New pedestrian path delineate line marking         1         Item         EXCL           4.15         CEILING FINISHES         1         Item         EXCL           4.16.1         JOINERY & METALWORK         1         Item         EXCL           4.17         FITMENTS, FITTINGS & EQUIPMENT         \$3,070.00           4.17.1         Items shown on drawings assumed form part of FF&F schedule provided by the client         NOTED           4.17.1         Items shown on drawings assumed form part of FF&F schedule provided by the client         1         Item         EXCL           4.17.1         Handwash trough to remain         2         Item         EXCL           4.17.3         Safety shower to remain         1         Item         EXCL           4.17.4         Variety of drills, grinders, welders, holsts, power and holsts, power and least sufficient         1         Item         EXCL           4.17.5         Safety shower to remain         1         Item         EXCL           4.17.6         Statutory Signage         614         m2         \$5.00         \$3,070.00           4.18.1         Hydraulic - No changes to existing warehouse         1         Item         EXCL           4.19.1         MeCHANICAL SERVICES         1         Item	4.13.1	Wall finishes	1	Item		EXCL
### ### ##############################	4.14	FLOOR FINISHES				
4.15.1         Ceiling Finishes         1         Item         EXCL           4.16         JOINERY & METALWORK         1         Item         EXCL           4.17         FITMENTS, FITTINGS & EQUIPMENT         \$3,070.00           4.17.1         Items shown on drawings assumed form part of FFRE schedule provided by the client         NOTED from part of FFRE schedule provided by the client         NOTED form part of FFRE schedule provided by the client         EXCL           4.17.2         Handwash trough to remain         2         Item         EXCL           4.17.3         Safety shower to remain         1         Item         EXCL           4.17.4         Variety of drills, grinders, welders, holists, pneumatic tools and hand tools         1         Item         EXCL           4.17.5         Storage or racking for the above equipment - Existing assumed         1         Item         EXCL           4.17.5         Statutory Signage         614         m2         \$5.00         \$3,070.00           4.18         HYDRAULIC SERVICES           4.19.1         MECHANICAL SERVICES         1         Item         EXCL           4.19.1         Mechanical services - No changes to existing warehouse which was a sixting warehouse which was a sixt	4.14.1	· · · · · · · · · · · · · · · · · · ·	1	Item		EXCL
4.16.	4.15					
1   1   1   1   1   1   1   1   1   1	4.15.1	Ceiling Finishes	1	Item		EXCL
### ### ### ### ### ### ### ### ### ##	4.16	JOINERY & METALWORK				
4.17.1 Items shown on drawings assumed form part of FFRE schedule provided by the client form part of FFRE schedule provided by the client 4.17.2 Handwash trough to remain 2 Item EXCL 4.17.3 Safety shower to remain 1 Item EXCL 4.17.4 Variety of drills, grinders, welders, hoists, pneumatic tools and hand tools Storage or racking for the above equipment - Existing assumed sufficient 4.17.5 Statutory Signage 614 m2 \$5.00 \$3,070.00 4.18 HYDRAULIC SERVICES 4.18.1 Hydraulic - No changes to existing 1 Item EXCL 4.19.1 Mechanical services - No changes to existing warehouse 4.19.1 Mechanical services - No changes to existing 4.19.1 Item EXCL 4.20.2 New Mainboards 1 Item EXCL 4.20.1 New Distribution boards 1 Item EXCL 4.20.2 New Mainboards 1 Item EXCL 4.20.3 Modification to existing power and comms layout for new equipment comms layout for new equipment 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.21.1 Exervices \$6,140.00	4.16.1	Joinery & Metalwork	1	Item		EXCL
4.17.1       form part of FF&E schedule provided by the client       NOTED by the client         4.17.2       Handwash trough to remain       2       Item       EXCL         4.17.3       Safety shower to remain       1       Item       EXCL         4.17.4       Variety of drills, grinders, welders, hoists, pneumatic tools and hand tools       1       Item       EXCL         Storage or racking for the above equipment - Existing assumed       1       Item       EXCL         4.17.6       Statutory Signage       614       m2       \$5.00       \$3,070.00         4.18.1       HYDRAULIC SERVICES         4.18.1       HYDRAULIC SERVICES         4.19.1       MECHANICAL SERVICES       EXCL         4.19.1       Mechanical services - No changes to existing warehouse       1       Item       EXCL         4.20       ELECTRICAL SERVICES       1       Item       EXCL         4.20.1       New Distribution boards       1       Item       EXCL         4.20.2       New Mainboards       1       Item       EXCL         4.20.3       Modification to existing power and comms layout for new equipment       580       m2       EXCL         4.20.4       Existing lighting to remain in current locations       1       Item </td <td>4.17</td> <td>FITMENTS, FITTINGS &amp; EQUIPMENT</td> <td></td> <td></td> <td></td> <td>\$3,070.00</td>	4.17	FITMENTS, FITTINGS & EQUIPMENT				\$3,070.00
4.17.3 Safety shower to remain 1 Item EXCL 4.17.4 Variety of drills, grinders, welders, hoists, pneumatic tools and hand tools 5 Storage or racking for the above equipment - Existing assumed 1 Item EXCL 4.17.5 Statutory Signage 614 m2 \$5.00 \$3,070.00 4.18 HYDRAULIC SERVICES 4.18.1 Hydraulic - No changes to existing 1 Item EXCL 4.19 MECHANICAL SERVICES 4.19.1 Mechanical services - No changes to existing warehouse 1 Item EXCL 4.20 ELECTRICAL SERVICES 4.20.1 New Distribution boards 1 Item EXCL 4.20.2 New Mainboards 1 Item EXCL 4.20.3 Modification to existing power and comms layout for new equipment 580 m2 EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.20.5 FIRE SERVICES 4.21 FIRE SERVICES 56,140.00 4.21.1 Wet sprinkler system to building - Not required 614 m2 \$10.00 \$6,140.00	4.17.1	form part of FF&E schedule provided				NOTED
4.17.4 Variety of drills, grinders, welders, hoists, pneumatic tools and hand tools 4.17.5 Storage or racking for the above equipment - Existing assumed 4.17.6 Statutory Signage 614 m2 \$5.00 \$3,070.00 4.18 HYDRAULIC SERVICES 4.18.1 Hydraulic - No changes to existing warehouse 4.19 MECHANICAL SERVICES 4.19.1 Mechanical services - No changes to existing warehouse 4.20 ELECTRICAL SERVICES 4.20.1 New Distribution boards 1 Item EXCL 4.20.2 New Mainboards 1 Item EXCL 4.20.3 Modification to existing power and comms layout for new equipment comms layout for new equipment locations 4.20.4 Existing lighting to remain in current locations 4.21 FIRE SERVICES 4.21 Wet sprinkler system to building - Not required 4.21.2 Dry fire services 614 m2 \$10.00 \$6,140.00	4.17.2	Handwash trough to remain	2	Item		EXCL
hoists, pneumatic tools and hand tools  4.17.5 Storage or racking for the above equipment - Existing assumed  4.17.6 Statutory Signage  4.18 HYDRAULIC SERVICES  4.18.1 Hydraulic - No changes to existing warehouse  4.19 MECHANICAL SERVICES  4.19.1 Mechanical services - No changes to existing warehouse  4.20 ELECTRICAL SERVICES  4.20.1 New Distribution boards  4.20.2 New Mainboards  4.20.3 Modification to existing power and comms layout for new equipment  4.20.4 Existing lighting to remain in current locations  4.20.5 FIRE SERVICES  4.21.1 Wet sprinkler system to building - Not required  4.21.2 Dry fire services  4.17.5 Item  EXCL	4.17.3	Safety shower to remain	1	Item		EXCL
4.17.5       equipment - Existing assumed sufficient       1       Item       EXCL sufficient         4.17.6       Statutory Signage       614       m2       \$5.00       \$3,070.00         4.18       HYDRAULIC SERVICES         4.18.1       Hydraulic - No changes to existing warehouse       1       Item       EXCL         4.19       MECHANICAL SERVICES         4.19.1       Mechanical services - No changes to existing warehouse       1       Item       EXCL         4.20       ELECTRICAL SERVICES         4.20.1       New Distribution boards       1       Item       EXCL         4.20.2       New Mainboards       1       Item       EXCL         4.20.3       Modification to existing power and comms layout for new equipment locations       580       m2       EXCL         4.20.4       Existing lighting to remain in current locations       1       Item       EXCL         4.21.1       FIRE SERVICES       \$6,140.00         4.21.1       Wet sprinkler system to building - Not required       614       m2       \$10.00       \$6,140.00	4.17.4	hoists, pneumatic tools and hand tools	1	Item		EXCL
4.18 HYDRAULIC SERVICES  4.18.1 Hydraulic - No changes to existing warehouse 1 Item EXCL  4.19 MECHANICAL SERVICES  4.19.1 Mechanical services - No changes to existing warehouse 1 Item EXCL  4.20 ELECTRICAL SERVICES  4.20.1 New Distribution boards 1 Item EXCL  4.20.2 New Mainboards 1 Item EXCL  4.20.3 Modification to existing power and comms layout for new equipment 1 Ocations 1 Item EXCL  4.20.4 Existing lighting to remain in current 1 Item EXCL  4.21.1 Wet sprinkler system to building - Not required 1 Met sprinkler system to building - No	4.17.5	equipment - Existing assumed	1	Item		EXCL
4.18.1 Hydraulic - No changes to existing warehouse 1 Item EXCL  4.19 MECHANICAL SERVICES  4.19.1 Mechanical services - No changes to existing warehouse 1 Item EXCL  4.20 ELECTRICAL SERVICES  4.20.1 New Distribution boards 1 Item EXCL  4.20.2 New Mainboards 1 Item EXCL  4.20.3 Modification to existing power and comms layout for new equipment 2.20.4 Existing lighting to remain in current 1 Item EXCL  4.20.4 FIRE SERVICES  4.21.1 Wet sprinkler system to building - Not required  4.21.2 Dry fire services 614 m2 \$10.00 \$6,140.00	4.17.6	Statutory Signage	614	m2	\$5.00	\$3,070.00
4.19 MECHANICAL SERVICES  4.19 Mechanical services - No changes to existing warehouse    4.19.1 Mechanical services - No changes to existing warehouse    4.20 ELECTRICAL SERVICES  4.20.1 New Distribution boards	4.18	HYDRAULIC SERVICES				
4.19.1 Mechanical services - No changes to existing warehouse  4.20 ELECTRICAL SERVICES  4.20.1 New Distribution boards 1 Item EXCL 4.20.2 New Mainboards 1 Item EXCL 4.20.3 Modification to existing power and comms layout for new equipment 580 m2 EXCL 4.20.4 Existing lighting to remain in current 1 Item EXCL 4.21 FIRE SERVICES \$6,140.00  4.21.1 Wet sprinkler system to building - Not required 614 m2 EXCL 4.21.2 Dry fire services 614 m2 \$10.00 \$6,140.00	4.18.1	1	1	Item		EXCL
4.20 ELECTRICAL SERVICES  4.20.1 New Distribution boards 1 Item EXCL 4.20.2 New Mainboards 1 Item EXCL 4.20.3 Modification to existing power and comms layout for new equipment 1 Item EXCL 4.20.4 Existing lighting to remain in current locations 1 Item EXCL 4.21 FIRE SERVICES \$6,140.00  4.21.1 Wet sprinkler system to building - Not required 1 Prequired 1 Prequired 1 Prequired 1 Prequired 1 Prequired 1 Prepared 1 Prep	4.19	MECHANICAL SERVICES				
4.20.1 New Distribution boards 1 Item EXCL 4.20.2 New Mainboards 1 Item EXCL 4.20.3 Modification to existing power and comms layout for new equipment 580 m2 EXCL 4.20.4 Existing lighting to remain in current locations 1 Item EXCL 4.21 FIRE SERVICES \$6,140.00 4.21.1 Wet sprinkler system to building - Not required 614 m2 EXCL 4.21.2 Dry fire services 614 m2 \$10.00 \$6,140.00	4.19.1		1	Item		EXCL
4.20.2 New Mainboards 1 Item EXCL 4.20.3 Modification to existing power and comms layout for new equipment 580 m2 EXCL 4.20.4 Existing lighting to remain in current locations 1 Item EXCL  4.21 FIRE SERVICES \$6,140.00  4.21.1 Wet sprinkler system to building - Not required 1 m2 EXCL  4.21.2 Dry fire services 614 m2 \$10.00 \$6,140.00	4.20	ELECTRICAL SERVICES				
4.20.3 Modification to existing power and comms layout for new equipment 4.20.4 Existing lighting to remain in current locations  4.21 FIRE SERVICES  4.21.1 Wet sprinkler system to building - Not required  4.21.2 Dry fire services  580 m2  EXCL  EXCL  EXCL  4.20.4 Item  EXCL  \$6,140.00	4.20.1	New Distribution boards	1	Item		EXCL
4.20.4 Existing lighting to remain in current locations  4.21 FIRE SERVICES  4.21.1 Wet sprinkler system to building - Not required  4.21.2 Dry fire services  580 III2  1 Item  EXCL  586,140.00  56,140.00  56,140.00	4.20.2	New Mainboards	1	Item		EXCL
4.21       FIRE SERVICES       \$6,140.00         4.21.1       Wet sprinkler system to building - Not required       614       m2       EXCL         4.21.2       Dry fire services       614       m2       \$10.00       \$6,140.00	4.20.3		580	m2		EXCL
4.21.1 Wet sprinkler system to building - Not required 614 m2 EXCL 4.21.2 Dry fire services 614 m2 \$10.00 \$6,140.00	4.20.4		1	Item		EXCL
4.21.1 required 614 m2 \$10.00 \$6,140.00	4.21	FIRE SERVICES				\$6,140.00
4.21.2 Dry fire services 614 m2 \$10.00 \$6,140.00	4.21.1		614	m2		EXCL
4.21.3 Internal fire hydrant 1 Item EXCL	4.21.2	·	614	m2	\$10.00	\$6,140.00
	4.21.3	Internal fire hydrant	1	Item		EXCL



		Quantity	Unit	Rate	Total
4.22	LIFT SERVICES				
4.22.1	Lift services	1	Item		EXCL
4.23	BUILDERS WORK IN CONNECTION WIT	H SERVICES			\$307.00
4.23.1	Builders work in connection with services 5%	1	Item	\$307.00	\$307.00
4.24	SPECIAL EQUIPMENT				
4.24.1	Works to existing Inspection Pits or creation of new	1	Item		EXCL
4.24.2	Loading docks	1	Item		EXCL
4.24.3	Battery Storage	1	Item		EXCL
4.24.4	Air compressors	1	Item		EXCL
4.24.5	Wheel change	1	Item		EXCL
5	EXTERNAL WORKS AND SERVICES				\$1,028,562.00
5.1	EXTERNAL SERVICES				\$344,021.00
5.1.1	External Stormwater Services				\$287,681.00
5.1.1.1	Existing stormwater system to be retained				NOTED
5.1.1.2	Existing Detention tank	2	No		EXCL
5.1.1.3	Existing grated drain	27	m		EXCL
5.1.1.4	Existing water reuse tank	1	Item		EXCL
5.1.1.5	Connection to existing stormwater system	1	Item	\$5,000.00	\$5,000.00
5.1.1.6	New below ground OSD tank [110m3 storage and infiltration system with 120m2 (min) infiltration area -assumed infiltration rate 100mm/hr]	120	m2	\$1,200.00	\$144,000.00
5.1.1.7	Install Ocean Protect Storm Filter Cartridges	11	No	\$7,500.00	\$82,500.00
5.1.1.8	Supply and install 300mm dia RCP - Assumed size	159	m	\$259.00	\$41,181.00
5.1.1.9	Allowance for 900x900 reinforced concrete pits	6	No	\$2,500.00	\$15,000.00
5.1.1.10	Access lid	1	Item		INCL
5.1.2	External Sewer Services				
5.1.2.1	Connection to existing sewer system - No works to sewer system	1	Item		EXCL
5.1.3	External Water Supply				
5.1.3.1	Connection to existing water authority main	1	Item		EXCL
5.1.4	External Gas Supply				
5.1.4.1	Gas supply	1	Item		EXCL
5.1.5	External Fire Protection				



		Quantity	Unit	Rate	Total
5.1.5.1	Existing hydrants	8	No		EXCL
5.1.5.2	New fire hydrant	1	Item		EXCL
5.1.5.3	Upgrade existing fire hydrant system	1	Item		EXCL
5.1.6	External Electrical				\$56,340.00
5.1.6.1	New Substation	1	Item		EXCL
5.1.6.2	Amplification of existing services	1	Item		EXCL
5.1.6.3	Connection to external electrical supply	1	Item	\$5,000.00	\$5,000.00
5.1.6.4	External lighting	3,634	m2	\$10.00	\$36,340.00
5.1.6.5	Access control & communications system to weigh bridge	1	Item	\$15,000.00	\$15,000.00
5.1.6.6	External security	1	Item		EXCL
5.2	SITE & LANDSCAPING				\$684,541.00
5.2.1	Roads, Footpaths and Paving				\$358,741.00
5.2.1.1	Allowance to strip vegetative material and stockpile the material on site	60,568	m2	\$0.75	\$45,426.00
5.2.1.2	Bulk excavation including road box out to depth n.e 300mm thick	970	m3	\$50.00	\$48,500.00
5.2.1.3	Unbound granular pavement: subgrade, 150mm thick DGS40 or equivalent compacted to 95% MMDD, 150mm thick (RCC) recycled crushed concrete compacted to 98% MMDD [Assumed no details provided]	3,231	m2	\$75.00	\$242,325.00
5.2.1.4	Line marking	467	m	\$5.00	\$2,335.00
5.2.1.5	Wheel stops	10	No	\$120.00	\$1,200.00
5.2.1.6	Kerb	189	m	\$85.00	\$16,065.00
5.2.1.7	Concrete drop edge	34	m	\$85.00	\$2,890.00
5.2.1.8	Re-profile and lay asphalt to existing concrete surface	1	Item		EXCL
5.2.2	Fencing and Gates				\$70,440.00
5.2.2.1	Retain existing mesh fence	658	m		EXCL
5.2.2.2	Ex. double Gate	1	No		EXCL
5.2.2.3	Ex. sliding gate	1	No		EXCL
5.2.2.4	New security fence	371	m	\$140.00	\$51,940.00
5.2.2.5	Boom gate	1	No	\$3,500.00	\$3,500.00
5.2.2.6	Sliding gate	1	No	\$15,000.00	\$15,000.00
5.2.3	External Structures				\$255,360.00
5.2.3.1	AWS 26m weighbridge single lane bridge - Provisional Sum	1	Item	\$80,000.00	\$80,000.00
5.2.3.2	Existing security office	1	Item		EXCL
5.2.3.3	Existing compressors	1	No		EXCL



		Quantity	Unit	Rate	Total
5.2.3.4	Existing cooling towers	1	No		EXCL
5.2.3.5	New lightweight roof assumed with posts over diesel tank	162	m2	\$280.00	\$45,360.00
5.2.3.6	New Diesel tank & bunded refuelling area [ 60,000L] - Provisional Sum] New waste oil tank - No specification	1	No	\$65,000.00	\$65,000.00
5.2.3.7	provided, assumed same size as New tank above -Provisional Sum	1	No	\$65,000.00	\$65,000.00
5.2.4	Landscaping and Improvements				
5.2.4.1	Soft landscaping	1	Item		EXCL
5.2.5	Retaining Walls				
5.2.5.1	Retaining Wall	1	Item		EXCL
6	PRELIMINARIES & MARGIN				\$815,952.00
6.1	Allowance for Builders preliminaries, overhead & margin (10%)	1	Item	\$815,952.00	\$815,952.00
7	IDENTIFIED RISK ITEMS				
7.1	Identified risk items	1	Item		EXCL
8	CONSTRUCTION CONTINGENCY				
8.1	Allowance for general construction contingency	1	Item		EXCL
8.2	Design Development allowance	1	Item		EXCL
9	PROFESSIONAL FEES				
9.1	Professional Fees	1	Item		EXCL
10	AUTHORITY FEES AND CONTRIBUTIONS				
10.1	Authority Fees	1	Item		EXCL
11	ESCALATION				
11.1	Escalation	1	item		EXCL
12	\$/m2 - GFA - 10,110 m2			\$887.78	
				Subtotal	\$8,975,468.00
			_	Adjustment	\$0.00
				Total	\$8,975,468.00