




4A

POINT	NORTHING	EASTING	CURVE
831	50496.120	822.824	
950	50500.011	823.546	
951	50501.184	823.237	
23	50496.766	823.643	
309	50495.360	823.818	
341	50513.856	823.135	RAD=172.000
345	50530.092	823.312	R=107.000
349	50543.488	823.183	ARC=29.671
351	50546.261	823.150	RAD=17.000
355	50559.457	823.051	R=196.331
359	50573.063	823.156	ARC=27.032
741	50710.648	824.244	RAD=40.000
745	50707.440	823.216	R=157.000
749	50720.852	824.431	ARC=10.472
751	50721.519	824.569	RAD=15.000
755	50716.490	825.920	R=75.000
759	50731.442	826.401	ARC=19.635
783	50730.452	827.727	

4B

POINT	NORTHING	EASTING	CURVE
461	50512.111	823.164	R=111.500
465	50510.111	823.202	R=111.500
469	50508.111	823.171	ARC=8.217
471	50511.111	823.181	RAD=15.000
475	50513.111	823.181	R=157.000
479	50515.111	823.171	ARC=8.217
389	50512.111	823.164	
513	50483.813	824.272	RAD=0.500
425	50487.813	823.171	R=125.000
431	50489.813	823.171	R=125.000
435	50491.813	823.171	R=125.000
439	50493.813	823.171	R=125.000
443	50495.813	823.171	R=125.000
447	50497.813	823.171	R=125.000
451	50499.813	823.171	R=125.000
455	50501.813	823.171	R=125.000
459	50503.813	823.171	R=125.000
463	50505.813	823.171	R=125.000
467	50507.813	823.171	R=125.000
471	50509.813	823.171	R=125.000
475	50511.813	823.171	R=125.000
479	50513.813	823.171	R=125.000
483	50515.813	823.171	R=125.000
487	50517.813	823.171	R=125.000
491	50519.813	823.171	R=125.000
495	50521.813	823.171	R=125.000
499	50523.813	823.171	R=125.000

4C

POINT	SETTING OUT DATA		
	NORTHING	EASTING	CURVE
441	50509.111	824.111	R=111.500
445	50507.111	824.111	R=111.500
449	50505.111	824.111	R=111.500
453	50503.111	824.111	R=111.500
457	50501.111	824.111	R=111.500
461	50499.111	824.111	R=111.500
465	50497.111	824.111	R=111.500
469	50495.111	824.111	R=111.500
473	50493.111	824.111	R=111.500
477	50491.111	824.111	R=111.500
481	50489.111	824.111	R=111.500
485	50487.111	824.111	R=111.500
489	50485.111	824.111	R=111.500
493	50483.111	824.111	R=111.500
497	50481.111	824.111	R=111.500
501	50479.111	824.111	R=111.500
505	50477.111	824.111	R=111.500
509	50475.111	824.111	R=111.500
513	50473.111	824.111	R=111.500
517	50471.111	824.111	R=111.500
521	50469.111	824.111	R=111.500
525	50467.111	824.111	R=111.500
529	50465.111	824.111	R=111.500
533	50463.111	824.111	R=111.500
537	50461.111	824.111	R=111.500
541	50459.111	824.111	R=111.500
545	50457.111	824.111	R=111.500
549	50455.111	824.111	R=111.500
553	50453.111	824.111	R=111.500
557	50451.111	824.111	R=111.500
561	50449.111	824.111	R=111.500
565	50447.111	824.111	R=111.500
569	50445.111	824.111	R=111.500
573	50443.111	824.111	R=111.500
577	50441.111	824.111	R=111.500
581	50439.111	824.111	R=111.500
585	50437.111	824.111	R=111.500
589	50435.111	824.111	R=111.500
593	50433.111	824.111	R=111.500
597	50431.111	824.111	R=111.500
601	50429.111	824.111	R=111.500
605	50427.111	824.111	R=111.500
609	50425.111	824.111	R=111.500
613	50423.111	824.111	R=111.500
617	50421.111	824.111	R=111.500
621	50419.111	824.111	R=111.500
625	50417.111	824.111	R=111.500
629	50415.111	824.111	R=111.500
633	50413.111	824.111	R=111.500
637	50411.111	824.111	R=111.500
641	50409.111	824.111	R=111.500
645	50407.111	824.111	R=111.500
649	50405.111	824.111	R=111.500
653	50403.111	824.111	R=111.500
657	50401.111	824.111	R=111.500
661	50399.111	824.111	R=111.500
665	50397.111	824.111	R=111.500
669	50395.111	824.111	R=111.500
673	50393.111	824.111	R=111.500
677	50391.111	824.111	R=111.500
681	50389.111	824.111	R=111.500
685	50387.111	824.111	R=111.500
689	50385.111	824.111	R=111.500
693	50383.111	824.111	R=111.500
697	50381.111	824.111	R=111.500
701	50379.111	824.111	R=111.500
705	50377.111	824.111	R=111.500
709	50375.111	824.111	R=111.500
713	50373.111	824.111	R=111.500
717	50371.111	824.111	R=111.500
721	50369.111	824.111	R=111.500
725	50367.111	824.111	R=111.500
729	50365.111	824.111	R=111.500
733	50363.111	824.111	R=111.500
737	50361.111	824.111	R=111.500
741	50359.111	824.111	R=111.500
745	50357.111	824.111	R=111.500
749	50355.111	824.111	R=111.500
753	50353.111	824.111	R=111.500
757	50351.111	824.111	R=111.500
761	50349.111	824.111	R=111.500
765	50347.111	824.111	R=111.500
769	50345.111	824.111	R=111.500
773	50343.111	824.111	R=111.500
777	50341.111	824.111	R=111.500
781	50339.111	824.111	R=111.500
785	50337.111	824.111	R=111.500
789	50335.111	824.111	R=111.500
793	50333.111	824.111	R=111.500
797	50331.111	824.111	R=111.500
801	50329.111	824.111	R=111.500
805	50327.111	824.111	R=111.500
809	50325.111	824.111	R=111.500
813	50323.111	824.111	R=111.500
817	50321.111	824.111	R=111.500
821	50319.111	824.111	R=111.500
825	50317.111	824.111	R=111.500
829	50315.111	824.111	R=111.500
833	50313.111	824.111	R=111.500
837	50311.111	824.111	R=111.500
841	50309.111	824.111	R=111.500
845	50307.111	824.111	R=111.500
849	50305.111	824.111	R=111.500
853	50303.111	824.111	R=111.500
857	50301.111	824.111	R=111.500
861	50299.111	824.111	R=111.500
865	50297.111	824.111	R=111.500
869	50295.111	824.111	R=111.500
873	50293.111	824.111	R=111.500
877	50291.111	824.111	R=111.500
881	50289.111	824.111	R=111.500
885	50287.111	824.111	R=111.500
889	50285.111	824.111	R=111.500
893	50283.111	824.111	R=111.500
897	50281.111	824.111	R=111.500
901	50279.111	824.111	R=111.500
905	50277.111	824.111	R=111.500
909	50275.111	824.111	R=111.500
913	50273.111	824.111	R=111.500
917	50271.111	824.111	R=111.500
921	50269.111	824.111	R=111.500
925	50267.111	824.111	R=111.500
929	50265.111	824.111	R=111.500
933	50263.111	824.111	R=111.500
937	50261.111	824.111	R=111.500
941	50259.111	824.111	R=111.500
945	50257.111	824.111	R=111.500
949	50255.111	824.111	R=111.500
953	50253.111	824.111	R=111.500
957	50251.111	824.111	R=111.500
961	50249.111	824.111	R=111.500
965	50247.111	824.111	R=111.500
969	50245.111	824.111	R=111.500
973	50243.111	824.111	R=111.500
977	50241.111	824.111	R=111.500
981	50239.111	824.111	R=111.500
985	50237.111	824.111	R=111.500
989	50235.111	824.111	R=111.500
993	50233.111	824.111	R=111.500
997	50231.111	824.111	R=111.500
1001	50229.111	824.111	R=111.500
1005	50227.111	824.111	R=111.500
1009	50225.111	824.111	R=111.500
1013	50223.111	824.111	R=111.500
1017	50221.111	824.111	R=111.500
1021	50219.111	824.111	R=111.500
1025	50217.111	824.111	R=111.500
1029	50215.111	824.111	R=111.500
1033	50213.111	824.111	R=111.500
1037	50211.111	824.111	R=111.500
1041	50209.111	824.111	R=111.500
1045	50207.111	824.111	R=111.500
1049	50205.111	824.111	R=111.500
1053	50203.111	824.111	R=111.500
1057	50201.111	824.111	R=111.500
1061	50199.111	824.111	R=111.500
1065	50197.111	824.111	R=111.500
1069	50195.111	824.111	R=111.500
1073	50193.111	824.111	R=111.500
1077	50191.111	824.111	R=111.500
1081	50189.111	824.111	R=111.500
1085	50187.111	824.111	R=111.500
1089	50185.111	824.111	R=111.500
1093	50183.111	824.111	R=111.500
1097	50181.111	824.111	R=111.500
1101	50179.111	824.111	R=111.500
1105	50177.111	824.111	R=111.500
1109	50175.111	824.111	R=111.500
1113	50173.111	824.111	R=111.500
1117	50171.111	824.111	R=111.500
1121	50169.111	824.111	R=111.500
1125	50167.111	824.111	R=111.500
1129	50165.111	824.111	R=111.500
1133	50163.111	824.111	R=111.500
1137	50161.111	824.111	R=111.500
1141	50159.111	824.111	R=111.500
1145	50157.111	824.111	R=111.500
1149	50155.111	824.111	R=111.500
1153	50153.111	824.111	R=111.500
1157	50151.111	824.111	R=111.500
1161	50149.111	824.111	R=111.500
1165	50147.111	824.111	R=111.500
1169	50145.111	824.111	R=111.500
1173	50143.111	824.111	R=111.500
1177	50141.111	824.111	R=111.500
1181	50139.111	824.111	R=111.500
1185	50137.111	824.111	R=111.500
1189	50135.111	824.111	R=111.500
1193	50133.111	824.111	R=111.500
1197	50131.111	824.111	R=111.500
1201	50129.111	824.111	R=111.500
1205	50127.111	824.111	R=111.500
1209	50125.111	824.111	R=111.500
1213	50123.111	824.111	R=111.500
1217	50121.111	824.111	R=111.500
1221	50119.111	824.111	R=111.500
1225	50117.111	824.111	R=111.500
1229	50115.111	824.111	R=111.500
1233	50113.111	824.111	R=111.500
1237	50111.111	824.111	R=111.500
1241	50109.111	824.111	R=111.500
1245	50107.111	824.111	R=111.500
1249	50105.111	824.111	R=111.500
1253	50103.111	824.111	R=111.500
1257	50101.111	824.111	R=111.500
1261	50099.111	824.111	R=111.500
1265	50097.111	824.111	R=111.500
1269	50095.111	824.111	R=111.500
1273	50093.111	824.111	R=111.500
1277	50091.111	824.111	R=111.500
1281	50089.111	824.111	R=111.500
1285	50087.111	824.111	R=111.500
1289	50085.111	824.111	R=111.500
1293	50083.111	824.111	R=111.500
1297	50081.111	824.111	R=111.500
1301	50079.111	824.111	R=111.500
1305	50077.111	824.111	R=111.500
1309	50075.111	824.111	R=111.500
1313	50073.111	824.111	R=111.500
1317	50071.111	824.111	R=111.500
1321	50069.111	824.111	R=111.500
1325	50067.111	824.111	R=111.500
1329	50065.111	824.111	R=111.500
1333	50063.111	824.111	R=111.500
1337	50061.111	824.111	R=111.500
1341	50059.111	824.111	R=111.500
1345	50057.111	824.111	R=111.500
1349	50055.111	824.111	R=111.500
1353	50053.111	824.111	R=111.500
1357	50051.111	824.111	R=111.500
1361	50049.111	824.111	

