

SANDSTONE PRECINCT

DESIGN REVIEW PANEL - ADVICE 13

13 July 2020

PANEL

Brian Zulaikha

Peter Mould

Kerry Clare

ISSUE

The Panel was briefed on a range of changes that have been generated through design development, manufacture or supply. The Panel understands the reasons behind the changes and is generally supportive, as outlined in advice below.

ADVICE

EXTERNAL FAÇADE CHANGES

- . *Curved glass radius increase to 1500mm (External and Internal) & Mullion adjustment around curved glass corners.*
- . *External North elevation changes to cladding on level 9*
- . *External East elevation hidden door relocation on level 9*

The Panel supports these changes.

INTERNAL COURTYARD FAÇADE CHANGES

- . *Increased radius of curved glass to 1500mm and removal of West curved glass*
- . *West Elevation - Changes to louvres and spandrels in courtyard*
- . *East Elevation - Changes to louvres and hoods in courtyard.*

The Panel supports these changes.

It was agreed that more detailed drawings and materials samples supporting these issues would be provided for further Panel review.



Brian Zulaikha



Kerry Clare



Peter Mould