


Prepared for: Qube Property Management Services Pty Ltd c/o Tactical Group Pty Ltd EP1340.003_v2 | 4 February 2020













Qube Property Management Services Pty Ltd c/o Tactical Group Pty Ltd Level 27, 45 Clarence Street Sydney NSW 2000

Via email: feichen@tacticalgroup.com.au

Attention: Mr Fei Chen

Technical Note – Contaminated Land Project Bell – 400 Moorebank Avenue Moorebank NSW

INTRODUCTION

Qube Property Management Services Pty Ltd c/o Tactical Group Pty Ltd (Tactical) engaged EP Risk Management Pty Ltd (EP Risk) to provide a technical note regarding the boundary of Contaminated Land Assessments (CLAs) undertaken within the Moorebank Precinct West Stage 2 (MPW Stage 2) in comparison to the Project Bell footprint (Attachment 1).

MPW Stage 2 is identified legally as Lots 1, 2 and 3 Deposited Plan (DP) 1197707 and Lots 100 and 101 DP 1049508 and part Anzac Road and Moorebank Avenue public road reserves.

The MPW Stage 2 development has been approved under State Significant Development (SSD) 7709.

It is understood the proposed Project Bell footprint (Attachment 1) falls within the MPW Stage 2 boundary.

BACKGROUND

A number of previous CLAs have been undertaken across Lot 1 DP 1197707 and Lot 100 DP 1049508.

In July 2014, Site Auditor Frank Mohen issued a part B Audit Statement¹ stating the Moorebank Land Preparation Work - Demolition and Remediation (LPWDR) site could be made suitable for commercial/industrial use subject to implementation of the Parsons Brinkerhoff Moorebank Intermodal Terminal Preliminary Remediation Action Plan (RAP), May 2014. Subsequent to the issuing of the part B Audit Statement, the development consent (SSD 5066) for the intermodal development required the subject site be remediated in accordance with the RAP, SEPP 55² and guidelines in force under the Contaminated Land Management (CLM) Act. Amendments to the approved RAP as a result of further site investigations would require approval by a Site Auditor, in consultation with the NSW EPA.

Golder Associates Pty Ltd (Golder) was commissioned by the Moorebank Intermodal Company (MIC) to undertake data gap investigations (Golder, 2015³) and subsequently Tactical commissioned Golder to amend the RAP (Golder, 2016a⁴). The objective of the RAP was to remediate and/or manage

⁴ Moorebank Intermodal Company Property West Land Preparation Works Stage 1 and Stage 2 – Remediation Action Plan, Golder Associates, 9 August 2016 (Golder 2016a)








Sydney

¹ Site Audit Report and Site Audit Statement Moorebank Intermodal Terminal, Moorebank, NSW, AECOM Australia Pty Ltd Mr Frank Mohen NSW EPA Accredited Site Auditor No.9801, 10 July 2014 (AECOM 2014).

² State Environmental Planning Policy No 55 – Remediation of Land. 31 August 2018 (SEPP 55).

³ Post Phase 2 Environmental Site Assessment. Golder Associates (Golder 2015)





contamination risks at the site, such that the site is suitable for the proposed commercial / industrial land use or conservation / open space land use.

James Davis of Enviroview Pty Ltd was engaged in 2016 to provide the services of a NSW EPA Contaminated Land Accredited Site Auditor in relation to the Moorebank Intermodal Terminal and reviewed the RAP (Golder 2016a). Mr Davis concluded ...the RAP provided meets the requirements of the guidelines and it is my opinion that the site can be made suitable with the implementation of the RAP... (Enviroview 2016⁵).

To render the site suitable for the proposed land use, remedial works for the site were undertaken in accordance with the requirements of the RAP (Golder 2016a), and the outcomes provided in the Validation Report for Land Preparation Work – Demolition and Remediation MPW, Moorebank, NSW (JBS&G 2019a⁶).

CONCLUSION

Given the Project Bell footprint (**Attachment 1**) is situated within the assessment areas located within Lot 1 DP1197707 and Lot 100 DP 1049508, it is confirmed the Secretary's Environmental Assessment Requirements (SEARs) addressed within SSD 7709 and SSD 5066 and its associated MOD (MPW Concept Plan – Modification 1 SSD-5066-MOD1) remain unchanged in relation to contamination for the Project Bell proposal.

CLOSURE

Please feel free to contact the undersigned on 0408 811 549 should you have any queries.

Yours sincerely

Kellie Guenther

Principal Environmental Scientist Certified Environmental Practitioner – Site Contamination EP Risk Management Pty Ltd

ABN: 81 147 147 591

Xalie lucatro

Attachments

Attachment 1 - SSD 7709 Modification Proposal

⁵ Site Audit Interim Advice – Golder Associates, Moorebank Intermodal Terminal Stage Specific Remediation Action Plan, Enviroview Pty Ltd, Letter to Tactical Group dated 22 August 2016 from Mr James Davis (Enviroview 2016).

⁶ Remediation Validation Report Land Preparation Work – Demolition and Remediation Moorebank Intermodal Company Property West, JBS&G Australia Pty Ltd, 31 January 2019 Ref: 51997-120265/Rev A (JBS&G 2019a).

4 February 2020 Ref: EP1340.003_LTR01




QUALITY CONTROL

| Version | Author | Date | Reviewer | Date | Quality Review | Date |
|---------|-------------|------------|------------|------------|----------------|------------|
| v1 | K. Guenther | 02.12.2019 | P. Simpson | 02.12.2019 | P. Simpson | 02.12.2019 |
| V2 | K. Guenther | 04.02.2020 | P. Simpson | 02.12.2019 | P. Simpson | 02.12.2019 |

DOCUMENT CONTROL

| Version | Date | Reference | Submitted to |
|---------|------------|------------------|---|
| V2 | 04.02.2020 | EP1340.003 LTR01 | Qube Property Management Services Pty Ltd c/o Tactical Group Pty Ltd |





LIMITATIONS

This Technical Note – Contaminated Land was conducted on the behalf of Qube Property Management Services Pty Ltd c/o Tactical Group Pty Ltd for the purpose/s stated in the Introduction section.

The scope of work undertaken was specifically to address Project Bell requirements and the remit of the advice provided herein does not constitute a site investigation nor technical review of the Site.

EP Risk has prepared this document in good faith, but is unable to provide certification outside of areas over which EP Risk had some control or were reasonably able to check. The report also relies upon information provided by third parties. EP Risk has undertaken all practical steps to confirm the reliability of the information provided by third parties and do not accept any liability for false or misleading information provided by these parties.

It is not possible in an Technical Note – Contaminated Land to present all data, which could be of interest to all readers of this report. Readers are referred to any referenced investigation reports for further data.

Users of this document should satisfy themselves concerning its application to, and where necessary seek expert advice in respect to, their situation.


All work conducted and reports produced by EP Risk are based on a specific scope and have been prepared for Technical Note – Contaminated Land and therefore cannot be relied upon by any other third parties unless agreed in writing by EP Risk.

The report(s) and/or information produced by EP Risk should not be reproduced and/or presented/reviewed except in full.

4 February 2020 Ref: EP1340.003_LTR01



Attachment 1 – SSD 7709 Modification Proposal



PRELIMINARY - FOR DISCUSSION ONLY

| Notes | Issue | Description | Date | | | | Client | Managing Consultant |
|--|-----------|----------------|------------|--|---------|----------------|--------|-------------------------|
| -This drawing and design is subject to Reid Campbell (NSW) Pty Ltd copyright and may not be reproduced without prior written consent. | A Issue f | or Information | 27/11/2019 | REIDCAMPBELL | CONCEPT | | | |
| -Contractor to verify all dimensions on site before commencing work. | ζ. | | | Architecture, Interiors, Project Management | CONCEPT | | | |
| -Report all discrepancies to project manager prior to construction. -Figured dimensions to be taken in preference to scaled drawings. | | | | ACN 002 033 801 ABN 28 317 605 875 | DESIGN | | | TACTICA |
| -All work is to conform to relevant Australian Standards and other Codes as applicable, together with other Authorities' requirements | | | | Level 15, 124 Walker Street North Sydney NSW 2060 Australia | DESIGN | MOOREBANK | | |
| and regulations. | | | | Tel: 61 02 9954 5011 Email: sydney@reidcampbell.com | | LOGISTICS PARK | | |
| 10115 | | | | Fax: 61 02 9954 4946 Web: www.reidcamphell.com | | | | |

NSW Registered Architect James Webb, 10187



| Project | | | | | | | |
|---|--|--|--|--|--|--|--|
| MOOREBANK LOGISTICS | | | | | | | |
| PARK 400 MOOREBANK AVENUE, MOOREBANK, NSW | | | | | | | |
| Drawn Charlest Drint Data | | | | | | | |

AM MF 27/11/2019 5:22:02 PM

SSD 7709 MODIFICATION PROPOSAL

LEGEND

─ • ─ MPW SSD 2 OPERATIONAL BOUNDARY

---- PROJECT BELL PROPOSED BOUNDARY

PROPOSED STAGE 2

DEVELOPMENT TABLE

WAREHOUSE 1A

WAREHOUSE 1B

WAREHOUSE 2A

WAREHOUSE 2B

WAREHOUSE JR

WAREHOUSE JN

SSD 7709 MOD TOTAL

WAREHOUSE AREAS

LAND PARTNERS SURVEY - PREC-

OPERATIONAL BOUNDARY

(APPROX)

21,000m²

20,600m²

39,500m²

57,958m²

33,721m²

42,221m²

215,000m²

LPN-SU-DWG-0001_01 Plan of Coordinates of Boundaries; DATED

PIWW-RCG-AR-SKC-155

