

TRADING AS



15 Econo Place Silverdale 2752  
POSTAL: PO Box 32 Silverdale NSW 2752  
sepservice@bigpond.net.au



1300 132 666

### AERATED SEPTIC SYSTEM SERVICE ADVICE

CUSTOMER COPY

**Contract No. & Council:** 5661 Wollondilly Shire Council  
**Name:** Allied Mills Australia Pty Ltd  
**Address:** 330 Picton Road MALDON  
**Brand:** Econocycle Maxi 30/4  
**Identification:**  
**Customer Email:** accountspayable.picton@alliedpinnacle.com.au

|                           |                                         |         |
|---------------------------|-----------------------------------------|---------|
| <b>General Inspection</b> | Free chlorine (mg/L):                   | 0.3     |
|                           | Water meter reading (L):                |         |
| <b>Septic Tank</b>        | Check sludge depth:                     | Med     |
|                           | Check scum depth:                       | Med     |
|                           | Is desludge required?:                  | No      |
|                           | Are septic junctions in place?:         | Yes     |
|                           | Excessive kitchen fats?:                | Yes     |
|                           | Garbage in septic section?:             |         |
| <b>Aeration Tank</b>      | Blower - Check pressure:                | Good    |
|                           | Blower - Check noise:                   | Low     |
|                           | Blower Filter:                          | Replace |
|                           | Pump - Check flow:                      | Good    |
|                           | Circulating Pump Operating:             |         |
|                           | Inspect connections & fittings:         | Good    |
|                           | Inspect water flow through unit:        | Good    |
|                           | Check &/or adjust air controls:         | Yes     |
|                           | Check &/or adjust sludge & scum return: | Yes     |
|                           | U.V. Lamp:                              |         |
|                           | Inspect bio-mass/filter media:          | Good    |
|                           | Inspect clarifier clarity:              | Good    |
|                           | Inspect retention chamber clarity:      | Good    |
|                           | 10 mins. Settlement test 500ml:         |         |
|                           | Replenish chlorine No. of tablets:      | 12      |
|                           | Check chlorinator:                      | Yes     |
|                           | Do tablets contain cyanurate?:          | Yes     |
| <b>Irrigation</b>         | Inspect sprinklers operational:         | Yes     |
|                           | Inspect irrigation area for ponding:    | Yes     |
|                           | Clean Irrigation filter:                |         |

**Technician's Name:** Neville Mellish **Date:** 29/05/2020  
**Notes (if any):** Replaced filters and changed signs. charged for time to do induction (Inv 35245 \$84.00)