

Appendix B

Site photographs



Photograph 1: View of south east corner of Woodville Reservoir footprint.



Photograph 2: View of north east corner of Woodville Reservoir footprint.



Photograph 3: View looking west over Woodville Reservoir footprint.




Photograph 4: View of excavation next to Woodville reservoir footprint, uncovering building material and water.



Photograph 5: View of typical soil profile at most locations.



Photograph 6: View of excavator on roadside, Barbers Street



Photograph 7: Locater marking out services



Photograph 8: View of excavation in Durham Street showing small layer of ash present



Photograph 9: View of excavation showing typical red to grey mottled clay layer encountered where ASS soils are present.