



APPENDIX D



Unattended Noise Monitoring Data







D









Project: Integra Independent Review
Location: 997 Bridgman Road, Garvie Residence
Filter: 1000HP:Raw



































































Project: Integra Independent Review
Location: 74 Thomas Lane, Craven Residence
Filter: 1000LP:A:Raw





























































Project: Integra Independent Review
Location: 936 Middle Falbrook Road, Cheetham Residence
Filter: 1000LP:A:Raw

